



Inspection Report

Inspection Date: See Recorded Date	Inspect History ID: 3108260 - 1 Monthly - WFE Safety Inspection of C609-BANBRIDGE / CRAIGAVON on 09/02/2024	Inspection Type: 1 Monthly - WFE Safety Inspection
		Inspector:

Section Code: 7060C0706_01	Section Description: KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD
--------------------------------------	--

Defect Ref: DCD249016000	Defect Type: DEFECT	Comments: Bt manhole surround deteriorating	Location Description: Outside kiln avenue	Priority: R2 - 5 Working days	Defect Dimensions: Length (m): 2.50	Width (m): 1.35	Depth (mm): 90.00
--	-------------------------------	---	---	---	---	------------------------	--------------------------

Recorded Date: 14-February-2024
Recorded By: [REDACTED]

Repair Description: D24023A	Repair Item Name: ^ 70mm bit. patch w/c 3-15 m2	Quantity: 3.38	Units: SQ.M	Repair Measures: L 2.50 W 1.35 D 0.00
---------------------------------------	---	--------------------------	-----------------------	---

Defect Ref: DCD249021183	Defect Type: THIRD PARTY REFERRAL	Comments: ?	Location Description: 10m from kiln avenue	Priority: R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
--	---	-----------------------	--	---	--	-------------------	--------------------

Recorded Date: 20-February-2024
Recorded By: [REDACTED]



Inspection Report

Inspection Date: See Recorded Date	Inspect History ID: -	Inspection Type:
		Inspector:

Section Code: 7060C0706_01	Section Description: KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD
--------------------------------------	--

Defect Ref: D249028121	Defect Type: DEFECT	Comments: Make safe / replace manhole cover. Made safe by O&M Steel Plate 1/3/24 Passed to Small Scale Contractor [REDACTED] repaired 2/3/24	Location Description: Kiln Road at Traffic Lights	Priority: R2 - 5 Working days	Defect Dimensions: Length (m): 50.00	Width (m): 0.00	Depth (mm): 0.00
--	-------------------------------	--	---	---	---	------------------------	-------------------------

Recorded Date: 28-February-2024
Recorded By: [REDACTED]

MANHOLE LID/COVER BROKEN (MMBR)

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
U06050A	Gully top (D400) 150mm deep x (600mm x 600mm) double triangular	1.00	no	L 0.00 W 0.00 D 0.00

Defect Ref: D249050507	Defect Type: ROADS SERVICE EMERGENCY RESPONSE	Comments: Sign off loose Manhole Cover	Location Description: Kiln Road near Kiln Avenue	Priority: R0 - As Soon As Practical	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
--	---	--	--	---	---	-------------------	--------------------

Recorded Date: 08-April-2024
Recorded By: [REDACTED]

CULVERT / MANHOLE COLLAPSE (CMER)

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
G01001A	^ Unplanned envir. work norm.hrs (2-man operation)	1.00	HR	L 0.00 W 0.00 D 0.00



Inspection Report

Inspection	Date: See Recorded Date	Inspect History ID: 3109180 - 1 Monthly - WFE Safety Inspection of C506-BANBRIDGE / CRAIGAVON on 04/04/2024	Inspection Type: 1 Monthly - WFE Safety Inspection
			Inspector:

Section Code: 7060C0706_01	Section Description: KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD
--------------------------------------	--

Defect Ref: [DCD249063156](#) Defect Type: DEFECT Comments: ? Location Description: Lough road / kiln road traffic lights Priority: R2 - 5 Working days Defect Dimensions: Length (m): 1.50 Width (m): 0.90 Depth (mm): 85.00

Recorded Date: 24-April-2024 ASPHALT POTHOLE (CAPH)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures				
D24022A	^ 70mm bit. patch w/c 1-3 m2	1.72	SQ.M	L 1.50	W 1.15	D 0.00		
D24022A	^ 70mm bit. patch w/c 1-3 m2	1.43	SQ.M	L 1.30	W 1.10	D 0.00		
D24021A	^ 70mm bit. patch w/c <1 m2	1.00	no	L 0.00	W 0.00	D 0.00		



Inspection Report

Inspection Date: 3-Mar-2024 Inspect History ID: 3108149 - 3 Monthly - WFE Safety Inspection of C506-BANBRIDGE / CRAIGAVON on 04/02/2024 Inspection Type: 3 Monthly - WFE Safety Inspection
 Inspector: [REDACTED]

Section Code: 7060C0706_01 Section Description: KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD

Defect Ref: [DCD249030066](#) Defect Type: DEFECT Comments: ? Location Description: At Silverwood Green junction Priority: R3 - 4 Weeks Defect Dimensions: Length (m): 0.40 Width (m): 0.30 Depth (mm): 27.00

Recorded Date: 03-March-2024 ASPHALT POTHOLE (CAPH)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D24421A	70mm deep Bitmac W/C patch in 14mm CGA - 0-1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Defect Ref: [DCD249030067](#) Defect Type: THIRD PARTY REFERRAL Comments: Cover noisy. Damage to surrounding area Location Description: Near Kiln Lane junction Priority: R4 - next available programme Defect Dimensions: Length (m): Width (m): Depth (mm):

Recorded Date: 03-March-2024 UTILITY MANHOLE LID/COVER DEFECTIVE (UMDF)

Recorded By: [REDACTED]



Inspection Report

Inspection Date: 3-Mar-2024 Inspect History ID: 3108149 - 3 Monthly - WFE Safety Inspection of C506-BANBRIDGE / CRAIGAVON on 04/02/2024 Inspection Type: 3 Monthly - WFE Safety Inspection
 Inspector: [REDACTED]

Section Code: 7060C0706_01 Section Description: KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD

Defect Ref: DCD249030068	Defect Type: THIRD PARTY REFERRAL	Comments: Covers noisy. Damage to surrounding area	Location Description: Near Kiln Avenue junction	Priority: R4 - next available programme	Defect Dimensions:			
Recorded Date: 03-March-2024	UTILITY MANHOLE LID/COVER DEFECTIVE (UMDF)				Length (m):	Width (m):	Depth (mm):	
Recorded By: [REDACTED]								



Inspection Report

Inspection Date: 7-May-2024

Inspect History ID: 3109706 - 3 Monthly - WFE Safety Inspection of C506-BANBRIDGE / CRAIGAVON on 04/05/2024

Inspection Type: 3 Monthly - WFE Safety Inspection

Inspector: [REDACTED]

Section Code:
7060C0706_01

Section Description:
KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD

Defect Ref: DCD249073395	Defect Type: DEFECT	Comments: ?	Location Description: 10m from silverwood green	Priority R2 - 5 Working days	Defect Dimensions: Length (m): 0.72	Width (m): 0.72	Depth (mm): 52.00
---	------------------------	----------------	--	---------------------------------	--	-----------------	-------------------

Recorded Date:
08-May-2024

BITMAC POTHOLE (CBPH)

Recorded By:
[REDACTED]

Repair Description: D24021A	Repair Item Name: ^ 70mm bit. patch w/c <1 m2	Quantity 1.00	Units no	Repair Measures L 0.00 W 0.00 D 0.00
--------------------------------	--	------------------	-------------	---

Defect Ref: DCD249073405	Defect Type: DEFECT	Comments: ?	Location Description: 5m from silverwood green	Priority R2 - 5 Working days	Defect Dimensions: Length (m): 1.20	Width (m): 0.48	Depth (mm): 84.00
---	------------------------	----------------	---	---------------------------------	--	-----------------	-------------------

Recorded Date:
08-May-2024

BITMAC POTHOLE (CBPH)

Recorded By:
[REDACTED]

Repair Description: D24021A	Repair Item Name: ^ 70mm bit. patch w/c <1 m2	Quantity 1.00	Units no	Repair Measures L 0.00 W 0.00 D 0.00
--------------------------------	--	------------------	-------------	---



Inspection Report

Inspection Date: 7-May-2024 Inspect History ID: 3109706 - 3 Monthly - WFE Safety Inspection of C506-BANBRIDGE / CRAIGAVON on 04/05/2024 Inspection Type: 3 Monthly - WFE Safety Inspection
 Inspector: [REDACTED]

Section Code: 7060C0706_01 Section Description: KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD

Defect Ref: DCD249073416	Defect Type: THIRD PARTY REFERRAL	Comments: Low and noisy NIW notified NISRANS LA REF 1433936	Location Description: Opp kiln vale	Priority: From Matrix	Defect Dimensions: Length (m): 0.00 Width (m): 0.00 Depth (mm): 0.00
---	--------------------------------------	---	---	---------------------------------	--

Recorded Date: 08-May-2024 UTILITY MANHOLE LID/COVER LOW (UMLO)

Recorded By:
[REDACTED]