



Inspection Report

Inspection Date: See Recorded Date	Inspect History ID: -	Inspection Type:
		Inspector:

Section Code: 7125U9105_01	Section Description: PORTS RD1: U9674 KILLYCLONNY RD TO END
--------------------------------------	---

Defect Ref: D1616740	Defect Type: DEFECT	Comments: Liaise with [REDACTED] Section Rd, Enniskillen as he wish's to attend on site for repair.	Location Description: Ports Road	Priority: R3 - 4 Weeks	Defect Dimensions: Length (m): 5.00 Width (m): 3.00 Depth (mm): 70.00
--	-------------------------------	---	--	----------------------------------	---

Recorded Date:
22-July-2016

Recorded By:
[REDACTED]

BITMAC UNEVEN (CBUN)

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D24023A	^ 70mm bit. patch w/c 3-15 m2	15.00	SQ.M	L 5.00 W 3.00 D 0.00



Inspection Report

Inspection Date: See Recorded Date	Inspect History ID: -	Inspection Type:
		Inspector:

Section Code: 7125U9105_01	Section Description: PORTS RD1: U9674 KILLYCLONNY RD TO END
----------------------------	---

Defect Ref: D1621954	Defect Type: DEFECT	Comments: Excavate soft spot to a depth of 450mm fill with Type 3 and top with 100mm of bitmac	Location Description: At Quay	Priority: R4 - next available programme	Defect Dimensions:		
					Length (m):	Width (m):	Depth (mm):

Recorded Date: 31-August-2016

Recorded By: [REDACTED]

BITMAC CRAZED (CBCZ)

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
D22122A	^ 250mm bitmac & 3M stone base patch 3-15	15.00	SQ.M	L 6.00	W 2.50	D 0.00	
D22122A	^ 250mm bitmac & 3M stone base patch 3-15	15.00	SQ.M	L 6.00	W 2.50	D 0.00	
D22122A	^ 250mm bitmac & 3M stone base patch 3-15	15.00	SQ.M	L 6.00	W 2.50	D 0.00	
D22122A	^ 250mm bitmac & 3M stone base patch 3-15	15.00	SQ.M	L 6.00	W 2.50	D 0.00	
U29110A	^ Excavate soft spots and voids	12.00	CU.M	L 6.00	W 10.00	D 200.00	
U29130A	^ Fill soft spots with Type 3M	12.00	CU.M	L 6.00	W 10.00	D 200.00	



Inspection Report

Inspection Date: See Recorded Date	Inspect History ID: 3067427 - Full Sector - Safety Inspection of FN2-FERMANAGH & OMAGH WEST on 16 February 2018	Inspection Type: Full Sector - Safety Inspection
		Inspector:

Section Code: 7125U9105_01	Section Description: PORTS RD1: U9674 KILLYCLONNY RD TO END
-----------------------------------	--

Defect Ref: DCD26-3067427-34	Defect Type: DEFECT	Comments: Killard Road	Location Description: 28m past tp 238 lhs	Priority: R3 - 4 Weeks	Defect Dimensions:		
Recorded Date: 17-February-2018	BITMAC POTHOLE (CBPH)				Length (m): 0.66	Width (m): 0.40	Depth (mm): 63.00
Recorded By:	[REDACTED]						

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
D24021A	^ 70mm bit. patch w/c <1 m2	1.00	no	L 0.00	W 0.00	D 0.00	



Inspection Report

Inspection Date: 13-Feb-1997 Inspect History ID: 2999165 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 20-Mar-1997 Inspect History ID: 2822605 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 13-May-1997 Inspect History ID: 2530463 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 20-May-1997 Inspect History ID: 3025797 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST41689	Defect Type: All Categories	Comments: GRASS	Location Description: KITTYCLONEY TO END	Priority N2 Historical	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 20-May-1997	OTHER TYPE OF DEFECT (OTHR)						
Recorded By: Ivan Willis							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
G12004	Cut grass tractor	10.80	km	L 10.80	W 0.00	D 0.00	



Inspection Report

Inspection Date: 26-Jun-1997 Inspect History ID: 2547753 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 14-Jul-1997 Inspect History ID: 2782012 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST52615	Defect Type: All Categories	Comments: grass	Location Description: Killyclonney Rd to end	Priority N2 Historical	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 14-July-1997	OTHER TYPE OF DEFECT (OTHR)						
Recorded By: [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
G12004	Cut grass tractor	10.80	km	L 10.80	W 0.00	D 0.00	



Inspection Report

Inspection Date: 4-Sep-1997 Inspect History ID: 2871346 - Historical Inspection Inspection Type: Inspector:

Section Code: 7125U9105_01 Section Description: PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST61087	Defect Type: All Categories	Comments: CZ 6.0X1.60	Location Description: AT TP 4	Priority 4 Historical	Defect Dimensions:		
Recorded Date: 04-September-1997	BITMAC CRAZED (CBCZ)				Length (m):	Width (m):	Depth (mm):
Recorded By: Fermanagh East Inspectors							
	Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures		
	D27013	40mm bit. patch 10mm W/C 3-15sq.m	9.60	SQ.M	L 6.00	W 1.60	D 0.00

Defect Ref: WEST61088	Defect Type: All Categories	Comments: CZ 2.60X1.80	Location Description: 10M FROM TP 4	Priority 4 Historical	Defect Dimensions:		
Recorded Date: 04-September-1997	BITMAC CRAZED (CBCZ)				Length (m):	Width (m):	Depth (mm):
Recorded By: Fermanagh East Inspectors							
	Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures		
	D27013	40mm bit. patch 10mm W/C 3-15sq.m	4.68	SQ.M	L 2.60	W 1.80	D 0.00



Inspection Report

Inspection Date: 4-Sep-1997 Inspect History ID: 2871346 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST61089	Defect Type: All Categories	Comments: CZ	Location Description: 15M FROM TP 4	Priority 4 Historical	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 04-September-1997	BITMAC CRAZED (CBCZ)						
Recorded By: Fermanagh East Inspectors							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
D87014	40mm bit. patch 10mm W/C 15-50sq.m	18.85	SQ.M	L 6.50	W 2.90	D 0.00	

Defect Ref: WEST61090	Defect Type: All Categories	Comments: CZ 5.0X1.20	Location Description: 15M FROM TP 4	Priority 4 Historical	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 04-September-1997	BITMAC CRAZED (CBCZ)						
Recorded By: Fermanagh East Inspectors							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
D27013	40mm bit. patch 10mm W/C 3-15sq.m	6.00	SQ.M	L 5.00	W 1.20	D 0.00	



Inspection Report

Inspection Date: 4-Sep-1997	Inspect History ID: 2871346 - Historical Inspection	Inspection Type:
		Inspector:

Section Code: 7125U9105_01	Section Description: PORTS RD1: U9674 KILLYCLONNY RD TO END
-------------------------------	--

Defect Ref: WEST61091	Defect Type: All Categories	Comments: CZ 2.30X1.60	Location Description: AT TP 4	Priority 4 Historical	Defect Dimensions:		
Recorded Date: 04-September-1997	BITMAC CRAZED (CBCZ)				Length (m):	Width (m):	Depth (mm):
Recorded By: Fermanagh East Inspectors							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
D27013	40mm bit. patch 10mm W/C 3-15sq.m	3.68	SQ.M	L 2.30 W 1.60 D 0.00			



Inspection Report

Inspection Date: 31-Oct-1997 Inspect History ID: 2915907 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 29-Dec-1997 Inspect History ID: 2775406 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 10-Feb-1998 Inspect History ID: 2577922 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 21-Apr-1998 Inspect History ID: 2996570 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 15-Jun-1998 Inspect History ID: 3038275 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 22-Jul-1998 Inspect History ID: 2931930 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 17-Aug-1998 Inspect History ID: 2591043 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 22-Sep-1998 Inspect History ID: 2427122 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 7-Oct-1998 Inspect History ID: 2707684 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST145296	Defect Type: All Categories	Comments: PH 2.0X2.0X100MM	Location Description: 10M FROM TP 4	Priority 3 Historical	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 07-October-1998	BITMAC POTHOLE (CBPH)						

Recorded By:



Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 1.00 W 0.00 D 0.00

Defect Ref: WEST145297	Defect Type: All Categories	Comments: PH 1.60X0.50X90MM	Location Description: 10M FROM TP 4	Priority 3 Historical	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 07-October-1998	BITMAC POTHOLE (CBPH)						

Recorded By:



Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 1.00 W 0.00 D 0.00



Inspection Report

Inspection Date: 7-Oct-1998 Inspect History ID: 2707684 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST145298	Defect Type: All Categories	Comments: PH 0.40X0.40X50MM	Location Description: 20M FROM TP 4	Priority: 4 Historical	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 07-October-1998	BITMAC POTHOLE (CBPH)						

Recorded By:



Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
D24021A	^ 70mm bit. patch w/c <1 m2	1.00	no	L 1.00	W 0.00	D 0.00	

Defect Ref: WEST145299	Defect Type: All Categories	Comments: PH 1.0X0.90X55MM	Location Description: 10M FROM TP 3	Priority: 4 Historical	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 07-October-1998	BITMAC POTHOLE (CBPH)						

Recorded By:



Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
D24021A	^ 70mm bit. patch w/c <1 m2	1.00	no	L 1.00	W 0.00	D 0.00	



Inspection Report

Inspection Date: 7-Oct-1998 Inspect History ID: 2707684 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST145300	Defect Type: All Categories	Comments: CZ 8.20X2.0	Location Description: AT TP 1	Priority: 4 Historical	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 07-October-1998	BITMAC CRAZED (CBCZ)						

Recorded By:



Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
D87014A	^ 40mm bit patch w/c 15-50 m2	16.40	SQ.M	L 8.20	W 2.00	D 0.00	

Defect Ref: WEST145301	Defect Type: All Categories	Comments: PH 0.40X0.40X55MM	Location Description: AT TP 1	Priority: 4 Historical	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 07-October-1998	BITMAC POTHOLE (CBPH)						

Recorded By:



Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
D24021A	^ 70mm bit. patch w/c <1 m2	1.00	no	L 1.00	W 0.00	D 0.00	



Inspection Report

Inspection Date: 7-Oct-1998 Inspect History ID: 2707684 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST145302	Defect Type: All Categories	Comments: ED 4.0X0.50X60MM	Location Description: 30M FROM KILLARD JCT	Priority: 4 Historical	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 07-October-1998	BITMAC EDGE DETERIORATION (CBED)						
Recorded By: [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
D24022A	^ 70mm bit. patch w/c 1-3 m2	2.00	SQ.M	L 4.00	W 0.50	D 0.00	



Inspection Report

Inspection Date: 6-Dec-1998 Inspect History ID: 2608741 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST158604	Defect Type: All Categories	Comments: PH 0.60X0.60X60MM	Location Description: AT TP 3	Priority: 4 Historical	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 06-December-1998	BITMAC POTHOLE (CBPH)						

Recorded By:



Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
D24021A	^ 70mm bit. patch w/c <1 m2	1.00	no	L 1.00	W 0.00	D 0.00	



Inspection Report

Inspection Date: 5-Feb-1999 Inspect History ID: 2893832 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST172983	Defect Type: All Categories	Comments: PH 0.60X0.70X70MM	Location Description: AT TP 21	Priority 4 Historical	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 03-February-1999	BITMAC POTHOLE (CBPH)						

Recorded By:



Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
D24021A	^ 70mm bit. patch w/c <1 m2	1.00	no	L 1.00	W 0.00	D 0.00	



Inspection Report

Inspection Date: 28-May-1999 Inspect History ID: 2963003 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 3-Aug-1999 Inspect History ID: 2992988 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST373868	Defect Type: All Categories	Comments: SLUNK	Location Description: AT TP4	Priority N1 Historical	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 23-July-1999	BITMAC UNEVEN (CBUN)						
Recorded By: [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
D20010A	^ EO overlay patch for tracking 50mm deep	23.50	LIN.M	L 23.50	W 0.00	D 0.00	
F53402A	^ Make up verge >5m2	57.40	SQ.M	L 57.40	W 1.00	D 0.00	
F53402A	^ Make up verge >5m2	40.00	SQ.M	L 40.00	W 1.00	D 0.00	
D80014A	^ 50mm overlay bit. patch W/C 15-50 m2	21.00	SQ.M	L 6.00	W 3.50	D 0.00	
D80014A	^ 50mm overlay bit. patch W/C 15-50 m2	19.14	SQ.M	L 17.40	W 1.10	D 0.00	
D80014A	^ 50mm overlay bit. patch W/C 15-50 m2	33.30	SQ.M	L 10.00	W 3.33	D 0.00	
D80014A	^ 50mm overlay bit. patch W/C 15-50 m2	33.30	SQ.M	L 10.00	W 3.33	D 0.00	
D80014A	^ 50mm overlay bit. patch W/C 15-50 m2	47.25	SQ.M	L 13.50	W 3.50	D 0.00	
D80014A	^ 50mm overlay bit. patch W/C 15-50 m2	35.00	SQ.M	L 10.00	W 3.50	D 0.00	
D80014A	^ 50mm overlay bit. patch W/C 15-50 m2	33.30	SQ.M	L 10.00	W 3.33	D 0.00	
D80014A	^ 50mm overlay bit. patch W/C 15-50 m2	33.30	SQ.M	L 10.00	W 3.33	D 0.00	



Inspection Report

Inspection Date: 29-Sep-1999 Inspect History ID: 2861919 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 20-Oct-1999 Inspect History ID: 2746654 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST395877	Defect Type: All Categories	Comments: slunk	Location Description:	Priority N1 Historical	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 20-October-1999	BITMAC UNEVEN (CBUN)						

Recorded By:



Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
F53402A	^ Make up verge >5m2	26.60	SQ.M	L 26.60	W 1.00	D 0.00	
D20024A	^ 40mm overlay bit. patch 14mm 15-50sq.m	33.00	SQ.M	L 11.00	W 3.00	D 0.00	
D20024A	^ 40mm overlay bit. patch 14mm 15-50sq.m	43.89	SQ.M	L 13.30	W 3.30	D 0.00	



Inspection Report

Inspection Date: 22-Nov-1999 Inspect History ID: 2813737 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 23-Dec-1999 Inspect History ID: 2887379 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 30-Jan-2000 Inspect History ID: 2633496 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST418064	Defect Type: All Categories	Comments: POTHOLE .4X.4X55MM	Location Description: 250M FROM JCT	Priority: 4 Historical	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 29-January-2000	BITMAC POTHOLE (CBPH)						

Recorded By:



Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
D24021A	^ 70mm bit. patch w/c <1 m2	1.00	no	L 1.00	W 0.00	D 0.00	



Inspection Report

Inspection Date: 20-Mar-2000 Inspect History ID: 2988754 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 30-May-2000 Inspect History ID: 3032365 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 11-Jun-2000 Inspect History ID: 2840216 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST462739	Defect Type: All Categories	Comments: PH	Location Description:	Priority N1 Historical	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 11-June-2000	BITMAC POTHOLE (CBPH)						

Recorded By:



Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
D24021A	^ 70mm bit. patch w/c <1 m2	3.00	no	L 3.00	W 0.00	D 0.00	



Inspection Report

Inspection Date: 11-Aug-2000 Inspect History ID: 2676003 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 6-Dec-2000 Inspect History ID: 2439474 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 29-Mar-2001 Inspect History ID: 2928179 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 10-Apr-2001 Inspect History ID: 2980188 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST535675	Defect Type: All Categories	Comments: .80 X .65 D:55mm	Location Description: OPP TP1	Priority: R3 - 4 Weeks	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 06-April-2001	BITMAC POTHOLE (CBPH)						

Recorded By:



Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
D24023A	^ 70mm bit. patch w/c 3-15 m2	3.24	SQ.M	L 1.85	W 1.75	D 0.00	



Inspection Report

Inspection Date: 10-Aug-2001 Inspect History ID: 2448753 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 3-Dec-2001 Inspect History ID: 2882894 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 3-Apr-2002 Inspect History ID: 2460387 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 28-May-2002 Inspect History ID: 2915614 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 8-Aug-2002 Inspect History ID: 2911127 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST666112	Defect Type: DEFECT	Comments: 120MM LOW VERGE D:0mm	Location Description: AT TP4	Priority R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 07-August-2002	GRASS VERGE RUTTED (VGRT)						
Recorded By: [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
F53402A	^ Make up verge >5m2	6.60	SQ.M	L 6.60	W 1.00	D 0.00	



Inspection Report

Inspection Date: 3-Dec-2002 Inspect History ID: 2533549 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 10-Apr-2003 Inspect History ID: 2754185 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST731948	Defect Type: DEFECT	Comments: 0.4MX0.25M D:45mm OPP BUNGALOW	Location Description: 30M FROM TP1 ON C/WAY	Priority R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 08-April-2003	BITMAC POTHOLE (CBPH)						
Recorded By: [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
D24021A	^ 70mm bit. patch w/c <1 m2	3.00	no	L 3.00 W 0.00 D 0.00			

Defect Ref: WEST731949	Defect Type: DEFECT	Comments: 1.0 D:0mm	Location Description: AT JCT WITH KILLYCLONNY ON C/W	Priority R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 08-April-2003	ROAD MARKINGS FADED (CYFD)						
Recorded By: [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
K31001A	^ Renew junction markings	1.00	no	L 1.00 W 0.00 D 0.00			



Inspection Report

Inspection Date: 28-May-2003 Inspect History ID: 2764834 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 5-Jul-2003 Inspect History ID: 2746481 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST755419	Defect Type: All Categories	Comments: GRASSCUTTING D:0mm	Location Description: KILLYCLONNY RD - END	Priority: R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 05-July-2003	OTHER TYPE OF DEFECT (OTHR)						
Recorded By: [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
G12004A	^ Tractor grass cutting	6.75	km	L 6.75	W 0.00	D 0.00	



Inspection Report

Inspection Date: 11-Aug-2003 Inspect History ID: 2738012 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST762545	Defect Type: All Categories	Comments: 0 D:0mm CLEAN CCENTRE OF RD	Location Description: FROM LAYBYE NEAR RD END- NEAR TP11	Priority R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 08-August-2003	DEBRIS ON SURFACE (DOSF)						

Recorded By:



Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
X50532A	^ Scrape clean & sweep road >10m2	327.60	SQ.M	L 546.00	W 0.60	D 0.00	

Defect Ref: WEST762546	Defect Type: DEFECT	Comments: 150MM LOW VERGE D:0mm	Location Description: AT TP56V4	Priority R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 08-August-2003	GRASS VERGE RUTTED (VGRT)						

Recorded By:



Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
F53402A	^ Make up verge >5m2	7.00	SQ.M	L 7.00	W 1.00	D 0.00	



Inspection Report

Inspection Date: 11-Aug-2003 Inspect History ID: 2738012 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST762547	Defect Type: All Categories	Comments: .35 X .29 D:60mm	Location Description: BTWN TP1 - TP2	Priority: R3 - 4 Weeks	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 08-August-2003	BITMAC POTHOLE (CBPH)						

Recorded By:



Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
D24022A	^ 70mm bit. patch w/c 1-3 m2	1.65	SQ.M	L 1.50	W 1.10	D 0.00	

Defect Ref: WEST762548	Defect Type: All Categories	Comments: 0 D:0mm FIT NEW GIVEWAY SIGN	Location Description: AT JCT KILLARD RD	Priority: R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
---	--------------------------------	--	--	--	-----------------------------------	------------	-------------

Recorded Date:
08-August-2003

SIGN FADED (CSFD)

Recorded By:



Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
R11410A	EO signs for Class 1 signs	0.45	SQ.M	L 0.60	W 0.75	D 0.00	
R11422A	^ Triangular class 1 sign 0-900mm high	1.00	no	L 1.00	W 0.00	D 0.00	



Inspection Report

Inspection Date: 30-Sep-2003 Inspect History ID: 2904916 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 27-Nov-2003 Inspect History ID: 2674802 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST789216	Defect Type: All Categories	Comments: 0 D:0mm	Location Description: BTWN TP10 - TP11	Priority R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 27-November-2003	BITMAC UNEVEN (CBUN)						
Recorded By: [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
F53401A	^ Make up verge 0-5m2	1.00	no	L 1.00 W 0.00 D 0.00
D24023A	^ 70mm bit. patch w/c 3-15 m2	12.04	SQ.M	L 8.60 W 1.40 D 0.00
D24023A	^ 70mm bit. patch w/c 3-15 m2	4.30	SQ.M	L 4.30 W 1.00 D 0.00

Defect Ref: WEST789217	Defect Type: All Categories	Comments: .42 X .29 D:70mm	Location Description: BTWN TP1 - TP2	Priority R3 - 4 Weeks	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 27-November-2003	BITMAC POTHOLE (CBPH)						
Recorded By: [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D24022A	^ 70mm bit. patch w/c 1-3 m2	1.65	SQ.M	L 1.50 W 1.10 D 0.00



Inspection Report

Inspection Date: 27-Nov-2003 Inspect History ID: 2674802 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST789218	Defect Type: DEFECT	Comments: .30 X .23 D:35mm	Location Description: APP 20M BEFORE TP1	Priority: R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 27-November-2003	BITMAC POTHOLE (CBPH)						
Recorded By: [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
D24022A	^ 70mm bit. patch w/c 1-3 m2	1.92	SQ.M	L 1.60	W 1.20	D 0.00	



Inspection Report

Inspection Date: 9-Mar-2004 Inspect History ID: 3034878 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 15-Mar-2004 Inspect History ID: 2978787 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST818812	Defect Type: All Categories	Comments:	Location Description:	Priority R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 15-March-2004	OTHER TYPE OF DEFECT (OTHR)						
Recorded By: [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
X42004A	^ Clean open drain >500mm deep >5m	325.00	LIN.M	L 325.00 W 0.00 D 0.00



Inspection Report

Inspection Date: 3-Apr-2004 Inspect History ID: 2967664 - Historical Inspection

Inspection Type:

Inspector:

Defect Ref: WEST825768	Defect Type: All Categories	Comments: .36 X .33 D:60mm	Location Description: AT TP1	Priority: R3 - 4 Weeks	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 02-April-2004	BITMAC POTHOLE (CBPH)						

Recorded By:



Repair Description: D24022A	Repair Item Name: ^ 70mm bit. patch w/c 1-3 m2	Quantity: 2.16	Units: SQ.M	Repair Measures: L 1.80 W 1.20 D 0.00
--------------------------------	---	-------------------	----------------	--



Inspection Report

Inspection Date: 9-Jul-2004 Inspect History ID: 2887187 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 12-Aug-2004 Inspect History ID: 2811453 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 13-Aug-2004 Inspect History ID: 2514014 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST857623	Defect Type: DEFECT	Comments: .33 X .20 D:40mm	Location Description: AT TP10 APP 400M FROM RD END	Priority: R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 13-August-2004	BITMAC POTHOLE (CBPH)						
Recorded By: [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
D27011A	^ 40mm bit patch w/c 0-1 m2	3.00	no	L 3.00	W 0.00	D 0.00	



Inspection Report

Inspection Date: 3-Sep-2004 Inspect History ID: 2553583 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST862256	Defect Type: All Categories	Comments: DIRT ON CENTRE OF RD D:0mm CLEAN CENTRE OF RD	Location Description: AT TP12	Priority R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
---	--------------------------------	--	----------------------------------	---	-----------------------------------	------------	-------------

Recorded Date: 03-September-2004
DEBRIS ON SURFACE (DOSF)

Recorded By:

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
X50531A	^ Scrape clean & sweep road edge >20m	40.00	LIN.M	L 40.00 W 0.00 D 0.00

Defect Ref: WEST862257	Defect Type: All Categories	Comments: DIRT ON CENTRE OF RD D:0mm CLEAN CENTRE OF RD	Location Description: BTWN TP8 - TP1	Priority R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
---	--------------------------------	--	---	---	-----------------------------------	------------	-------------

Recorded Date: 03-September-2004
DEBRIS ON SURFACE (DOSF)

Recorded By:

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
X50531A	^ Scrape clean & sweep road edge >20m	326.00	LIN.M	L 326.00 W 0.00 D 0.00



Inspection Report

Inspection Date: 6-Dec-2004 Inspect History ID: 2513978 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 31-Jan-2005 Inspect History ID: 2790612 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST897820	Defect Type: All Categories	Comments: 0 D:0mm PLOUGH AND SWEEP RD	Location Description: BTWN KILLYCLONNEY RD - RD END	Priority R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
---	--------------------------------	---	--	--	-----------------------------------	------------	-------------

Recorded Date: 31-January-2005 DEBRIS ON SURFACE (DOSF)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
X31200A	^ Mechanical sweep in C/W	2.71	km	L 2.71 W 0.00 D 0.00
X31200A	^ Mechanical sweep in C/W	2.71	km	L 2.71 W 0.00 D 0.00
G34734A	^ Edging with plough and tractor	2.71	km	L 2.71 W 0.00 D 0.00
G34734A	^ Edging with plough and tractor	2.71	km	L 2.71 W 0.00 D 0.00



Inspection Report

Inspection Date: 6-Apr-2005 Inspect History ID: 3026263 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST916900	Defect Type: All Categories	Comments: .36 X .31 D:52mm	Location Description: OPP TP21	Priority: R3 - 4 Weeks	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 06-April-2005	BITMAC POTHOLE (CBPH)						

Recorded By:
[REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
D24021A	^ 70mm bit. patch w/c <1 m2	1.00	no	L 1.00	W 0.00	D 0.00	



Inspection Report

Inspection Date: 12-Aug-2005 Inspect History ID: 2647683 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 18-Aug-2005 Inspect History ID: 2903940 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 2-Dec-2005 Inspect History ID: 2797394 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST979955	Defect Type: All Categories	Comments: .30 X .20 D:55mm ON 1ST RH BEND	Location Description: APP 200M FROM KILLARD RD	Priority: R3 - 4 Weeks	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 01-December-2005	BITMAC POTHOLE (CBPH)						
Recorded By: [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
D24021A	^ 70mm bit. patch w/c <1 m2	1.00	no	L 1.00	W 0.00	D 0.00	



Inspection Report

Inspection Date: 28-Jan-2006 Inspect History ID: 2653343 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: [WEST990395](#) Defect Type: All Categories Comments: 0 D:0mm Location Description: OPP TP4 Priority: R4 - next available programme Defect Dimensions: Length (m): Width (m): Depth (mm):

Recorded Date: 28-January-2006 BITMAC UNEVEN (CBUN)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
F53402A	^ Make up verge >5m2	6.88	SQ.M	L 8.60 W 0.80 D 0.00
D24023A	^ 70mm bit. patch w/c 3-15 m2	14.36	SQ.M	L 8.60 W 1.67 D 0.00

Defect Ref: [WEST990396](#) Defect Type: All Categories Comments: 0 D:0mm Location Description: AT TP2 Priority: R4 - next available programme Defect Dimensions: Length (m): Width (m): Depth (mm):

Recorded Date: 28-January-2006 BITMAC UNEVEN (CBUN)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
F53402A	^ Make up verge >5m2	12.49	SQ.M	L 35.70 W 0.35 D 0.00
D84024A	^ 70mm bit. patch W/C 15-50 m2	38.56	SQ.M	L 35.70 W 1.08 D 0.00



Inspection Report

Inspection Date: 2-Feb-2006 Inspect History ID: 2766486 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST991436	Defect Type: DEFECT	Comments: DRAIN BLOCKED D:0mm	Location Description: BETWEEN TP2 AND TP3	Priority R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 02-February-2006	VERGE DRAIN/DITCH BLOCKED (VDBL)						
Recorded By:	[REDACTED]						

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
X42300A	^ New roadside open drain	42.70	CU.M	L 87.60 W 0.65 D 0.75

Defect Ref: WEST991437	Defect Type: DEFECT	Comments: DRAIN OVERGROWN D:0mm	Location Description: BETWEEN TP2 AND TP3	Priority R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 02-February-2006	VERGE DRAIN/DITCH OVERGROWN (VDOG)						
Recorded By:	[REDACTED]						

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
X42002A	^ Clean open drain <500mm deep >5m	93.60	LIN.M	L 93.60 W 0.00 D 0.00



Inspection Report

Inspection Date: 2-Feb-2006 Inspect History ID: 2766486 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST991438	Defect Type: DEFECT	Comments: DRAIN OVERGROWN D:0mm	Location Description: BETWEEN TP187 AND TP2	Priority R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 02-February-2006	VERGE DRAIN/DITCH OVERGROWN (VDOG)						

Recorded By:



Repair Description: X42002A	Repair Item Name: ^ Clean open drain <500mm deep >5m	Quantity 95.00	Units LIN.M	Repair Measures L 95.00 W 0.00 D 0.00
---------------------------------------	--	--------------------------	-----------------------	---

Defect Ref: WEST991439	Defect Type: DEFECT	Comments: DRAIN OVERGROWN D:0mm	Location Description: BETWEEN TP233 AND TP235	Priority R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 02-February-2006	VERGE DRAIN/DITCH OVERGROWN (VDOG)						

Recorded By:



Repair Description: X42002A	Repair Item Name: ^ Clean open drain <500mm deep >5m	Quantity 33.00	Units LIN.M	Repair Measures L 33.00 W 0.00 D 0.00
---------------------------------------	--	--------------------------	-----------------------	---



Inspection Report

Inspection Date: 2-Feb-2006 Inspect History ID: 2766486 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST991440	Defect Type: DEFECT	Comments: DRAIN OVERGROWN D:0mm	Location Description: BETWEEN TP41 AND TP241	Priority R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 02-February-2006	VERGE DRAIN/DITCH OVERGROWN (VDOG)						

Recorded By:



Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
X42002A	^ Clean open drain <500mm deep >5m	103.00	LIN.M	L 103.00 W 0.00 D 0.00

Defect Ref: WEST991441	Defect Type: DEFECT	Comments: 275MM LOW VERGE D:0mm	Location Description: OPP TP01	Priority R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 02-February-2006	GRASS VERGE RUTTED (VGRT)						

Recorded By:



Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
F53402A	^ Make up verge >5m2	7.75	SQ.M	L 6.20 W 1.25 D 0.00



Inspection Report

Inspection Date: 11-Feb-2006 Inspect History ID: 2824277 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST994119	Defect Type: All Categories	Comments: 0 D:0mm PLOUGH AND SWEEP	Location Description: BTWN KILLYCLONNY - RD END	Priority R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 11-February-2006	DEBRIS ON SURFACE (DOSF)						
Recorded By: [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
X31200A	^ Mechanical sweep in C/W	2.70	km	L 2.70	W 0.00	D 0.00	
X31200A	^ Mechanical sweep in C/W	2.70	km	L 2.70	W 0.00	D 0.00	
G34734A	^ Edging with plough and tractor	2.70	km	L 2.70	W 0.00	D 0.00	
G34734A	^ Edging with plough and tractor	2.70	km	L 2.70	W 0.00	D 0.00	



Inspection Report

Inspection Date: 1-Mar-2006 Inspect History ID: 2829968 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST998199	Defect Type: DEFECT	Comments: BLOCKED DRAIN CLEAN AND SINK DRAIN	Location Description: AT TP241	Priority R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 01-March-2006	VERGE DRAIN/DITCH BLOCKED (VDBL)						
Recorded By: [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
X42300A	^ New roadside open drain	20.00	CU.M	L 100.00	W 0.40	D 0.50	



Inspection Report

Inspection Date: 2-Mar-2006 Inspect History ID: 2540800 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST998233	Defect Type: DEFECT	Comments: BLOCKED DRAIN CLEAN AND SINK DRAINS	Location Description: BTWN TP251-TP252 OPP SIDE	Priority R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 02-March-2006	VERGE DRAIN/DITCH BLOCKED (VDBL)						
Recorded By: [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
X42300A	^ New roadside open drain	5.00	CU.M	L 20.00	W 0.50	D 0.50	

Defect Ref: WEST998235	Defect Type: DEFECT	Comments: CLEAN AND SINK DRAIN CLEAN AND SINK DRAIN	Location Description: AT TP241	Priority R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 02-March-2006	VERGE DRAIN/DITCH BLOCKED (VDBL)						
Recorded By: [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
X42300A	^ New roadside open drain	20.00	CU.M	L 100.00	W 0.40	D 0.50	



Inspection Report

Inspection Date: 6-Apr-2006 Inspect History ID: 2703520 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST1011505	Defect Type: All Categories	Comments: 0.40X0.29 D:52mm	Location Description: OPP TP 243 RHS	Priority: R3 - 4 Weeks	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 05-April-2006	BITMAC POTHOLE (CBPH)						

Recorded By:
[REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D24021A	^ 70mm bit. patch w/c <1 m2	1.00	no	L 1.00 W 0.00 D 0.00

Defect Ref: WEST1011506	Defect Type: All Categories	Comments: 0.50X0.32 D:55mm	Location Description: 32M PAST TP 264	Priority: R3 - 4 Weeks	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 05-April-2006	BITMAC POTHOLE (CBPH)						

Recorded By:
[REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D24021A	^ 70mm bit. patch w/c <1 m2	2.00	no	L 2.00 W 0.00 D 0.00



Inspection Report

Inspection Date: 6-Apr-2006 Inspect History ID: 2703520 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST1011507	Defect Type: All Categories	Comments: 0.31X0.28 D:54mm	Location Description: 20M PAST TP 265 LHS	Priority: R3 - 4 Weeks	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 05-April-2006	BITMAC POTHOLE (CBPH)						
Recorded By: [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
D24021A	^ 70mm bit. patch w/c <1 m2	2.00	no	L 2.00	W 0.00	D 0.00	



Inspection Report

Inspection Date: 17-Aug-2006 Inspect History ID: 2957789 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST1042447	Defect Type: DEFECT	Comments: .55 X 1.20 HOLE IN VERGEx .520mmD:0 NO SIGNS OR CONES	Location Description: AT TP246	Priority R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
--	------------------------	--	-----------------------------------	--	-----------------------------------	------------	-------------

Recorded Date: 14-August-2006
GRASS VERGE RUTTED (VGRT)

Recorded By:



Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
F53401A	^ Make up verge 0-5m2	1.00	no	L 1.00 W 0.00 D 0.00

Defect Ref: WEST1042448	Defect Type: DEFECT	Comments: MOSTLY SID OVER D:0mm	Location Description: AT JCT KILLARD RD	Priority R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
--	------------------------	------------------------------------	--	--	-----------------------------------	------------	-------------

Recorded Date: 14-August-2006
ROAD MARKINGS MISSING (CYMI)

Recorded By:



Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
K31001A	^ Renew junction markings	1.00	no	L 1.00 W 0.00 D 0.00



Inspection Report

Inspection Date: 17-Aug-2006 Inspect History ID: 2957789 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST1042449	Defect Type: DEFECT	Comments: 80MM LOW VERGE RD RESURFAD D:0mm	Location Description: AT HOUSE OPP TP238	Priority R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 14-August-2006	GRASS VERGE RUTTED (VGRT)						
Recorded By: [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
F53402A	^ Make up verge >5m2	61.50	SQ.M	L 41.00	W 1.50	D 0.00	



Inspection Report

Inspection Date: 11-Sep-2006 Inspect History ID: 2797299 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST1046410	Defect Type: All Categories	Comments:	Location Description: Killyclonny Rd to end	Priority R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 01-May-2006	BITMAC DEFECTIVE (CBDF)						
Recorded By: [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
B11820A	EO per 0.1 lit/ sq.m binder	8,806.40	SQ.M	L 2,752.00	W 3.20	D 0.00	
B11820A	EO per 0.1 lit/ sq.m binder	8,806.40	SQ.M	L 2,752.00	W 3.20	D 0.00	
B11130A	^ 10mm single s.dressing PSV=50	8,806.40	SQ.M	L 2,752.00	W 3.20	D 0.00	



Inspection Report

Inspection Date: 4-Dec-2006 Inspect History ID: 2929231 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST1068720	Defect Type: DEFECT	Comments: 140MM LOW VERGE D:0mm	Location Description: OPP TP240	Priority R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 02-December-2006	GRASS VERGE RUTTED (VGRT)						
Recorded By: [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
F53401A	^ Make up verge 0-5m2	1.00	no	L 1.00 W 0.00 D 0.00

Defect Ref: WEST1068721	Defect Type: All Categories	Comments: .65 X .40 D:51mm	Location Description: AT TP246	Priority R3 - 4 Weeks	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 02-December-2006	BITMAC POTHOLE (CBPH)						
Recorded By: [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D24022A	^ 70mm bit. patch w/c 1-3 m2	1.47	SQ.M	L 2.10 W 0.70 D 0.00



Inspection Report

Inspection Date: 30-Mar-2007 Inspect History ID: 2907574 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST1097839	Defect Type: All Categories	Comments: 0 D:0mm	Location Description: AT JCT KILLARD RD	Priority R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 29-March-2007	DEBRIS ON SURFACE (DOSF)						
Recorded By: [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
X50532A	^ Scrape clean & sweep road >10m2	60.00	SQ.M	L 12.00	W 5.00	D 0.00	



Inspection Report

Inspection Date: 9-Aug-2007 Inspect History ID: 2551290 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 29-Nov-2007 Inspect History ID: 2519158 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 3-Dec-2007 Inspect History ID: 2923271 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST1156561	Defect Type: All Categories	Comments: 1.10 X .30 D:60mm OVERHEAD CABLES	Location Description: AT TP2482	Priority: R3 - 4 Weeks	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
--	--------------------------------	---	------------------------------------	---------------------------	-----------------------------------	------------	-------------

Recorded Date: 30-November-2007
BITMAC POTHOLE (CBPH)

Recorded By:
Fermanagh East
Inspectors

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D24021A	^ 70mm bit. patch w/c <1 m2	1.00	no	L 1.00 W 0.00 D 0.00



Inspection Report

Inspection Date: 7-Apr-2008 Inspect History ID: 2987494 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST1186608	Defect Type: DEFECT	Comments: 160MM LOW VERGE D:0mm OVERHEAD CABLES	Location Description: OPP TP240	Priority R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
--	------------------------	--	------------------------------------	--	-----------------------------------	------------	-------------

Recorded Date: 04-April-2008
GRASS VERGE RUTTED (VGRT)

Recorded By:
[REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
F53401A	^ Make up verge 0-5m2	1.00	no	L 1.00 W 0.00 D 0.00

Defect Ref: WEST1186609	Defect Type: DEFECT	Comments: .60 X .43 D:45mm	Location Description: BTWN TP262 - TP263	Priority R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
--	------------------------	-------------------------------	---	--	-----------------------------------	------------	-------------

Recorded Date: 04-April-2008
BITMAC POTHOLE (CBPH)

Recorded By:
[REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D27011A	^ 40mm bit patch w/c 0-1 m2	1.00	no	L 1.00 W 0.00 D 0.00
D24021A	^ 70mm bit. patch w/c <1 m2	1.00	no	L 1.00 W 0.00 D 0.00



Inspection Report

Inspection Date: 7-Aug-2008 Inspect History ID: 2595530 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST1212620	Defect Type: All Categories	Comments: .15 X .20 D:80mm	Location Description: BTWN TP253 - TP254	Priority: R3 - 4 Weeks	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 06-August-2008	BITMAC POTHOLE (CBPH)						

Recorded By:



Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures		
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 1.00	W 0.00	D 0.00



Inspection Report

Inspection Date: 6-Oct-2008 Inspect History ID: 2969304 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 27-Nov-2008 Inspect History ID: 2812031 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST1243958	Defect Type: All Categories	Comments: .47 X .33 D:60mm	Location Description: AT HOUSE AT TP237	Priority R3 - 4 Weeks	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 27-November-2008	BITMAC POTHOLE (CBPH)						

Recorded By:



Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
D24021A	^ 70mm bit. patch w/c <1 m2	1.00	no	L 1.00	W 0.00	D 0.00	

Defect Ref: WEST1243959	Defect Type: All Categories	Comments: STANDING WATER D:0mm CONTACT P MOOHAN	Location Description: OPP TP261	Priority R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 27-November-2008	WATER RUNNING (UWRN)						

Recorded By:



Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
U01001A	^ Unplanned drainage works norm.hrs	1.00	HR	L 1.00	W 0.00	D 0.00	



Inspection Report

Inspection Date: 6-Apr-2009 Inspect History ID: 2744547 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST1281474	Defect Type: All Categories	Comments: .53 X .38 D:55mm	Location Description: BTWN TP261 - TP262	Priority: R3 - 4 Weeks	Defect Dimensions:		
Recorded Date: 06-April-2009	BITMAC POTHOLE (CBPH)				Length (m):	Width (m):	Depth (mm):

Recorded By:



Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
D27011A	^ 40mm bit patch w/c 0-1 m2	4.00	no	L 4.00	W 0.00	D 0.00	
D24021A	^ 70mm bit. patch w/c <1 m2	1.00	no	L 1.00	W 0.00	D 0.00	



Inspection Report

Inspection Date: 12-Aug-2009 Inspect History ID: 2739598 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 19-Aug-2009 Inspect History ID: 3018624 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST1320165	Defect Type: DEFECT	Comments: 0 D:0mm	Location Description: AP 200M BUN SIDE KILLYCLONNEY RD	Priority: R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
--	------------------------	----------------------	--	---	-----------------------------------	------------	-------------

Recorded Date: 19-August-2009
Recorded By: [REDACTED]
VERGE DRAIN/DITCH
BLOCKED (VDBL)

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
X42004A	^ Clean open drain >500mm deep >5m	140.00	LIN.M	L 140.00 W 0.00 D 0.00



Inspection Report

Inspection Date: 8-Oct-2009 Inspect History ID: 2594513 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 21-Oct-2009 Inspect History ID: 2977691 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 7-Dec-2009 Inspect History ID: 2541778 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 9-Apr-2010 Inspect History ID: 2712107 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST1384146	Defect Type: All Categories	Comments: .70 X .42 D:60mm OVERHEAD CABLES	Location Description: AT TP246	Priority: R3 - 4 Weeks	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
--	--------------------------------	--	-----------------------------------	---------------------------	-----------------------------------	------------	-------------

Recorded Date:
08-April-2010

BITMAC POTHOLE
(CBPH)

Recorded By:



Repair Description: D24021A	Repair Item Name: ^ 70mm bit. patch w/c <1 m2	Quantity: 1.00	Units: no	Repair Measures: L 1.00 W 0.00 D 0.00
---------------------------------------	--	-------------------	--------------	--



Inspection Report

Inspection Date: 13-Aug-2010 Inspect History ID: 2987136 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 20-Aug-2010 Inspect History ID: 2772356 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 25-Oct-2010 Inspect History ID: 3004633 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 15-Dec-2010 Inspect History ID: 2956364 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 30-Mar-2011 Inspect History ID: 2624508 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST1483844	Defect Type: All Categories	Comments: .35 X .33 D:55mm	Location Description: AT HOUSE AT TP237	Priority: R3 - 4 Weeks	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 30-March-2011	BITMAC POTHOLE (CBPH)						
Recorded By: [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
D24021A	^ 70mm bit. patch w/c <1 m2	1.00	no	L 1.00	W 0.00	D 0.00	

Defect Ref: WEST1483845	Defect Type: All Categories	Comments: MEN AT WORK D:0mm ONGOING WORK NO SIGNS OR S	Location Description: NEAR TP246	Priority: R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 30-March-2011	HAZARD CAUSED BY ON-GOING WORKS (SAOW)						
Recorded By: [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
D01001A	^ Unplanned patching work norm.hrs	1.00	HR	L 1.00	W 0.00	D 0.00	



Inspection Report

Inspection Date: 30-Mar-2011 Inspect History ID: 2624508 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST1483846	Defect Type: All Categories	Comments: .32 X .41 D:60mm	Location Description: OPP TP243	Priority: R3 - 4 Weeks	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 30-March-2011	BITMAC POTHOLE (CBPH)						

Recorded By:



Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
D24021A	^ 70mm bit. patch w/c <1 m2	1.00	no	L 1.00	W 0.00	D 0.00	



Inspection Report

Inspection Date: 11-Jul-2011 Inspect History ID: 2574703 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 8-Aug-2011 Inspect History ID: 2540602 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST1516242	Defect Type: All Categories	Comments: AT SIGN D:0mm SLOW ON RD	Location Description: AT SIGN APP 50M FROM RD END	Priority R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 05-August-2011	OTHER TYPE OF DEFECT (OTHR)						
Recorded By: [REDACTED]							

Repair Description: K33721A	Repair Item Name: ^ 701-1599mm letters	Quantity 4.00	Units no	Repair Measures L 4.00 W 0.00 D 0.00
---------------------------------------	---	------------------	-------------	---

Defect Ref: WEST1516243	Defect Type: All Categories	Comments: .15 X .16 D:130mm	Location Description: NEAR TP254	Priority R2 - 5 Working days	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 05-August-2011	BITMAC POTHOLE (CBPH)						
Recorded By: [REDACTED]							

Repair Description: D23111A	Repair Item Name: ^ 100mm bit. patch W/C & B/C <1 m2	Quantity 1.00	Units no	Repair Measures L 1.00 W 0.00 D 0.00
---------------------------------------	--	------------------	-------------	---



Inspection Report

Inspection Date: 28-Sep-2011 Inspect History ID: 2526143 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 30-Dec-2011 Inspect History ID: 2770204 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 29-Mar-2012 Inspect History ID: 2764118 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST1580822	Defect Type: All Categories	Comments: AT SIGN D:0mm SLOW AT SIGN	Location Description: AT SIGN AT RD END	Priority R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 29-March-2012	OTHER TYPE OF DEFECT (OTHR)						
Recorded By: [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
K33721A	^ 701-1599mm letters	4.00	no	L 4.00 W 0.00 D 0.00



Inspection Report

Inspection Date: 16-May-2012 Inspect History ID: 2865167 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST1591643	Defect Type: All Categories	Comments: CLEAN DRAINS	Location Description: PORTS RD	Priority R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 16-May-2012	WATER RUNNING (UWRN)						

Recorded By:



Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
X42004A	^ Clean open drain >500mm deep >5m	250.00	LIN.M	L 250.00 W 0.00 D 0.00			

Defect Ref: WEST1591644	Defect Type: All Categories	Comments: DRAINAGE SEE DAMIEN	Location Description: ALONG BROWNS PORTS ROAD	Priority R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 16-May-2012	WATER RUNNING (UWRN)						

Recorded By:



Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
U27111A	^ PC.trap gully+connection 0-3m	3.00	no	L 3.00 W 0.00 D 0.00			
U01001A	^ Unplanned drainage works norm.hrs	1.00	HR	L 1.00 W 0.00 D 0.00			
U22332A	^ 250 UPVC S Exc.Matl. >10m verge 0-1.2	95.00	LIN.M	L 95.00 W 0.00 D 0.00			



Inspection Report

Inspection Date: 4-Jul-2012 Inspect History ID: 2908240 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 9-Aug-2012 Inspect History ID: 3034810 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST1607897	Defect Type: DEFECT	Comments: .41 X .33 D:40mm	Location Description: AT TP262	Priority R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 07-August-2012	BITMAC POTHOLE (CBPH)						
Recorded By: [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
D71021A	^ Velocity patch 0-1m2	2.00	no	L 2.00	W 0.00	D 0.00	



Inspection Report

Inspection Date: 27-Sep-2012 Inspect History ID: 2534530 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 30-Nov-2012 Inspect History ID: 2512676 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST1632693	Defect Type: DEFECT	Comments: 1.10 X .35 D:40mm	Location Description: OPP TP285	Priority: R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 28-November-2012	BITMAC POTHOLE (CBPH)						
Recorded By: [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
D71021A	^ Velocity patch 0-1m2	1.00	no	L 1.00	W 0.00	D 0.00	



Inspection Report

Inspection Date: 11-Dec-2012 Inspect History ID: 2654591 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 4-Feb-2013 Inspect History ID: 2769646 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 26-Mar-2013 Inspect History ID: 2901087 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 27-Mar-2013 Inspect History ID: 2903070 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST1664686	Defect Type: All Categories	Comments: .75 X .31 D:70mm	Location Description: OPP TP187	Priority: R3 - 4 Weeks	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 27-March-2013	BITMAC POTHOLE (CBPH)						

Recorded By:



Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
D71021A	^ Velocity patch 0-1m2	1.00	no	L 1.00	W 0.00	D 0.00	



Inspection Report

Inspection Date: 25-Jul-2013 Inspect History ID: 2516317 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 13-Aug-2013 Inspect History ID: 2497289 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 17-Sep-2013 Inspect History ID: 2629914 - Historical Inspection

Inspection Type:

Inspector:

Section Code:
7125U9105_01

Section Description:
PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: WEST1701918	Defect Type: All Categories	Comments: CLEAN OPEN DRAIN	Location Description: PORTS RD	Priority R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 17-September-2013	WATER RUNNING (UWRN)						
Recorded By: [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
X42002A	^ Clean open drain <500mm deep >5m	130.00	LIN.M	L 130.00	W 0.00	D 0.00	



Inspection Report

Inspection Date: 25-Sep-2013 Inspect History ID: 2861973 - Historical Inspection

Inspection Type:

Inspector:



Inspection Report

Inspection Date: 5-Dec-2013 Inspect History ID: 218249 - Full Sector - Safety Inspection of FE5 - FERMANAGH (Awaiting Return)

Inspection Type: Full Sector - Safety Inspection

Inspector: [REDACTED]

No Defects found on: 7125U9105_01 - PORTS RD1: U9674 KILLYCLONNY RD TO END by [REDACTED]



Inspection Report

Inspection Date: 27-Mar-2014 Inspect History ID: 999654 - Full Sector - Safety Inspection of FE5 - FERMANAGH on 25 March 2014 Inspection Type: Full Sector - Safety Inspection
 Inspector: [REDACTED]

Section Code: 7125U9105_01 Section Description: PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: [DCD54-999654-28](#) Defect Type: DEFECT Comments: Location Description: OPP TP240 Priority: R4 - next available programme Defect Dimensions: Length (m): 1.20 Width (m): 0.40 Depth (mm): 140.00
 Recorded Date: 27-March-2014 GRASS VERGE RUTTED (VGRT)
 Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
F53401A	^ Make up verge 0-5m2	1.00	no	L 0.00 W 0.00 D 0.00

Defect Ref: [DCD54-999654-29](#) Defect Type: DEFECT Comments: Location Description: AT TP254 Priority: R4 - next available programme Defect Dimensions: Length (m): 1.70 Width (m): 0.60 Depth (mm): 140.00
 Recorded Date: 27-March-2014 GRASS VERGE RUTTED (VGRT)
 Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
F53401A	^ Make up verge 0-5m2	1.00	no	L 0.00 W 0.00 D 0.00



Inspection Report

Inspection Date: 27-Mar-2014
 Inspect History ID: 999654 - Full Sector - Safety Inspection of FE5 - FERMANAGH on 25 March 2014
 Inspection Type: Full Sector - Safety Inspection
Inspector: ██████████

Section Code: 7125U9105_01
 Section Description: PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: [DCD54-999654-30](#)
Defect Type: DEFECT
Comments: 6 MINOR PHS ON RD
Location Description: AT TP244
Priority: R3 - 4 Weeks
Defect Dimensions:
Length (m): 0.33
Width (m): 0.40
Depth (mm): 60.00
Recorded Date: 27-March-2014
BITMAC POTHOLE (CBPH)

Recorded By:
██████████

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures		
D71021A	^ Velocity patch 0-1m2	1.00	no	L 0.00	W 0.00	D 0.00
D71021A	^ Velocity patch 0-1m2	6.00	no	L 0.00	W 0.00	D 0.00



Inspection Report

Inspection Date: 31-Jul-2014 Inspect History ID: 1005903 - Full Sector - Safety Inspection of FE5 - FERMANAGH on 29 July 2014

Inspection Type: Full Sector - Safety Inspection

Inspector: [REDACTED]

No Defects found on: 7125U9105_01 - PORTS RD1: U9674 KILLYCLONNY RD TO END by [REDACTED]



Inspection Report

Inspection Date: 1-Dec-2014

Inspect History ID: 1009339 - Full Sector - Safety Inspection of FE5 - FERMANAGH on 26 November 2014

Inspection Type: Full Sector - Safety Inspection

Inspector: [REDACTED]

No Defects found on: 7125U9105_01 - PORTS RD1: U9674 KILLYCLONNY RD TO END by [REDACTED]



Inspection Report

Inspection Date: 2-Apr-2015

Inspect History ID: 3045132 - Full Sector - Safety Inspection of FE5 - FERMANAGH on 01 April 2015

Inspection Type: Full Sector - Safety Inspection

Inspector: [REDACTED]

No Defects found on: 7125U9105_01 - PORTS RD1: U9674 KILLYCLONNY RD TO END by [REDACTED]



Inspection Report

Inspection Date: 29-Jul-2015 Inspect History ID: 3048314 - Full Sector - Safety Inspection of FE5 - FERMANAGH on 29 July 2015 Inspection Type: Full Sector - Safety Inspection
 Inspector: ██████████

Section Code: 7125U9105_01 Section Description: PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref:	Defect Type:	Comments:	Location Description:	Priority	Defect Dimensions:		
DCD54-3048314-28	DEFECT	WATCH FOR DOGS	NEAR RD END	R4 - next available programme	Length (m):	Width (m):	Depth (mm):

Recorded Date: 29-July-2015 ROAD MARKINGS FADED (CYFD)

Recorded By: ██████████

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
K33721A	^ 701-1599mm letters	4.00	no	L 0.00	W 0.00	D 0.00	



Inspection Report

Inspection Date: 9-Dec-2015

Inspect History ID: 3051695 - Full Sector - Safety Inspection of FE5 - FERMANAGH on 03 December 2015

Inspection Type: Full Sector - Safety Inspection

Inspector: [REDACTED]

No Defects found on: 7125U9105_01 - PORTS RD1: U9674 KILLYCLONNY RD TO END by [REDACTED]



Inspection Report

Inspection Date: 23-Sep-2016

Inspect History ID: 3058742 - Full Sector - Safety Inspection of FE7-FERMANAGH & OMAGH WEST on 19 September 2016

Inspection Type: Full Sector - Safety Inspection

Inspector: [REDACTED]

No Defects found on: 7125U9105_01 - PORTS RD1: U9674 KILLYCLONNY RD TO END by [REDACTED]



Inspection Report

Inspection Date: 20-Mar-2017 Inspect History ID: 3061741 - Full Sector - Safety Inspection of FE7-FERMANAGH & OMAGH WEST on 14 March 2017 Inspection Type: Full Sector - Safety Inspection

Inspector: [REDACTED]

Section Code: 7125U9105_01 Section Description: PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: [DCD90-3061741-50](#) Defect Type: DEFECT Comments: contact [REDACTED] Location Description: whole stretch Priority: R4 - next available programme Defect Dimensions: Length (m): Width (m): Depth (mm):

Recorded Date: 20-March-2017 VERGE DRAIN/DITCH BLOCKED (VDBL)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
U01001A	^ Unplanned drainage works norm.hrs	1.00	HR	L 0.00 W 0.00 D 0.00
X42002A	^ Clean open drain <500mm deep >5m	200.00	LIN.M	L 200.00 W 0.00 D 0.00

Defect Ref: [DCD90-3061741-51](#) Defect Type: DEFECT Comments: Location Description: 5m past tp no number ivey.on pole Priority: R3 - 4 Weeks Defect Dimensions: Length (m): 1.00 Width (m): 1.00 Depth (mm): 52.00

Recorded Date: 20-March-2017 BITMAC POTHOLE (CBPH)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D71021A	^ Velocity patch 0-1m2	1.00	no	L 0.00 W 0.00 D 0.00



Inspection Report

Inspection Date: 18-Sep-2017
 Inspect History ID: 3064722 - Full Sector - Safety Inspection of FE7-FERMANAGH & OMAGH WEST on 14 September 2017
 Inspection Type: Full Sector - Safety Inspection
Inspector: ██████████

Section Code: 7125U9105_01
 Section Description: PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: [DCD90-3064722-44](#)
Defect Type: DEFECT
Comments:
Location Description: 25m back from last house on right
Priority: R3 - 4 Weeks
Defect Dimensions: Length (m): 1.00 Width (m): 1.00 Depth (mm): 55.00
Recorded Date: 18-September-2017
Recorded By: ██████████
BITMAC POT HOLE (CBPH)

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures		
D71021A	^ Velocity patch 0-1m2	1.00	no	L 0.00	W 0.00	D 0.00



Inspection Report

Inspection Date: 26-Mar-2018 Inspect History ID: 3067941 - Full Sector - Safety Inspection of FE7-FERMANAGH & OMAGH WEST on 20 March 2018 Inspection Type: Full Sector - Safety Inspection
 Inspector: [REDACTED]

Section Code: 7125U9105_01 Section Description: PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: [DCD54-3067941-171](#) Defect Type: DEFECT Comments: Location Description: 10m towards tp 283 Priority: R3 - 4 Weeks Defect Dimensions: Length (m): 1.20 Width (m): 0.60 Depth (mm): 57.00
 Recorded Date: 26-March-2018 BITMAC EDGE DETERIORATION (CBED)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D71021A	^ Velocity patch 0-1m2	1.00	no	L 0.00 W 0.00 D 0.00
D71021A	^ Velocity patch 0-1m2	1.00	no	L 0.00 W 0.00 D 0.00

Defect Ref: [DCD54-3067941-172](#) Defect Type: DEFECT Comments: Location Description: At tp 257 Priority: R3 - 4 Weeks Defect Dimensions: Length (m): 0.40 Width (m): 0.30 Depth (mm): 52.00
 Recorded Date: 26-March-2018 BITMAC POTHOLE (GBPH)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D71021A	^ Velocity patch 0-1m2	1.00	no	L 0.00 W 0.00 D 0.00



Inspection Report

Inspection Date: 26-Mar-2018
 Inspect History ID: 3067941 - Full Sector - Safety Inspection of FE7-FERMANAGH & OMAGH WEST on 20 March 2018
 Inspection Type: Full Sector - Safety Inspection
Inspector: ██████████

Section Code: 7125U9105_01
 Section Description: PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: [DCD54-3067941-173](#)
Defect Type: DEFECT
Comments:
Location Description: 10m past tp 245
Priority: R3 - 4 Weeks
Defect Dimensions:
Length (m): 16.00
Width (m): 1.50
Depth (mm): 70.00
Recorded Date: 26-March-2018
BITMAC DEPRESSED (CBDP)

Recorded By: ██████████

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D83114A	^ 100mm bit.patch W/C & B/C 15-50 m2	25.50	SQ.M	L 17.00 W 1.50 D 0.00

Defect Ref: [DCD54-3067941-174](#)
Defect Type: DEFECT
Comments:
Location Description: 10m past tp 245
Priority: R3 - 4 Weeks
Defect Dimensions:
Length (m): 1.00
Width (m): 0.40
Depth (mm): 53.00
Recorded Date: 26-March-2018
BITMAC POTHOLE (CBPH)

Recorded By: ██████████

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D71021A	^ Velocity patch 0-1m2	1.00	no	L 0.00 W 0.00 D 0.00
D71021A	^ Velocity patch 0-1m2	1.00	no	L 0.00 W 0.00 D 0.00



Inspection Report

Inspection Date: 17-Sep-2018 Inspect History ID: 3070930 - Full Sector - Safety Inspection of FE7-FERMANAGH & OMAGH WEST on 14 September 2018 Inspection Type: Full Sector - Safety Inspection

Inspector: [REDACTED]

Section Code: 7125U9105_01 Section Description: PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: [DCD90-3070930-27](#) Defect Type: DEFECT Comments: Location Description: give way line at port sign missing Priority: R4 - next available programme Defect Dimensions: Length (m): Width (m): Depth (mm):

Recorded Date: 17-September-2018 ROAD MARKINGS MISSING (CYMI)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
K31001A	^ Renew junction markings	1.00	no	L 0.00 W 0.00 D 0.00

Defect Ref: [DCD90-3070930-28](#) Defect Type: DEFECT Comments: Location Description: give way line faded Priority: R4 - next available programme Defect Dimensions: Length (m): Width (m): Depth (mm):

Recorded Date: 17-September-2018 ROAD MARKINGS FADED (CYFD)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
K31001A	^ Renew junction markings	1.00	no	L 0.00 W 0.00 D 0.00



Inspection Report

Inspection Date: 17-Apr-2019 Inspect History ID: 3074824 - Full Sector - Safety Inspection of FE7-FERMANAGH & OMAGH WEST on 09 April 2019 Inspection Type: Full Sector - Safety Inspection
 Inspector: [REDACTED]

Section Code: 7125U9105_01 Section Description: PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: [DCD61-3074824-191](#) Defect Type: DEFECT Comments: Location Description: at bt pole 265 Priority: R3 - 4 Weeks Defect Dimensions: Length (m): 0.50 Width (m): 0.50 Depth (mm): 53.00
 Recorded Date: 17-April-2019 BITMAC POTHOLE (CBPH)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D24021A	^ 70mm bit. patch w/c <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Defect Ref: [DCD61-3074824-192](#) Defect Type: DEFECT Comments: Location Description: at bt pole 230 Priority: R3 - 4 Weeks Defect Dimensions: Length (m): 7.00 Width (m): 0.90 Depth (mm): 64.00
 Recorded Date: 17-April-2019 BITMAC EDGE DETERIORATION (CBED)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D24023A	^ 70mm bit. patch w/c 3-15 m2	6.30	SQ.M	L 7.00 W 0.90 D 0.00



Inspection Report

Inspection Date: 19-Sep-2019 Inspect History ID: 3077448 - Full Sector - Safety Inspection of FE7-FERMANAGH & OMAGH WEST on 10 September 2019 Inspection Type: Full Sector - Safety Inspection

Inspector: [REDACTED]

Section Code: 7125U9105_01 Section Description: PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: DCD61-3077448-154	Defect Type: DEFECT	Comments: renew jtn lines	Location Description: at jtn of killard rd	Priority R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
Recorded Date: 19-September-2019	ROAD MARKINGS FADED (CYFD)						
Recorded By: [REDACTED]							
	Repair Description: K31001A	Repair Item Name: ^ Renew junction markings	Quantity 1.00	Units no	Repair Measures L 0.00 W 0.00 D 0.00		

Defect Ref: DCD61-3077448-155	Defect Type: DEFECT	Comments: same patch	Location Description: at bt pole 236	Priority R3 - 4 Weeks	Defect Dimensions: Length (m): 21.00	Width (m): 2.80	Depth (mm): 95.00
Recorded Date: 19-September-2019	BITMAC UNEVEN (CBUN)						
Recorded By: [REDACTED]							
	Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures		
	D83114A	^ 100mm bit.patch W/C & B/C 15-50 m2	50.00	SQ.M	L 50.00 W 1.00 D 0.00		
	D23113A	^ 100mm bit. patch W/C & B/C 3-15 m2	8.80	SQ.M	L 8.80 W 1.00 D 0.00		
	D20024A	^ 40mm overlay bit. patch 14mm 15-50sq.m	50.00	SQ.M	L 50.00 W 1.00 D 0.00		
	D20023A	^ 40mm overlay bit. patch 14mm 3-15sq.m	8.80	SQ.M	L 8.80 W 1.00 D 0.00		



Inspection Report

Inspection Date: 19-Sep-2019 Inspect History ID: 3077448 - Full Sector - Safety Inspection of FE7-FERMANAGH & OMAGH WEST on 10 September 2019 Inspection Type: Full Sector - Safety Inspection
 Inspector: [REDACTED]

Section Code: 7125U9105_01 Section Description: PORTS RD1: U9674 KILLYCLONNY RD TO END

Defect Ref: [DCD61-3077448-156](#) Defect Type: DEFECT Comments: same patch Location Description: 20m past bt pole 236 Priority: R3 - 4 Weeks Defect Dimensions: Length (m): 19.00 Width (m): 2.80 Depth (mm): 95.00
 Recorded Date: 19-September-2019 BITMAC UNEVEN (CBUN)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures		
D83114A	^ 100mm bit.patch W/C & B/C 15-50 m2	50.00	SQ.M	L 50.00	W 1.00	D 0.00
D23112A	^ 100mm bit. patch W/C & B/C 1-3 m2	3.20	SQ.M	L 3.20	W 1.00	D 0.00
D20024A	^ 40mm overlay bit. patch 14mm 15-50sq.m	50.00	SQ.M	L 50.00	W 1.00	D 0.00
D20023A	^ 40mm overlay bit. patch 14mm 3-15sq.m	3.20	SQ.M	L 3.20	W 1.00	D 0.00



Inspection Report

Inspection Date: 16-Mar-2020

Inspect History ID: 3080365 - Full Sector - Safety Inspection of FE7-FERMANAGH & OMAGH WEST on 05 March 2020

Inspection Type: Full Sector - Safety Inspection

Inspector: [REDACTED]

No Defects found on: 7125U9105_01 - PORTS RD1: U9674 KILLYCLONNY RD TO END by [REDACTED]



Inspection Report

Inspection Date: 3-Sep-2020

Inspect History ID: 3083097 - Full Sector - Safety Inspection of FE7-FERMANAGH & OMAGH WEST on 24 August 2020

Inspection Type: Full Sector - Safety Inspection

Inspector: [REDACTED]

No Defects found on: 7125U9105_01 - PORTS RD1: U9674 KILLYCLONNY RD TO END by [REDACTED]



Inspection Report

Inspection Date: 10-Mar-2021 Inspect History ID: 3086159 - Full Sector - Safety Inspection of FE7-FERMANAGH & OMAGH WEST on 04 March 2021

Inspection Type: Full Sector - Safety Inspection

Inspector: [REDACTED]

No Defects found on: 7125U9105_01 - PORTS RD1: U9674 KILLYCLONNY RD TO END by [REDACTED]