



# Inspection Report

<b>Inspection Date:</b>	<b>See Recorded Date</b>	<b>Inspect History ID:</b> -	<b>Inspection Type:</b>
			<b>Inspector:</b>

<b>Section Code:</b> 7035U0417_36	<b>Section Description:</b> HAZELBURN RD1: MANSE RD4 TO CARNMONEY RD N1
--------------------------------------	--

<b>Defect Ref:</b> <a href="#">D2027225</a>	<b>Defect Type:</b> PLANNED WORKS	<b>Comments:</b> Install new gully	<b>Location Description:</b> Hazelburn Road. Opp No1 Rowan Grove.	<b>Priority</b> Not Applicable (Planned Works)	<b>Defect Dimensions:</b>	<b>Length (m):</b>	<b>Width (m):</b>	<b>Depth (mm):</b>
<b>Recorded Date:</b> 08-December-2020	NOT APPLICABLE							
<b>Recorded By:</b>	[REDACTED]							

<b>Defect Ref:</b> <a href="#">D2027230</a>	<b>Defect Type:</b> PLANNED WORKS	<b>Comments:</b> Install new gully	<b>Location Description:</b> Hazelburn Road. Opposite No1 Rowan Grove	<b>Priority</b> Not Applicable (Planned Works)	<b>Defect Dimensions:</b>	<b>Length (m):</b>	<b>Width (m):</b>	<b>Depth (mm):</b>
<b>Recorded Date:</b> 08-December-2020	NOT APPLICABLE							
<b>Recorded By:</b>	[REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures				
U27112A	Precast concrete trapped gully with 375mm (dia.) clear opening BS EN 124 Group 3 Class C250 gully top including connections up to 3 metres long to main drain or sewer.	1.00	no	L 0.00	W 0.00	D 0.00		
D13443A	^ 100mm patch 14mm /20mm HRA 3-15 m2	15.00	SQ.M	L 3.00	W 5.00	D 0.00		



# Inspection Report

<b>Inspection Date:</b>	<b>See Recorded Date</b>	<b>Inspect History ID:</b>	<b>3084798 - 1 Monthly - Safety Inspection of AAN1-05-ANTRIM &amp; NEWTOWNABBEY on 08 December 2020</b>	<b>Inspection Type:</b>	<b>1 Monthly - Safety Inspection</b>
				<b>Inspector:</b>	

<b>Section Code:</b>	<b>Section Description:</b>
<b>7035U0417_36</b>	<b>HAZELBURN RD1: MANSE RD4 TO CARNMONEY RD N1</b>

<b>Defect Ref:</b>	<b>Defect Type:</b>	<b>Comments:</b>	<b>Location Description:</b>	<b>Priority</b>	<b>Defect Dimensions:</b>		
<a href="#">DCD74-3084798-12</a>	DEFECT	RESET KERBS REF ENQUIRY E2005603	<b>KERBS AT JCT HAZELBURN ROAD</b>	<b>R3 - 4 Weeks</b>	<b>Length (m): 1.90</b>	<b>Width (m): 0.25</b>	<b>Depth (mm): 22.00</b>

**Recorded Date:** 08-December-2020  
**Recorded By:** ██████████

FOOTPATH KERB HIGH (FKHI)

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
<b>M64111A</b>	<b>^ Lift &amp; relay kerbs &gt;12m rad, 0-5m</b>	<b>3.00</b>	<b>LIN.M</b>	<b>L 3.00</b>	<b>W 0.00</b>	<b>D 0.00</b>	

<b>Defect Ref:</b>	<b>Defect Type:</b>	<b>Comments:</b>	<b>Location Description:</b>	<b>Priority</b>	<b>Defect Dimensions:</b>		
<a href="#">DCD74-3084798-13</a>	DEFECT	REF ENQUIRY E2005603	<b>CWAY AT JCT HAZELBURN ROAD</b>	<b>R3 - 4 Weeks</b>	<b>Length (m): 1.30</b>	<b>Width (m): 0.40</b>	<b>Depth (mm): 41.00</b>

**Recorded Date:** 08-December-2020  
**Recorded By:** ██████████

ASPHALT POTHOLE (CAPH)

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
<b>D13441A</b>	<b>^ 100mm patch 14mm W/C &amp; 20mm B/C HRA &lt;1m2</b>	<b>1.00</b>	<b>no</b>	<b>L 0.00</b>	<b>W 0.00</b>	<b>D 0.00</b>	



# Inspection Report

<b>Inspection Date:</b>	<b>See Recorded Date</b>	<b>Inspect History ID:</b>	<b>3084798 - 1 Monthly - Safety Inspection of AAN1-05-ANTRIM &amp; NEWTOWNABBEY on 08 December 2020</b>	<b>Inspection Type:</b>	<b>1 Monthly - Safety Inspection</b>
				<b>Inspector:</b>	

<b>Section Code:</b>	<b>Section Description:</b>
<b>7035U0417_36</b>	<b>HAZELBURN RD1: MANSE RD4 TO CARNMONEY RD N1</b>

<b>Defect Ref:</b>	<b>Defect Type:</b>	<b>Comments:</b>	<b>Location Description:</b>	<b>Priority</b>	<b>Defect Dimensions:</b>		
<a href="#">DCD74-3084798-20</a>	DEFECT	REET KERBS REF ENQUIRY E2005603	KERBS LHS STL 11	R3 - 4 Weeks	<b>Length (m): 0.50</b>	<b>Width (m): 0.25</b>	<b>Depth (mm): 22.00</b>
<b>Recorded Date:</b>	<b>FOOTPATH KERB HIGH (FKHI)</b>						
08-December-2020							
<b>Recorded By:</b>	[REDACTED]						

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
<b>M64111A</b>	<b>^ Lift &amp; relay kerbs &gt;12m rad, 0-5m</b>	<b>2.00</b>	<b>LIN.M</b>	<b>L 2.00</b>	<b>W 0.00</b>	<b>D 0.00</b>	

<b>Defect Ref:</b>	<b>Defect Type:</b>	<b>Comments:</b>	<b>Location Description:</b>	<b>Priority</b>	<b>Defect Dimensions:</b>		
<a href="#">DCD74-3084798-21</a>	DEFECT	RESET KERB REF ENQUIRY E2005603	KERB OPP HOUSE 12	R3 - 4 Weeks	<b>Length (m): 0.92</b>	<b>Width (m): 0.25</b>	<b>Depth (mm): 22.00</b>
<b>Recorded Date:</b>	<b>FOOTPATH KERB HIGH (FKHI)</b>						
08-December-2020							
<b>Recorded By:</b>	[REDACTED]						

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
<b>M64111A</b>	<b>^ Lift &amp; relay kerbs &gt;12m rad, 0-5m</b>	<b>1.00</b>	<b>LIN.M</b>	<b>L 1.00</b>	<b>W 0.00</b>	<b>D 0.00</b>	



## Inspection Report

<b>Inspection Date:</b>	<b>See Recorded Date</b>	<b>Inspect History ID:</b>	<b>3084798 - 1 Monthly - Safety Inspection of AAN1-05-ANTRIM &amp; NEWTOWNABBEY on 08 December 2020</b>	<b>Inspection Type:</b>	<b>1 Monthly - Safety Inspection</b>
				<b>Inspector:</b>	

<b>Section Code:</b>	<b>Section Description:</b>
<b>7035U0417_36</b>	<b>HAZELBURN RD1: MANSE RD4 TO CARNMONEY RD N1</b>

<b>Defect Ref:</b>	<b>Defect Type:</b>	<b>Comments:</b>	<b>Location Description:</b>	<b>Priority</b>	<b>Defect Dimensions:</b>		
<a href="#">DCD74-3084798-22</a>	DEFECT	REPLACE ROUND TOP PIN KERBS AT GRASS AREA. REF ENQUIRY E2005603	<b>KERBS RHS STL 15</b>	<b>R3 - 4 Weeks</b>	<b>Length (m): 0.92</b>	<b>Width (m): 0.05</b>	<b>Depth (mm): 22.00</b>

<b>Recorded Date:</b>	<b>FOOTPATH KERB LOW (FKLO)</b>
08-December-2020	

Recorded By:

<b>Repair Description:</b>	<b>Repair Item Name:</b>	<b>Quantity</b>	<b>Units</b>	<b>Repair Measures</b>			
<b>M61322A</b>	<b>^ 150 x 50 round top edging &gt;12m rad &gt;5m</b>	<b>6.00</b>	<b>LIN.M</b>	<b>L 6.00</b>	<b>W 0.00</b>	<b>D 0.00</b>	

<b>Defect Ref:</b>	<b>Defect Type:</b>	<b>Comments:</b>	<b>Location Description:</b>	<b>Priority</b>	<b>Defect Dimensions:</b>		
<a href="#">DCD74-3084798-23</a>	DEFECT	RESET 1 KERB AND REPLACE 1 KERB REF ENQUIRY E2005603	<b>KERBS RHS STL 9</b>	<b>R3 - 4 Weeks</b>	<b>Length (m): 1.80</b>	<b>Width (m): 0.25</b>	<b>Depth (mm): 22.00</b>

<b>Recorded Date:</b>	<b>FOOTPATH KERB HIGH (FKHI)</b>
08-December-2020	

Recorded By:

<b>Repair Description:</b>	<b>Repair Item Name:</b>	<b>Quantity</b>	<b>Units</b>	<b>Repair Measures</b>			
<b>M64111A</b>	<b>^ Lift &amp; relay kerbs &gt;12m rad, 0-5m</b>	<b>2.00</b>	<b>LIN.M</b>	<b>L 2.00</b>	<b>W 0.00</b>	<b>D 0.00</b>	



# Inspection Report

<b>Inspection Date:</b> See Recorded Date	<b>Inspect History ID:</b> 3084798 - 1 Monthly - Safety Inspection of AAN1-05-ANTRIM & NEWTOWNABBEY on 08 December 2020	<b>Inspection Type:</b> 1 Monthly - Safety Inspection
		<b>Inspector:</b>

<b>Section Code:</b> 7035U0417_36	<b>Section Description:</b> HAZELBURN RD1: MANSE RD4 TO CARNMONEY RD N1
-----------------------------------	---

<b>Defect Ref:</b> <a href="#">DCD74-3084798-24</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b> RESET PIN KERB REF ENQUIRY E2005603	<b>Location Description:</b> PIN KERB RHS STL 4	<b>Priority:</b> R3 - 4 Weeks	<b>Defect Dimensions:</b>		
<b>Recorded Date:</b> 08-December-2020	FOOTPATH KERB HIGH (FKHI)				<b>Length (m):</b> 0.50	<b>Width (m):</b> 0.05	<b>Depth (mm):</b> 22.00
<b>Recorded By:</b>	[Redacted]						

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures		
<b>M61321A</b>	<b>^ 150 x 50 round top edging &gt;12m rad 0-5m</b>	<b>1.00</b>	<b>LIN.M</b>	<b>L 1.00</b>	<b>W 0.00</b>	<b>D 0.00</b>

<b>Defect Ref:</b> <a href="#">DCD74-3084798-25</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b> RESET KERBS REF ENQUIRY E2005603	<b>Location Description:</b> KERBS RHS JCT CHERRYMOUNT	<b>Priority:</b> R3 - 4 Weeks	<b>Defect Dimensions:</b>		
<b>Recorded Date:</b> 08-December-2020	FOOTPATH KERB HIGH (FKHI)				<b>Length (m):</b> 1.20	<b>Width (m):</b> 0.25	<b>Depth (mm):</b> 22.00
<b>Recorded By:</b>	[Redacted]						

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures		
<b>M64111A</b>	<b>^ Lift &amp; relay kerbs &gt;12m rad, 0-5m</b>	<b>4.00</b>	<b>LIN.M</b>	<b>L 4.00</b>	<b>W 0.00</b>	<b>D 0.00</b>



# Inspection Report

<b>Inspection Date:</b> See Recorded Date	<b>Inspect History ID:</b> 3084798 - 1 Monthly - Safety Inspection of AAN1-05-ANTRIM & NEWTOWNABBEY on 08 December 2020	<b>Inspection Type:</b> 1 Monthly - Safety Inspection
		<b>Inspector:</b>

<b>Section Code:</b> 7035U0417_36	<b>Section Description:</b> HAZELBURN RD1: MANSE RD4 TO CARNMONEY RD N1
-----------------------------------	---

<b>Defect Ref:</b> <a href="#">DCD74-3084798-26</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b> RESET 2 KERBS AND REPLACE 4 KERBS REF ENQUIRY E2005603	<b>Location Description:</b> KERBS RHS STL 1	<b>Priority:</b> R3 - 4 Weeks	<b>Defect Dimensions:</b> <b>Length (m): 5.50</b>	<b>Width (m): 0.25</b>	<b>Depth (mm): 22.00</b>
--	-------------------------------	--	---	----------------------------------	--	------------------------	--------------------------

**Recorded Date:** 08-December-2020  
**FOOTPATH KERB HIGH (FKHI)**

**Recorded By:**  
[Redacted]

<b>Repair Description:</b>	<b>Repair Item Name:</b>	<b>Quantity</b>	<b>Units</b>	<b>Repair Measures</b>
<b>M64112A</b>	<b>^ Lift &amp; relay kerbs &gt;12m rad, &gt;5m</b>	<b>6.00</b>	<b>LIN.M</b>	<b>L 6.00      W 0.00      D 0.00</b>

<b>Defect Ref:</b> <a href="#">DCD74-3084798-27</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b> REPLACE KERB REF ENQUIRY E2005603	<b>Location Description:</b> KERB LHS STL 3	<b>Priority:</b> R3 - 4 Weeks	<b>Defect Dimensions:</b> <b>Length (m): 0.92</b>	<b>Width (m): 0.25</b>	<b>Depth (mm): 22.00</b>
--	-------------------------------	---	--	----------------------------------	--	------------------------	--------------------------

**Recorded Date:** 08-December-2020  
**FOOTPATH KERB HIGH (FKHI)**

**Recorded By:**  
[Redacted]

<b>Repair Description:</b>	<b>Repair Item Name:</b>	<b>Quantity</b>	<b>Units</b>	<b>Repair Measures</b>
<b>M64111A</b>	<b>^ Lift &amp; relay kerbs &gt;12m rad, 0-5m</b>	<b>1.00</b>	<b>LIN.M</b>	<b>L 1.00      W 0.00      D 0.00</b>



# Inspection Report

<b>Inspection Date:</b>	<b>See Recorded Date</b>	<b>Inspect History ID:</b>	<b>3084798 - 1 Monthly - Safety Inspection of AAN1-05-ANTRIM &amp; NEWTOWNABBEY on 08 December 2020</b>	<b>Inspection Type:</b>	<b>1 Monthly - Safety Inspection</b>
				<b>Inspector:</b>	

<b>Section Code:</b>	<b>Section Description:</b>
<b>7035U0417_36</b>	<b>HAZELBURN RD1: MANSE RD4 TO CARNMONEY RD N1</b>

<b>Defect Ref:</b>	<b>Defect Type:</b>	<b>Comments:</b>	<b>Location Description:</b>	<b>Priority</b>	<b>Defect Dimensions:</b>		
<a href="#">DCD74-3084798-28</a>	DEFECT	RESET KERB REF ENQUIRY E2005603	KERB RHS STL 3	R3 - 4 Weeks	<b>Length (m):</b>	<b>Width (m):</b>	<b>Depth (mm):</b>
<b>Recorded Date:</b>	FOOTPATH KERB LOW (FKLO)						
08-December-2020							
<b>Recorded By:</b>	[REDACTED]						

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
<b>M64111A</b>	<b>^ Lift &amp; relay kerbs &gt;12m rad, 0-5m</b>	<b>1.00</b>	<b>LIN.M</b>	<b>L 1.00</b>	<b>W 0.00</b>	<b>D 0.00</b>	



# Inspection Report

<b>Inspection Date:</b> 13-Jan-2019	<b>Inspect History ID:</b> 3073307 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 11 January 2019	<b>Inspection Type:</b> Full Sector - Safety Inspection
		<b>Inspector:</b> [REDACTED]

<b>Section Code:</b> 7035U0417_36	<b>Section Description:</b> HAZELBURN RD1: MANSE RD4 TO CARNMONEY RD N1
--------------------------------------	--

**Defect Ref:** [DCD113-3073307-79](#)  
**Defect Type:** DEFECT  
**Comments:** REPLACE KERB  
**Location Description:** 15M ABOVE STL 3  
**Priority:** R3 - 4 Weeks  
**Defect Dimensions:**  
**Length (m):** 0.90    **Width (m):** 0.25    **Depth (mm):** 23.00  
**Recorded Date:** 13-January-2019  
**Recorded By:** [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
<b>M64111A</b>	<b>^ Lift &amp; relay kerbs &gt;12m rad, 0-5m</b>	<b>1.00</b>	<b>LIN.M</b>	<b>L 1.00    W 0.00    D 0.00</b>

**Defect Ref:** [DCD113-3073307-84](#)  
**Defect Type:** DEFECT  
**Comments:** ASPHALT CRACKED (FACR)  
**Location Description:** FPATH OPPOSITE STL 16 ON BEND  
**Priority:** R2 - 5 Working days  
**Defect Dimensions:**  
**Length (m):** 1.80    **Width (m):** 0.20    **Depth (mm):** 60.00  
**Recorded Date:** 13-January-2019  
**Recorded By:** [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
<b>M12013A</b>	<b>^ 75mm asphalt patch &gt;3 square metres</b>	<b>4.05</b>	<b>SQ.M</b>	<b>L 4.50    W 0.90    D 0.00</b>
<b>Z01700A</b>	<b>EO all items for Priority 2 response</b>	<b>81.76</b>	<b>%</b>	<b>L 0.00    W 0.00    D 0.00</b>



# Inspection Report

Inspection Date: 13-Jan-2019      Inspect History ID: 3073307 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 11 January 2019      Inspection Type: Full Sector - Safety Inspection  
 Inspector: [REDACTED]

Section Code: 7035U0417\_36      Section Description: HAZELBURN RD1: MANSE RD4 TO CARNMONEY RD N1

Defect Ref: [DCD113-3073307-85](#)      Defect Type: DEFECT      Comments:      Location Description: OPPOSITE STL 16 ON BEND      Priority: R3 - 4 Weeks      Defect Dimensions: Length (m): 0.45      Width (m): 0.25      Depth (mm): 22.00  
 Recorded Date: 13-January-2019      FOOTPATH KERB LOW (FKLO)  
 Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	0.50	LIN.M	L 0.50      W 0.00      D 0.00
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	1.00	LIN.M	L 1.00      W 0.00      D 0.00

Defect Ref: [DCD113-3073307-88](#)      Defect Type: DEFECT      Comments:      Location Description: AT STL 16      Priority: R3 - 4 Weeks      Defect Dimensions: Length (m): 4.00      Width (m): 0.25      Depth (mm): 24.00  
 Recorded Date: 13-January-2019      FOOTPATH KERB HIGH (FKHI)  
 Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	4.00	LIN.M	L 4.00      W 0.00      D 0.00
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	2.00	LIN.M	L 2.00      W 0.00      D 0.00
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	1.00	LIN.M	L 1.00      W 0.00      D 0.00



# Inspection Report

Inspection Date: 13-Jan-2019      Inspect History ID: 3073307 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 11 January 2019      Inspection Type: Full Sector - Safety Inspection  
 Inspector: [REDACTED]

Section Code: 7035U0417\_36      Section Description: HAZELBURN RD1: MANSE RD4 TO CARNMONEY RD N1

Defect Ref: [DCD113-3073307-89](#)      Defect Type: DEFECT      Comments:      Location Description: BETWEEN STL 10 + 11 (entrance elderburn)      Priority: R3 - 4 Weeks      Defect Dimensions: Length (m): 1.20      Width (m): 0.25      Depth (mm): 21.00

Recorded Date: 13-January-2019      FOOTPATH KERB HIGH (FKHI)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	1.20	LIN.M	L 1.20      W 0.00      D 0.00

Defect Ref: [DCD113-3073307-80](#)      Defect Type: DEFECT      Comments:      Location Description: 8M ABOVE STL 7 (entrance school)      Priority: R3 - 4 Weeks      Defect Dimensions: Length (m): 0.45      Width (m): 0.25      Depth (mm): 22.00

Recorded Date: 13-January-2019      FOOTPATH KERB LOW (FKLO)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	1.00	LIN.M	L 1.00      W 0.00      D 0.00



# Inspection Report

Inspection Date: 13-Jan-2019      Inspect History ID: 3073307 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 11 January 2019      Inspection Type: Full Sector - Safety Inspection  
 Inspector: [REDACTED]

Section Code: 7035U0417\_36      Section Description: HAZELBURN RD1: MANSE RD4 TO CARNMONEY RD N1

Defect Ref: [DCD113-3073307-81](#)      Defect Type: DEFECT      Comments:      Location Description: 5M ABOVE STL 11 (on.bend)      Priority: R3 - 4 Weeks      Defect Dimensions: Length (m): 0.45      Width (m): 0.25      Depth (mm): 21.00

Recorded Date: 13-January-2019      FOOTPATH KERB HIGH (FKHI)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	0.50	LIN.M	L 0.50      W 0.00      D 0.00
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	0.50	LIN.M	L 0.50      W 0.00      D 0.00

Defect Ref: [DCD113-3073307-82](#)      Defect Type: DEFECT      Comments: REPLACE 1 KERB      Location Description: AT STL 12      Priority: R3 - 4 Weeks      Defect Dimensions: Length (m): 0.90      Width (m): 0.25      Depth (mm): 24.00

Recorded Date: 13-January-2019      FOOTPATH KERB LOW (FKLO)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	3.00	LIN.M	L 3.00      W 0.00      D 0.00



# Inspection Report

**Inspection Date:** 13-Jan-2019     
 **Inspect History ID:** 3073307 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 11 January 2019     
 **Inspection Type:** Full Sector - Safety Inspection  
**Inspector:** [REDACTED]

**Section Code:** 7035U0417\_36     
 **Section Description:** HAZELBURN RD1: MANSE RD4 TO CARNMONEY RD N1

**Defect Ref:** [DCD113-3073307-83](#)     
**Defect Type:** DEFECT     
**Comments:**     
**Location Description:** BETWEEN STL 12 + 13     
**Priority:** R3 - 4 Weeks     
**Defect Dimensions:** Length (m): 0.90      Width (m): 0.25      Depth (mm): 22.00  
**Recorded Date:** 13-January-2019     
**FOOTPATH KERB HIGH (FKHI)**  
**Recorded By:** [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	1.00	LIN.M	L 1.00      W 0.00      D 0.00

**Defect Ref:** [DCD113-3073307-92](#)     
**Defect Type:** DEFECT     
**Comments:**     
**Location Description:** 2M BELOW STL 9     
**Priority:** R3 - 4 Weeks     
**Defect Dimensions:** Length (m): 3.00      Width (m): 0.25      Depth (mm): 30.00  
**Recorded Date:** 13-January-2019     
**FOOTPATH KERB HIGH (FKHI)**  
**Recorded By:** [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	3.00	LIN.M	L 3.00      W 0.00      D 0.00



# Inspection Report

Inspection Date: 13-Jan-2019	Inspect History ID: 3073307 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 11 January 2019	Inspection Type: Full Sector - Safety Inspection
		Inspector: [REDACTED]

Section Code: 7035U0417_36	Section Description: HAZELBURN RD1: MANSE RD4 TO CARNMONEY RD N1
----------------------------	--

Defect Ref: [DCD113-3073307-93](#) Defect Type: DEFECT Comments: Location Description: BETWEEN STL 8 + 9 Priority: R3 - 4 Weeks Defect Dimensions: Length (m): 2.00 Width (m): 0.25 Depth (mm): 25.00

Recorded Date: 13-January-2019 FOOTPATH KERB HIGH (FKHI)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	2.00	LIN.M	L 2.00 W 0.00 D 0.00

Defect Ref: [DCD113-3073307-94](#) Defect Type: DEFECT Comments: REPLACE KERB Location Description: BETWEEN STL 6 + 7 on bend approaching school Priority: R3 - 4 Weeks Defect Dimensions: Length (m): 0.90 Width (m): 0.25 Depth (mm): 25.00

Recorded Date: 13-January-2019 FOOTPATH KERB HIGH (FKHI)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	1.00	LIN.M	L 1.00 W 0.00 D 0.00
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	1.00	LIN.M	L 1.00 W 0.00 D 0.00



# Inspection Report

Inspection Date: 13-Jan-2019	Inspect History ID: 3073307 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 11 January 2019	Inspection Type: Full Sector - Safety Inspection
		Inspector: [REDACTED]

Section Code: 7035U0417_36	Section Description: HAZELBURN RD1: MANSE RD4 TO CARNMONEY RD N1
----------------------------	--

Defect Ref: <a href="#">DCD113-3073307-95</a>	Defect Type: DEFECT	Comments: REPLACE KERB	Location Description: BETWEEN STL 5 + 6	Priority: R3 - 4 Weeks	Defect Dimensions:			
Recorded Date: 13-January-2019	FOOTPATH KERB HIGH (FKHI)				Length (m): 0.90	Width (m): 0.25	Depth (mm): 22.00	

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	1.00	LIN.M	L 1.00 W 0.00 D 0.00
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	1.00	LIN.M	L 1.00 W 0.00 D 0.00



# Inspection Report

<b>Inspection Date:</b> 4-Jul-2019	<b>Inspect History ID:</b> 3076223 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 01 July 2019	<b>Inspection Type:</b> Full Sector - Safety Inspection
		<b>Inspector:</b> [REDACTED]

<b>Section Code:</b> 7035U0417_36	<b>Section Description:</b> HAZELBURN RD1: MANSE RD4 TO CARNMONEY RD N1
--------------------------------------	--

**Defect Ref:** [DCD74-3076223-129](#)  
**Defect Type:** DEFECT  
**Comments:** RESET KERBS  
**Location Description:** LHS STL 15  
**Priority:** R3 - 4 Weeks  
**Defect Dimensions:**  
**Length (m):** 0.90    **Width (m):** 0.25    **Depth (mm):** 22.00  
**Recorded Date:** 04-July-2019  
**Recorded By:** [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	1.00	LIN.M	L 1.00    W 0.00    D 0.00

**Defect Ref:** [DCD74-3076223-130](#)  
**Defect Type:** DEFECT  
**Comments:** GIVEWAY MARKINGS FADED  
**Location Description:** MARKINS AT JCT MANSE ROAD  
**Priority:** R4 - next available programme  
**Defect Dimensions:**  
**Length (m):**    **Width (m):**    **Depth (mm):**  
**Recorded Date:** 04-July-2019  
**Recorded By:** [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
K31341A	^ 200mm intermittent white screed	10.90	LIN.M	L 10.90    W 0.00    D 0.00
K31321A	^ 100mm intermittent white screed	20.00	LIN.M	L 20.00    W 0.00    D 0.00



# Inspection Report

<b>Inspection Date:</b> 4-Jul-2019	<b>Inspect History ID:</b> 3076223 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 01 July 2019	<b>Inspection Type:</b> Full Sector - Safety Inspection
		<b>Inspector:</b> [REDACTED]

<b>Section Code:</b> 7035U0417_36	<b>Section Description:</b> HAZELBURN RD1: MANSE RD4 TO CARNMONEY RD N1
--------------------------------------	--

Defect Ref: [DCD74-3076223-132](#)      Defect Type: DEFECT      Comments: RESET KERB      Location Description: OPP MOSSLEY PRIMARY SCHOOL      Priority: R3 - 4 Weeks      Defect Dimensions: Length (m): 0.90      Width (m): 0.25      Depth (mm): 22.00

Recorded Date: 04-July-2019      FOOTPATH KERB HIGH (FKHI)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	1.00	LIN.M	L 1.00      W 0.00      D 0.00

Defect Ref: [DCD74-3076223-134](#)      Defect Type: DEFECT      Comments: RESET KERB      Location Description: RHS OPP STL 3      Priority: R3 - 4 Weeks      Defect Dimensions: Length (m): 0.35      Width (m): 0.25      Depth (mm): 22.00

Recorded Date: 04-July-2019      FOOTPATH KERB HIGH (FKHI)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	0.35	LIN.M	L 0.35      W 0.00      D 0.00



# Inspection Report

<b>Inspection Date:</b> 4-Jul-2019	<b>Inspect History ID:</b> 3076223 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 01 July 2019	<b>Inspection Type:</b> Full Sector - Safety Inspection
		<b>Inspector:</b> [REDACTED]

<b>Section Code:</b> 7035U0417_36	<b>Section Description:</b> HAZELBURN RD1: MANSE RD4 TO CARNMONEY RD N1
--------------------------------------	--

<b>Defect Ref:</b> <a href="#">DCD74-3076223-141</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b> RESET KERBS	<b>Location Description:</b> OPP LHS STL 16	<b>Priority:</b> R3 - 4 Weeks	<b>Defect Dimensions:</b>		
<b>Recorded Date:</b> 05-July-2019	FOOTPATH KERB HIGH (FKHI)				<b>Length (m):</b> 1.50	<b>Width (m):</b> 0.25	<b>Depth (mm):</b> 22.00

**Recorded By:**  
[REDACTED]

<b>Repair Description:</b>	<b>Repair Item Name:</b>	<b>Quantity</b>	<b>Units</b>	<b>Repair Measures</b>			
<b>M64111A</b>	<b>^ Lift &amp; relay kerbs &gt;12m rad, 0-5m</b>	<b>1.50</b>	<b>LIN.M</b>	<b>L 1.50</b>	<b>W 0.00</b>	<b>D 0.00</b>	

<b>Defect Ref:</b> <a href="#">DCD74-3076223-139</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b> RESET KERB	<b>Location Description:</b> AT HOUSE 18	<b>Priority:</b> R3 - 4 Weeks	<b>Defect Dimensions:</b>		
<b>Recorded Date:</b> 05-July-2019	FOOTPATH KERB HIGH (FKHI)				<b>Length (m):</b> 0.90	<b>Width (m):</b> 0.25	<b>Depth (mm):</b> 22.00

**Recorded By:**  
[REDACTED]

<b>Repair Description:</b>	<b>Repair Item Name:</b>	<b>Quantity</b>	<b>Units</b>	<b>Repair Measures</b>			
<b>M64111A</b>	<b>^ Lift &amp; relay kerbs &gt;12m rad, 0-5m</b>	<b>1.00</b>	<b>LIN.M</b>	<b>L 1.00</b>	<b>W 0.00</b>	<b>D 0.00</b>	



## Inspection Report

Inspection Date: 9-Jan-2020

Inspect History ID: 3079265 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY  
on 06 January 2020

Inspection Type: Full Sector - Safety Inspection

Inspector: [REDACTED]Section Code:  
7035U0417\_36Section Description:  
HAZELBURN RD1: MANSE RD4 TO CARNMONEY RD N1

Defect Ref: <a href="#">DCD74-3079265-118</a>	Defect Type: DEFECT	Comments: REPLACE KERB 1(NO)	Location Description: KERB RHS STL 3	Priority: R3 - 4 Weeks	Defect Dimensions: Length (m): 0.92	Width (m): 0.25	Depth (mm): 22.00
Recorded Date: 09-January-2020	FOOTPATH KERB LOW (FKLO)						

Recorded By:

[REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	1.00	LIN.M	L 1.00	W 0.00	D 0.00	

Defect Ref: <a href="#">DCD74-3079265-131</a>	Defect Type: DEFECT	Comments: GIVEWAY MARKINGS FADED	Location Description: MARKINGS AT JCT CARNMONEY ROAD NORTH	Priority: R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
--	------------------------	--	---	---	-----------------------------------	------------	-------------

Recorded Date: 09-January-2020  
ROAD MARKINGS  
FADED (CYFD)

Recorded By:

[REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
K31341A	^ 200mm intermittent white screed	9.70	LIN.M	L 9.70	W 0.00	D 0.00	
K31321A	^ 100mm intermittent white screed	28.00	LIN.M	L 28.00	W 0.00	D 0.00	
K38311A	480mm road hump triangle	5.00	no	L 0.00	W 0.00	D 0.00	



# Inspection Report

<b>Inspection Date:</b> 7-Jul-2020	<b>Inspect History ID:</b> 3082250 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 01 July 2020	<b>Inspection Type:</b> Full Sector - Safety Inspection
		<b>Inspector:</b> [REDACTED]

<b>Section Code:</b> 7035U0417_36	<b>Section Description:</b> HAZELBURN RD1: MANSE RD4 TO CARNMONEY RD N1
--------------------------------------	--

<b>Defect Ref:</b> <a href="#">DCD74-3082250-156</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b> RELAY KERB X 1	<b>Location Description:</b> KERB AT STL 4	<b>Priority:</b> R3 - 4 Weeks	<b>Defect Dimensions:</b> <b>Length (m): 0.92</b>	<b>Width (m): 0.25</b>	<b>Depth (mm): 22.00</b>
<b>Recorded Date:</b> 07-July-2020	<b>FOOTPATH KERB LOW (FKLO)</b>						

**Recorded By:**  
[REDACTED]

<b>Repair Description:</b> M64111A	<b>Repair Item Name:</b> ^ Lift & relay kerbs >12m rad, 0-5m	<b>Quantity:</b> 1.00	<b>Units:</b> LIN.M	<b>Repair Measures:</b> L 1.00    W 0.00    D 0.00
---------------------------------------	---	--------------------------	------------------------	---

<b>Defect Ref:</b> <a href="#">DCD74-3082250-159</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b>	<b>Location Description:</b> FWAY AT MOSSLEY PRIMARY SCHOOL	<b>Priority:</b> R3 - 4 Weeks	<b>Defect Dimensions:</b> <b>Length (m): 25.00</b>	<b>Width (m): 0.50</b>	<b>Depth (mm): 40.00</b>
<b>Recorded Date:</b> 07-July-2020	<b>ASPHALT CRACKED (FACR)</b>						

**Recorded By:**  
[REDACTED]

<b>Repair Description:</b> M12013A	<b>Repair Item Name:</b> ^ 75mm asphalt patch >3 square metres	<b>Quantity:</b> 12.50	<b>Units:</b> SQ.M	<b>Repair Measures:</b> L 25.00    W 0.50    D 0.00
---------------------------------------	---	---------------------------	-----------------------	--



# Inspection Report

<b>Inspection Date:</b> 7-Jul-2020	<b>Inspect History ID:</b> 3082250 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 01 July 2020	<b>Inspection Type:</b> Full Sector - Safety Inspection
		<b>Inspector:</b> [REDACTED]

<b>Section Code:</b> 7035U0417_36	<b>Section Description:</b> HAZELBURN RD1: MANSE RD4 TO CARNMONEY RD N1
--------------------------------------	--

<b>Defect Ref:</b> <a href="#">DCD74-3082250-151</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b> RELAY KERBS X 2 (NO)	<b>Location Description:</b> KERBS LHS HOUSE 16	<b>Priority:</b> R3 - 4 Weeks	<b>Defect Dimensions:</b>		
					<b>Length (m):</b> 1.80	<b>Width (m):</b> 0.25	<b>Depth (mm):</b> 22.00
<b>Recorded Date:</b> 07-July-2020	<b>FOOTPATH KERB LOW (FKLO)</b>						
<b>Recorded By:</b> [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
<b>M64111A</b>	<b>^ Lift &amp; relay kerbs &gt;12m rad, 0-5m</b>	<b>2.00</b>	<b>LIN.M</b>	<b>L 2.00</b>	<b>W 0.00</b>	<b>D 0.00</b>	

<b>Defect Ref:</b> <a href="#">DCD74-3082250-152</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b> SCHOOL SIGNS DISPLACED X 2	<b>Location Description:</b> FWAY AT HOUSE 4	<b>Priority:</b> R4 - next available programme	<b>Defect Dimensions:</b>		
					<b>Length (m):</b>	<b>Width (m):</b>	<b>Depth (mm):</b>
<b>Recorded Date:</b> 07-July-2020	<b>TRAFFIC SIGN DISPLACED (TSDI)</b>						
<b>Recorded By:</b> [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
<b>R16212A</b>	<b>^ Re- erect traffic sign 0.3-1sqm</b>	<b>2.00</b>	<b>no</b>	<b>L 0.00</b>	<b>W 0.00</b>	<b>D 0.00</b>	



# Inspection Report

<b>Inspection Date:</b> 7-Jul-2020	<b>Inspect History ID:</b> 3082250 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 01 July 2020	<b>Inspection Type:</b> Full Sector - Safety Inspection
		<b>Inspector:</b> [REDACTED]

<b>Section Code:</b> 7035U0417_36	<b>Section Description:</b> HAZELBURN RD1: MANSE RD4 TO CARNMONEY RD N1
--------------------------------------	--

<b>Defect Ref:</b> <a href="#">DCD74-3082250-153</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b> RELAY KERB X 1	<b>Location Description:</b> KERB AT HOUSE 2	<b>Priority:</b> R3 - 4 Weeks	<b>Defect Dimensions:</b>		
<b>Recorded Date:</b> 07-July-2020	FOOTPATH KERB HIGH (FKHI)				<b>Length (m):</b> 0.92	<b>Width (m):</b> 0.25	<b>Depth (mm):</b> 22.00

**Recorded By:**  
[REDACTED]

<b>Repair Description:</b> M64111A	<b>Repair Item Name:</b> ^ Lift & relay kerbs >12m rad, 0-5m	<b>Quantity:</b> 1.00	<b>Units:</b> LIN.M	<b>Repair Measures:</b> L 1.00    W 0.00    D 0.00
---------------------------------------	---	--------------------------	------------------------	---

<b>Defect Ref:</b> <a href="#">DCD74-3082250-154</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b> REPLACE 1(NO) AND RELAY 1(NO)	<b>Location Description:</b> KERBS AT STL 9	<b>Priority:</b> R3 - 4 Weeks	<b>Defect Dimensions:</b>		
<b>Recorded Date:</b> 07-July-2020	FOOTPATH KERB HIGH (FKHI)				<b>Length (m):</b> 1.80	<b>Width (m):</b> 0.25	<b>Depth (mm):</b> 22.00

**Recorded By:**  
[REDACTED]

<b>Repair Description:</b> M64111A	<b>Repair Item Name:</b> ^ Lift & relay kerbs >12m rad, 0-5m	<b>Quantity:</b> 2.00	<b>Units:</b> LIN.M	<b>Repair Measures:</b> L 2.00    W 0.00    D 0.00
---------------------------------------	---	--------------------------	------------------------	---



# Inspection Report

<b>Inspection Date:</b> 7-Jul-2020	<b>Inspect History ID:</b> 3082250 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 01 July 2020	<b>Inspection Type:</b> Full Sector - Safety Inspection
		<b>Inspector:</b> [REDACTED]

<b>Section Code:</b> 7035U0417_36	<b>Section Description:</b> HAZELBURN RD1: MANSE RD4 TO CARNMONEY RD N1
--------------------------------------	--

<b>Defect Ref:</b> <a href="#">DCD74-3082250-160</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b> RELAY KERBS X 2	<b>Location Description:</b> KERBS AT LHS STL 15	<b>Priority:</b> R3 - 4 Weeks	<b>Defect Dimensions:</b>		
					<b>Length (m):</b> 0.92	<b>Width (m):</b> 0.25	<b>Depth (mm):</b> 22.00
<b>Recorded Date:</b> 07-July-2020	<b>FOOTPATH KERB HIGH (FKHI)</b>						
<b>Recorded By:</b> [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	1.00	LIN.M	L 1.00	W 0.00	D 0.00	



# Inspection Report

<b>Inspection Date:</b> 7-Jan-2021	<b>Inspect History ID:</b> 3085111 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 05 January 2021	<b>Inspection Type:</b> Full Sector - Safety Inspection
		<b>Inspector:</b> [REDACTED]

<b>Section Code:</b> 7035U0417_36	<b>Section Description:</b> HAZELBURN RD1: MANSE RD4 TO CARNMONEY RD N1
--------------------------------------	--

<b>Defect Ref:</b> <a href="#">DCD74-3085111-83</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b> RESET KERBS. PARKED CARS ON FWAYS	<b>Location Description:</b> KERBS AT HOUSE 14	<b>Priority:</b> R3 - 4 Weeks	<b>Defect Dimensions:</b>		
					<b>Length (m):</b> 5.60	<b>Width (m):</b> 0.25	<b>Depth (mm):</b> 22.00
<b>Recorded Date:</b> 07-January-2021	<b>FOOTPATH KERB HIGH (FKHI)</b>						
<b>Recorded By:</b> [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
<b>M64111A</b>	<b>^ Lift &amp; relay kerbs &gt;12m rad, 0-5m</b>	<b>5.00</b>	<b>LIN.M</b>	<b>L 5.00</b>	<b>W 0.00</b>	<b>D 0.00</b>	

<b>Defect Ref:</b> <a href="#">DCD74-3085111-84</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b> RESET KERB. CARS PARKED ON FWAYS.	<b>Location Description:</b> KERB RHS ELDERBURN	<b>Priority:</b> R3 - 4 Weeks	<b>Defect Dimensions:</b>		
					<b>Length (m):</b> 0.92	<b>Width (m):</b> 0.25	<b>Depth (mm):</b> 22.00
<b>Recorded Date:</b> 07-January-2021	<b>FOOTPATH KERB HIGH (FKHI)</b>						
<b>Recorded By:</b> [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
<b>M64111A</b>	<b>^ Lift &amp; relay kerbs &gt;12m rad, 0-5m</b>	<b>1.00</b>	<b>LIN.M</b>	<b>L 1.00</b>	<b>W 0.00</b>	<b>D 0.00</b>	



# Inspection Report

<b>Inspection Date:</b> 7-Jan-2021	<b>Inspect History ID:</b> 3085111 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 05 January 2021	<b>Inspection Type:</b> Full Sector - Safety Inspection
		<b>Inspector:</b> [REDACTED]

<b>Section Code:</b> 7035U0417_36	<b>Section Description:</b> HAZELBURN RD1: MANSE RD4 TO CARNMONEY RD N1
--------------------------------------	--

<b>Defect Ref:</b> <a href="#">DCD74-3085111-85</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b>	<b>Location Description:</b> FWAY LHS STL 1	<b>Priority:</b> R3 - 4 Weeks	<b>Defect Dimensions:</b>		
<b>Recorded Date:</b> 07-January-2021	ASPHALT POTHOLE (FAPH)				<b>Length (m):</b> 0.70	<b>Width (m):</b> 0.43	<b>Depth (mm):</b> 22.00
<b>Recorded By:</b> [REDACTED]							

<b>Repair Description:</b> M12013A	<b>Repair Item Name:</b> ^ 75mm asphalt patch >3 square metres	<b>Quantity:</b> 9.92	<b>Units:</b> SQ.M	<b>Repair Measures:</b>			
				<b>L</b> 6.20	<b>W</b> 1.60	<b>D</b> 0.00	

<b>Defect Ref:</b> <a href="#">DCD74-3085111-97</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b> RESET KERB	<b>Location Description:</b> KERB 20M RHS STL 3	<b>Priority:</b> R3 - 4 Weeks	<b>Defect Dimensions:</b>		
<b>Recorded Date:</b> 07-January-2021	FOOTPATH KERB LOW (FKLO)				<b>Length (m):</b> 0.92	<b>Width (m):</b> 0.25	<b>Depth (mm):</b> 22.00
<b>Recorded By:</b> [REDACTED]							

<b>Repair Description:</b> M64111A	<b>Repair Item Name:</b> ^ Lift & relay kerbs >12m rad, 0-5m	<b>Quantity:</b> 1.00	<b>Units:</b> LIN.M	<b>Repair Measures:</b>			
				<b>L</b> 1.00	<b>W</b> 0.00	<b>D</b> 0.00	



# Inspection Report

**Inspection Date:** 7-Jan-2021     
 **Inspect History ID:** 3085111 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 05 January 2021     
 **Inspection Type:** Full Sector - Safety Inspection  
**Inspector:** [REDACTED]

**Section Code:** 7035U0417\_36     
 **Section Description:** HAZELBURN RD1: MANSE RD4 TO CARNMONEY RD N1

**Defect Ref:** [DCD74-3085111-98](#)     
**Defect Type:** DEFECT     
**Comments:** REPLACE ROUND TOP PIN KERBS     
**Location Description:** KERBS RHS STL 15     
**Priority:** R3 - 4 Weeks     
**Defect Dimensions:** Length (m): 6.00      Width (m): 0.05      Depth (mm): 22.00  
**Recorded Date:** 07-January-2021     
**Recorded By:** FOOTPATH KERB LOW (FKLO) [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures		
M61322A	^ 150 x 50 round top edging >12m rad >5m	6.00	LIN.M	L 6.00	W 0.00	D 0.00



# Inspection Report

<b>Inspection Date:</b> 5-Jul-2021	<b>Inspect History ID:</b> 3088039 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 01 July 2021	<b>Inspection Type:</b> Full Sector - Safety Inspection
		<b>Inspector:</b> [REDACTED]

<b>Section Code:</b> 7035U0417_36	<b>Section Description:</b> HAZELBURN RD1: MANSE RD4 TO CARNMONEY RD N1
--------------------------------------	--

**Defect Ref:** [DCD101-3088039-82](#)  
**Defect Type:** DEFECT  
**Comments:** RESET KERB  
**Location Description:** KERB AT HOUSE 2  
**Priority:** R3 - 4 Weeks  
**Defect Dimensions:**  
**Length (m):** 0.92    **Width (m):** 0.25    **Depth (mm):** 22.00  
**Recorded Date:** 05-July-2021  
**Recorded By:** [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	1.00	LIN.M	L 1.00    W 0.00    D 0.00

**Defect Ref:** [DCD101-3088039-92](#)  
**Defect Type:** DEFECT  
**Comments:** RESET KERB  
**Location Description:** KERB RHS STL 12  
**Priority:** R2 - 5 Working days  
**Defect Dimensions:**  
**Length (m):** 0.92    **Width (m):** 0.25    **Depth (mm):** 81.00  
**Recorded Date:** 05-July-2021  
**Recorded By:** [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	1.00	LIN.M	L 1.00    W 0.00    D 0.00



# Inspection Report

Inspection Date: 5-Jul-2021      Inspect History ID: 3088039 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 01 July 2021      Inspection Type: Full Sector - Safety Inspection  
 Inspector: [REDACTED]

Section Code: 7035U0417\_36      Section Description: HAZELBURN RD1: MANSE RD4 TO CARNMONEY RD N1

Defect Ref: [DCD101-3088039-88](#)      Defect Type: DEFECT      Comments: BOLLARD MISSING NEEDS NEW BOLLARD INSTALLED. ALSO NEES MADE SAFE.      Location Description: FWAY RHS LARCH GROVE      Priority: R4 - next available programme      Defect Dimensions: Length (m):      Width (m):      Depth (mm):

Recorded Date: 05-July-2021      NON ILLUMINATED BOLLARD DEFECTIVE (TNDF)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
M12011A	^ 75mm asphalt patch 0-1 square metres	1.00	no	L 0.00      W 0.00      D 0.00
R11330A	^ Erect bollard	1.00	no	L 0.00      W 0.00      D 0.00

Defect Ref: [DCD101-3088039-89](#)      Defect Type: DEFECT      Comments: RESET PIN KERB      Location Description: PIN KERB RHS STL 4      Priority: R2 - 5 Working days      Defect Dimensions: Length (m): 0.45      Width (m): 0.05      Depth (mm): 60.00

Recorded Date: 05-July-2021      FOOTPATH KERB HIGH (FKHI)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
M61324A	^ 150 x 50 round top edging <12m rad,0-5m	1.00	LIN.M	L 1.00      W 0.00      D 0.00



# Inspection Report

<b>Inspection Date:</b> 5-Jul-2021	<b>Inspect History ID:</b> 3088039 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 01 July 2021	<b>Inspection Type:</b> Full Sector - Safety Inspection
		<b>Inspector:</b> [REDACTED]

<b>Section Code:</b> 7035U0417_36	<b>Section Description:</b> HAZELBURN RD1: MANSE RD4 TO CARNMONEY RD N1
--------------------------------------	--

**Defect Ref:** [DCD101-3088039-90](#)  
**Recorded Date:** 05-July-2021  
**Recorded By:** [REDACTED]

**Defect Type:** DEFECT  
**Comments:** ASPHALT CRACKED (FACR)  
**Location Description:** FWAY AT STL 8  
**Priority:** R3 - 4 Weeks  
**Defect Dimensions:** Length (m): 14.20 Width (m): 0.03 Depth (mm): 24.00

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
M12013A	^ 75mm asphalt patch >3 square metres	19.20	SQ.M	L 24.00 W 0.80 D 0.00

**Defect Ref:** [DCD101-3088039-91](#)  
**Recorded Date:** 05-July-2021  
**Recorded By:** [REDACTED]

**Defect Type:** DEFECT  
**Comments:** ASPHALT POTHOLE (FAPH)  
**Location Description:** FWAY RHS STL 11 AND RHS STL 12  
**Priority:** R1 - 1 Calendar Day  
**Defect Dimensions:** Length (m): 0.45 Width (m): 0.40 Depth (mm): 86.00

### Defect Escalation Details

Old Response Time	New Response Time	Reason For Upgrade
R2 - 5 Working days	R1 - 1 Calendar Day	footway patch

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
M12011A	^ 75mm asphalt patch 0-1 square metres	1.00	no	L 0.00 W 0.00 D 0.00
Z01800A	EO all items for Priority 1 response	26.84	%	L 0.00 W 0.00 D 0.00



# Inspection Report

<b>Inspection Date:</b> See Recorded Date	<b>Inspect History ID:</b> 3088624 - 1 and 3 Monthly - Safety Inspection of AAN1-05-ANTRIM & NEWTOWNABBEY on 13 August 2021	<b>Inspection Type:</b> 1 and 3 Monthly - Safety Inspection
		<b>Inspector:</b>

<b>Section Code:</b> 7035U0417_40	<b>Section Description:</b> MOSSBANK1: BIRCHMOUNT TO END
--------------------------------------	---

<b>Defect Ref:</b> <a href="#">DCD101-3088624-29</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b> REF ENQUIRY W211039532	<b>Location Description:</b> KERBS AT REAR HOUSE 2	<b>Priority:</b> R3 - 4 Weeks	<b>Defect Dimensions:</b> <b>Length (m): 1.40</b> <b>Width (m): 0.25</b> <b>Depth (mm): 22.00</b>
<b>Recorded Date:</b> 16-August-2021	<b>FOOTPATH KERB LOW (FKLO)</b>				

**Recorded By:**  
[REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures		
<b>M64111A</b>	<b>^ Lift &amp; relay kerbs &gt;12m rad, 0-5m</b>	<b>1.40</b>	<b>LIN.M</b>	<b>L 1.40</b>	<b>W 0.00</b>	<b>D 0.00</b>



## Inspection Report

Inspection Date: 13-Jan-2019

Inspect History ID: 3073307 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY  
on 11 January 2019

Inspection Type: Full Sector - Safety Inspection

Inspector: [REDACTED]

No Defects found on: 7035U0417\_40 - MOSSBANK1: BIRCHMOUNT TO END by [REDACTED]



## Inspection Report

Inspection Date: 4-Jul-2019

Inspect History ID: 3076223 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY  
on 01 July 2019

Inspection Type: Full Sector - Safety Inspection

Inspector: [REDACTED]

No Defects found on: 7035U0417\_40 - MOSSBANK1: BIRCHMOUNT TO END by [REDACTED]



## Inspection Report

Inspection Date: 9-Jan-2020

Inspect History ID: 3079265 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY  
on 06 January 2020

Inspection Type: Full Sector - Safety Inspection

Inspector: [REDACTED]

No Defects found on: 7035U0417\_40 - MOSSBANK1: BIRCHMOUNT TO END by [REDACTED]



# Inspection Report

<b>Inspection Date:</b> 7-Jul-2020	<b>Inspect History ID:</b> 3082250 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 01 July 2020	<b>Inspection Type:</b> Full Sector - Safety Inspection
		<b>Inspector:</b> [REDACTED]

<b>Section Code:</b> 7035U0417_40	<b>Section Description:</b> MOSSBANK1: BIRCHMOUNT TO END
--------------------------------------	---

**Defect Ref:** [DCD74-3082250-144](#)  
**Defect Type:** DEFECT  
**Comments:** RESET KERBS  
**Location Description:** KERBS RHS STL 3  
**Priority:** R3 - 4 Weeks  
**Defect Dimensions:**  
**Length (m):** 1.80    **Width (m):** 0.25    **Depth (mm):** 22.00  
**Recorded Date:** 07-July-2020  
**Recorded By:** [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	2.00	LIN.M	L 2.00    W 0.00    D 0.00

**Defect Ref:** [DCD74-3082250-145](#)  
**Defect Type:** DEFECT  
**Comments:** REPLAC 1 (NO) KERB AND RELAY 1(NO) KERB  
**Location Description:** KERB RHS STL 1  
**Priority:** R3 - 4 Weeks  
**Defect Dimensions:**  
**Length (m):** 1.80    **Width (m):** 0.25    **Depth (mm):** 22.00  
**Recorded Date:** 07-July-2020  
**Recorded By:** [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	2.00	LIN.M	L 2.00    W 0.00    D 0.00



## Inspection Report

Inspection Date: 7-Jan-2021

Inspect History ID: 3085111 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY  
on 05 January 2021

Inspection Type: Full Sector - Safety Inspection

Inspector: [REDACTED]

No Defects found on: 7035U0417\_40 - MOSSBANK1: BIRCHMOUNT TO END by [REDACTED]



# Inspection Report

**Inspection Date:** 5-Jul-2021     
 **Inspect History ID:** 3088039 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 01 July 2021     
 **Inspection Type:** Full Sector - Safety Inspection  
**Inspector:** [REDACTED]

**Section Code:** 7035U0417\_40     
 **Section Description:** MOSSBANK1: BIRCHMOUNT TO END

**Defect Ref:** [DCD101-3088039-80](#)     
 **Defect Type:** DEFECT     
 **Comments:** RESET KERB     
 **Location Description:** KERB AT RHS STL 1     
 **Priority:** R3 - 4 Weeks     
 **Defect Dimensions:** Length (m): 0.92      Width (m): 0.25      Depth (mm): 22.00  
**Recorded Date:** 05-July-2021     
**Footnote:** FOOTPATH KERB HIGH (FKHI)

**Recorded By:** [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures		
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	1.00	LIN.M	L 1.00	W 0.00	D 0.00



# Inspection Report

Inspection Date: 13-Jan-2019	Inspect History ID: 3073307 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 11 January 2019	Inspection Type: Full Sector - Safety Inspection
		Inspector: [REDACTED]

Section Code: 7035U0417_39	Section Description: BIRCHMOUNT1: HAZELBURN RD1 TO END
----------------------------	--

Defect Ref: <a href="#">DCD113-3073307-86</a>	Defect Type: DEFECT	Comments:	Location Description: AT JCT HAZELBURN ROAD (on bend)	Priority: R3 - 4 Weeks	Defect Dimensions: Length (m): 1.50 Width (m): 0.25 Depth (mm): 25.00
Recorded Date: 13-January-2019	FOOTPATH KERB LOW (FKLO)				
Recorded By: [REDACTED]					

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	1.50	LIN.M	L 1.50 W 0.00 D 0.00

Defect Ref: <a href="#">DCD113-3073307-87</a>	Defect Type: DEFECT	Comments:	Location Description: AT HOUSE 2	Priority: R3 - 4 Weeks	Defect Dimensions: Length (m): 1.20 Width (m): 0.25 Depth (mm): 25.00
Recorded Date: 13-January-2019	FOOTPATH KERB HIGH (FKHI)				
Recorded By: [REDACTED]					

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	1.20	LIN.M	L 1.20 W 0.00 D 0.00



## Inspection Report

Inspection Date: 4-Jul-2019

Inspect History ID: 3076223 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY  
on 01 July 2019

Inspection Type: Full Sector - Safety Inspection

Inspector: [REDACTED]

No Defects found on: 7035U0417\_39 - BIRCHMOUNT1: HAZELBURN RD1 TO END by [REDACTED]



## Inspection Report

Inspection Date: 9-Jan-2020

Inspect History ID: 3079265 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY  
on 06 January 2020

Inspection Type: Full Sector - Safety Inspection

Inspector: [REDACTED]

No Defects found on: 7035U0417\_39 - BIRCHMOUNT1: HAZELBURN RD1 TO END by [REDACTED]



# Inspection Report

Inspection Date: 7-Jul-2020	Inspect History ID: 3082250 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 01 July 2020	Inspection Type: Full Sector - Safety Inspection
		Inspector: [REDACTED]

Section Code: 7035U0417_39	Section Description: BIRCHMOUNT1: HAZELBURN RD1 TO END
----------------------------	--

Defect Ref: <a href="#">DCD74-3082250-150</a>	Defect Type: DEFECT	Comments: RELAY KERBS	Location Description: KERBS AT HOUSE 13	Priority: R3 - 4 Weeks	Defect Dimensions: Length (m): 0.92 Width (m): 0.25 Depth (mm): 22.00
Recorded Date: 07-July-2020	FOOTPATH KERB LOW (FKLO)				

Recorded By: [REDACTED]	Repair Description: M64111A	Repair Item Name: ^ Lift & relay kerbs >12m rad, 0-5m	Quantity: 3.00	Units: LIN.M	Repair Measures: L 3.00 W 0.00 D 0.00
-------------------------	-----------------------------	---	----------------	--------------	---------------------------------------



# Inspection Report

<b>Inspection Date:</b> 7-Jan-2021	<b>Inspect History ID:</b> 3085111 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 05 January 2021	<b>Inspection Type:</b> Full Sector - Safety Inspection
		<b>Inspector:</b> [REDACTED]

<b>Section Code:</b> 7035U0417_39	<b>Section Description:</b> BIRCHMOUNT1: HAZELBURN RD1 TO END
--------------------------------------	--

<b>Defect Ref:</b> <a href="#">DCD74-3085111-78</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b> RESET KERBS	<b>Location Description:</b> KERBS AT HOUSE 2	<b>Priority:</b> R3 - 4 Weeks	<b>Defect Dimensions:</b>			
<b>Recorded Date:</b> 07-January-2021	FOOTPATH KERB HIGH (FKHI)				<b>Length (m):</b> 1.50	<b>Width (m):</b> 0.25	<b>Depth (mm):</b> 22.00	

**Recorded By:**  
[REDACTED]

<b>Repair Description:</b> M64111A	<b>Repair Item Name:</b> ^ Lift & relay kerbs >12m rad, 0-5m	<b>Quantity:</b> 5.00	<b>Units:</b> LIN.M	<b>Repair Measures:</b> L 5.00    W 0.00    D 0.00
---------------------------------------	---	--------------------------	------------------------	---

<b>Defect Ref:</b> <a href="#">DCD74-3085111-79</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b> RESET KERBS PARKED CARS ON FWAYS	<b>Location Description:</b> KERBS AT HOUSE 13	<b>Priority:</b> R3 - 4 Weeks	<b>Defect Dimensions:</b>			
<b>Recorded Date:</b> 07-January-2021	FOOTPATH KERB HIGH (FKHI)				<b>Length (m):</b> 1.20	<b>Width (m):</b> 0.25	<b>Depth (mm):</b> 22.00	

**Recorded By:**  
[REDACTED]

<b>Repair Description:</b> M64111A	<b>Repair Item Name:</b> ^ Lift & relay kerbs >12m rad, 0-5m	<b>Quantity:</b> 4.00	<b>Units:</b> LIN.M	<b>Repair Measures:</b> L 4.00    W 0.00    D 0.00
---------------------------------------	---	--------------------------	------------------------	---



# Inspection Report

<b>Inspection Date:</b> 5-Jul-2021	<b>Inspect History ID:</b> 3088039 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 01 July 2021	<b>Inspection Type:</b> Full Sector - Safety Inspection
		<b>Inspector:</b> [REDACTED]

<b>Section Code:</b> 7035U0417_39	<b>Section Description:</b> BIRCHMOUNT1: HAZELBURN RD1 TO END
--------------------------------------	--

<b>Defect Ref:</b> <a href="#">DCD101-3088039-81</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b> RESET KERBS	<b>Location Description:</b> KERBS OPP STL 5	<b>Priority:</b> R3 - 4 Weeks	<b>Defect Dimensions:</b>			
<b>Recorded Date:</b> 05-July-2021	FOOTPATH KERB HIGH (FKHI)				<b>Length (m):</b> 1.80	<b>Width (m):</b> 0.25	<b>Depth (mm):</b> 22.00	

**Recorded By:**  
[REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures		
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	2.00	LIN.M	L 2.00	W 0.00	D 0.00



# Inspection Report

<b>Inspection Date:</b> 13-Jan-2019	<b>Inspect History ID:</b> 3073307 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 11 January 2019	<b>Inspection Type:</b> Full Sector - Safety Inspection
		<b>Inspector:</b> [REDACTED]

<b>Section Code:</b> 7035U0417_41	<b>Section Description:</b> ELDERBURN1: HAZELBURN RD1 TO END
--------------------------------------	---

<b>Defect Ref:</b> <a href="#">DCD113-3073307-90</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b>	<b>Location Description:</b> CWAY AT HOUSE 6	<b>Priority:</b> R3 - 4 Weeks	<b>Defect Dimensions:</b>		
<b>Recorded Date:</b> 13-January-2019	BITMAC POTHOLE (CBPH)				<b>Length (m):</b> 0.40	<b>Width (m):</b> 0.20	<b>Depth (mm):</b> 30.00

**Recorded By:**  
[REDACTED]

<b>Repair Description:</b> D23111A	<b>Repair Item Name:</b> ^ 100mm bit. patch W/C & B/C <1 m2	<b>Quantity:</b> 1.00	<b>Units:</b> no	<b>Repair Measures:</b> L 0.00    W 0.00    D 0.00
---------------------------------------	--	--------------------------	---------------------	---

<b>Defect Ref:</b> <a href="#">DCD113-3073307-91</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b> REPLACE GULLY	<b>Location Description:</b> CWAY AT HOUSE 1	<b>Priority:</b> R2 - 5 Working days	<b>Defect Dimensions:</b>		
<b>Recorded Date:</b> 13-January-2019	GULLY LID BROKEN (GGBR)				<b>Length (m):</b>	<b>Width (m):</b>	<b>Depth (mm):</b>

**Recorded By:**  
[REDACTED]

<b>Repair Description:</b> U12162A	<b>Repair Item Name:</b> ^ Reset c/way gully top 150-300mm	<b>Quantity:</b> 1.00	<b>Units:</b> no	<b>Repair Measures:</b> L 0.00    W 0.00    D 0.00
---------------------------------------	---	--------------------------	---------------------	---



## Inspection Report

Inspection Date: 4-Jul-2019

Inspect History ID: 3076223 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY  
on 01 July 2019

Inspection Type: Full Sector - Safety Inspection

Inspector: [REDACTED]

No Defects found on: 7035U0417\_41 - ELDERBURN1: HAZELBURN RD1 TO END by [REDACTED]



# Inspection Report

<b>Inspection Date:</b> 9-Jan-2020	<b>Inspect History ID:</b> 3079265 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 06 January 2020	<b>Inspection Type:</b> Full Sector - Safety Inspection
		<b>Inspector:</b> [REDACTED]

<b>Section Code:</b> 7035U0417_41	<b>Section Description:</b> ELDERBURN1: HAZELBURN RD1 TO END
--------------------------------------	---

<b>Defect Ref:</b> <a href="#">DCD74-3079265-121</a>	<b>Defect Type:</b> THIRD PARTY REFERRAL	<b>Comments:</b> NIW TOBY LID BROKEN	<b>Location Description:</b> RHS STL1	<b>Priority:</b> R4 - next available programme	<b>Defect Dimensions:</b>		
<b>Recorded Date:</b> 09-January-2020	UTILITY VALVE COVER BROKEN (UVBR)				<b>Length (m):</b>	<b>Width (m):</b>	<b>Depth (mm):</b>
<b>Recorded By:</b> [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
A09999A	^ CW / HS RESUR/RECON	1.00	no	L 0.00	W 0.00	D 0.00	



## Inspection Report

Inspection Date: 7-Jul-2020

Inspect History ID: 3082250 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY  
on 01 July 2020

Inspection Type: Full Sector - Safety Inspection

Inspector: [REDACTED]

No Defects found on: 7035U0417\_41 - ELDERBURN1: HAZELBURN RD1 TO END by [REDACTED]



# Inspection Report

<b>Inspection Date:</b> 7-Jan-2021	<b>Inspect History ID:</b> 3085111 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 05 January 2021	<b>Inspection Type:</b> Full Sector - Safety Inspection
		<b>Inspector:</b> [REDACTED]

<b>Section Code:</b> 7035U0417_41	<b>Section Description:</b> ELDERBURN1: HAZELBURN RD1 TO END
--------------------------------------	---

**Defect Ref:** [DCD74-3085111-86](#)  
**Recorded Date:** 07-January-2021  
**Recorded By:** [REDACTED]

**Defect Type:** DEFECT  
**Comments:** BITMAC POTHOLE (CBPH)  
**Location Description:** CWAY AT STL 1  
**Priority:** R3 - 4 Weeks  
**Defect Dimensions:** Length (m): 0.80 Width (m): 0.35 Depth (mm): 21.00

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

**Defect Ref:** [DCD74-3085111-87](#)  
**Recorded Date:** 07-January-2021  
**Recorded By:** [REDACTED]

**Defect Type:** DEFECT  
**Comments:** BITMAC POTHOLE (CBPH)  
**Location Description:** CWAY AT HOUSE 4. CARS PARKED ON FWAYS  
**Priority:** R3 - 4 Weeks  
**Defect Dimensions:** Length (m): 0.50 Width (m): 0.50 Depth (mm): 41.00

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	3.00	no	L 0.00 W 0.00 D 0.00



# Inspection Report

<b>Inspection Date:</b> 5-Jul-2021	<b>Inspect History ID:</b> 3088039 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 01 July 2021	<b>Inspection Type:</b> Full Sector - Safety Inspection
		<b>Inspector:</b> [REDACTED]

<b>Section Code:</b> 7035U0417_41	<b>Section Description:</b> ELDERBURN1: HAZELBURN RD1 TO END
--------------------------------------	---

<b>Defect Ref:</b> <a href="#">DCD101-3088039-83</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b>	<b>Location Description:</b> FWAY LHS STL 1 AT JCT	<b>Priority:</b> R3 - 4 Weeks	<b>Defect Dimensions:</b>		
<b>Recorded Date:</b> 05-July-2021	ASPHALT POTHOLE (FAPH)				<b>Length (m):</b> 0.80	<b>Width (m):</b> 0.55	<b>Depth (mm):</b> 29.00
<b>Recorded By:</b> [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures		
<b>M12013A</b>	<b>^ 75mm asphalt patch &gt;3 square metres</b>	<b>11.04</b>	<b>SQ.M</b>	<b>L 6.90</b>	<b>W 1.60</b>	<b>D 0.00</b>

<b>Defect Ref:</b> <a href="#">DCD101-3088039-84</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b>	<b>Location Description:</b> CWAY AT HOUSE 4	<b>Priority:</b> R3 - 4 Weeks	<b>Defect Dimensions:</b>		
<b>Recorded Date:</b> 05-July-2021	BITMAC POTHOLE (CBPH)				<b>Length (m):</b> 0.50	<b>Width (m):</b> 0.30	<b>Depth (mm):</b> 41.00
<b>Recorded By:</b> [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures		
<b>D23111A</b>	<b>^ 100mm bit. patch W/C &amp; B/C &lt;1 m2</b>	<b>2.00</b>	<b>no</b>	<b>L 0.00</b>	<b>W 0.00</b>	<b>D 0.00</b>



# Inspection Report

<b>Inspection Date:</b> 5-Jul-2021	<b>Inspect History ID:</b> 3088039 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 01 July 2021	<b>Inspection Type:</b> Full Sector - Safety Inspection
		<b>Inspector:</b> [REDACTED]

<b>Section Code:</b> 7035U0417_41	<b>Section Description:</b> ELDERBURN1: HAZELBURN RD1 TO END
--------------------------------------	---

<b>Defect Ref:</b> <a href="#">DCD101-3088039-85</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b>	<b>Location Description:</b> CWAY OPP STL 10 AT JCT AT GULLY	<b>Priority:</b> R3 - 4 Weeks	<b>Defect Dimensions:</b> Length (m): 0.67    Width (m): 0.50    Depth (mm): 31.00
---	-------------------------------	------------------	---	----------------------------------	---

**Recorded Date:** 05-July-2021  
**Recorded By:** [REDACTED]

**ASPHALT POTHOLE (GAPH)**

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures		
D13441A	^ 100mm patch 14mm W/C & 20mm B/C HRA <1m2	1.00	no	L 0.00	W 0.00	D 0.00



# Inspection Report

<b>Inspection Date:</b>	<b>See Recorded Date</b>	<b>Inspect History ID:</b>	<b>3083807 - 1 Monthly - Safety Inspection of AAN1-06-ANTRIM &amp; NEWTOWNABBEY on 21 October 2020</b>	<b>Inspection Type:</b>	<b>1 Monthly - Safety Inspection</b>
				<b>Inspector:</b>	

<b>Section Code:</b>	<b>Section Description:</b>
<b>7035U0417_38</b>	<b>HOLLYVALE1: HAZELBURN RD1 TO END</b>

<b>Defect Ref:</b>	<b>Defect Type:</b>	<b>Comments:</b>	<b>Location Description:</b>	<b>Priority</b>	<b>Defect Dimensions:</b>		
<a href="#">DCD74-3083807-14</a>	DEFECT	REF ENQUIRY E2004858	<b>CWAY AT REAR HOUSE 8</b>	<b>R3 - 4 Weeks</b>	<b>Length (m): 0.70</b>	<b>Width (m): 0.24</b>	<b>Depth (mm): 31.00</b>

**Recorded Date:**  
21-October-2020

**Defect Type:**  
BITMAC POTHOLE (GBPH)

**Recorded By:**  
[REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
<b>D23111A</b>	<b>^ 100mm bit. patch W/C &amp; B/C &lt;1 m2</b>	<b>2.00</b>	<b>no</b>	<b>L 0.00</b>	<b>W 0.00</b>	<b>D 0.00</b>	



# Inspection Report

<b>Inspection Date:</b>	<b>See Recorded Date</b>	<b>Inspect History ID:</b> -	<b>Inspection Type:</b>
			<b>Inspector:</b>

<b>Section Code:</b> 7035U0417_38	<b>Section Description:</b> HOLLYVALE1: HAZELBURN RD1 TO END
--------------------------------------	---

**Defect Ref:** [D2026302](#)     
**Defect Type:** DEFECT     
**Comments:** please lift and relay drop down kerbs     
**Location Description:** 4 Hollyvale Road     
**Priority:** R2 - 5 Working days     
**Defect Dimensions:** Length (m): 4.00      Width (m): 0.24      Depth (mm): 52.00

**Recorded Date:** 26-November-2020     
**Defect Type:** FOOTPATH KERB LOW (FKLO)

**Recorded By:**

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures		
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	1.00	LIN.M	L 1.00	W 0.00	D 0.00
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	1.00	LIN.M	L 1.00	W 0.00	D 0.00
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	1.00	LIN.M	L 1.00	W 0.00	D 0.00
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	0.25	LIN.M	L 0.25	W 0.00	D 0.00
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	0.25	LIN.M	L 0.25	W 0.00	D 0.00
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	0.25	LIN.M	L 0.25	W 0.00	D 0.00
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	0.25	LIN.M	L 0.25	W 0.00	D 0.00



# Inspection Report

<b>Inspection Date:</b>	<b>See Recorded Date</b>	<b>Inspect History ID:</b>	<b>3084520 - 1 Monthly - Safety Inspection of AAN1-12-ANTRIM &amp; NEWTOWNABBEY on 25 November 2020</b>	<b>Inspection Type:</b>	<b>1 Monthly - Safety Inspection</b>
				<b>Inspector:</b>	

<b>Section Code:</b>	<b>Section Description:</b>
<b>7035U0417_38</b>	<b>HOLLYVALE1: HAZELBURN RD1 TO END</b>

<b>Defect Ref:</b>	<b>Defect Type:</b>	<b>Comments:</b>	<b>Location Description:</b>	<b>Priority</b>	<b>Defect Dimensions:</b>		
<a href="#">DCD74-3084520-34</a>	DEFECT	KERB ROCKING PARKED CARS ON FWAY.	KERB AT HOUSE 4 AND LHS HOUSE 4.	R3 - 4 Weeks	<b>Length (m): 0.92</b>	<b>Width (m): 0.25</b>	<b>Depth (mm): 22.00</b>
<b>Recorded Date:</b>	<b>FOOTPATH KERB HIGH (FKHI)</b>						
26-November-2020							
<b>Recorded By:</b>	[REDACTED]						

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	1.00	LIN.M	L 1.00	W 0.00	D 0.00	
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	1.00	LIN.M	L 1.00	W 0.00	D 0.00	
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	1.00	LIN.M	L 1.00	W 0.00	D 0.00	

<b>Defect Ref:</b>	<b>Defect Type:</b>	<b>Comments:</b>	<b>Location Description:</b>	<b>Priority</b>	<b>Defect Dimensions:</b>		
<a href="#">DCD74-3084520-37</a>	DEFECT		CWAY AY REAR HOUSE 8	R3 - 4 Weeks	<b>Length (m): 0.70</b>	<b>Width (m): 0.24</b>	<b>Depth (mm): 31.00</b>
<b>Recorded Date:</b>	<b>BITMAC POTHOLE (CBPH)</b>						
30-November-2020							
<b>Recorded By:</b>	[REDACTED]						

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	2.00	no	L 0.00	W 0.00	D 0.00	



# Inspection Report

<b>Inspection Date:</b> See Recorded Date	<b>Inspect History ID:</b> 3084520 - 1 Monthly - Safety Inspection of AAN1-12-ANTRIM & NEWTOWNABBEY on 25 November 2020	<b>Inspection Type:</b> 1 Monthly - Safety Inspection
		<b>Inspector:</b>

<b>Section Code:</b> 7035U0417_38	<b>Section Description:</b> HOLLYVALE1: HAZELBURN RD1 TO END
-----------------------------------	--

<b>Defect Ref:</b> <a href="#">DCD74-3084520-38</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b>	<b>Location Description:</b> CWAY AT REAR HOUSE 2	<b>Priority:</b> R3 - 4 Weeks	<b>Defect Dimensions:</b>		
<b>Recorded Date:</b> 30-November-2020	BITMAC POTHOLE (CBPH)				<b>Length (m):</b> 0.30	<b>Width (m):</b> 0.15	<b>Depth (mm):</b> 27.00

Recorded By:



Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00	W 0.00	D 0.00	



## Inspection Report

Inspection Date: 13-Jan-2019

Inspect History ID: 3073307 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY  
on 11 January 2019

Inspection Type: Full Sector - Safety Inspection

Inspector: [REDACTED]

No Defects found on: 7035U0417\_38 - HOLLYVALE1: HAZELBURN RD1 TO END by [REDACTED]



## Inspection Report

Inspection Date: 4-Jul-2019

Inspect History ID: 3076223 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY  
on 01 July 2019

Inspection Type: Full Sector - Safety Inspection

Inspector: [REDACTED]

No Defects found on: 7035U0417\_38 - HOLLYVALE1: HAZELBURN RD1 TO END by [REDACTED]



# Inspection Report

<b>Inspection Date:</b> 9-Jan-2020	<b>Inspect History ID:</b> 3079265 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 06 January 2020	<b>Inspection Type:</b> Full Sector - Safety Inspection
		<b>Inspector:</b> [REDACTED]

<b>Section Code:</b> 7035U0417_38	<b>Section Description:</b> HOLLYVALE1: HAZELBURN RD1 TO END
--------------------------------------	---

<b>Defect Ref:</b> <a href="#">DCD74-3079265-123</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b>	<b>Location Description:</b> CWAY OPP STL 1	<b>Priority:</b> R3 - 4 Weeks	<b>Defect Dimensions:</b>		
<b>Recorded Date:</b> 09-January-2020	BITMAC POTHOLE (CBPH)				<b>Length (m):</b> 0.50	<b>Width (m):</b> 0.50	<b>Depth (mm):</b> 43.00
<b>Recorded By:</b> [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00	W 0.00	D 0.00	



## Inspection Report

Inspection Date: 7-Jul-2020

Inspect History ID: 3082250 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY  
on 01 July 2020

Inspection Type: Full Sector - Safety Inspection

Inspector: [REDACTED]

No Defects found on: 7035U0417\_38 - HOLLYVALE1: HAZELBURN RD1 TO END by [REDACTED]



# Inspection Report

<b>Inspection Date:</b> 7-Jan-2021	<b>Inspect History ID:</b> 3085111 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 05 January 2021	<b>Inspection Type:</b> Full Sector - Safety Inspection
		<b>Inspector:</b> [REDACTED]

<b>Section Code:</b> 7035U0417_38	<b>Section Description:</b> HOLLYVALE1: HAZELBURN RD1 TO END
--------------------------------------	---

<b>Defect Ref:</b> <a href="#">DCD74-3085111-89</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b> CARS PARKED ON FWAYS	<b>Location Description:</b> CWAY AT HOUSE 2	<b>Priority:</b> R3 - 4 Weeks	<b>Defect Dimensions:</b>		
<b>Recorded Date:</b> 07-January-2021	BITMAC POTHOLE (CBPH)				<b>Length (m):</b> 0.30	<b>Width (m):</b> 0.20	<b>Depth (mm):</b> 28.00

**Recorded By:**  
[REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures		
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00	W 0.00	D 0.00



# Inspection Report

<b>Inspection Date:</b> 5-Jul-2021	<b>Inspect History ID:</b> 3088039 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 01 July 2021	<b>Inspection Type:</b> Full Sector - Safety Inspection
		<b>Inspector:</b> [REDACTED]

<b>Section Code:</b> 7035U0417_38	<b>Section Description:</b> HOLLYVALE1: HAZELBURN RD1 TO END
--------------------------------------	---

<b>Defect Ref:</b> <a href="#">DCD101-3088039-86</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b>	<b>Location Description:</b> CWAY OPP RHS STL 1	<b>Priority:</b> R3 - 4 Weeks	<b>Defect Dimensions:</b>		
<b>Recorded Date:</b> 05-July-2021	BITMAC POTHOLE (GBPH)				<b>Length (m):</b> 0.50	<b>Width (m):</b> 0.23	<b>Depth (mm):</b> 29.00
<b>Recorded By:</b> [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00      W 0.00      D 0.00

<b>Defect Ref:</b> <a href="#">DCD101-3088039-87</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b> RESET KERB	<b>Location Description:</b> KERB RHS STL 1	<b>Priority:</b> R3 - 4 Weeks	<b>Defect Dimensions:</b>		
<b>Recorded Date:</b> 05-July-2021	FOOTPATH KERB LOW (FKLO)				<b>Length (m):</b> 0.92	<b>Width (m):</b> 0.25	<b>Depth (mm):</b> 22.00
<b>Recorded By:</b> [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	1.00	LIN.M	L 1.00      W 0.00      D 0.00



# Inspection Report

<b>Inspection Date:</b>	<b>See Recorded Date</b>	<b>Inspect History ID:</b>	<b>3084798 - 1 Monthly - Safety Inspection of AAN1-05-ANTRIM &amp; NEWTOWNABBEY on 08 December 2020</b>	<b>Inspection Type:</b>	<b>1 Monthly - Safety Inspection</b>
				<b>Inspector:</b>	

<b>Section Code:</b>	<b>Section Description:</b>
<b>7035U0417_37</b>	<b>LARCHGROVE1: HAZELBURN RD1 TO END</b>

Defect Ref: [DCD74-3084798-14](#) Defect Type: DEFECT Comments: RESET KERBS REF ENQUIRY E2005603 Location Description: KERBS AT RHS JCT HAZELBURN ROAD Priority: R3 - 4 Weeks Defect Dimensions: Length (m): 3.70 Width (m): 0.25 Depth (mm): 22.00

Recorded Date: 08-December-2020 FOOTPATH KERB HIGH (FKHI)

Recorded By:

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
<b>M64111A</b>	<b>^ Lift &amp; relay kerbs &gt;12m rad, 0-5m</b>	<b>4.00</b>	<b>LIN.M</b>	<b>L 4.00 W 0.00 D 0.00</b>

Defect Ref: [DCD74-3084798-15](#) Defect Type: DEFECT Comments: REF ENQUIRY E2005603 Location Description: FWAY AT HOUSE 26 Priority: R3 - 4 Weeks Defect Dimensions: Length (m): 0.30 Width (m): 0.12 Depth (mm): 39.00

Recorded Date: 08-December-2020 ASPHALT POTHOLE (FAPH)

Recorded By:

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
<b>M12011A</b>	<b>^ 75mm asphalt patch 0-1 square metres</b>	<b>1.00</b>	<b>no</b>	<b>L 0.00 W 0.00 D 0.00</b>



# Inspection Report

<b>Inspection Date:</b> 13-Jan-2019	<b>Inspect History ID:</b> 3073307 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 11 January 2019	<b>Inspection Type:</b> Full Sector - Safety Inspection
		<b>Inspector:</b> [REDACTED]

<b>Section Code:</b> 7035U0417_37	<b>Section Description:</b> LARCHGROVE1: HAZELBURN RD1 TO END
--------------------------------------	--

<b>Defect Ref:</b> <a href="#">DCD113-3073307-96</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b> REPLACE GULLY	<b>Location Description:</b> CWAY AT HOUSE 11	<b>Priority:</b> R2 - 5 Working days	<b>Defect Dimensions:</b>		
<b>Recorded Date:</b> 13-January-2019	GULLY LID BROKEN (CGBR)				<b>Length (m):</b>	<b>Width (m):</b>	<b>Depth (mm):</b>
<b>Recorded By:</b> [REDACTED]							

<b>Repair Description:</b> U12162A	<b>Repair Item Name:</b> ^ Reset c/way gully top 150-300mm	<b>Quantity:</b> 1.00	<b>Units:</b> no	<b>Repair Measures</b>			
				<b>L</b> 0.00	<b>W</b> 0.00	<b>D</b> 0.00	

<b>Defect Ref:</b> <a href="#">DCD113-3073307-97</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b>	<b>Location Description:</b> CWAY AT JCT HAZELBURN ROAD	<b>Priority:</b> R3 - 4 Weeks	<b>Defect Dimensions:</b>		
<b>Recorded Date:</b> 13-January-2019	BITMAC POTHOLE (GBPH)				<b>Length (m):</b> 0.60	<b>Width (m):</b> 0.40	<b>Depth (mm):</b> 25.00
<b>Recorded By:</b> [REDACTED]							

<b>Repair Description:</b> D23111A	<b>Repair Item Name:</b> ^ 100mm bit. patch W/C & B/C <1 m2	<b>Quantity:</b> 1.00	<b>Units:</b> no	<b>Repair Measures</b>			
				<b>L</b> 0.00	<b>W</b> 0.00	<b>D</b> 0.00	



# Inspection Report

Inspection Date: 13-Jan-2019	Inspect History ID: 3073307 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 11 January 2019	Inspection Type: Full Sector - Safety Inspection
		Inspector: [REDACTED]

Section Code: 7035U0417_37	Section Description: LARCHGROVE1: HAZELBURN RD1 TO END
----------------------------	--

Defect Ref: <a href="#">DCD113-3073307-98</a>	Defect Type: DEFECT	Comments:	Location Description: AT JCT HAZELBURN ROAD	Priority: R3 - 4 Weeks	Defect Dimensions: Length (m): 2.40 Width (m): 0.20 Depth (mm): 25.00
Recorded Date: 13-January-2019	FOOTPATH KERB HIGH (FKHI)				

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures		
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	2.40	LIN.M	L 2.40	W 0.00	D 0.00



# Inspection Report

**Inspection Date:** 4-Jul-2019     
 **Inspect History ID:** 3076223 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 01 July 2019     
 **Inspection Type:** Full Sector - Safety Inspection  
**Inspector:** [REDACTED]

**Section Code:** 7035U0417\_37     
 **Section Description:** LARCHGROVE1: HAZELBURN RD1 TO END

**Defect Ref:** [DCD74-3076223-133](#)     
**Defect Type:** DEFECT     
**Comments:** RESET KERB     
**Location Description:** HOUSE 26     
**Priority:** R3 - 4 Weeks     
**Defect Dimensions:** Length (m): 0.90      Width (m): 0.25      Depth (mm): 22.00  
**Recorded Date:** 04-July-2019     
**Recorded By:** [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures		
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	1.00	LIN.M	L 1.00	W 0.00	D 0.00



# Inspection Report

<b>Inspection Date:</b> 9-Jan-2020	<b>Inspect History ID:</b> 3079265 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 06 January 2020	<b>Inspection Type:</b> Full Sector - Safety Inspection
		<b>Inspector:</b> [REDACTED]

<b>Section Code:</b> 7035U0417_37	<b>Section Description:</b> LARCHGROVE1: HAZELBURN RD1 TO END
--------------------------------------	--

<b>Defect Ref:</b> <a href="#">DCD74-3079265-124</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b> RESET KERB	<b>Location Description:</b> KERB AT HOUSE 26	<b>Priority:</b> R3 - 4 Weeks	<b>Defect Dimensions:</b>		
<b>Recorded Date:</b> 09-January-2020	FOOTPATH KERB LOW (FKLO)				<b>Length (m):</b> 0.92	<b>Width (m):</b> 0.25	<b>Depth (mm):</b> 22.00

**Recorded By:**  
[REDACTED]

<b>Repair Description:</b> M64111A	<b>Repair Item Name:</b> ^ Lift & relay kerbs >12m rad, 0-5m	<b>Quantity:</b> 1.00	<b>Units:</b> LIN.M	<b>Repair Measures</b>			
				<b>L</b> 1.00	<b>W</b> 0.00	<b>D</b> 0.00	



# Inspection Report

<b>Inspection Date:</b> 7-Jul-2020	<b>Inspect History ID:</b> 3082250 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 01 July 2020	<b>Inspection Type:</b> Full Sector - Safety Inspection
		<b>Inspector:</b> [REDACTED]

<b>Section Code:</b> 7035U0417_37	<b>Section Description:</b> LARCHGROVE1: HAZELBURN RD1 TO END
--------------------------------------	--

<b>Defect Ref:</b> <a href="#">DCD74-3082250-155</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b> RELAY KERB X 1	<b>Location Description:</b> KERB AT HOUSE 26	<b>Priority:</b> R3 - 4 Weeks	<b>Defect Dimensions:</b>			
<b>Recorded Date:</b> 07-July-2020	FOOTPATH KERB LOW (FKLO)				<b>Length (m):</b> 0.92	<b>Width (m):</b> 0.25	<b>Depth (mm):</b> 22.00	

**Recorded By:**  
[REDACTED]

<b>Repair Description:</b>	<b>Repair Item Name:</b>	<b>Quantity</b>	<b>Units</b>	<b>Repair Measures</b>			
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	1.00	LIN.M	L 1.00	W 0.00	D 0.00	



# Inspection Report

<b>Inspection Date:</b> 7-Jan-2021	<b>Inspect History ID:</b> 3085111 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 05 January 2021	<b>Inspection Type:</b> Full Sector - Safety Inspection
		<b>Inspector:</b> [REDACTED]

<b>Section Code:</b> 7035U0417_37	<b>Section Description:</b> LARCHGROVE1: HAZELBURN RD1 TO END
--------------------------------------	--

<b>Defect Ref:</b> <a href="#">DCD74-3085111-91</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b> CARS PARKED ON FWAYS	<b>Location Description:</b> CWAY AT STL 7	<b>Priority:</b> R3 - 4 Weeks	<b>Defect Dimensions:</b>		
<b>Recorded Date:</b> 07-January-2021	BITMAC POTHOLE (CBPH)				<b>Length (m):</b> 0.30	<b>Width (m):</b> 0.13	<b>Depth (mm):</b> 33.00
<b>Recorded By:</b> [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures		
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00	W 0.00	D 0.00

<b>Defect Ref:</b> <a href="#">DCD74-3085111-92</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b> RESET KERBS. CARS PARKED ON FWAYS	<b>Location Description:</b> KERBS RHS JCT HAZELBURN ROAD	<b>Priority:</b> R3 - 4 Weeks	<b>Defect Dimensions:</b>		
<b>Recorded Date:</b> 07-January-2021	FOOTPATH KERB HIGH (FKHI)				<b>Length (m):</b> 3.60	<b>Width (m):</b> 0.25	<b>Depth (mm):</b> 22.00
<b>Recorded By:</b> [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures		
M64112A	^ Lift & relay kerbs >12m rad, >5m	12.00	LIN.M	L 12.00	W 0.00	D 0.00



## Inspection Report

Inspection Date: 5-Jul-2021

Inspect History ID: 3088039 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY  
on 01 July 2021

Inspection Type: Full Sector - Safety Inspection

Inspector: [REDACTED]

No Defects found on: 7035U0417\_37 - LARCHGROVE1: HAZELBURN RD1 TO END by [REDACTED]



# Inspection Report

<b>Inspection Date:</b>	<b>See Recorded Date</b>	<b>Inspect History ID:</b>	<b>3084798 - 1 Monthly - Safety Inspection of AAN1-05-ANTRIM &amp; NEWTOWNABBEY on 08 December 2020</b>	<b>Inspection Type:</b>	<b>1 Monthly - Safety Inspection</b>
				<b>Inspector:</b>	

<b>Section Code:</b>	<b>Section Description:</b>
<b>7035U0417_35</b>	<b>CHERRYMOUNT1: HAZELBURN RD1 TO END</b>

<b>Defect Ref:</b>	<b>Defect Type:</b>	<b>Comments:</b>	<b>Location Description:</b>	<b>Priority</b>	<b>Defect Dimensions:</b>		
<a href="#">DCD74-3084798-8</a>	DEFECT	REF ENQUIRY E2005603	<b>CWAY BETWEEN HOUSE 2 &amp; 8</b>	<b>R3 - 4 Weeks</b>	<b>Length (m): 0.40</b>	<b>Width (m): 0.30</b>	<b>Depth (mm): 30.00</b>
<b>Recorded Date:</b>	<b>BITMAC POTHOLE (CBPH)</b>						
08-December-2020							
<b>Recorded By:</b>	[REDACTED]						

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
<b>D23111A</b>	<b>^ 100mm bit. patch W/C &amp; B/C &lt;1 m2</b>	<b>11.00</b>	<b>no</b>	<b>L 0.00</b>	<b>W 0.00</b>	<b>D 0.00</b>	

<b>Defect Ref:</b>	<b>Defect Type:</b>	<b>Comments:</b>	<b>Location Description:</b>	<b>Priority</b>	<b>Defect Dimensions:</b>		
<a href="#">DCD74-3084798-9</a>	DEFECT	REF ENQUIRY E2005603	<b>CWAY AT HOUSE 3</b>	<b>R3 - 4 Weeks</b>	<b>Length (m): 0.40</b>	<b>Width (m): 0.15</b>	<b>Depth (mm): 33.00</b>
<b>Recorded Date:</b>	<b>BITMAC POTHOLE (CBPH)</b>						
08-December-2020							
<b>Recorded By:</b>	[REDACTED]						

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
<b>D23111A</b>	<b>^ 100mm bit. patch W/C &amp; B/C &lt;1 m2</b>	<b>1.00</b>	<b>no</b>	<b>L 0.00</b>	<b>W 0.00</b>	<b>D 0.00</b>	



# Inspection Report

<b>Inspection Date:</b>	<b>See Recorded Date</b>	<b>Inspect History ID:</b>	<b>3084798 - 1 Monthly - Safety Inspection of AAN1-05-ANTRIM &amp; NEWTOWNABBEY on 08 December 2020</b>	<b>Inspection Type:</b>	<b>1 Monthly - Safety Inspection</b>
				<b>Inspector:</b>	

<b>Section Code:</b>	<b>Section Description:</b>
<b>7035U0417_35</b>	<b>CHERRYMOUNT1: HAZELBURN RD1 TO END</b>

<b>Defect Ref:</b>	<b>Defect Type:</b>	<b>Comments:</b>	<b>Location Description:</b>	<b>Priority</b>	<b>Defect Dimensions:</b>		
<a href="#">DCD74-3084798-10</a>	DEFECT	RESET KERB REF ENQUIRY E2005603	KERB AT HOUSE 3	R3 - 4 Weeks	<b>Length (m): 0.92</b>	<b>Width (m): 0.25</b>	<b>Depth (mm): 22.00</b>
<b>Recorded Date:</b>	<b>FOOTPATH KERB HIGH (FKHI)</b>						
08-December-2020							
<b>Recorded By:</b>	[REDACTED]						

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
<b>M64111A</b>	<b>^ Lift &amp; relay kerbs &gt;12m rad, 0-5m</b>	<b>1.00</b>	<b>LIN.M</b>	<b>L 1.00</b>	<b>W 0.00</b>	<b>D 0.00</b>	

<b>Defect Ref:</b>	<b>Defect Type:</b>	<b>Comments:</b>	<b>Location Description:</b>	<b>Priority</b>	<b>Defect Dimensions:</b>		
<a href="#">DCD74-3084798-11</a>	DEFECT	REF ENQUIRY E2005603	CWAY LHS HOUSE 2 AT JCT	R3 - 4 Weeks	<b>Length (m): 0.40</b>	<b>Width (m): 0.50</b>	<b>Depth (mm): 38.00</b>
<b>Recorded Date:</b>	<b>BITMAC POTHOLE (CBPH)</b>						
08-December-2020							
<b>Recorded By:</b>	[REDACTED]						

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
<b>D23111A</b>	<b>^ 100mm bit. patch W/C &amp; B/C &lt;1 m2</b>	<b>3.00</b>	<b>no</b>	<b>L 0.00</b>	<b>W 0.00</b>	<b>D 0.00</b>	



# Inspection Report

<b>Inspection Date:</b>	<b>See Recorded Date</b>	<b>Inspect History ID:</b> -	<b>Inspection Type:</b>
			<b>Inspector:</b>

<b>Section Code:</b> 7035U0417_35	<b>Section Description:</b> CHERRYMOUNT1: HAZELBURN RD1 TO END
--------------------------------------	---

<b>Defect Ref:</b> <a href="#">D2104453</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b> ?	<b>Location Description:</b> Outside 20 & 21 Cherrymount	<b>Priority</b> R4 - next available programme	<b>Defect Dimensions:</b>	<b>Length (m):</b>	<b>Width (m):</b>	<b>Depth (mm):</b>
<b>Recorded Date:</b> 23-February-2021	<b>GULLY BLOCKED (GGBL)</b>							
<b>Recorded By:</b>	[REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures				
X77001A	^ Responsive cleaning of gully surround	2.00	no	L 0.00	W 0.00	D 0.00		
X15011A	^ Responsive machine gully emptying	2.00	no	L 0.00	W 0.00	D 0.00		
X25031A	^ Responsive jetting outlets	2.00	no	L 0.00	W 0.00	D 0.00		

<b>Defect Ref:</b> <a href="#">D2113340</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b> SCRAPE AND CLEAN FRONT OF KERB LINE TO PREVENT WATER RUNNING OVER KERB INTO PROPERTY. ALSO SCRAPE AND SWEEP SURROUNDING FWAY.	<b>Location Description:</b> REAR OF NO.30 CHERRYMOUNT CWAY AND FWAY	<b>Priority</b> R4 - next available programme	<b>Defect Dimensions:</b>	<b>Length (m):</b> 40.00	<b>Width (m):</b> 1.00	<b>Depth (mm):</b> 0.00
<b>Recorded Date:</b> 11-May-2021	<b>WEEDS PRESENT ON INSPECTION (WPOC)</b>							
<b>Recorded By:</b>	[REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures				
G01001A	^ Unplanned envir. work norm.hrs	1.00	HR	L 0.00	W 0.00	D 0.00		



# Inspection Report

<b>Inspection Date:</b> 13-Jan-2019	<b>Inspect History ID:</b> 3073307 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 11 January 2019	<b>Inspection Type:</b> Full Sector - Safety Inspection
		<b>Inspector:</b> [REDACTED]

<b>Section Code:</b> 7035U0417_35	<b>Section Description:</b> CHERRYMOUNT1: HAZELBURN RD1 TO END
--------------------------------------	---

<b>Defect Ref:</b> <a href="#">DCD113-3073307-99</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b>	<b>Location Description:</b> CWAY AT HOUSE 19 - 21	<b>Priority</b> R2 - 5 Working days	<b>Defect Dimensions:</b>		
					<b>Length (m):</b> 0.60	<b>Width (m):</b> 0.40	<b>Depth (mm):</b> 55.00
<b>Recorded Date:</b> 13-January-2019	<b>BITMAC POTHOLE (CBPH)</b>						
<b>Recorded By:</b> [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	3.00	no	L 0.00	W 0.00	D 0.00	

<b>Defect Ref:</b> <a href="#">DCD113-3073307-100</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b>	<b>Location Description:</b> CWAY AT HOUSE 10	<b>Priority</b> R3 - 4 Weeks	<b>Defect Dimensions:</b>		
					<b>Length (m):</b> 0.20	<b>Width (m):</b> 0.20	<b>Depth (mm):</b> 30.00
<b>Recorded Date:</b> 13-January-2019	<b>BITMAC POTHOLE (CBPH)</b>						
<b>Recorded By:</b> [REDACTED]							

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00	W 0.00	D 0.00	



# Inspection Report

<b>Inspection Date:</b> 4-Jul-2019	<b>Inspect History ID:</b> 3076223 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 01 July 2019	<b>Inspection Type:</b> Full Sector - Safety Inspection
		<b>Inspector:</b> [REDACTED]

<b>Section Code:</b> 7035U0417_35	<b>Section Description:</b> CHERRYMOUNT1: HAZELBURN RD1 TO END
--------------------------------------	---

<b>Defect Ref:</b> <a href="#">DCD74-3076223-135</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b> MAKE SAFE	<b>Location Description:</b> CWAY ATHOUSE 5	<b>Priority:</b> R3 - 4 Weeks	<b>Defect Dimensions:</b>			
<b>Recorded Date:</b> 04-July-2019	BITMAC POTHOLE (CBPH)				<b>Length (m):</b> 0.30	<b>Width (m):</b> 0.20	<b>Depth (mm):</b> 40.96	

**Recorded By:**  
[REDACTED]

<b>Repair Description:</b> D37031A	<b>Repair Item Name:</b> ^ 40mm patch deferred set 0-1m2	<b>Quantity:</b> 1.00	<b>Units:</b> no	<b>Repair Measures:</b> L 0.00    W 0.00    D 0.00
---------------------------------------	---	--------------------------	---------------------	---

<b>Defect Ref:</b> <a href="#">DCD74-3076223-136</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b> MAKE SAFE	<b>Location Description:</b> CWAY AT HOUSE 19	<b>Priority:</b> R3 - 4 Weeks	<b>Defect Dimensions:</b>			
<b>Recorded Date:</b> 04-July-2019	BITMAC POTHOLE (CBPH)				<b>Length (m):</b> 0.20	<b>Width (m):</b> 0.20	<b>Depth (mm):</b> 31.61	

**Recorded By:**  
[REDACTED]

<b>Repair Description:</b> D30061A	<b>Repair Item Name:</b> ^ Temp. patch 6mm deferred set 0-1m2	<b>Quantity:</b> 2.00	<b>Units:</b> no	<b>Repair Measures:</b> L 0.00    W 0.00    D 0.00
---------------------------------------	--	--------------------------	---------------------	---



# Inspection Report

<b>Inspection Date:</b> 9-Jan-2020	<b>Inspect History ID:</b> 3079265 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 06 January 2020	<b>Inspection Type:</b> Full Sector - Safety Inspection
		<b>Inspector:</b> [REDACTED]

<b>Section Code:</b> 7035U0417_35	<b>Section Description:</b> CHERRYMOUNT1: HAZELBURN RD1 TO END
--------------------------------------	---

**Defect Ref:** [DCD74-3079265-125](#)  
**Recorded Date:** 09-January-2020  
**Recorded By:** [REDACTED]

**Defect Type:** DEFECT  
**Comments:** BITMAC POTHOLE (CBPH)  
**Location Description:** CWAY AT HOUSE 4  
**Priority:** R3 - 4 Weeks  
**Defect Dimensions:** Length (m): 0.30 Width (m): 0.20 Depth (mm): 39.00

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	6.00	no	L 0.00 W 0.00 D 0.00

**Defect Ref:** [DCD74-3079265-126](#)  
**Recorded Date:** 09-January-2020  
**Recorded By:** [REDACTED]

**Defect Type:** DEFECT  
**Comments:** BITMAC POTHOLE (CBPH)  
**Location Description:** CWAY AT HOUSE5  
**Priority:** R2 - 5 Working days  
**Defect Dimensions:** Length (m): 0.60 Width (m): 0.26 Depth (mm): 56.00

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00 W 0.00 D 0.00



# Inspection Report

<b>Inspection Date:</b> 9-Jan-2020	<b>Inspect History ID:</b> 3079265 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 06 January 2020	<b>Inspection Type:</b> Full Sector - Safety Inspection
		<b>Inspector:</b> [REDACTED]

<b>Section Code:</b> 7035U0417_35	<b>Section Description:</b> CHERRYMOUNT1: HAZELBURN RD1 TO END
--------------------------------------	---

<b>Defect Ref:</b> <a href="#">DCD74-3079265-127</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b> RESET KERB	<b>Location Description:</b> KERB AT HOUSE 22	<b>Priority:</b> R3 - 4 Weeks	<b>Defect Dimensions:</b> <b>Length (m): 0.92</b>	<b>Width (m): 0.25</b>	<b>Depth (mm): 22.00</b>
<b>Recorded Date:</b> 09-January-2020	<b>FOOTPATH KERB HIGH (FKHI)</b>						

**Recorded By:**  
[REDACTED]

<b>Repair Description:</b> M64111A	<b>Repair Item Name:</b> ^ Lift & relay kerbs >12m rad, 0-5m	<b>Quantity:</b> 1.00	<b>Units:</b> LIN.M	<b>Repair Measures:</b> L 1.00 W 0.00 D 0.00
---------------------------------------	---	--------------------------	------------------------	---

<b>Defect Ref:</b> <a href="#">DCD74-3079265-128</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b>	<b>Location Description:</b> CWAY AT HOUSE 21	<b>Priority:</b> R2 - 5 Working days	<b>Defect Dimensions:</b> <b>Length (m): 0.30</b>	<b>Width (m): 0.30</b>	<b>Depth (mm): 51.00</b>
<b>Recorded Date:</b> 09-January-2020	<b>BITMAC POTHOLE (CBPH)</b>						

**Recorded By:**  
[REDACTED]

<b>Repair Description:</b> D23111A	<b>Repair Item Name:</b> ^ 100mm bit. patch W/C & B/C <1 m2	<b>Quantity:</b> 2.00	<b>Units:</b> no	<b>Repair Measures:</b> L 0.00 W 0.00 D 0.00
---------------------------------------	--	--------------------------	---------------------	---



# Inspection Report

<b>Inspection Date:</b> 9-Jan-2020	<b>Inspect History ID:</b> 3079265 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 06 January 2020	<b>Inspection Type:</b> Full Sector - Safety Inspection
		<b>Inspector:</b> [REDACTED]

<b>Section Code:</b> 7035U0417_35	<b>Section Description:</b> CHERRYMOUNT1: HAZELBURN RD1 TO END
--------------------------------------	---

<b>Defect Ref:</b> <a href="#">DCD74-3079265-129</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b> RESET KERB	<b>Location Description:</b> KERB AT HOUSE 16	<b>Priority:</b> R3 - 4 Weeks	<b>Defect Dimensions:</b>			
<b>Recorded Date:</b> 09-January-2020	FOOTPATH KERB HIGH (FKHI)				<b>Length (m):</b> 0.92	<b>Width (m):</b> 0.25	<b>Depth (mm):</b> 22.00	

**Recorded By:**  
[REDACTED]

<b>Repair Description:</b> M64111A	<b>Repair Item Name:</b> ^ Lift & relay kerbs >12m rad, 0-5m	<b>Quantity:</b> 1.00	<b>Units:</b> LIN.M	<b>Repair Measures:</b> L 1.00    W 0.00    D 0.00
---------------------------------------	---	--------------------------	------------------------	---

<b>Defect Ref:</b> <a href="#">DCD74-3079265-130</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b>	<b>Location Description:</b> CWAY RHS HOUSE 2	<b>Priority:</b> R3 - 4 Weeks	<b>Defect Dimensions:</b>			
<b>Recorded Date:</b> 09-January-2020	BITMAC POTHOLE (CBPH)				<b>Length (m):</b> 0.30	<b>Width (m):</b> 0.20	<b>Depth (mm):</b> 33.00	

**Recorded By:**  
[REDACTED]

<b>Repair Description:</b> D23111A	<b>Repair Item Name:</b> ^ 100mm bit. patch W/C & B/C <1 m2	<b>Quantity:</b> 2.00	<b>Units:</b> no	<b>Repair Measures:</b> L 0.00    W 0.00    D 0.00
---------------------------------------	--	--------------------------	---------------------	---



# Inspection Report

<b>Inspection Date:</b> 7-Jul-2020	<b>Inspect History ID:</b> 3082250 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 01 July 2020	<b>Inspection Type:</b> Full Sector - Safety Inspection
		<b>Inspector:</b> [REDACTED]

<b>Section Code:</b> 7035U0417_35	<b>Section Description:</b> CHERRYMOUNT1: HAZELBURN RD1 TO END
--------------------------------------	---

**Defect Ref:** [DCD74-3082250-157](#)  
**Recorded Date:** 07-July-2020  
**Recorded By:** [REDACTED]

**Defect Type:** DEFECT  
**Comments:** BITMAC POTHOLE (CBPH)  
**Location Description:** CWAY AT HOUSE 4  
**Priority:** R3 - 4 Weeks  
**Defect Dimensions:** Length (m): 0.30 Width (m): 0.25 Depth (mm): 29.00

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	8.00	no	L 0.00 W 0.00 D 0.00

**Defect Ref:** [DCD74-3082250-158](#)  
**Recorded Date:** 07-July-2020  
**Recorded By:** [REDACTED]

**Defect Type:** DEFECT  
**Comments:** BITMAC POTHOLE (CBPH)  
**Location Description:** CWAY AT LHS HOUSE 2  
**Priority:** R3 - 4 Weeks  
**Defect Dimensions:** Length (m): 0.30 Width (m): 0.20 Depth (mm): 32.00

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	3.00	no	L 0.00 W 0.00 D 0.00



# Inspection Report

<b>Inspection Date:</b> 7-Jan-2021	<b>Inspect History ID:</b> 3085111 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 05 January 2021	<b>Inspection Type:</b> Full Sector - Safety Inspection
		<b>Inspector:</b> [REDACTED]

<b>Section Code:</b> 7035U0417_35	<b>Section Description:</b> CHERRYMOUNT1: HAZELBURN RD1 TO END
--------------------------------------	---

<b>Defect Ref:</b> <a href="#">DCD74-3085111-94</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b> CARS PARKED ON FWAYS	<b>Location Description:</b> CWAY OPP STL 8	<b>Priority:</b> R3 - 4 Weeks	<b>Defect Dimensions:</b>		
<b>Recorded Date:</b> 07-January-2021	BITMAC POTHOLE (CBPH)				<b>Length (m):</b> 0.30	<b>Width (m):</b> 0.25	<b>Depth (mm):</b> 34.00

**Recorded By:**  
[REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures		
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00	W 0.00	D 0.00



## Inspection Report

Inspection Date: 5-Jul-2021

Inspect History ID: 3088039 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY  
on 01 July 2021

Inspection Type: Full Sector - Safety Inspection

Inspector: [REDACTED]

No Defects found on: 7035U0417\_35 - CHERRYMOUNT1: HAZELBURN RD1 TO END by [REDACTED]



# Inspection Report

<b>Inspection Date:</b> 13-Jan-2019	<b>Inspect History ID:</b> 3073307 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 11 January 2019	<b>Inspection Type:</b> Full Sector - Safety Inspection
		<b>Inspector:</b> [REDACTED]

<b>Section Code:</b> 7035U0417_34	<b>Section Description:</b> ROWAN GVE1: HAZELBURN RD1 TO END
--------------------------------------	---

<b>Defect Ref:</b> <a href="#">DCD113-3073307-101</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b>	<b>Location Description:</b> AT HOUSE 2	<b>Priority:</b> R3 - 4 Weeks	<b>Defect Dimensions:</b>		
<b>Recorded Date:</b> 13-January-2019	FOOTPATH KERB HIGH (FKHI)				<b>Length (m):</b> 0.90	<b>Width (m):</b> 0.25	<b>Depth (mm):</b> 21.00

**Recorded By:**  
[REDACTED]

<b>Repair Description:</b> M64111A	<b>Repair Item Name:</b> ^ Lift & relay kerbs >12m rad, 0-5m	<b>Quantity:</b> 1.00	<b>Units:</b> LIN.M	<b>Repair Measures</b>			
				<b>L</b> 1.00	<b>W</b> 0.00	<b>D</b> 0.00	

<b>Defect Ref:</b> <a href="#">DCD113-3073307-102</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b>	<b>Location Description:</b> AT JCT ROWAN GROVE	<b>Priority:</b> R3 - 4 Weeks	<b>Defect Dimensions:</b>		
<b>Recorded Date:</b> 13-January-2019	FOOTPATH KERB HIGH (FKHI)				<b>Length (m):</b> 2.50	<b>Width (m):</b> 0.25	<b>Depth (mm):</b> 25.00

**Recorded By:**  
[REDACTED]

<b>Repair Description:</b> M64111A	<b>Repair Item Name:</b> ^ Lift & relay kerbs >12m rad, 0-5m	<b>Quantity:</b> 2.50	<b>Units:</b> LIN.M	<b>Repair Measures</b>			
				<b>L</b> 2.50	<b>W</b> 0.00	<b>D</b> 0.00	



## Inspection Report

Inspection Date: 4-Jul-2019

Inspect History ID: 3076223 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY  
on 01 July 2019

Inspection Type: Full Sector - Safety Inspection

Inspector: [REDACTED]

No Defects found on: 7035U0417\_34 - ROWAN GVE1: HAZELBURN RD1 TO END by [REDACTED]



## Inspection Report

Inspection Date: 9-Jan-2020

Inspect History ID: 3079265 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY  
on 06 January 2020

Inspection Type: Full Sector - Safety Inspection

Inspector: [REDACTED]

No Defects found on: 7035U0417\_34 - ROWAN GVE1: HAZELBURN RD1 TO END by [REDACTED]



## Inspection Report

Inspection Date: 7-Jul-2020

Inspect History ID: 3082250 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY  
on 01 July 2020

Inspection Type: Full Sector - Safety Inspection

Inspector: [REDACTED]

No Defects found on: 7035U0417\_34 - ROWAN GVE1: HAZELBURN RD1 TO END by [REDACTED]



# Inspection Report

Inspection Date: 7-Jan-2021	Inspect History ID: 3085111 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY on 05 January 2021	Inspection Type: Full Sector - Safety Inspection
		Inspector: [REDACTED]

Section Code: 7035U0417_34	Section Description: ROWAN GVE1: HAZELBURN RD1 TO END
----------------------------	---

Defect Ref: <a href="#">DCD74-3085111-96</a>	Defect Type: DEFECT	Comments: RESET KERBS. CARS PARKED ON FWAYS	Location Description: KERBS AT STL 1	Priority: R3 - 4 Weeks	Defect Dimensions:			
					Length (m): 1.80	Width (m): 0.25	Depth (mm): 22.00	

Recorded Date: 07-January-2021  
 FOOTPATH KERB HIGH (FKHI)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
M64111A	^ Lift & relay kerbs >12m rad, 0-5m	2.00	LIN.M	L 2.00 W 0.00 D 0.00



## Inspection Report

Inspection Date: 5-Jul-2021

Inspect History ID: 3088039 - Full Sector - Safety Inspection of AAN1-01-ANTRIM & NEWTOWNABBEY  
on 01 July 2021

Inspection Type: Full Sector - Safety Inspection

Inspector: [REDACTED]

No Defects found on: 7035U0417\_34 - ROWAN GVE1: HAZELBURN RD1 TO END by [REDACTED]