



# Inspection Report

**Inspection Date:** 20-Aug-2020    
 **Inspect History ID:** 3082938 - Full Sector - Safety Inspection of BM11-BANBRIDGE / CRAIGAVON on 18 August 2020    
 **Inspection Type:** Full Sector - WFE Safety  
**Inspector:** [REDACTED]

No Defects found on: 7060U4468\_16 - PINLEY GREEN1: C0351 02 BALLYGOWAN RD TO END by [REDACTED]

**Section Code:** 7060U4468\_50    
 **Section Description:** PINLEY GREEN1: U4468 16 PINLEY GREEN TO END

**Defect Ref:** [DCD81-3082938-20](#)    
**Defect Type:** DEFECT    
**Comments:**    
**Location Description:** opp ho no 17 pinley green    
**Priority:** R3 - 4 Weeks    
**Defect Dimensions:** Length (m): 1.60     Width (m): 0.80     Depth (mm): 78.00

**Recorded Date:** 20-August-2020    
**BITMAC DEPRESSED - EDGE GRADIENT > 45 DEGREES (FBDG)**

**Recorded By:** [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures		
M22023A	^ 75mm macadam patch, >3m* in footway	3.64	SQ.M	L 2.60	W 1.40	D 0.00



# Inspection Report

<b>Inspection Date:</b> 20-Nov-2020	<b>Inspect History ID:</b> 3084406 - Full Sector - Safety Inspection of BM11-BANBRIDGE / CRAIGAVON on 18 November 2020	<b>Inspection Type:</b> Full Sector - WFE Safety
		<b>Inspector:</b> [REDACTED]

No Defects found on: 7060U4468\_16 - PINLEY GREEN1: C0351 02 BALLYGOWAN RD TO END [REDACTED]

<b>Section Code:</b> 7060U4468_50	<b>Section Description:</b> PINLEY GREEN1: U4468 16 PINLEY GREEN TO END
--------------------------------------	--

<b>Defect Ref:</b> <a href="#">DCD81-3084406-9</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b>	<b>Location Description:</b> opp ho no 15	<b>Priority</b> R2 - 5 Working days	<b>Defect Dimensions:</b>		
<b>Recorded Date:</b> 20-November-2020	BITMAC POTHOLE (FBPH)				<b>Length (m):</b> 0.30	<b>Width (m):</b> 0.20	<b>Depth (mm):</b> 52.00

**Recorded By:**  
[REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
M22021A	^ 75mm macadam patch, 0-1m* in footway	2.00	no	L 0.00	W 0.00	D 0.00	



# Inspection Report

<b>Inspection Date:</b> 3-Mar-2021	<b>Inspect History ID:</b> 3085821 - Full Sector - Safety Inspection of BM11-BANBRIDGE / CRAIGAVON on 01 March 2021	<b>Inspection Type:</b> Full Sector - WFE Safety
		<b>Inspector:</b> [REDACTED]

No Defects found on: 7060U4468\_16 - PINLEY GREEN1: C0351 02 BALLYGOWAN RD TO END by [REDACTED]

<b>Section Code:</b> 7060U4468_50	<b>Section Description:</b> PINLEY GREEN1: U4468 16 PINLEY GREEN TO END
--------------------------------------	--

<b>Defect Ref:</b> <a href="#">DCD81-3085821-18</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b>	<b>Location Description:</b> at ho no 9	<b>Priority</b> R3 - 4 Weeks	<b>Defect Dimensions:</b>		
<b>Recorded Date:</b> 03-March-2021	BITMAC POTHOLE (FBPH)				<b>Length (m):</b> 0.60	<b>Width (m):</b> 0.40	<b>Depth (mm):</b> 22.00

**Recorded By:**  
[REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
M22021A	^ 75mm macadam patch, 0-1m* in footway	1.00	no	L 0.00	W 0.00	D 0.00	



# Inspection Report

Inspection Date: 10-Jun-2021	Inspect History ID: 3087392 - Full Sector - Safety Inspection of BM11-BANBRIDGE / CRAIGAVON on 08 June 2021	Inspection Type: Full Sector - WFE Safety
		Inspector: [REDACTED]

No Defects found on: 7060U4468\_16 - PINLEY GREEN1: C0351 02 BALLYGOWAN RD TO END by [REDACTED]

Section Code: 7060U4468_50	Section Description: PINLEY GREEN1: U4468 16 PINLEY GREEN TO END
----------------------------	--

Defect Ref: <a href="#">DCD81-3087392-23</a>	Defect Type: THIRD PARTY REFERRAL	Comments: notify ni water LA REF: 1188713	Location Description: at ho no 24	Priority: R4 - next available programme	Defect Dimensions: Length (m): 1.00 Length (m): 1.00	Width (m): 1.00 Width (m): 1.00	Depth (mm): 1.00 Depth (mm): 1.00
Recorded Date: 10-June-2021	SERVICE REINSTATEMENT DEFECTIVE (SRDF)						

Recorded By: [REDACTED]

Repair Description: M09999A	Repair Item Name: ^ FW / CT PATCH	Quantity: 1.00	Units: no	Repair Measures: L 0.00 W 0.00 D 0.00
-----------------------------	-----------------------------------	----------------	-----------	---------------------------------------

Defect Ref: <a href="#">DCD81-3087392-24</a>	Defect Type: THIRD PARTY REFERRAL	Comments: notify ni water LA REF: 1179695	Location Description: at ho no 13	Priority: R4 - next available programme	Defect Dimensions: Length (m): 1.00 Length (m): 1.00	Width (m): 1.00 Width (m): 1.00	Depth (mm): 1.00 Depth (mm): 1.00
Recorded Date: 10-June-2021	SERVICE REINSTATEMENT DEFECTIVE (SRDF)						

Recorded By: [REDACTED]

Repair Description: M09999A	Repair Item Name: ^ FW / CT PATCH	Quantity: 1.00	Units: no	Repair Measures: L 0.00 W 0.00 D 0.00
-----------------------------	-----------------------------------	----------------	-----------	---------------------------------------



## Inspection Report

<b>Inspection Date:</b> 14-Sep-2021	<b>Inspect History ID:</b> 3088904 - Full Sector - Safety Inspection of BM11-BANBRIDGE / CRAIGAVON on 07 September 2021	<b>Inspection Type:</b> Full Sector - WFE Safety
		<b>Inspector:</b> [REDACTED]

No Defects found on: 7060U4468\_16 - PINLEY GREEN1: C0351 02 BALLYGOWAN RD TO END [REDACTED]

No Defects found on: 7060U4468\_50 - PINLEY GREEN1: U4468 16 PINLEY GREEN TO END [REDACTED]



# Inspection Report

<b>Inspection Date:</b> 10-Dec-2021	<b>Inspect History ID:</b> 3090417 - Full Sector - Safety Inspection of BM11-BANBRIDGE / CRAIGAVON on 08 December 2021	<b>Inspection Type:</b> Full Sector - WFE Safety
		<b>Inspector:</b> [REDACTED]

<b>Section Code:</b> 7060U4468_16	<b>Section Description:</b> PINLEY GREEN1: C0351 02 BALLYGOWAN RD TO END
--------------------------------------	---

Defect Ref:	Defect Type:	Comments:	Location Description:	Priority	Defect Dimensions:		
					Length (m):	Width (m):	Depth (mm):
<a href="#">DCD81-3090417-17</a>	THIRD PARTY REFERRAL	notify ni water  la ref 1230828	at ballygowan rd jct	R4 - next available programme			

Recorded Date: 10-December-2021  
 UTILITY VALVE COVER BROKEN (UVBR)

Recorded By:  
 [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures		
U13120A	^ Collect +install sup'd c/way toby /hyd t	1.00	no	L 0.00	W 0.00	D 0.00

No Defects found on: 7060U4468\_50 - PINLEY GREEN1: U4468 16 PINLEY GREEN TO END [REDACTED]



## Inspection Report

Inspection Date: 24-Mar-2022      Inspect History ID: 3091908 - Full Sector - Safety Inspection of BM11-BANBRIDGE / CRAIGAVON on 22 March 2022      Inspection Type: Full Sector - WFE Safety  
Inspector: [REDACTED]

No Defects found on: 7060U4468\_16 - PINLEY GREEN1: C0351 02 BALLYGOWAN RD TO END [REDACTED]

No Defects found on: 7060U4468\_50 - PINLEY GREEN1: U4468 16 PINLEY GREEN TO END [REDACTED]



## Inspection Report

Inspection Date: 5-Jul-2022

Inspect History ID: 3093499 - Full Sector - Safety Inspection of BM11-BANBRIDGE / CRAIGAVON on 30  
June 2022

Inspection Type: Full Sector - WFE Safety

Inspector: [REDACTED]

No Defects found on: 7060U4468\_16 - PINLEY GREEN1: C0351 02 BALLYGOWAN RD TO END [REDACTED]

No Defects found on: 7060U4468\_50 - PINLEY GREEN1: U4468 16 PINLEY GREEN TO END [REDACTED]



# Inspection Report

Inspection Date: 13-Oct-2022      Inspect History ID: 3094955 - Full Sector - Safety Inspection of BM11-BANBRIDGE / CRAIGAVON on 11 October 2022      Inspection Type: Full Sector - WFE Safety  
 Inspector: [REDACTED]

No Defects found on: 7060U4468\_16 - PINLEY GREEN1: C0351 02 BALLYGOWAN RD TO END by [REDACTED]

Section Code: 7060U4468\_50      Section Description: PINLEY GREEN1: U4468 16 PINLEY GREEN TO END

Defect Ref: [DCD81-3094955-13](#)      Defect Type: DEFECT      Comments:      Location Description: opp ho no 1 pinley green      Priority: R3 - 4 Weeks      Defect Dimensions: Length (m): 0.30      Width (m): 0.20      Depth (mm): 21.00

Recorded Date: 13-October-2022      BITMAC POTHOLE (FBPH)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
M22021A	^ 75mm macadam patch, 0-1m* in footway	1.00	no	L 0.00      W 0.00      D 0.00