



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 07/09/2022
Until Less Than: 07/09/2023

Section:
7065C0278_03 LOUGHINISLAND RD1: CRAWFORDSTOWN RD C288 TO ANNACLOY RD B2

Commencement date of Inspection:	03 Mar 2023	Inspect History ID & Description:	3101997 - 3 Monthly - WFE Safety Inspection of 3NRD-DOWN	Inspector Name:	[REDACTED]
Class:	C Class	Environment:	RURAL	Traffic Level:	Medium Traffic

Ref: [DCD238819833](#) **Defect Type:** DEFECT **Location Description:** At junction opposite Jim monaghan motors **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 1.90 Width (m): 0.40 Depth (mm): 51.00

Comments: Previously recorded failed

Defect Date: 08-March-2023 **Defect Category:** BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Ref: [DCD238819850](#) **Defect Type:** DEFECT **Location Description:** At 146 **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 3.00 Width (m): 0.50 Depth (mm): 70.00

Comments: ?

Defect Date: 08-March-2023 **Defect Category:** BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23112A	^ 100mm bit. patch W/C & B/C 1-3 m2	1.50	SQ.M	L 3.00 W 0.50 D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 07/09/2022
Until Less Than: 07/09/2023

Section:
7065C0278_03 LOUGHINISLAND RD1: CRAWFORDSTOWN RD C288 TO ANNACLOY RD B2

Commencement date of Inspection:	03 Mar 2023	Inspect History ID & Description:	3101997 - 3 Monthly - WFE Safety Inspection of 3NRD-DOWN	Inspector Name:	[REDACTED]
Class:	C Class	Environment:	RURAL	Traffic Level:	Medium Traffic

Ref: [DCD238819854](#) **Defect Type:** DEFECT **Location Description:** At house 146 **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 0.80 Width (m): 0.50 Depth (mm): 65.00

Comments: ?

Defect Date: 08-March-2023 **Defect Category:** BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Ref: [DCD238819861](#) **Defect Type:** DEFECT **Location Description:** 30m Before house 146 **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 1.20 Width (m): 0.50 Depth (mm): 75.00

Comments: ?

Defect Date: 08-March-2023 **Defect Category:** BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 07/09/2022
Until Less Than: 07/09/2023

Section:
7065C0278_03 LOUGHINISLAND RD1: CRAWFORDSTOWN RD C288 TO ANNACLOY RD B2

Commencement date of Inspection:	03 Mar 2023	Inspect History ID & Description:	3101997 - 3 Monthly - WFE Safety Inspection of 3NRD-DOWN	Inspector Name:	[REDACTED]
Class:	C Class	Environment:	RURAL	Traffic Level:	Medium Traffic

Ref: [DCD238819870](#) **Defect Type:** DEFECT **Location Description:** 35m before house 146 **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 3.80 Width (m): 1.10 Depth (mm): 58.00

Comments: Take out slump sealed well

Defect Date: 08-March-2023 **Defect Category:** BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23113A	^ 100mm bit. patch W/C & B/C 3-15 m2	4.18	SQ.M	L 3.80 W 1.10 D 0.00

Photographs or Documents attached: No

Ref: [DCD238819882](#) **Defect Type:** DEFECT **Location Description:** 80m after opposite 146 **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 2.40 Width (m): 0.50 Depth (mm): 60.00

Comments: ?

Defect Date: 08-March-2023 **Defect Category:** BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23112A	^ 100mm bit. patch W/C & B/C 1-3 m2	1.20	SQ.M	L 2.40 W 0.50 D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 07/09/2022
Until Less Than: 07/09/2023

Section:
7065C0278_03 LOUGHINISLAND RD1: CRAWFORDSTOWN RD C288 TO ANNACLOY RD B2

Commencement date of Inspection:	03 Mar 2023	Inspect History ID & Description:	3101997 - 3 Monthly - WFE Safety Inspection of 3NRD-DOWN	Inspector Name:	[REDACTED]
Class:	C Class	Environment:	RURAL	Traffic Level:	Medium Traffic

Ref: [DCD238819892](#) **Defect Type:** DEFECT **Location Description:** 100m after house 146 **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 2.20 Width (m): 0.60 Depth (mm): 56.00

Comments: ?

Defect Date: 08-March-2023 **Defect Category:** BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23112A	^ 100mm bit. patch W/C & B/C 1-3 m2	1.32	SQ.M	L 2.20 W 0.60 D 0.00

Photographs or Documents attached: No

Ref: [DCD238819927](#) **Defect Type:** DEFECT **Location Description:** Opposite pole 244 **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 10.00 Width (m): 0.50 Depth (mm): 60.00

Comments: ?

Defect Date: 08-March-2023 **Defect Category:** BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23113A	^ 100mm bit. patch W/C & B/C 3-15 m2	5.00	SQ.M	L 10.00 W 0.50 D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 07/09/2022
Until Less Than: 07/09/2023

Section:
7065C0278_03 LOUGHINISLAND RD1: CRAWFORDSTOWN RD C288 TO ANNACLOY RD B2

Commencement date of Inspection:	03 Mar 2023	Inspect History ID & Description:	3101997 - 3 Monthly - WFE Safety Inspection of 3NRD-DOWN	Inspector Name:	[REDACTED]
Class:	C Class	Environment:	RURAL	Traffic Level:	Medium Traffic

Ref: [DCD238819929](#) **Defect Type:** DEFECT **Location Description:** After pole 244 **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 4.00 Width (m): 0.50 Depth (mm): 68.00

Comments: ?

Defect Date: 08-March-2023 **Defect Category:** BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23112A	^ 100mm bit. patch W/C & B/C 1-3 m2	2.00	SQ.M	L 4.00 W 0.50 D 0.00

Photographs or Documents attached: No

Ref: [DCD238819933](#) **Defect Type:** DEFECT **Location Description:** After pole 244 **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 1.00 Width (m): 0.30 Depth (mm): 55.00

Comments: ?

Defect Date: 08-March-2023 **Defect Category:** BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 07/09/2022
Until Less Than: 07/09/2023

Section:
7065C0278_03 LOUGHINISLAND RD1: CRAWFORDSTOWN RD C288 TO ANNACLOY RD B2

Commencement date of Inspection:	03 Mar 2023	Inspect History ID & Description:	3101997 - 3 Monthly - WFE Safety Inspection of 3NRD-DOWN	Inspector Name:	[REDACTED]
Class:	C Class	Environment:	RURAL	Traffic Level:	Medium Traffic

Ref: [DCD238819940](#) **Defect Type:** DEFECT **Location Description:** 20m before pole 244 **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 1.20 Width (m): 0.40 Depth (mm): 58.00

Comments: ?

Defect Date: 08-March-2023 **Defect Category:** BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Ref: [DCD238819972](#) **Defect Type:** DEFECT **Location Description:** At entrance opposite pole 243 **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 9.00 Width (m): 0.80 Depth (mm): 80.00

Comments: ?

Defect Date: 08-March-2023 **Defect Category:** BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23113A	^ 100mm bit. patch W/C & B/C 3-15 m2	7.20	SQ.M	L 9.00 W 0.80 D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 07/09/2022
Until Less Than: 07/09/2023

Section:
7065C0278_03 LOUGHINISLAND RD1: CRAWFORDSTOWN RD C288 TO ANNACLOY RD B2

Commencement date of Inspection:	03 Mar 2023	Inspect History ID & Description:	3101997 - 3 Monthly - WFE Safety Inspection of 3NRD-DOWN	Inspector Name:	[REDACTED]
Class:	C Class	Environment:	RURAL	Traffic Level:	Medium Traffic

Ref: [DCD238819981](#) **Defect Type:** DEFECT **Location Description:** Opposite pole 243 **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 3.40 Width (m): 0.70 Depth (mm): 73.00

Comments: ?

Defect Date: 08-March-2023 **Defect Category:** BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23112A	^ 100mm bit. patch W/C & B/C 1-3 m2	2.38	SQ.M	L 3.40 W 0.70 D 0.00

Photographs or Documents attached: No

Ref: [DCD238819991](#) **Defect Type:** DEFECT **Location Description:** At house 128 **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 1.50 Width (m): 0.60 Depth (mm): 60.00

Comments: ?

Defect Date: 08-March-2023 **Defect Category:** BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 07/09/2022
Until Less Than: 07/09/2023

Section:
7065C0278_03 LOUGHINISLAND RD1: CRAWFORDSTOWN RD C288 TO ANNACLOY RD B2

Commencement date of Inspection:	03 Mar 2023	Inspect History ID & Description:	3101997 - 3 Monthly - WFE Safety Inspection of 3NRD-DOWN	Inspector Name:	[REDACTED]
Class:	C Class	Environment:	RURAL	Traffic Level:	Medium Traffic

Ref: [DCD238819994](#) **Defect Type:** DEFECT **Location Description:** At house 128 **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 1.10 Width (m): 0.70 Depth (mm): 51.00

Comments: ?

Defect Date: 08-March-2023 **Defect Category:** BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Ref: [DCD238820006](#) **Defect Type:** DEFECT **Location Description:** Opposite junction woodgrange Road **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 2.50 Width (m): 0.50 Depth (mm): 53.00

Comments: ?

Defect Date: 08-March-2023 **Defect Category:** BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23112A	^ 100mm bit. patch W/C & B/C 1-3 m2	1.25	SQ.M	L 2.50 W 0.50 D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 07/09/2022
Until Less Than: 07/09/2023

Section:
7065C0278_03 LOUGHINISLAND RD1: CRAWFORDSTOWN RD C288 TO ANNACLOY RD B2

Commencement date of Inspection:	03 Mar 2023	Inspect History ID & Description:	3101997 - 3 Monthly - WFE Safety Inspection of 3NRD-DOWN	Inspector Name:	[REDACTED]
Class:	C Class	Environment:	RURAL	Traffic Level:	Medium Traffic

Ref: [DCD238820023](#) **Defect Type:** DEFECT **Location Description:** 70m after house 79 **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 10.00 Width (m): 1.00 Depth (mm): 73.00

Comments: Take slump out of Road seal well

Defect Date: 08-March-2023 **Defect Category:** BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23113A	^ 100mm bit. patch W/C & B/C 3-15 m2	10.00	SQ.M	L 10.00 W 1.00 D 0.00

Photographs or Documents attached: No

Ref: [DCD238820030](#) **Defect Type:** DEFECT **Location Description:** Opposite house 108 **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 1.50 Width (m): 0.50 Depth (mm): 71.00

Comments: ?

Defect Date: 08-March-2023 **Defect Category:** BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 07/09/2022
Until Less Than: 07/09/2023

Section:
7065C0278_03 LOUGHINISLAND RD1: CRAWFORDSTOWN RD C288 TO ANNACLOY RD B2

Commencement date of Inspection:	03 Mar 2023	Inspect History ID & Description:	3101997 - 3 Monthly - WFE Safety Inspection of 3NRD-DOWN	Inspector Name:	[REDACTED]
Class:	C Class	Environment:	RURAL	Traffic Level:	Medium Traffic

Ref: [DCD238820034](#) **Defect Type:** DEFECT **Location Description:** Opposite house 108 **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 2.50 Width (m): 0.50 Depth (mm): 80.00

Comments: ?

Defect Date: 08-March-2023 **Defect Category:** BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23112A	^ 100mm bit. patch W/C & B/C 1-3 m2	1.25	SQ.M	L 2.50 W 0.50 D 0.00

Photographs or Documents attached: No

Ref: [DCD238820045](#) **Defect Type:** DEFECT **Location Description:** At house 77 **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 12.00 Width (m): 0.30 Depth (mm): 65.00

Comments: Previously recorded failed

Defect Date: 08-March-2023 **Defect Category:** BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23113A	^ 100mm bit. patch W/C & B/C 3-15 m2	3.60	SQ.M	L 12.00 W 0.30 D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 07/09/2022
Until Less Than: 07/09/2023

Section:
7065C0278_03 LOUGHINISLAND RD1: CRAWFORDSTOWN RD C288 TO ANNACLOY RD B2

Commencement date of Inspection:	03 Mar 2023	Inspect History ID & Description:	3101997 - 3 Monthly - WFE Safety Inspection of 3NRD-DOWN	Inspector Name:	[REDACTED]
Class:	C Class	Environment:	RURAL	Traffic Level:	Medium Traffic

Ref: [DCD238820048](#) **Defect Type:** DEFECT **Location Description:** At house 77 **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 2.50 Width (m): 0.70 Depth (mm): 60.00

Comments: Previously recorded failed

Defect Date: 08-March-2023 **Defect Category:** BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D23112A	^ 100mm bit. patch W/C & B/C 1-3 m2	1.75	SQ.M	L 2.50	W 0.70	D 0.00

Photographs or Documents attached: No

Ref: [DCD238820077](#) **Defect Type:** DEFECT **Location Description:** 100m after house 65 **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 10.00 Width (m): 0.60 Depth (mm): 75.00

Comments: Previously recorded failed

Defect Date: 08-March-2023 **Defect Category:** BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D23113A	^ 100mm bit. patch W/C & B/C 3-15 m2	6.00	SQ.M	L 10.00	W 0.60	D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 07/09/2022
Until Less Than: 07/09/2023

Section:
7065C0278_03 LOUGHINISLAND RD1: CRAWFORDSTOWN RD C288 TO ANNACLOY RD B2

Commencement date of Inspection:	03 Mar 2023	Inspect History ID & Description:	3101997 - 3 Monthly - WFE Safety Inspection of 3NRD-DOWN	Inspector Name:	[REDACTED]
Class:	C Class	Environment:	RURAL	Traffic Level:	Medium Traffic

Ref: [DCD238820080](#) **Defect Type:** DEFECT **Location Description:** 100m after house 65 **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 0.50 Width (m): 0.50 Depth (mm): 52.00

Comments: ?

Defect Date: 08-March-2023 **Defect Category:** BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Ref: [DCD238820091](#) **Defect Type:** DEFECT **Location Description:** 50m after house 65 **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 10.00 Width (m): 0.90 Depth (mm): 65.00

Comments: Take out slump in Road seal well

Defect Date: 08-March-2023 **Defect Category:** BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23113A	^ 100mm bit. patch W/C & B/C 3-15 m2	9.00	SQ.M	L 10.00 W 0.90 D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 07/09/2022
Until Less Than: 07/09/2023

Section:
7065C0278_03 LOUGHINISLAND RD1: CRAWFORDSTOWN RD C288 TO ANNACLOY RD B2

Commencement date of Inspection:	03 Mar 2023	Inspect History ID & Description:	3101997 - 3 Monthly - WFE Safety Inspection of 3NRD-DOWN	Inspector Name:	[REDACTED]
Class:	C Class	Environment:	RURAL	Traffic Level:	Medium Traffic

Ref: [DCD238820097](#)
Defect Type: DEFECT
Location Description: Opposite and above house 65
Priority: R2 - 5 Working days
Defect Dimensions: Length (m): 0.90 Width (m): 0.50 Depth (mm): 52.00
Comments: ?
Defect Date: 08-March-2023
Defect Category: BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00	W 0.00	D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 07/09/2022
Until Less Than: 07/09/2023

Section:
7065C0278_03 LOUGHINISLAND RD1: CRAWFORDSTOWN RD C288 TO ANNACLOY RD B2

Commencement date of Inspection: 01 Dec 2022 **Inspect History ID & Description:** 3096543 - 3 Monthly - Safety Inspection of 3NRD-DOWN **Inspector Name:** [REDACTED]

Class: C Class **Environment:** RURAL **Traffic Level:** Medium Traffic

Ref: [DCD67-3096543-37](#) **Defect Type:** DEFECT **Location Description:** at buckshead rd **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 1.50 Width (m): 0.30 Depth (mm): 51.00

Comments:
Defect Date: 01-December-2022 **Defect Category:** BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Ref: [DCD67-3096543-38](#) **Defect Type:** DEFECT **Location Description:** at buckshead rd **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 0.40 Width (m): 0.30 Depth (mm): 60.00

Comments:
Defect Date: 01-December-2022 **Defect Category:** BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 07/09/2022
Until Less Than: 07/09/2023

Section:
7065C0278_03 LOUGHINISLAND RD1: CRAWFORDSTOWN RD C288 TO ANNACLOY RD B2

Commencement date of Inspection: 01 Dec 2022 **Inspect History ID & Description:** 3096543 - 3 Monthly - Safety Inspection of 3NRD-DOWN **Inspector Name:** [REDACTED]

Class: C Class **Environment:** RURAL **Traffic Level:** Medium Traffic

Ref: [DCD67-3096543-39](#) **Defect Type:** DEFECT **Location Description:** opp buckshead **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 0.50 Width (m): 0.30 Depth (mm): 56.00

Comments: gully loose reset at manhole cover hole with mesh &cement flush to top of manhole

Defect Date: 01-December-2022 **Defect Category:** GULLY LID LOW (CGLO)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
U12260A	^ Reset gully top with riser	1.00	no	L 0.00	W 0.00	D 0.00
D51011A	^ 200mm patch 30/20 conc 0-1 m2	1.00	no	L 0.00	W 0.00	D 0.00

Photographs or Documents attached: No

Ref: [DCD67-3096543-40](#) **Defect Type:** DEFECT **Location Description:** 60m from buckshead rd **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 2.00 Width (m): 0.40 Depth (mm): 52.00

Comments:
Defect Date: 01-December-2022 **Defect Category:** BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00	W 0.00	D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 07/09/2022
Until Less Than: 07/09/2023

Section:
7065C0278_03 LOUGHINISLAND RD1: CRAWFORDSTOWN RD C288 TO ANNACLOY RD B2

Commencement date of Inspection: 01 Dec 2022 **Inspect History ID & Description:** 3096543 - 3 Monthly - Safety Inspection of 3NRD-DOWN **Inspector Name:** [REDACTED]

Class: C Class **Environment:** RURAL **Traffic Level:** Medium Traffic

Ref: [DCD67-3096543-41](#) **Defect Type:** DEFECT **Location Description:** opp 86 at gully **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 0.30 Width (m): 0.20 Depth (mm): 60.00

Comments:
Defect Date: 01-December-2022 **Defect Category:** BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Ref: [DCD67-3096543-42](#) **Defect Type:** DEFECT **Location Description:** at bridge after 86 **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 0.30 Width (m): 0.30 Depth (mm): 61.00

Comments:
Defect Date: 01-December-2022 **Defect Category:** BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 07/09/2022
Until Less Than: 07/09/2023

Section:
7065C0278_03 LOUGHINISLAND RD1: CRAWFORDSTOWN RD C288 TO ANNACLOY RD B2

Commencement date of Inspection: 01 Dec 2022 **Inspect History ID & Description:** 3096543 - 3 Monthly - Safety Inspection of 3NRD-DOWN **Inspector Name:** [REDACTED]

Class: C Class **Environment:** RURAL **Traffic Level:** Medium Traffic

Ref: DCD67-3096543-43	Defect Type: DEFECT	Location Description: at bridge after ho 86	Priority R4 - next available programme	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
---	-------------------------------	---	--	---	-------------------	--------------------

Comments: clean leaves and silt at outlets

Defect Date: 01-December-2022
Defect Category: VERGE OUTLET OVERGROWN (VOOG)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
X41001A	^ Responsive cleaning road outlet (No)	11.00	no	L 0.00	W 0.00	D 0.00

Photographs or Documents attached: No

Ref: DCD67-3096543-44	Defect Type: DEFECT	Location Description: at 65	Priority R3 - 4 Weeks	Defect Dimensions: Length (m): 0.40	Width (m): 0.30	Depth (mm): 32.00
---	-------------------------------	---------------------------------------	---------------------------------	--	------------------------	--------------------------

Comments:
Defect Date: 01-December-2022
Defect Category: BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00	W 0.00	D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 07/09/2022
Until Less Than: 07/09/2023

Section:
7065C0278_03 LOUGHINISLAND RD1: CRAWFORDSTOWN RD C288 TO ANNACLOY RD B2

Commencement date of Inspection: 01 Dec 2022 **Inspect History ID & Description:** 3096543 - 3 Monthly - Safety Inspection of 3NRD-DOWN **Inspector Name:** [REDACTED]

Class: C Class **Environment:** RURAL **Traffic Level:** Medium Traffic

Ref: [DCD67-3096543-45](#) **Defect Type:** DEFECT **Location Description:** at 65 **Priority:** R3 - 4 Weeks **Defect Dimensions:** Length (m): 0.40 Width (m): 0.40 Depth (mm): 30.00

Comments:
Defect Date: 01-December-2022 **Defect Category:** BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Ref: [DCD67-3096543-46](#) **Defect Type:** DEFECT **Location Description:** at 65 **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 0.80 Width (m): 0.50 Depth (mm): 51.00

Comments:
Defect Date: 01-December-2022 **Defect Category:** BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 07/09/2022
Until Less Than: 07/09/2023

Section:
7065C0278_03 LOUGHINISLAND RD1: CRAWFORDSTOWN RD C288 TO ANNACLOY RD B2

Commencement date of Inspection: 01 Dec 2022 **Inspect History ID & Description:** 3096543 - 3 Monthly - Safety Inspection of 3NRD-DOWN **Inspector Name:** [REDACTED]

Class: C Class **Environment:** RURAL **Traffic Level:** Medium Traffic

Ref: [DCD67-3096543-47](#) **Defect Type:** DEFECT **Location Description:** at 65 **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 1.60 Width (m): 0.50 Depth (mm): 52.00

Comments:
Defect Date: 01-December-2022 **Defect Category:** BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00	W 0.00	D 0.00

Photographs or Documents attached: No

Ref: [DCD67-3096543-48](#) **Defect Type:** DEFECT **Location Description:** at 65 **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 1.80 Width (m): 0.70 Depth (mm): 51.00

Comments:
Defect Date: 01-December-2022 **Defect Category:** BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D23112A	^ 100mm bit. patch W/C & B/C 1-3 m2	1.26	SQ.M	L 1.80	W 0.70	D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 07/09/2022
Until Less Than: 07/09/2023

Section:
7065C0278_03 LOUGHINISLAND RD1: CRAWFORDSTOWN RD C288 TO ANNACLOY RD B2

Commencement date of Inspection: 01 Dec 2022 **Inspect History ID & Description:** 3096543 - 3 Monthly - Safety Inspection of 3NRD-DOWN **Inspector Name:** [REDACTED]

Class: C Class **Environment:** RURAL **Traffic Level:** Medium Traffic

Ref: [DCD67-3096543-49](#) **Defect Type:** DEFECT **Location Description:** at 65 **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 0.80 Width (m): 0.50 Depth (mm): 51.00

Comments:
Defect Date: 01-December-2022 **Defect Category:** BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Ref: [DCD67-3096543-50](#) **Defect Type:** DEFECT **Location Description:** at 65 **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 0.90 Width (m): 0.50 Depth (mm): 53.00

Comments:
Defect Date: 01-December-2022 **Defect Category:** BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 07/09/2022
Until Less Than: 07/09/2023

Section:
7065C0278_03 LOUGHINISLAND RD1: CRAWFORDSTOWN RD C288 TO ANNACLOY RD B2

Commencement date of Inspection: 01 Dec 2022 **Inspect History ID & Description:** 3096543 - 3 Monthly - Safety Inspection of 3NRD-DOWN **Inspector Name:** [REDACTED]

Class: C Class **Environment:** RURAL **Traffic Level:** Medium Traffic

Ref: [DCD67-3096543-51](#) **Defect Type:** DEFECT **Location Description:** at 65 **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 0.80 Width (m): 0.40 Depth (mm): 51.00

Comments:
Defect Date: 01-December-2022 **Defect Category:** BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Ref: [DCD67-3096543-52](#) **Defect Type:** DEFECT **Location Description:** at 65 **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 0.80 Width (m): 0.20 Depth (mm): 60.00

Comments:
Defect Date: 01-December-2022 **Defect Category:** BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 07/09/2022
Until Less Than: 07/09/2023

Section:
7065C0278_03 LOUGHINISLAND RD1: CRAWFORDSTOWN RD C288 TO ANNACLOY RD B2

Commencement date of Inspection: 01 Dec 2022 **Inspect History ID & Description:** 3096543 - 3 Monthly - Safety Inspection of 3NRD-DOWN **Inspector Name:** [REDACTED]

Class: C Class **Environment:** RURAL **Traffic Level:** Medium Traffic

Ref: [DCD67-3096543-53](#) **Defect Type:** DEFECT **Location Description:** at 65 at f/h **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 1.00 Width (m): 0.50 Depth (mm): 51.00

Comments:
Defect Date: 01-December-2022 **Defect Category:** BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Ref: [DCD67-3096543-54](#) **Defect Type:** DEFECT **Location Description:** 55m after 65 **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 0.90 Width (m): 0.50 Depth (mm): 53.00

Comments:
Defect Date: 01-December-2022 **Defect Category:** BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 07/09/2022
Until Less Than: 07/09/2023

Section:
7065C0278_03 LOUGHINISLAND RD1: CRAWFORDSTOWN RD C288 TO ANNACLOY RD B2

Commencement date of Inspection: 01 Dec 2022 **Inspect History ID & Description:** 3096543 - 3 Monthly - Safety Inspection of 3NRD-DOWN **Inspector Name:** [REDACTED]

Class: C Class **Environment:** RURAL **Traffic Level:** Medium Traffic

Ref: [DCD67-3096543-55](#) **Defect Type:** DEFECT **Location Description:** 75m after 65 **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 11.00 Width (m): 0.70 Depth (mm): 65.00

Comments:
Defect Date: 01-December-2022 **Defect Category:** BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23113A	^ 100mm bit. patch W/C & B/C 3-15 m2	7.70	SQ.M	L 11.00 W 0.70 D 0.00

Photographs or Documents attached: No

Ref: [DCD67-3096543-56](#) **Defect Type:** DEFECT **Location Description:** 85m after 65 **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 7.00 Width (m): 0.50 Depth (mm): 98.00

Comments:
Defect Date: 01-December-2022 **Defect Category:** BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23113A	^ 100mm bit. patch W/C & B/C 3-15 m2	3.50	SQ.M	L 7.00 W 0.50 D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 07/09/2022
Until Less Than: 07/09/2023

Section:
7065C0278_03 LOUGHINISLAND RD1: CRAWFORDSTOWN RD C288 TO ANNACLOY RD B2

Commencement date of Inspection: 01 Dec 2022 **Inspect History ID & Description:** 3096543 - 3 Monthly - Safety Inspection of 3NRD-DOWN **Inspector Name:** [REDACTED]

Class: C Class **Environment:** RURAL **Traffic Level:** Medium Traffic

Ref: [DCD67-3096543-57](#) **Defect Type:** DEFECT **Location Description:** 100m after 65 **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 1.40 Width (m): 0.40 Depth (mm): 51.00

Comments:
Defect Date: 01-December-2022 **Defect Category:** BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Ref: [DCD67-3096543-58](#) **Defect Type:** DEFECT **Location Description:** at ho 77 **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 14.00 Width (m): 0.30 Depth (mm): 85.00

Comments:
Defect Date: 01-December-2022 **Defect Category:** BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23113A	^ 100mm bit. patch W/C & B/C 3-15 m2	4.20	SQ.M	L 14.00 W 0.30 D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 07/09/2022
Until Less Than: 07/09/2023

Section:
7065C0278_03 LOUGHINISLAND RD1: CRAWFORDSTOWN RD C288 TO ANNACLOY RD B2

Commencement date of Inspection: 01 Dec 2022 **Inspect History ID & Description:** 3096543 - 3 Monthly - Safety Inspection of 3NRD-DOWN **Inspector Name:** [REDACTED]

Class: C Class **Environment:** RURAL **Traffic Level:** Medium Traffic

Ref: [DCD67-3096543-59](#) **Defect Type:** DEFECT **Location Description:** at 77 **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 1.40 Width (m): 0.70 Depth (mm): 61.00

Comments:
Defect Date: 01-December-2022 **Defect Category:** BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Ref: [DCD67-3096543-60](#) **Defect Type:** DEFECT **Location Description:** at 77 **Priority:** R3 - 4 Weeks **Defect Dimensions:** Length (m): 2.90 Width (m): 0.20 Depth (mm): 33.00

Comments:
Defect Date: 01-December-2022 **Defect Category:** BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 07/09/2022
Until Less Than: 07/09/2023

Section:
7065C0278_03 LOUGHINISLAND RD1: CRAWFORDSTOWN RD C288 TO ANNACLOY RD B2

Commencement date of Inspection: 01 Dec 2022 **Inspect History ID & Description:** 3096543 - 3 Monthly - Safety Inspection of 3NRD-DOWN **Inspector Name:** [REDACTED]

Class: C Class **Environment:** RURAL **Traffic Level:** Medium Traffic

Ref: [DCD67-3096543-61](#) **Defect Type:** DEFECT **Location Description:** opp 79 **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 6.00 Width (m): 0.50 Depth (mm): 95.00

Comments:
Defect Date: 01-December-2022 **Defect Category:** BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23112A	^ 100mm bit. patch W/C & B/C 1-3 m2	3.00	SQ.M	L 6.00 W 0.50 D 0.00

Photographs or Documents attached: No

Ref: [DCD67-3096543-62](#) **Defect Type:** DEFECT **Location Description:** 40m below 79 **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 1.40 Width (m): 0.60 Depth (mm): 51.00

Comments:
Defect Date: 01-December-2022 **Defect Category:** BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 07/09/2022
Until Less Than: 07/09/2023

Section:
7065C0278_03 LOUGHINISLAND RD1: CRAWFORDSTOWN RD C288 TO ANNACLOY RD B2

Commencement date of Inspection: 01 Dec 2022 **Inspect History ID & Description:** 3096543 - 3 Monthly - Safety Inspection of 3NRD-DOWN **Inspector Name:** [REDACTED]

Class: C Class **Environment:** RURAL **Traffic Level:** Medium Traffic

Ref: [DCD67-3096543-63](#) **Defect Type:** DEFECT **Location Description:** 80m below 79 **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 5.50 Width (m): 0.50 Depth (mm): 70.00

Comments:
Defect Date: 01-December-2022 **Defect Category:** BITMAC DEPRESSED (CBDP)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23112A	^ 100mm bit. patch W/C & B/C 1-3 m2	2.75	SQ.M	L 5.50 W 0.50 D 0.00

Photographs or Documents attached: No

Ref: [DCD67-3096543-64](#) **Defect Type:** DEFECT **Location Description:** at pole 262 **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 0.70 Width (m): 0.20 Depth (mm): 52.00

Comments:
Defect Date: 01-December-2022 **Defect Category:** BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 07/09/2022
Until Less Than: 07/09/2023

Section:
7065C0278_03 LOUGHINISLAND RD1: CRAWFORDSTOWN RD C288 TO ANNACLOY RD B2

Commencement date of Inspection: 01 Dec 2022 **Inspect History ID & Description:** 3096543 - 3 Monthly - Safety Inspection of 3NRD-DOWN **Inspector Name:** [REDACTED]

Class: C Class **Environment:** RURAL **Traffic Level:** Medium Traffic

Ref: [DCD67-3096543-65](#) **Defect Type:** DEFECT **Location Description:** above pole 262 **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 2.20 Width (m): 0.30 Depth (mm): 53.00

Comments:
Defect Date: 01-December-2022 **Defect Category:** BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Ref: [DCD67-3096543-66](#) **Defect Type:** DEFECT **Location Description:** above pole 262 **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 2.90 Width (m): 0.60 Depth (mm): 55.00

Comments:
Defect Date: 01-December-2022 **Defect Category:** BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23112A	^ 100mm bit. patch W/C & B/C 1-3 m2	1.74	SQ.M	L 2.90 W 0.60 D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 07/09/2022
Until Less Than: 07/09/2023

Section:
7065C0278_03 LOUGHINISLAND RD1: CRAWFORDSTOWN RD C288 TO ANNACLOY RD B2

Commencement date of Inspection: 01 Dec 2022 **Inspect History ID & Description:** 3096543 - 3 Monthly - Safety Inspection of 3NRD-DOWN **Inspector Name:** [REDACTED]

Class: C Class **Environment:** RURAL **Traffic Level:** Medium Traffic

Ref: [DCD67-3096543-67](#) **Defect Type:** DEFECT **Location Description:** opp woodgrange rd **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 3.90 Width (m): 0.60 Depth (mm): 60.00

Comments: previously recorded as an r1 only half done

Defect Date: 01-December-2022 **Defect Category:** BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23112A	^ 100mm bit. patch W/C & B/C 1-3 m2	2.34	SQ.M	L 3.90 W 0.60 D 0.00

Photographs or Documents attached: No

Ref: [DCD67-3096543-68](#) **Defect Type:** DEFECT **Location Description:** at woodgrange **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 0.90 Width (m): 0.50 Depth (mm): 51.00

Comments:
Defect Date: 01-December-2022 **Defect Category:** BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 07/09/2022
Until Less Than: 07/09/2023

Section:
7065C0278_03 LOUGHINISLAND RD1: CRAWFORDSTOWN RD C288 TO ANNACLOY RD B2

Commencement date of Inspection: 01 Dec 2022 **Inspect History ID & Description:** 3096543 - 3 Monthly - Safety Inspection of 3NRD-DOWN **Inspector Name:** [REDACTED]

Class: C Class **Environment:** RURAL **Traffic Level:** Medium Traffic

Ref: [DCD67-3096543-69](#) **Defect Type:** DEFECT **Location Description:** at annacloy junction **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 1.80 Width (m): 1.00 Depth (mm): 51.00

Comments:
Defect Date: 01-December-2022
Defect Category: BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D23112A	^ 100mm bit. patch W/C & B/C 1-3 m2	1.80	SQ.M	L 1.80	W 1.00	D 0.00

Photographs or Documents attached: No

Ref: [DCD67-3096543-70](#) **Defect Type:** DEFECT **Location Description:** at annacloy junction **Priority:** R3 - 4 Weeks **Defect Dimensions:** Length (m): 0.70 Width (m): 0.30 Depth (mm): 43.00

Comments:
Defect Date: 01-December-2022
Defect Category: BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00	W 0.00	D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 07/09/2022
Until Less Than: 07/09/2023

Section:
7065C0278_03 LOUGHINISLAND RD1: CRAWFORDSTOWN RD C288 TO ANNACLOY RD B2

Commencement date of Inspection: 01 Dec 2022 **Inspect History ID & Description:** 3096543 - 3 Monthly - Safety Inspection of 3NRD-DOWN **Inspector Name:** [REDACTED]

Class: C Class **Environment:** RURAL **Traffic Level:** Medium Traffic

Ref: [DCD67-3096543-71](#) **Defect Type:** DEFECT **Location Description:** at marners autos **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 12.00 Width (m): 0.50 Depth (mm): 70.00

Comments:
Defect Date: 01-December-2022 **Defect Category:** BITMAC DEPRESSED (CBDP)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23113A	^ 100mm bit. patch W/C & B/C 3-15 m2	6.00	SQ.M	L 12.00 W 0.50 D 0.00

Photographs or Documents attached: No

Ref: [DCD67-3096543-72](#) **Defect Type:** DEFECT **Location Description:** at 154 **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 4.00 Width (m): 0.50 Depth (mm): 85.00

Comments:
Defect Date: 01-December-2022 **Defect Category:** BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23112A	^ 100mm bit. patch W/C & B/C 1-3 m2	2.00	SQ.M	L 4.00 W 0.50 D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 07/09/2022
Until Less Than: 07/09/2023

Section:
7065C0278_03 LOUGHINISLAND RD1: CRAWFORDSTOWN RD C288 TO ANNACLOY RD B2

Commencement date of Inspection:	Inspect History ID & Description:	3101650 - 1 Monthly - WFE Safety Inspection of 1NE-DOWN	Inspector Name:	[REDACTED]
---	--	---	------------------------	------------

Class: C Class	Environment: RURAL	Traffic Level: Medium Traffic
-----------------------	---------------------------	--------------------------------------

Type: Ad Hoc Defect						
Ref: DCD238808370	Defect Type: THIRD PARTY REFERRAL	Location Description: Opposite woodgrange Road	Priority: R4 - next available programme	Defect Dimensions:		
				Length (m):	Width (m):	Depth (mm):

Comments: Fire hydrant lid keeps bouncing out on wheel track

Defect Date: 22-February-2023	Defect Category: PREVIOUSLY RECORDED NOT DONE (PRND)
---	--

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 07/09/2022
Until Less Than: 07/09/2023

Section:
7065C0278_03 LOUGHINISLAND RD1: CRAWFORDSTOWN RD C288 TO ANNACLOY RD B2

Commencement date of Inspection:	Inspect History ID & Description:	3101493 - 3 Monthly - WFE Safety Inspection of 3NRA-DOWN	Inspector Name:	[REDACTED]
Class: C Class	Environment: RURAL	Traffic Level: Medium Traffic		

Type: Ad Hoc Defect

Ref: DCD238800268	Defect Type: THIRD PARTY REFERRAL	Location Description: Opposite woodgrange junction	Priority: R4 - next available programme	Defect Dimensions: Length (m): 0.10 Width (m): 0.10 Depth (mm): 25.00
---	---	--	---	--

Comments: Fire hydrant loose and rocking lid keeps bouncing out

Defect Date: 14-February-2023	Defect Category: UTILITY CABINET OPEN/DAMAGED (UCOD)
---	--

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 07/09/2022
Until Less Than: 07/09/2023

Section:
7065C0278_03 LOUGHINISLAND RD1: CRAWFORDSTOWN RD C288 TO ANNACLOY RD B2

Commencement date of Inspection: **Inspect History ID & Description:** 3101459 - 6 Monthly - WFE Safety Inspection of 6NV3-DOWN **Inspector Name:** [REDACTED]

Class: C Class **Environment:** RURAL **Traffic Level:** Medium Traffic

Type: Ad Hoc Defect

Ref: [DCD238797324](#) **Defect Type:** DEFECT **Location Description:** At micky marners cars sales **Priority:** R2 - 5 Working days **Defect Dimensions:**
Length (m): 12.00 **Width (m):** 0.50 **Depth (mm):** 62.00

Comments: Pipeline sinking will need bictmac

Defect Date: 10-February-2023 **Defect Category:** BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23113A	^ 100mm bit. patch W/C & B/C 3-15 m2	6.00	SQ.M	L 12.00 W 0.50 D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 07/09/2022
Until Less Than: 07/09/2023

Section:
7065C0278_03 LOUGHINISLAND RD1: CRAWFORDSTOWN RD C288 TO ANNACLOY RD B2

Commencement date of Inspection:	Inspect History ID & Description:	3096209 - 1 Monthly - Safety Inspection of 1NW-DOWN	Inspector Name:	[REDACTED]
---	--	---	------------------------	------------

Class: C Class	Environment: RURAL	Traffic Level: Medium Traffic
-----------------------	---------------------------	--------------------------------------

Type: Ad Hoc Defect

Ref: DCD76-3096209-40	Defect Type: DEFECT	Location Description: 150m after 146	Priority R2 - 5 Working days	Defect Dimensions: Length (m): 1.00	Width (m): 0.30	Depth (mm): 52.00
---	-------------------------------	--	--	--	------------------------	--------------------------

Comments:

Defect Date: 17-November-2022

Defect Category: BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Type: Ad Hoc Defect

Ref: DCD76-3096209-41	Defect Type: DEFECT	Location Description: 155m after 146	Priority R2 - 5 Working days	Defect Dimensions: Length (m): 1.10	Width (m): 0.50	Depth (mm): 78.00
---	-------------------------------	--	--	--	------------------------	--------------------------

Comments:

Defect Date: 17-November-2022

Defect Category: BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 07/09/2022
Until Less Than: 07/09/2023

Section:
7065C0278_03 LOUGHINISLAND RD1: CRAWFORDSTOWN RD C288 TO ANNACLOY RD B2

Commencement date of Inspection:	Inspect History ID & Description:	3096209 - 1 Monthly - Safety Inspection of 1NW-DOWN	Inspector Name:	[REDACTED]
---	--	---	------------------------	------------

Class: C Class	Environment: RURAL	Traffic Level: Medium Traffic
-----------------------	---------------------------	--------------------------------------

Type: Ad Hoc Defect

Ref: DCD76-3096209-42	Defect Type: DEFECT	Location Description: 156m after 146	Priority R2 - 5 Working days	Defect Dimensions: Length (m): 1.90 Width (m): 0.40 Depth (mm): 55.00
---	-------------------------------	--	--	--

Comments:

Defect Date: 17-November-2022

Defect Category: BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Type: Ad Hoc Defect

Ref: DCD76-3096209-43	Defect Type: DEFECT	Location Description: 160m after 146	Priority R2 - 5 Working days	Defect Dimensions: Length (m): 2.90 Width (m): 0.50 Depth (mm): 68.00
---	-------------------------------	--	--	--

Comments:

Defect Date: 17-November-2022

Defect Category: BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23112A	^ 100mm bit. patch W/C & B/C 1-3 m2	1.45	SQ.M	L 2.90 W 0.50 D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 07/09/2022
Until Less Than: 07/09/2023

Section:
7065C0278_03 LOUGHINISLAND RD1: CRAWFORDSTOWN RD C288 TO ANNACLOY RD B2

Commencement date of Inspection:	Inspect History ID & Description:	3096209 - 1 Monthly - Safety Inspection of 1NW-DOWN	Inspector Name:	[REDACTED]
Class: C Class	Environment: RURAL	Traffic Level: Medium Traffic		

Type: Ad Hoc Defect

Ref: DCD76-3096209-44	Defect Type: DEFECT	Location Description: 161m after 146	Priority R2 - 5 Working days	Defect Dimensions: Length (m): 1.00	Width (m): 0.30	Depth (mm): 52.00
---	-------------------------------	--	--	--	------------------------	--------------------------

Comments:

Defect Date: 17-November-2022

Defect Category: BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00	W 0.00	D 0.00

Photographs or Documents attached: No

Type: Ad Hoc Defect

Ref: DCD76-3096209-45	Defect Type: DEFECT	Location Description: 162m after 146	Priority R2 - 5 Working days	Defect Dimensions: Length (m): 1.80	Width (m): 0.30	Depth (mm): 51.00
---	-------------------------------	--	--	--	------------------------	--------------------------

Comments:

Defect Date: 17-November-2022

Defect Category: BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00	W 0.00	D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 07/09/2022
Until Less Than: 07/09/2023

Section:
7065C0278_03 LOUGHINISLAND RD1: CRAWFORDSTOWN RD C288 TO ANNACLOY RD B2

Commencement date of Inspection:	Inspect History ID & Description:	3096209 - 1 Monthly - Safety Inspection of 1NW-DOWN	Inspector Name:	[REDACTED]
---	--	---	------------------------	------------

Class: C Class	Environment: RURAL	Traffic Level: Medium Traffic
-----------------------	---------------------------	--------------------------------------

Type: Ad Hoc Defect

Ref: DCD76-3096209-46	Defect Type: DEFECT	Location Description: 170m after 146	Priority R2 - 5 Working days	Defect Dimensions: Length (m): 11.00	Width (m): 0.40	Depth (mm): 58.00
---	-------------------------------	--	--	---	------------------------	--------------------------

Comments:

Defect Date: 17-November-2022

Defect Category: BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23113A	^ 100mm bit. patch W/C & B/C 3-15 m2	4.40	SQ.M	L 11.00 W 0.40 D 0.00

Photographs or Documents attached: No

Type: Ad Hoc Defect

Ref: DCD76-3096209-47	Defect Type: DEFECT	Location Description: 180m after 146	Priority R2 - 5 Working days	Defect Dimensions: Length (m): 11.00	Width (m): 0.50	Depth (mm): 65.00
---	-------------------------------	--	--	---	------------------------	--------------------------

Comments:

Defect Date: 17-November-2022

Defect Category: BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23113A	^ 100mm bit. patch W/C & B/C 3-15 m2	5.50	SQ.M	L 11.00 W 0.50 D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 07/09/2022
Until Less Than: 07/09/2023

Section:
7065C0278_03 LOUGHINISLAND RD1: CRAWFORDSTOWN RD C288 TO ANNACLOY RD B2

Commencement date of Inspection:	Inspect History ID & Description:	3096209 - 1 Monthly - Safety Inspection of 1NW-DOWN	Inspector Name:	[REDACTED]
Class: C Class	Environment: RURAL	Traffic Level: Medium Traffic		

Type: Ad Hoc Defect

Ref: [DCD76-3096209-52](#) **Defect Type:** DEFECT **Location Description:** opp woodgrange rd **Priority:** R1 - 1 Calendar Day **Defect Dimensions:** Length (m): 3.10 Width (m): 0.60 Depth (mm): 125.00

Comments: passed to AB at 10.55 am

Defect Date: 17-November-2022 **Defect Category:** BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D23112A	^ 100mm bit. patch W/C & B/C 1-3 m2	1.86	SQ.M	L 3.10	W 0.60	D 0.00

Photographs or Documents attached: No

Type: Ad Hoc Defect

Ref: [DCD76-3096209-53](#) **Defect Type:** DEFECT **Location Description:** opp woodgrange rd **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 0.90 Width (m): 0.50 Depth (mm): 58.00

Comments:

Defect Date: 17-November-2022 **Defect Category:** BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00	W 0.00	D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 07/09/2022
Until Less Than: 07/09/2023

Section:
7065C0278_03 LOUGHINISLAND RD1: CRAWFORDSTOWN RD C288 TO ANNACLOY RD B2

Commencement date of Inspection:	Inspect History ID & Description:	3096209 - 1 Monthly - Safety Inspection of 1NW-DOWN	Inspector Name:	[REDACTED]
---	--	---	------------------------	------------

Class: C Class	Environment: RURAL	Traffic Level: Medium Traffic
-----------------------	---------------------------	--------------------------------------

Type: Ad Hoc Defect

Ref: DCD76-3096209-54	Defect Type: DEFECT	Location Description: opp woodgrange rd	Priority R2 - 5 Working days	Defect Dimensions: Length (m): 3.20	Width (m): 0.30	Depth (mm): 56.00
---	-------------------------------	---	--	--	------------------------	--------------------------

Comments:

Defect Date: 17-November-2022

Defect Category: BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Type: Ad Hoc Defect

Ref: DCD76-3096209-55	Defect Type: DEFECT	Location Description: at lane airsoft sign	Priority R2 - 5 Working days	Defect Dimensions: Length (m): 1.60	Width (m): 0.80	Depth (mm): 80.00
---	-------------------------------	--	--	--	------------------------	--------------------------

Comments:

Defect Date: 17-November-2022

Defect Category: BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23112A	^ 100mm bit. patch W/C & B/C 1-3 m2	1.28	SQ.M	L 1.60 W 0.80 D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 07/09/2022
Until Less Than: 07/09/2023

Section:
7065C0278_03 LOUGHINISLAND RD1: CRAWFORDSTOWN RD C288 TO ANNACLOY RD B2

Commencement date of Inspection: **Inspect History ID & Description:** 3095944 - 6 Monthly - Safety Inspection of 6NV1-DOWN **Inspector Name:** [REDACTED]

Class: C Class **Environment:** RURAL **Traffic Level:** Medium Traffic

Type: Ad Hoc Defect

Ref: [DCD76-3095944-49](#) **Defect Type:** DEFECT **Location Description:** 70m below ho 79 **Priority:** R2 - 5 Working days **Defect Dimensions:**
Length (m): 1.20 **Width (m):** 0.70 **Depth (mm):** 90.00

Comments:
Defect Date: 07-November-2022 **Defect Category:** BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00	W 0.00	D 0.00

Photographs or Documents attached: No





Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:

From: 07/09/2022

Until Less Than: 07/09/2023

Section:

7065C0278_03 LOUGHINISLAND RD1: CRAWFORDSTOWN RD C288 TO ANNACLOY RD B2

