



### Enquiries (By Road Section)

Road Section: 7035U0812\_14 CUSSICK ST1: LISBURN RD3 TO END

Date Range: From 12/07/2020 00:00:00 until less than 12/07/2022 23:59:59

Category: No filter

Type: No filter

Source: No filter

Location: No filter

Client Office: None, comments, Complaint, Compliment, Correspondence, Public Enquiry, Request For Service, Petition, Asset Request, Incident (major), Third Party Referral, Call Centre Request For Services, Call Centre Incident (Major), Call Centre Public Enquiry, FLOODING - Into inhabited building, FLOODING - Into other property, FLOODING - on road, RT Room Request For Service, RT Room Incident (Major), RT Room Public Enquiry, Public Traffic Signal Enquiry, Call Centre Traffic Signal Enquiry, RT Room Traffic Signal Enquiry, FLOODING - Into inhabited building, FLOODING - Into other property, FLOODING - on road, NON-FLOOD, NON-FLOOD, BELFAST SOUTH

Division: No filter

Assigned to: No filter

Enquiry Status: No filter

Enquiry ID:	Date/time Received:	Enquirer Name:	Input Type:	Enquiry Type:	Comments to Customer:	Location / Description:	Enquiry Received By:	Assigned to:	Date/time assigned	Internal Action Comments:	Status:
<a href="#">W211018383</a>	28/3/21 3:48 pm	(1)	Public Enquiry	Missing Or Faded Road Marks	?	?	PIP	BELFAST SOUTH	28/3/21 3:48 pm	Passed onto traffic section via email	Standard - Completed Enquiries

Date/time inspection: 29-Mar-2021  
 Inspector Name: All Users  
 NFA Category: Other Internal Business Unit notified  
 NFA Comments: Not a maintenance issue  
 Item Details:  
 Defect Reference:

PIP Comments: when entering to Cussick street coming from Tates avenue it is hard to get in as the road is usually blocked by the cars stopping on the traffic light on Lisbon road, this could be resolved if there are yellow box keep clear way road marks. can you please consider this marking?

Photographs or Documents attached: No

Enquiry ID:	Date/time Received:	Enquirer Name:	Input Type:	Enquiry Type:	Comments to Customer:	Location / Description:	Enquiry Received By:	Assigned to:	Date/time assigned	Internal Action Comments:	Status:
<a href="#">W211031704</a>	24/6/21 3:13 pm	(1) (2)	Call Centre Public Enquiry	Missing Or Faded Road Marks	?	20	PIP		24/6/21 3:13 pm	Refresh disabled bay	Standard - Completed Enquiries

Date/time inspection: 2-Jul-2021  
 Inspector Name: All Users  
 NFA Category:  
 NFA Comments:  
 Item Details: ROAD MARKINGS FADED (CYFD)  
 Defect Reference: [D218427504](#)

PIP Comments: After roadworks, the disabled parking bay just outside 20 Cussick Street (BT9 6DU) has had the &#39;DISABLED&#39; marking removed. The caller would like this to be repainted.


Photographs or Documents attached: No



### Enquiries (By Road Section)

Enquiry ID:	Date/time Received:	Enquirer Name:	Input Type:	Enquiry Type:	Comments to Customer:	Location / Description:	Enquiry Received By:	Assigned to:	Date/time assigned	Internal Action Comments:	Status:
<a href="#">W211034324</a>	10/7/21 12:23 pm	(1)	Public Enquiry	Pothole	an inspection has been carried out on 27-7-21 and an area of uneven paving has been marked for repair.	?	PIP		10/7/21 12:23 pm	Not connected to NIE excavation. It seems bad ground, needs test hole.	Standard - In Progress
					<b>Regards</b>						
					Date/time inspection:	Inspector Name:	NFA Category:	NFA Comments:	Item Details:	Defect Reference:	
					27-Jul-2021				PAVIORS MISSING (FPMI)	<a href="#">D218439672</a>	
<b>PIP Comments:</b> Brickwork paving sinking into the ground following recent work by NIE to lay cable. ;This is outside a disabled mans home, at a disabled parking space and poses a significant risk to the public. A child has already nearly fallen off his bike when his wheel went over the hole.											
<b>Photographs or Documents attached:</b>					Yes						

### Enquiries (By Road Section)





**Defect Inspections (By Road Section) Report**

Selection Criteria:

**Dates:**  
 From: 12/07/2020  
 Until Less Than: 12/07/2022

**Section:**  
 7035U0812\_14 CUSSICK ST1: LISBURN RD3 TO END

<b>Commencement date of Inspection:</b>	08 Feb 2022	<b>Inspect History ID &amp; Description:</b>	3091083 - Full Sector - Safety Inspection of 1S3X-BELFAST SOUTH-CYCLE 1	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	Unclassified	<b>Environment:</b>	URBAN	<b>Traffic Level:</b>	Low Traffic
<b>Comments:</b>					

**No Defects Found During Inspection**

**Photographs or Documents attached:**



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
 From: 12/07/2020  
 Until Less Than: 12/07/2022

**Section:**  
 7035U0812\_14 CUSSICK ST1: LISBURN RD3 TO END

<b>Commencement date of Inspection:</b>	14 Jul 2021	<b>Inspect History ID &amp; Description:</b>	3088121 - Full Sector - Safety Inspection of 1S3X-BELFAST SOUTH-CYCLE 1	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	Unclassified	<b>Environment:</b>	URBAN	<b>Traffic Level:</b>	Low Traffic

**Ref:** [DCD32-3088121-67](#)  
**Defect Type:** DEFECT  
**Location Description:** rhs 4m 20  
**Priority:** R2 - 5 Working days  
**Defect Dimensions:** Length (m): 0.20 Width (m): 0.20 Depth (mm): 70.00  
**Comments:** brick pav missing - 70mm  
**Defect Date:** 14-July-2021  
**Defect Category:** PAVIORS MISSING (FPMI)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D30061A	^ Temp. patch 6mm deferred set 0-1m2	1.00	no	L 0.00 W 0.00 D 0.00

**Photographs or Documents attached:** No

**Ref:** [DCD32-3088121-68](#)  
**Defect Type:** DEFECT  
**Location Description:** lhs sl 3  
**Priority:** R4 - next available programme  
**Defect Dimensions:** Length (m): Width (m): Depth (mm):  
**Comments:** cut back overgrown branches etc  
**Defect Date:** 14-July-2021  
**Defect Category:** TREES/BUSHES OVERHANGING PAVEMENT (TBOP)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
G01001A	^ Unplanned envr. work norm.hrs	1.00	HR	L 0.00 W 0.00 D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
 From: 12/07/2020  
 Until Less Than: 12/07/2022

**Section:**  
 7035U0812\_14 CUSSICK ST1: LISBURN RD3 TO END

<b>Commencement date of Inspection:</b>	14 Jul 2021	<b>Inspect History ID &amp; Description:</b>	3088121 - Full Sector - Safety Inspection of 1S3X-BELFAST SOUTH-CYCLE 1	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	Unclassified	<b>Environment:</b>	URBAN	<b>Traffic Level:</b>	Low Traffic

**Ref:** [DCD32-3088121-76](#)  
**Defect Type:** DEFECT  
**Location Description:** opp rhs 2m sl 1  
**Priority:** R2 - 5 Working days  
**Defect Dimensions:** Length (m): 0.20 Width (m): 0.20 Depth (mm): 51.00  
**Comments:** 51mmt ph @ cc patch  
**Defect Date:** 14-July-2021  
**Defect Category:** ASPHALT POTHOLE (CAPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D30061A	^ Temp. patch 6mm deferred set 0-1m2	1.00	no	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No

**Ref:** [DCD32-3088121-77](#)  
**Defect Type:** ROADS SERVICE REFERRAL  
**Location Description:**  
**Priority:** Not Applicable  
**Defect Dimensions:** Length (m): Width (m): Depth (mm):  
**Comments:** heavy parking fway/ cway edge + Bins / recycling boxes fway  
**Defect Date:** 14-July-2021  
**Defect Category:** STRETCH COMMENTS  
**Completion Comments:** emailed

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
 From: 12/07/2020  
 Until Less Than: 12/07/2022

**Section:**  
 7035U0812\_14 CUSSICK ST1: LISBURN RD3 TO END

<b>Commencement date of Inspection:</b>	14 Jan 2021	<b>Inspect History ID &amp; Description:</b>	3085210 - Full Sector - Safety Inspection of 1S3X-BELFAST SOUTH-CYCLE 1	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	Unclassified	<b>Environment:</b>	URBAN	<b>Traffic Level:</b>	Low Traffic

**Ref:** [DCD32-3085210-61](#)  
**Defect Type:** DEFECT  
**Location Description:** rhs 5m sl 3  
**Priority:** R2 - 5 Working days  
**Defect Dimensions:** Length (m): 0.20 Width (m): 0.20 Depth (mm): 51.00  
**Comments:** 51mmt ph  
**Defect Date:** 14-January-2021  
**Defect Category:** ASPHALT POTHOLE (FAPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
M12011A	^ 75mm asphalt patch 0-1 square metres	1.00	no	L 0.00 W 0.00 D 0.00

**Photographs or Documents attached:** No

**Ref:** [DCD32-3085210-62](#)  
**Defect Type:** ROADS SERVICE REFERRAL  
**Location Description:**  
**Priority:** Not Applicable  
**Defect Dimensions:** Length (m): Width (m): Depth (mm):  
**Comments:** heavy parking fway/ cway edge  
**Defect Date:** 14-January-2021  
**Defect Category:** STRETCH COMMENTS  
**Completion Comments:** emailed

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
 From: 12/07/2020  
 Until Less Than: 12/07/2022

**Section:**  
 7035U0812\_14 CUSSICK ST1: LISBURN RD3 TO END

<b>Commencement date of Inspection:</b>	15 Jul 2020	<b>Inspect History ID &amp; Description:</b>	3082313 - Full Sector - Safety Inspection of 1S3X-BELFAST SOUTH-CYCLE 1	<b>Inspector Name:</b>	[Redacted]
<b>Class:</b>	Unclassified	<b>Environment:</b>	URBAN	<b>Traffic Level:</b>	Low Traffic

<b>Ref:</b> <a href="#">DCD32-3082313-20</a>	<b>Defect Type:</b> ROADS SERVICE REFERRAL	<b>Location Description:</b> heavy parking cway/ bins + recycling boxes fway	<b>Priority:</b> Not Applicable	<b>Defect Dimensions:</b>		
<b>Comments:</b>				<b>Length (m):</b>	<b>Width (m):</b>	<b>Depth (mm):</b>
<b>Defect Date:</b> 15-July-2020	<b>Defect Category:</b> STRETCH COMMENTS	<b>Completion Comments:</b> emailed				

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

**Selection Criteria:**

**Dates:** From: 12/07/2020 Until Less Than: 12/07/2022

**Section:** 7035U0812\_14 CUSSICK ST1: LISBURN RD3 TO END

<b>Commencement date of Inspection:</b>	<b>Ad Hoc Defect - See Inspect History ID &amp; Description:</b>	<b>Ad Hoc Defect - No Inspection ID</b>	<b>Inspector Name:</b>
<b>Class:</b> Unclassified	<b>Environment:</b> URBAN	<b>Traffic Level:</b> Low Traffic	

<b>Ref:</b> <a href="#">D2112005</a>	<b>Defect Type:</b> DEFECT	<b>Location Description:</b> RHS 24 AND AT GABLE OF 24 BRICK PAVING SUNK AT GABLE OF 24	<b>Priority:</b> R2 - 5 Working days	<b>Defect Dimensions:</b> Length (m): 0.90    Width (m): 0.00    Depth (mm): 52.00		
<b>Comments:</b> ?						
<b>Defect Date:</b> 27-April-2021						
<b>Defect Category:</b> CHANNEL HIGH (FXHI)						

Repair Losl Code:	Repair Item Name:	Quantity	Units	Repair Measures		
M61211A	^ 250x125 dish channel >12m rad 0-5m	2.00	LIN.M	L 2.00	W 0.00	D 0.00
M64202A	^ Lift & relay drain channel >12m rad, >5m	8.00	LIN.M	L 8.00	W 0.00	D 0.00
M43102A	^ Lift & relay conc block paving >3m*	24.00	SQ.M	L 12.00	W 2.00	D 0.00
M43102A	^ Lift & relay conc block paving >3m*	4.86	SQ.M	L 2.70	W 1.80	D 0.00
Y32014A	Take up and dispose off site precast concrete kerbing and drainage channets.	2.00	m	L 2.00	W 0.00	D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

**Selection Criteria:**

**Dates:**  
 From: 12/07/2020  
 Until Less Than: 12/07/2022

**Section:**  
 7035U0812\_14 CUSSICK ST1: LISBURN RD3 TO END

<b>Commencement date of Inspection:</b>	<b>Ad Hoc Defect - See Inspect History ID &amp; Description:</b>	<b>Ad Hoc Defect - No Inspection ID</b>	<b>Inspector Name:</b> [REDACTED]
<b>Class:</b> Unclassified	<b>Environment:</b> URBAN	<b>Traffic Level:</b> Low Traffic	

**Ref:** [D2112009](#)

**Defect Type:** DEFECT

**Location Description:** CONCRETE SURROUND AT TOBY LIDS LOW TO BRICK PAVING AND CRACKED. AT No 40

**Priority:** R2 - 5 Working days

**Defect Dimensions:**  
 Length (m): 0.20    Width (m): 0.10    Depth (mm): 51.00

**Comments:** ?

**Defect Date:** 27-April-2021

**Defect Category:** CONCRETE DEFECTIVE (FCDF)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D30061A	^ Temp. patch 6mm deferred set 0-1m2	2.00	no	L 0.00    W 0.00    D 0.00

**Photographs or Documents attached:** No

**Ref:** [D218427504](#)

**Defect Type:** DEFECT

**Location Description:** 20

**Priority:** R4 - next available programme

**Defect Dimensions:**  
 Length (m):    Width (m):    Depth (mm):

**Comments:** Refresh disabled bay

**Defect Date:** 02-July-2021

**Defect Category:** ROAD MARKINGS FADED (CYFD)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
K38111A	1215x750mm cycle lane symbol	1.00	no	L 0.00    W 0.00    D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:** **Section:**  
 From: 12/07/2020 7035U0812\_14 CUSSICK ST1: LISBURN RD3 TO END  
 Until Less Than: 12/07/2022

<b>Commencement date of Inspection:</b>	<b>Ad Hoc Defect - See Inspect History ID &amp; Description:</b>	<b>Ad Hoc Defect - No Inspection ID</b>	<b>Inspector Name:</b>
<b>Class:</b> Unclassified	<b>Environment:</b> URBAN	<b>Traffic Level:</b> Low Traffic	

**Ref:** [D218439672](#)      **Defect Type:** DEFECT      **Location Description:** brick paviour missing at 20. stub and make safe.  
 Priority: R1 - 1 Calendar Day      **Defect Dimensions:** Length (m): 0.20      Width (m): 0.10      Depth (mm): 120.00  
 dish channel high at gully 10m rhs 24. dress ends with rapid set cement

**Comments:** ?  
**Defect Date:** 27-July-2021  
**Defect Category:** PAVIORS MISSING (FPMI)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D30061A	^ Temp. patch 6mm deferred set 0-1m2	1.00	no	L 0.00	W 0.00	D 0.00
M60130A	^ Repair kerb with rapid cement mortar	2.00	no	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:** From: 12/07/2020 Until Less Than: 12/07/2022

**Section:** 7035U0812\_14 CUSSICK ST1: LISBURN RD3 TO END

<b>Commencement date of Inspection:</b>	Ad Hoc Defect - See Inspect History ID & Description:	Ad Hoc Defect - No Inspection ID	<b>Inspector Name:</b>
<b>Class:</b> Unclassified	<b>Environment:</b> URBAN	<b>Traffic Level:</b> Low Traffic	

**Ref:** [D218439674](#)     **Defect Type:** DEFECT     **Location Description:** brick paving at No 20     **Priority:** R2 - 5 Working days     **Defect Dimensions:** Length (m): 0.20     Width (m): 0.10     Depth (mm): 55.00

**Comments:** ?

**Defect Date:** 27-July-2021     **Defect Category:** PAVIORS LOW (FPLO)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
M43101A	^ Lift & relay conc block paving 0-3m*	1.00	SQ.M	L 1.00     W 1.00     D 0.00

**Photographs or Documents attached:** No

**Ref:** [D218489867](#)     **Defect Type:** DEFECT     **Location Description:** footway around car parking park on cussick street - see map sent to 20/10/21     **Priority:** R4 - next available programme     **Defect Dimensions:** Length (m): 30.00     Width (m): 1.50     Depth (mm): 0.00

**Comments:** footway around car parking park on cussick street - see map sent to 20/10/21

**Defect Date:** 20-October-2021     **Defect Category:** WEEDS PRESENT ON INSPECTION (WPOF)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
G73202A	^ Scuffle weeds in footway >10m2	45.00	SQ.M	L 30.00     W 1.50     D 0.00

**Photographs or Documents attached:** No




### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 12/07/2020  
Until Less Than: 12/07/2022

**Section:**  
7035U0812\_14 CUSSICK ST1: LISBURN RD3 TO END





### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:** From: 12/07/2022 Until Less Than: 13/10/2023

**Section:** 7035U0812\_14 CUSSICK ST1: LISBURN RD3 TO END

<b>Commencement date of Inspection:</b>	07 Aug 2022	<b>Inspect History ID &amp; Description:</b>	3094093 - Full Sector - Safety Inspection of 1S3X-BELFAST SOUTH-CYCLE 1	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	Unclassified	<b>Environment:</b>	URBAN	<b>Traffic Level:</b>	Low Traffic

<b>Ref:</b>	<b>Defect Type:</b>	<b>Location Description:</b>	<b>Priority</b>	<b>Defect Dimensions:</b>		
<a href="#">DCD100-3094093-16</a>	DEFECT	cw opp 11. opp sl5	R2 - 5 Working days	<b>Length (m):</b> 0.30	<b>Width (m):</b> 0.20	<b>Depth (mm):</b> 52.00

**Comments:**

<b>Defect Date:</b>	<b>Defect Category:</b>
07-August-2022	BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No

<b>Ref:</b>	<b>Defect Type:</b>	<b>Location Description:</b>	<b>Priority</b>	<b>Defect Dimensions:</b>		
<a href="#">DCD100-3094093-17</a>	DEFECT	cw at 36	R2 - 5 Working days	<b>Length (m):</b> 0.10	<b>Width (m):</b> 0.10	<b>Depth (mm):</b> 55.00

**Comments:** 4no. stubs or epoxy resin repairs

<b>Defect Date:</b>	<b>Defect Category:</b>
07-August-2022	PAVIORS LOW (FPLO)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D30061A	^ Temp. patch 6mm deferred set 0-1m2	2.00	no	L 0.00	W 0.00	D 0.00
M60120A	^ Repair kerb with epoxy resin	2.00	no	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
 From: 12/07/2022  
 Until Less Than: 13/10/2023

**Section:**  
 7035U0812\_14 CUSSICK ST1: LISBURN RD3 TO END

<b>Commencement date of Inspection:</b>	07 Aug 2022	<b>Inspect History ID &amp; Description:</b>	3094093 - Full Sector - Safety Inspection of 1S3X-BELFAST SOUTH-CYCLE 1	<b>Inspector Name:</b>	[Redacted]
<b>Class:</b>	Unclassified	<b>Environment:</b>	URBAN	<b>Traffic Level:</b>	Low Traffic

<b>Ref:</b>	<b>Defect Type:</b>	<b>Location Description:</b>	<b>Priority</b>	<b>Defect Dimensions:</b>		
<a href="#">DCD100-3094093-18</a>	DEFECT	fw both sides of jnc Lisburn rd	R4 - next available programme	<b>Length (m):</b>	<b>Width (m):</b>	<b>Depth (mm):</b>

**Comments:** reset 2no. leaning traffic sign posts

<b>Defect Date:</b>	<b>Defect Category:</b>
07-August-2022	TRAFFIC SIGN POST DEFECTIVE (TSPD)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
R01001A	^ Unplanned Tr/sign repair norm. hrs	1.00	HR	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No