



Inspection Report

Inspection Date:	See Recorded Date	Inspect History ID: 3085370 - 3 Monthly - Safety Inspection of 3WRD-DOWN on 26 January 2021	Inspection Type:	3 Monthly - WFE Safety Inspection
			Inspector:	

Section Code:	Section Description:
7065C0308_02	CLONVARGHAN RD1: WOOD RD C324 TO SLIEVENISKY RD U152

Defect Ref:	Defect Type:	Comments:	Location Description:	Priority	Defect Dimensions:		
DCD49-3085370-39	DEFECT		CLONVARGHAN RD - BETWEEN BALLYWILLWILL RD+SLIEVEHANNY RD ON HILL	R4 - next available programme	Length	Width (m):	Depth (mm):

Recorded Date: 29-January-2021
Recorded By: [REDACTED]

DEBRIS ON SURFACE (DOSF)

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
V66000A	^ Place grit / salt pile	12.00	no	L 0.00	W 0.00	D 0.00	

Defect Ref:	Defect Type:	Comments:	Location Description:	Priority	Defect Dimensions:		
DCD49-3085416-26	DEFECT	ENQUIRY REF E2101128 - [REDACTED] / PLACE 1 ADDITIONAL PILE BETWEEN ENGLISH PUB + SPEED LIMIT SIGN	CLONVARGHAN RD - BETWEEN CHAPEL + BALLYWILLWILL RD	R4 - next available programme	Length (m):	Width (m):	Depth (mm):

Recorded Date: 05-February-2021
Recorded By: [REDACTED]

DEBRIS ON SURFACE (DOSF)

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures			
V66000A	^ Place grit / salt pile	5.00	no	L 0.00	W 0.00	D 0.00	

Inspection Date:	See Recorded Date	Inspect History ID: 3086265 - 3 Monthly - Safety Inspection of 3WRA-DOWN on 14 April 2021	Inspection Type:	3 Monthly - WFE Safety Inspection
			Inspector:	

Section Code: 7065C0308_02 Section Description: CLONVARAGHAN RD1: WOOD RD C324 TO SLIEVENISKY RD U152

Defect Ref: [DCD49-3086265-7](#) Defect Type: DEFECT Comments: CLEAN FWAY Location Description: CLONVARGHAN RD - FROM ENGLISHS PUB TO END FWAY AT HO NO 58 Priority: R4 - next available programme Defect Dimensions: Length (m): Width (m): Depth (mm):

Recorded Date: 15-April-2021 DEBRIS ON SURFACE (DOSF)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
G01001A	^ Unplanned envir. work norm.hrs (2-man operation)	7.50	HR	L 0.00 W 0.00 D 0.00

Inspection Date: 1-Apr-2021 Inspect History ID: 3086062 - 3 Monthly - Safety Inspection of 3WRC-DOWN on 25 March 2021 Inspection Type: 3 Monthly - WFE Safety Inspection Inspector: [REDACTED]

Section Code: 7065C0308_02 Section Description: CLONVARAGHAN RD1: WOOD RD C324 TO SLIEVENISKY RD U152

Defect Ref: [DCD49-3086062-108](#) Defect Type: DEFECT Comments: Location Description: AT SL 13 / BELOW JCT SLIEVEHANNY PARK Priority: R2 - 5 Working Defect Dimensions: Length: 0.70 Width (m): 0.32 Depth (mm): 65.00

Recorded Date: 01-April-2021 BITMAC POTHOLE (CBPH)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D24022A	^ 70mm bit. patch w/c 1-3 m2	1.26	SQ.M	L 2.10 W 0.60 D 0.00

Defect Ref: [DCD49-3086062-109](#) Defect Type: DEFECT Comments: Location Description: BETWEEN BT POLE NO 1519+1520 / 200M ABOVE+OPP HO NO 58 Priority: R2 - 5 Working Defect Dimensions: Length: 0.55 Width (m): 0.45 Depth (mm): 60.00

Recorded Date: 01-April-2021 BITMAC POTHOLE (CBPH)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D24021A	^ 70mm bit. patch w/c <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Inspection Date: 1-Apr-2021 Inspect History ID: 3086062 - 3 Monthly - Safety Inspection of 3WRC-DOWN on 25 March 2021

Inspection Type: 3 Monthly - WFE Safety Inspection

Inspector: [REDACTED]

Section Code: 7065C0308_02 Section Description: CLONVARAGHAN RD1: WOOD RD C324 TO SLIEVENISKY RD U152

Defect Ref:	Defect Type:	Comments:	Location Description:	Priority	Defect Dimensions:
DCD49-3086062-110	DEFECT		BETWEEN BT POLE NO 1519+1520 / 200M ABOVE + OPP HO NO 58	R2 - 5 Working	Length 1.75 Width (m): 0.30 Depth (mm): 60.00

Recorded Date: 01-April-2021 BITMAC EDGE DETERIORATION (CBED)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D24022A	^ 70mm bit. patch w/c 1-3 m2	2.20	SQ.M	L 4.40 W 0.50 D 0.00
D24022A	^ 70mm bit. patch w/c 1-3 m2	1.40	SQ.M	L 2.55 W 0.55 D 0.00
D24021A	^ 70mm bit. patch w/c <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Inspection Date: 1-Apr-2021 Inspect History ID: 3086062 - 3 Monthly - Safety Inspection of 3WRC-DOWN on 25 March 2021

Inspection Type: 3 Monthly - WFE Safety Inspection

Inspector: [REDACTED]

Section Code: 7065C0308_02 Section Description: CLONVARAGHAN RD1: WOOD RD C324 TO SLIEVENISKY RD U152

Defect Ref:	Defect Type:	Comments:	Location Description:	Priority	Defect Dimensions:
DCD49-3086062-111	DEFECT		ABOVE BT POLE NO 1520	R3 - 4 Weeks	Length 1.10 Width (m): 0.45 Depth (mm): 50.00

Recorded Date: 01-April-2021 BITMAC EDGE DETERIORATION (CBED)

Recorded By:

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D24022A	^ 70mm bit. patch w/c 1-3 m2	1.44	SQ.M	L 2.40 W 0.60 D 0.00
D24021A	^ 70mm bit. patch w/c <1 m2	1.00	no	L 0.00 W 0.00 D 0.00
D24021A	^ 70mm bit. patch w/c <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Defect Ref:

[DCD49-3086062-112](#)

Defect Type:	Comments:	Location Description:	Priority	Defect Dimensions:
DEFECT	PASSED TO O+M AT 1450 HRS (GJ)	23M ABOVE BT POLE NO 1522 / 250M ABOVE + OPP HO NO 58	R1 - 1 Calendar Day	Length (m): 0.87 Width (m): 0.61 Depth (mm): 105.00

Recorded Date:

01-April-2021

BITMAC POTHOLE (CBPH)

Recorded By:

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Inspection Date: 1-Apr-2021 Inspect History ID: 3086062 - 3 Monthly - Safety Inspection of 3WRC-DOWN on 25 March 2021

Inspection Type: 3 Monthly - WFE Safety Inspection

Inspector:

Section Code:

7065C0308_02

Section Description:

CLONVARAGHAN RD1: WOOD RD C324 TO SLIEVENISKY RD U152

Defect Ref:

[DCD49-3086062-113](#)

Defect Type:	Comments:	Location Description:	Priority	Defect Dimensions:
DEFECT		OPP HO NO 72 RHS	R2 - 5 Working	Length 8.00 Width (m): 0.30 Depth (mm): 100.00

Recorded Date:

01-April-2021

BITMAC EDGE DETERIORATION (CBED)

Recorded By:

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D23113A	^ 100mm bit. patch W/C & B/C 3-15 m2	4.05	SQ.M	L 9.00 W 0.45 D 0.00

Defect Ref:

[DCD49-3086062-114](#)

Defect Type:	Comments:	Location Description:	Priority	Defect Dimensions:
DEFECT		20M ABOVE + OPP	R3 - 4 Weeks	Length 0.50 Width (m): 0.31 Depth (mm): 40.00

Recorded Date: BITMAC POTHOLE
01-April-2021 (CBPH)

Recorded By:
[REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures				
D24023A	^ 70mm bit. patch w/c 3-15 m2	4.08	SQ.M	L 2.40	W 1.70	D 0.00		

Inspection Date:	1-Apr-2021	Inspect History ID:	3086062 - 3 Monthly - Safety Inspection of 3WRC-DOWN on 25 March 2021				Inspection Type:	3 Monthly - WFE Safety Inspection
						Inspector:	[REDACTED]	

Section Code:	7065C0308_02	Section Description:	CLONVARAGHAN RD1: WOOD RD C324 TO SLIEVENISKY RD U152				
---------------	--------------	----------------------	---	--	--	--	--

Defect Ref:	Defect Type:	Comments:	Location Description:	Priority	Defect Dimensions:					
DCD49-3086062-115	DEFECT		AT ENT HO NO 76	R2 - 5 Working	Length	0.80	Width (m):	0.60	Depth (mm):	54.00

Recorded Date: BITMAC POTHOLE
01-April-2021 (CBPH)

Recorded By:
[REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures				
D24023A	^ 70mm bit. patch w/c 3-15 m2	4.64	SQ.M	L 2.90	W 1.60	D 0.00		

Defect Ref:	Defect Type:	Comments:	Location Description:	Priority	Defect Dimensions:					
DCD49-3086062-116	DEFECT		30M ABOVE ENT HO NO 76	R3 - 4 Weeks	Length	0.75	Width (m):	0.33	Depth (mm):	35.00

Recorded Date: BITMAC POTHOLE
01-April-2021 (CBPH)

Recorded By:
[REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures				
D27012A	^ 40mm bit patch w/c 1-3 m2	2.11	SQ.M	L 2.35	W 0.90	D 0.00		

Inspection Date:	1-Apr-2021	Inspect History ID:	3086062 - 3 Monthly - Safety Inspection of 3WRC-DOWN on 25 March 2021				Inspection Type:	3 Monthly - WFE Safety Inspection
------------------	------------	---------------------	---	--	--	--	------------------	-----------------------------------

Section Code: **7065C0308_02** Section Description: **CLONVARAGHAN RD1: WOOD RD C324 TO SLIEVENISKY RD U152**

Defect Ref: [DCD49-3086062-117](#) Defect Type: DEFECT Comments: Location Description: **15M ABOVE+OPP BT POLE NO 1543** Priority: **R2 - 5 Working** Defect Dimensions: Length: **0.75** Width (m): **0.30** Depth (mm): **75.00**

Recorded Date: **01-April-2021** BITMAC EDGE DETERIORATION (CBED)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Defect Ref: [DCD49-3086062-118](#) Defect Type: DEFECT Comments: Location Description: **15M ABOVE BT POLE NO 1544** Priority: **R2 - 5 Working** Defect Dimensions: Length: **0.60** Width (m): **0.48** Depth (mm): **60.00**

Recorded Date: **01-April-2021** BITMAC EDGE DETERIORATION (CBED)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D24021A	^ 70mm bit. patch w/c <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Inspection Date: **7-Apr-2021** Inspect History ID: **3086062 - 3 Monthly - Safety Inspection of 3WRC-DOWN on 25 March 2021**

Inspection Type: **3 Monthly - WFE Safety Inspection**
Inspector: [REDACTED]

Section Code: **7065C0308_03** Section Description: **CLONVARAGHAN RD1: SLIEVENISKY RD U152 TO BOUNDARY**

Defect Ref: [DCD49-3086062-137](#) Defect Type: DEFECT Comments: Location Description: **AT BT POLE NO 1643 / 250M ABOVE JCT MACNISH RD** Priority: **R2 - 5 Working** Defect Dimensions: Length: **12.00** Width (m): **0.30** Depth (mm): **90.00**

Recorded Date: BITMAC EDGE DETERIORATION

07-April-2021

DEFECTS
(CBED)

Recorded By:

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures				
D71023A	^ Velocity patch 3-15 m2	11.00	SQ.M	L 20.00	W 0.55	D 0.00		
D71023A	^ Velocity patch 3-15 m2	9.35	SQ.M	L 17.00	W 0.55	D 0.00		
D71024A	^ Velocity patch 15-50 m2	16.00	SQ.M	L 40.00	W 0.40	D 0.00		
D71022A	^ Velocity patch 1-3 m2	2.00	SQ.M	L 2.50	W 0.80	D 0.00		

Inspection Date: 7-Apr-2021 Inspect History ID: 3086062 - 3 Monthly - Safety Inspection of 3WRC-DOWN on 25 March 2021

Inspection
Time:
Inspector:

3 Monthly - WFE Safety
Inspection

Section Code:
7065C0308_03

Section Description:
CLONVARAGHAN RD1: SLIEVENISKY RD U152 TO BOUNDARY

Defect Ref: [DCD49-3086062-138](#) Defect Type: DEFECT Comments: VERGE OVERIDDEN+WASHINGS ON CWAY / SCRAPE+CLEAN ALONG ROAD EDGE / REQUIRE MINI DIGGER Location Description: BETWEEN BT POLE NO 1642+1643 / 200M ABOVE JCT MACNISH RD LHS Priority: R4 - next available programme Defect Dimensions: Length (m): 30.00 Width (m): 1.00 Depth (mm): 100.00

Recorded Date: 07-April-2021 Defect Type: GRASS VERGE RUTTED (VGRT)

Recorded By:

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures				
U01001A	^ Unplanned drainage works norm.hrs (2-man operation)	4.00	HR	L 0.00	W 0.00	D 0.00		
X50536A	^ Scrape clean & sweep road edge 0-20m	35.00	no	L 0.00	W 0.00	D 0.00		

Defect Ref: [DCD49-3086062-139](#) Defect Type: DEFECT Comments: Location Description: 18M ABOVE+OPP BT POLE NO 1644 / OPP SHED Priority: R2 - 5 Working Defect Dimensions: Length 0.22 Width (m): 0.20 Depth (mm): 52.00

Recorded Date: 07-April-2021 Defect Type: BITMAC POTHOLE (CBPH)

Recorded By:

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D71022A	^ Velocity patch 1-3 m2	1.68	SQ.M	L 1.40 W 1.20 D 0.00

Inspection Date: 7-Apr-2021 Inspect History ID: 3086062 - 3 Monthly - Safety Inspection of 3WRC-DOWN on 25 March 2021

Inspection Type: 3 Monthly - WFE Safety Inspection

Inspector: [REDACTED]

Section Code: 7065C0308_03 Section Description: CLONVARAGHAN RD1: SLIEVENISKY RD U152 TO BOUNDARY

Defect Ref:	Defect Type:	Comments:	Location Description:	Priority	Defect Dimensions:
DCD49-3086062-140	DEFECT		BELOW ENT HO NO 136A	R2 - 5 Working	Length 4.00 Width (m): 0.30 Depth (mm): 75.00

Recorded Date: 07-April-2021
 Recorded By: [REDACTED]
 BITMAC EDGE DETERIORATION (CBED)

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D71023A	^ Velocity patch 3-15 m2	3.50	SQ.M	L 7.00 W 0.50 D 0.00

Defect Ref:	Defect Type:	Comments:	Location Description:	Priority	Defect Dimensions:
DCD49-3086062-141	DEFECT		8M ABOVE+OPP ENT HO NO 136A	R2 - 5 Working	Length 1.00 Width (m): 0.56 Depth (mm): 65.00

Recorded Date: 07-April-2021
 Recorded By: [REDACTED]
 BITMAC POTHOLE (CBPH)

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D71023A	^ Velocity patch 3-15 m2	4.50	SQ.M	L 6.00 W 0.75 D 0.00
D71021A	^ Velocity patch 0-1m2	1.00	no	L 0.00 W 0.00 D 0.00

Inspection Date: 7-Apr-2021 Inspect History ID: 3086062 - 3 Monthly - Safety Inspection of 3WRC-DOWN on 25 March 2021

Inspection Type: 3 Monthly - WFE Safety Inspection

Inspector: [REDACTED]

Section Code: 7065C0308_03 Section Description: CLONVARAGHAN RD1: SLIEVENISKY RD U152 TO BOUNDARY

Defect Ref: [DCD49-3086062-142](#) Defect Type: DEFECT Comments: Location Description: ABOVE ENT LANE TO HO NO 138 ON BEND LHS Priority: R2 - 5 Working Defect Dimensions: Length 12.00 Width (m): 0.30 Depth (mm): 60.00

Recorded Date: 07-April-2021 BITMAC EDGE DETERIORATION (CBED)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D71023A	^ Velocity patch 3-15 m2	9.00	SQ.M	L 18.00 W 0.50 D 0.00

Inspection Date: 22-Jul-2021 Inspect History ID: 3087546 - 3 Monthly - Safety Inspection of 3WRC-DOWN on 08 July 2021 Inspection Type: 3 Monthly - WFE Safety Inspection Inspector: [REDACTED]

Section Code: 7065C0308_01 Section Description: CLONVARAGHAN RD1: BALLYLOUGH RD B175 TO WOOD RD C324

Defect Ref: [DCD49-3087546-48](#) Defect Type: DEFECT Comments: Location Description: 180M FROM JCT BALLYLOUGH RD AT LANE LHS Priority: R3 - 4 Weeks Defect Dimensions: Length 0.60 Width (m): 0.35 Depth (mm): 40.00

Recorded Date: 22-July-2021 BITMAC EDGE DETERIORATION (CBED)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D24021A	^ 70mm bit. patch w/c <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Defect Ref: [DCD49-3087546-46](#) Defect Type: THIRD PARTY REFERRAL Comments: BT - CWAY OPENING 1.4/0.7/60MM Location Description: 130M FROM JCT BALLYLOUGH RD Priority: R4 - next available programme Defect Dimensions: Length (m): 1.40 Width (m): 0.70 Depth (mm): 60.00

Recorded Date: 22-July-2021 SERVICE OPENING DEFECTIVE/HAZARDOUS (SODF)

Recorded By: [REDACTED]

Inspection Date: 22-Jul-2021 Inspect History ID: 3087546 - 3 Monthly - Safety Inspection of 3WRC-DOWN on 08 July 2021

Inspection Type: 3 Monthly - WFE Safety Inspection
Inspector: [REDACTED]

Section Code: 7065C0308_01 Section Description: CLONVARAGHAN RD1: BALLYLOUGH RD B175 TO WOOD RD C324

Defect Ref: [DCD49-3087546-47](#) Defect Type: DEFECT Comments: Location Description: 170M FROM JCT BALLYLOUGH RD Priority: R2 - 5 Working Defect Dimensions: Length: 0.45 Width (m): 0.36 Depth (mm): 60.00

Recorded Date: 22-July-2021 BITMAC POTHOLE (CBPH)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D24022A	^ 70mm bit. patch w/c 1-3 m2	1.82	SQ.M	L 2.60 W 0.70 D 0.00

Section Code: 7065C0308_03 Section Description: CLONVARAGHAN RD1: SLIEVENISKY RD U152 TO BOUNDARY

Defect Ref: [DCD49-3087546-49](#) Defect Type: DEFECT Comments: Location Description: ABOVE ENT TO LANE NO 138 Priority: R3 - 4 Weeks Defect Dimensions: Length: 3.30 Width (m): 0.30 Depth (mm): 50.00

Recorded Date: 22-July-2021 BITMAC EDGE DETERIORATION (CBED)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D71023A	^ Velocity patch 3-15 m2	4.00	SQ.M	L 8.00 W 0.50 D 0.00

Inspection Date: 22-Jul-2021 Inspect History ID: 3087546 - 3 Monthly - Safety Inspection of 3WRC-DOWN on 08 July 2021

Inspection Type: 3 Monthly - WFE Safety Inspection
Inspector: [REDACTED]

Section Code: 7065C0308_03 Section Description: CLONVARAGHAN RD1: SLIEVENISKY RD U152 TO BOUNDARY

Defect Ref: [DCD49-3087546-50](#) Defect Type: DEFECT Comments: Location Description: 30M ABOVE JCT MACNISH RD Priority: R3 - 4 Weeks Defect Dimensions: Length 0.85 Width (m): 0.35 Depth (mm): 35.00

Recorded Date: 22-July-2021 BITMAC POTHOLE (CBPH)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D71023A	^ Velocity patch 3-15 m2	6.45	SQ.M	L 4.30 W 1.50 D 0.00
D71022A	^ Velocity patch 1-3 m2	1.87	SQ.M	L 1.70 W 1.10 D 0.00

Defect Ref: [DCD49-3087546-51](#) Defect Type: DEFECT Comments: Location Description: OPP JCT MACNISH RD Priority: R3 - 4 Weeks Defect Dimensions: Length 0.46 Width (m): 0.28 Depth (mm): 50.00

Recorded Date: 22-July-2021 BITMAC EDGE DETERIORATION (CBED)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D71021A	^ Velocity patch 0-1m2	1.00	no	L 0.00 W 0.00 D 0.00

Inspection Date: 22-Jul-2021 Inspect History ID: 3087546 - 3 Monthly - Safety Inspection of 3WRC-DOWN on 08 July 2021 Inspection Type: 3 Monthly - WFE Safety Inspection Inspector: [REDACTED]

Section Code: 7065C0308_03 Section Description: CLONVARAGHAN RD1: SLIEVENISKY RD U152 TO BOUNDARY

Defect Ref: [DCD49-3087546-52](#) Defect Type: DEFECT Comments: REPLACING MISSING MARKER POSTS Location Description: OPP HO NO 188 ON BEND / BELOW SEACONNELL Priority: R4 - next available programme Defect Dimensions: Length (m): Width (m): Depth (mm):

Recorded Date: 22-July-2021 VERGE MARKER POST MISSING (VNMI)

Recorded By:

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
R42100A	^ Type 1 UPVC marker post	6.00	no	L 0.00 W 0.00 D 0.00

Defect Ref:	Defect Type:	Comments:	Location Description:	Priority	Defect Dimensions:
DCD49-3087546-53	DEFECT		OPP TWIN LANES / BELOW SEACONNEL	R3 - 4 Weeks	Length 4.00 Width (m): 0.30 Depth (mm): 50.00

Recorded Date: 22-July-2021
BITMAC EDGE DETERIORATION (CBED)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D71023A	^ Velocity patch 3-15 m2	6.30	SQ.M	L 14.00 W 0.45 D 0.00

Section Code:	Section Description:
7065C0308_02	CLONVARAGHAN RD1: WOOD RD C324 TO SLIEVENISKY RD U152

Inspection Date:	22-Jul-2021	Inspect History ID:	3087546 - 3 Monthly - Safety Inspection of 3WRC-DOWN on 08 July 2021	Inspection Type:	3 Monthly - WFE Safety Inspection
				Inspector:	[REDACTED]

Section Code:	Section Description:
7065C0308_02	CLONVARAGHAN RD1: WOOD RD C324 TO SLIEVENISKY RD U152

Defect Ref:	Defect Type:	Comments:	Location Description:	Priority	Defect Dimensions:
DCD49-3087546-54	DEFECT		50M BELOW+OPP LANE NO 87	R3 - 4 Weeks	Length 3.00 Width (m): 0.40 Depth (mm): 50.00

Recorded Date: 22-July-2021
BITMAC EDGE DETERIORATION (CBED)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D71023A	^ Velocity patch 3-15 m2	14.00	SQ.M	L 14.00 W 1.00 D 0.00
D71021A	^ Velocity patch 0-1m2	1.00	no	L 0.00 W 0.00 D 0.00

Defect Ref:	Defect Type:	Comments:	Location Description:	Priority	Defect Dimensions:
DCD49-3087546-55	DEFECT		100M BELOW+OPP	R3 - 4 Weeks	Length 0.35 Width (m): 0.22 Depth (mm): 45.00

Recorded Date: BITMAC POTHOLE
22-July-2021 (CBPH)

Recorded By:
[REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures					
D71021A	^ Velocity patch 0-1m2	1.00	no	L	0.00	W	0.00	D	0.00

Inspection Date: 22-Jul-2021 **Inspect History ID:** 3087546 - 3 Monthly - Safety Inspection of 3WRC-DOWN on 08 July 2021 **Inspection Type:** 3 Monthly - WFE Safety Inspection
Inspector: [REDACTED]

Section Code: 7065C0308_02 **Section Description:** CLONVARAGHAN RD1: WOOD RD C324 TO SLIEVENISKY RD U152

Defect Ref:	Defect Type:	Comments:	Location Description:	Priority	Defect Dimensions:			
DCD49-3087546-56	DEFECT		50M ABOVE ENT HO NO 58	R2 - 5 Working	Length	2.00	Width (m): 0.30	Depth (mm): 90.00

Recorded Date: BITMAC EDGE
22-July-2021 DETERIORATION
(CBED)

Recorded By:
[REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures					
D23113A	^ 100mm bit. patch W/C & B/C 3-15 m2	5.00	SQ.M	L	5.00	W	1.00	D	0.00

Defect Ref:	Defect Type:	Comments:	Location Description:	Priority	Defect Dimensions:			
DCD49-3087546-57	DEFECT		20M FROM ENT HO NO 58	R3 - 4 Weeks	Length	0.60	Width (m): 0.30	Depth (mm): 45.00

Recorded Date: BITMAC EDGE
22-July-2021 DETERIORATION
(CBED)

Recorded By:
[REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures					
D71023A	^ Velocity patch 3-15 m2	5.00	SQ.M	L	5.00	W	1.00	D	0.00

Inspection Date: 22-Jul-2021 Inspect History ID: 3087546 - 3 Monthly - Safety Inspection of 3WRC-DOWN on 08 July 2021

Inspection Type: 3 Monthly - WFE Safety Inspection

Inspector: [REDACTED]

Section Code: 7065C0308_02 Section Description: CLONVARAGHAN RD1: WOOD RD C324 TO SLIEVENISKY RD U152

Defect Ref: [DCD49-3087546-58](#) Defect Type: DEFECT Comments: Location Description: BETWEEN ENGLISHS PUB + JCT BALLYWILLWILL RD Priority: R3 - 4 Weeks Defect Dimensions: Length: 0.20 Width (m): 0.20 Depth (mm): 25.00

Recorded Date: 22-July-2021 BITMAC POTHOLE (CBPH)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D27011A	^ 40mm bit patch w/c 0-1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Inspection Date: 14-Oct-2021 Inspect History ID: 3089014 - 3 Monthly - Safety Inspection of 3WRC-DOWN on 12 October 2021

Inspection Type: 3 Monthly - WFE Safety Inspection

Inspector: [REDACTED]

Section Code: 7065C0308_03 Section Description: CLONVARAGHAN RD1: SLIEVENISKY RD U152 TO BOUNDARY

Defect Ref: [DCD49-3089014-20](#) Defect Type: DEFECT Comments: MARKER POSTS PULLED OUT / RESET Location Description: OPP HO NO 118 Priority: R4 - next available programme Defect Dimensions: Length (m): Width (m): Depth (mm):

Recorded Date: 14-October-2021 VERGE MARKER POST DISPLACED (VNDI)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
R42100A	^ Type 1 UPVC marker post	8.00	no	L 0.00 W 0.00 D 0.00

Defect Ref: [DCD49-3089014-18](#) Defect Type: DEFECT Comments: Location Description: OPP BT POLE NO Priority: R3 - 4 Weeks Defect Dimensions: Length: 15.00 Width (m): 0.30 Depth (mm): 40.00

1649 / 200M
 ABOVE+OPP
 COTTAGES RHS

Recorded Date: BITMAC EDGE
 DETERIORATION
 14-October-2021 (CBED)

Recorded By:
 [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures					
D71024A	^ Velocity patch 15-50 m2	20.40	SQ.M	L	34.00	W	0.60	D	0.00

Inspection Date: 14-Oct-2021 Inspect History ID: 3089014 - 3 Monthly - Safety Inspection of 3WRC-DOWN on 12 October 2021
 Inspection Type: 3 Monthly - WFE Safety Inspection
 Inspector: [REDACTED]

Section Code: 7065C0308_03
 Section Description: CLONVARAGHAN RD1: SLIEVENISKY RD U152 TO BOUNDARY

Defect Ref: [DCD49-3089014-19](#)
 Defect Type: DEFECT
 Comments:
 Location Description: 200M ABOVE JCT MACNISH RD IN HOLLOW
 Priority: R4 - next available programme
 Defect Dimensions:
 Length: Width (m): Depth (mm):

Recorded Date: GULLY BLOCKED
 14-October-2021 (CGBL)

Recorded By:
 [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures					
X77001A	^ Responsive cleaning of gully surround	2.00	no	L	0.00	W	0.00	D	0.00

Section Code: 7065C0308_02
 Section Description: CLONVARAGHAN RD1: WOOD RD C324 TO SLIEVENISKY RD U152

Defect Ref: [DCD49-3089014-21](#)
 Defect Type: DEFECT
 Comments:
 Location Description: AT LANE NO 87
 Priority: R3 - 4 Weeks
 Defect Dimensions:
 Length: 0.35 Width (m): 0.26 Depth (mm): 40.00

Recorded Date: BITMAC POTHOLE
 14-October-2021 (CBPH)

Recorded By:

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures				
D71022A	^ Velocity patch 1-3 m2	1.80	SQ.M	L 3.00	W 0.60	D 0.00		

Inspection Date: 14-Oct-2021 Inspect History ID: 3089014 - 3 Monthly - Safety Inspection of 3WRC-DOWN on 12 October 2021

Inspection Type: 3 Monthly - WFE Safety Inspection
Inspector: [REDACTED]

Section Code: 7065C0308_02 Section Description: CLONVARAGHAN RD1: WOOD RD C324 TO SLIEVENISKY RD U152

Defect Ref:	Defect Type:	Comments:	Location Description:	Priority	Defect Dimensions:			
DCD49-3089014-22	DEFECT		AT LANE NO 87 AT GULLY	R3 - 4 Weeks	Length	0.30	Width (m): 0.25	Depth (mm): 35.00

Recorded Date: 14-October-2021
Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures				
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00	W 0.00	D 0.00		
U12161A	^ Reset c/way gully top 0-150mm	1.00	no	L 0.00	W 0.00	D 0.00		

Defect Ref:	Defect Type:	Comments:	Location Description:	Priority	Defect Dimensions:			
DCD49-3089014-24	DEFECT		AT BT POLE NO 1535 / OPP WOODEN MOBILE HOME	R2 - 5 Working	Length	20.00	Width (m): 0.30	Depth (mm): 80.00

Recorded Date: 14-October-2021
Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures				
D71023A	^ Velocity patch 3-15 m2	13.80	SQ.M	L 23.00	W 0.60	D 0.00		

Inspection Date: 14-Oct-2021 Inspect History ID: 3089014 - 3 Monthly - Safety Inspection of 3WRC-DOWN on 12 October 2021

Inspection Type: 3 Monthly - WFE Safety Inspection
Inspector: John McCauley

Section Code: 7065C0308_02 Section Description: CLONVARAGHAN RD1: WOOD RD C324 TO SLIEVENISKY RD U152

Defect Ref: [DCD49-3089014-25](#) Defect Type: DEFECT Comments: Location Description: BELOW BT POLE NO 1536 / OPP WOODEN MOBILE HOME Priority: R2 - 5 Working Defect Dimensions: Length 6.00 Width (m): 0.30 Depth (mm): 55.00

Recorded Date: 14-October-2021 BITMAC EDGE DETERIORATION (CBED)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D71023A	^ Velocity patch 3-15 m2	5.00	SQ.M	L 10.00 W 0.50 D 0.00

Defect Ref: [DCD49-3089014-26](#) Defect Type: DEFECT Comments: Location Description: 3M FROM+OPP SL 12 / ABOVE MCVIEGHS SHOP / CLONVARGHAN Priority: R2 - 5 Working Defect Dimensions: Length 0.40 Width (m): 0.21 Depth (mm): 60.00

Recorded Date: 14-October-2021 BITMAC POTHOLE (CBPH)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D24022A	^ 70mm bit. patch w/c 1-3 m2	2.73	SQ.M	L 3.90 W 0.70 D 0.00

Inspection Date: 14-Oct-2021 Inspect History ID: 3089014 - 3 Monthly - Safety Inspection of 3WRC-DOWN on 12 October 2021 Inspection Type: 3 Monthly - WFE Safety Inspection Inspector: [REDACTED]

Section Code: 7065C0308_02 Section Description: CLONVARAGHAN RD1: WOOD RD C324 TO SLIEVENISKY RD U152

Defect Ref: [DCD49-3089014-23](#) Defect Type: DEFECT Comments: Location Description: OPP LANE NO 87 Priority: R2 - 5 Working Defect Dimensions: Length 0.45 Width (m): 0.35 Depth (mm): 60.00

Recorded Date: 14-October-2021 BITMAC EDGE DETERIORATION (CBED)

Recorded By:



Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures		
D71021A	^ Velocity patch 0-1m2	1.00	no	L 0.00	W 0.00	D 0.00