Defect Inspections (By Road Section) Report

Department for Infrastructure

Selection Criteria:

Dates:
From: 12/08/2019
Until Less Than: 12/08/2024

Section:
7035U0011_01 BOGHILL RD1: HYDEPARK RD TO FLUSH RD (DIV. BOUNDARY)

Commencement date of Inspection: 05 Jun 2024 **Inspect History ID & Description:** 3110365 - Full Sector - WFE Safety Inspection of AAN4-06-ANTRIM & NEWTOWNABBEY **Inspector Name:** [redacted]

Class: Unclassified **Environment:** RURAL **Traffic Level:** Low Traffic

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions:		
DCD249093465	DEFECT	Junction with flush rd	R3 - 4 Weeks	Length (m): 0.40	Width (m): 0.40	Depth (mm): 51.00

Comments: ?

Defect Date: 05-June-2024

Defect Category: BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D23221A	100mm deep Bitmac c/w patch (14mm wc in CGA/20mm bc in DAC) - 0-1 m2	1.00	no	L 0.00	W 0.00	D 0.00
A14401A	14mm asphalt W/C 0-15 t	1.00	Tonne	L 0.00	W 0.00	D 0.00

Photographs or Documents attached: No

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions:		
DCD249093467	DEFECT	40 70,90,m from flush rd junction 3 repairs	R3 - 4 Weeks	Length (m): 0.30	Width (m): 0.30	Depth (mm): 51.00

Comments: ?

Defect Date: 05-June-2024

Defect Category: BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D23221A	100mm deep Bitmac c/w patch (14mm wc in CGA/20mm bc in DAC) - 0-1 m2	3.00	no	L 0.00	W 0.00	D 0.00

Photographs or Documents attached: No

Copyright

Defect Inspections (By Road Section) Report

Department for Infrastructure

Selection Criteria:

Dates:
From: 12/08/2019
Until Less Than: 12/08/2024

Section:
7035U0011_01 BOGHILL RD1: HYDEPARK RD TO FLUSH RD (DIV. BOUNDARY)

Commencement date of Inspection:	**05 Jun 2024**	**Inspect History ID & Description:**	**3110365 - Full Sector - WFE Safety Inspection of AAN4-06-ANTRIM & NEWTOWNABBEY**	**Inspector Name:**	[redacted]
Class: Unclassified		**Environment:** RURAL		**Traffic Level:** Low Traffic	

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions:		
DCD249093475	DEFECT	As above	R3 - 4 Weeks	**Length (m):** 0.20	**Width (m):** 2.00	**Depth (mm):** 51.00

Comments: 50 an 60mrhs number 55

Defect Date: 05-June-2024

Defect Category: BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D23221A	100mm deep Bitmac c/w patch (14mm wc in CGA/20mm bc in DAC) - 0-1 m2	6.00	no	L 0.00	W 0.00	D 0.00

Photographs or Documents attached: No

Copyright

Defect Inspections (By Road Section) Report

Department for Infrastructure

Selection Criteria:

Dates:
From: 12/08/2019
Until Less Than: 12/08/2024

Section:
7035U0011_01 BOGHILL RD1: HYDEPARK RD TO FLUSH RD (DIV. BOUNDARY)

Commencement date of Inspection:	**05 Jun 2024**	**Inspect History ID & Description:**	**3110365 - Full Sector - WFE Safety Inspection of AAN4-06-ANTRIM & NEWTOWNABBEY**	**Inspector Name:**	[redacted]
Class: Unclassified		**Environment:** RURAL		**Traffic Level:** Low Traffic	

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions:		
DCD249093483	DEFECT	70m rhs 55	R3 - 4 Weeks	**Length (m):** 0.30	**Width (m):** 0.30	**Depth (mm):** 51.00

Comments: ?

Defect Date: 05-June-2024

Defect Category: BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D23223A	100mm deep Bitmac c/w patch (14mm wc in CGA/ 20mm bc in DAC) - 3-15 m2	15.00	m2	L 15.00	W 1.00	D 0.00
D23223A	100mm deep Bitmac c/w patch (14mm wc in CGA/ 20mm bc in DAC) - 3-15 m2	15.00	m2	L 15.00	W 1.00	D 0.00

Photographs or Documents attached: No

Copyright

Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 12/08/2019
Until Less Than: 12/08/2024

Section:
7035U0011_01 BOGHILL RD1: HYDEPARK RD TO FLUSH RD (DIV. BOUNDARY)

Commencement date of Inspection:	**05 Jun 2024**	**Inspect History ID & Description:**	**3110365 - Full Sector - WFE Safety Inspection of AAN4-06-ANTRIM & NEWTOWNABBEY**	**Inspector Name:**	[redacted]
Class: Unclassified		**Environment:** RURAL		**Traffic Level:** Low Traffic	

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions:		
DCD249093497	DEFECT	80 and 90m rhs55	R3 - 4 Weeks	**Length (m):** 3.00	**Width (m):** 3.00	**Depth (mm):** 55.00

Comments: ?

Defect Date: 05-June-2024

Defect Category: BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D23221A	100mm deep Bitmac c/w patch (14mm wc in CGA/20mm bc in DAC) - 0-1 m2	4.00	no	L 0.00	W 0.00	D 0.00
D23223A	100mm deep Bitmac c/w patch (14mm wc in CGA/ 20mm bc in DAC) - 3-15 m2	13.50	m2	L 9.00	W 1.50	D 0.00

Photographs or Documents attached: No

Copyright

Defect Inspections (By Road Section) Report

Department for Infrastructure

Selection Criteria:

Dates:
From: 12/08/2019
Until Less Than: 12/08/2024

Section:
7035U0011_01 BOGHILL RD1: HYDEPARK RD TO FLUSH RD (DIV. BOUNDARY)

Commencement date of Inspection:	**05 Jun 2024**	**Inspect History ID & Description:**	**3110365 - Full Sector - WFE Safety Inspection of AAN4-06-ANTRIM & NEWTOWNABBEY**	**Inspector Name:**	[redacted]
Class: Unclassified		**Environment:** RURAL		**Traffic Level:** Low Traffic	

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions:		
DCD249093566	DEFECT	Junction with flush rd	R3 - 4 Weeks	**Length (m):** 0.40	**Width (m):** 0.40	**Depth (mm):** 51.00

Comments: Markings wrong do worst part 10x1.5 and10x1.5 and six 1sqm repairs

Defect Date: 05-June-2024

Defect Category: BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D23223A	100mm deep Bitmac c/w patch (14mm wc in CGA/ 20mm bc in DAC) - 3-15 m2	150.00	m2	L 10.00	W 15.00	D 0.00
D23223A	100mm deep Bitmac c/w patch (14mm wc in CGA/ 20mm bc in DAC) - 3-15 m2	15.00	m2	L 10.00	W 1.50	D 0.00
D23221A	100mm deep Bitmac c/w patch (14mm wc in CGA/20mm bc in DAC) - 0-1 m2	6.00	no	L 0.00	W 0.00	D 0.00

Photographs or Documents attached: No

Stretch Comments:

Copyright

Defect Inspections (By Road Section) Report

Department for Infrastructure

Selection Criteria:

Dates:
From: 12/08/2019
Until Less Than: 12/08/2024

Section:
7035U0011_01 BOGHILL RD1: HYDEPARK RD TO FLUSH RD (DIV. BOUNDARY)

Commencement date of Inspection: 18 Dec 2023 **Inspect History ID & Description:** 3107003 - Full Sector - WFE Safety Inspection of AAN4-06-ANTRIM & NEWTOWNABBEY **Inspector Name:** [redacted]

Class: Unclassified **Environment:** RURAL **Traffic Level:** Low Traffic

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
DCD238986574	ROADS SERVICE REFERRAL	All rd	Not Applicable			

Comments: Heavy surface water

Defect Date: 18-December-2023 **Defect Category:** STRETCH COMMENTS **Completion Comments:** noted

Photographs or Documents attached: No

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
DCD238986597	DEFECT	100m from hydepark rd 1 pothole 15m rhs opp quarry 1 pothole 30m lhs 45 7 potholes Lhs and rhs opp 55 2 potholes 30m and 40m rhs number 64 2 potholes Junction with flush rd 5 potholes	R3 - 4 Weeks	0.30	0.30	51.00

Comments: Make potholes safe total 18 potholes no marks ground wet

Defect Date: 18-December-2023 **Defect Category:** BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D30061A	^ Temp. patch 6mm deferred set 0-1m2	18.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Copyright

Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:

From: 12/08/2019

Until Less Than: 12/08/2024

Section:

7035U0011_01 BOGHILL RD1: HYDEPARK RD TO FLUSH RD (DIV. BOUNDARY)

Stretch Comments:

Copyright

Defect Inspections (By Road Section) Report

Department for Infrastructure

Selection Criteria:

Dates:
From: 12/08/2019
Until Less Than: 12/08/2024

Section:
7035U0011_01 BOGHILL RD1: HYDEPARK RD TO FLUSH RD (DIV. BOUNDARY)

Commencement date of Inspection: 15 Jun 2023 **Inspect History ID & Description:** 3103923 - Full Sector - WFE Safety Inspection of AAN4-06-ANTRIM & NEWTOWNABBEY **Inspector Name:** [redacted]

Class: Unclassified **Environment:** RURAL **Traffic Level:** Low Traffic

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions:		
DCD238886934	DEFECT	60m lhs from quarry	R3 - 4 Weeks	Length (m): 0.20	Width (m): 0.20	Depth (mm): 51.00

Comments: ?

Defect Date: 15-June-2023

Defect Category: BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00	W 0.00	D 0.00

Photographs or Documents attached: No

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions:		
DCD238886941	DEFECT	Lhs bt telegraph pole b5,8l0011	R2 - 5 Working days	Length (m): 0.50	Width (m): 0.50	Depth (mm): 120.00

Comments: 12 potholes

Defect Date: 15-June-2023

Defect Category: BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	12.00	no	L 0.00	W 0.00	D 0.00
Z01700A	EO all items for Priority 2 response	468.86	%	L 0.00	W 0.00	D 0.00

Photographs or Documents attached: No

Stretch Comments:

Copyright

Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:

From: 12/08/2019

Until Less Than: 12/08/2024

Section:

7035U0011_01 BOGHILL RD1: HYDEPARK RD TO FLUSH RD (DIV. BOUNDARY)

Copyright

Defect Inspections (By Road Section) Report

Department for Infrastructure

Selection Criteria:

Dates:
From: 12/08/2019
Until Less Than: 12/08/2024

Section:
7035U0011_01 BOGHILL RD1: HYDEPARK RD TO FLUSH RD (DIV. BOUNDARY)

Commencement date of Inspection: 05 Dec 2022 **Inspect History ID & Description:** 3096593 - Full Sector - Safety Inspection of AAN4-06-ANTRIM & NEWTOWNABBEY **Inspector Name:** [redacted]

Class: Unclassified **Environment:** RURAL **Traffic Level:** Low Traffic

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
DCD92-3096593-33	DEFECT	junct of hydepark rd	R4 - next available programme			

Comments: give way sign

Defect Date: 05-December-2022

Defect Category: TRAFFIC SIGN DISPLACED (TSDI)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
R93220A	^ Reposition sign face	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
DCD92-3096593-34	ROADS SERVICE REFERRAL	all rd	Not Applicable			

Comments: h/s water falling leaves

Defect Date: 05-December-2022

Defect Category: STRETCH COMMENTS

Completion Comments: noted

Photographs or Documents attached: No

Copyright

Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 12/08/2019
Until Less Than: 12/08/2024

Section:
7035U0011_01 BOGHILL RD1: HYDEPARK RD TO FLUSH RD (DIV. BOUNDARY)

Commencement date of Inspection:	**05 Dec 2022**	**Inspect History ID & Description:**	**3096593 - Full Sector - Safety Inspection of AAN4-06-ANTRIM & NEWTOWNABBEY**	**Inspector Name:**	[redacted]
Class: Unclassified		**Environment:** RURAL		**Traffic Level:** Low Traffic	

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions:		
DCD92-3096593-35	DEFECT	opp num 55	R3 - 4 Weeks	**Length (m):** 0.20	**Width (m):** 0.20	**Depth (mm):** 51.00

Comments:

Defect Date:
05-December-2022

Defect Category:
BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00	W 0.00	D 0.00

Photographs or Documents attached: No

Stretch Comments: ?

Copyright

Defect Inspections (By Road Section) Report

Department for Infrastructure

Selection Criteria:

Dates:
From: 12/08/2019
Until Less Than: 12/08/2024

Section:
7035U0011_01 BOGHILL RD1: HYDEPARK RD TO FLUSH RD (DIV. BOUNDARY)

Commencement date of Inspection: 11 Jun 2022 **Inspect History ID & Description:** 3093694 - Full Sector - Safety Inspection of AAN4-06-ANTRIM & NEWTOWNABBEY **Inspector Name:** [redacted]

Class: Unclassified **Environment:** RURAL **Traffic Level:** Low Traffic

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions:		
DCD92-3093694-48	DEFECT	before bridge	R3 - 4 Weeks	Length (m): 0.30	Width (m): 0.30	Depth (mm): 51.00

Comments:

Defect Date: 11-June-2022

Defect Category: BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	5.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions:		
DCD92-3093694-49	DEFECT	160m rhs 26	R3 - 4 Weeks	Length (m): 0.20	Width (m): 0.20	Depth (mm): 51.00

Comments:

Defect Date: 11-June-2022

Defect Category: BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Copyright

Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 12/08/2019
Until Less Than: 12/08/2024

Section:
7035U0011_01 BOGHILL RD1: HYDEPARK RD TO FLUSH RD (DIV. BOUNDARY)

Commencement date of Inspection: 11 Jun 2022 **Inspect History ID & Description:** 3093694 - Full Sector - Safety Inspection of AAN4-06-ANTRIM & NEWTOWNABBEY **Inspector Name:** [redacted]

Class: Unclassified **Environment:** RURAL **Traffic Level:** Low Traffic

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions:		
DCD92-3093694-50	DEFECT	rhs num 40 and 40m rhs num 40	R3 - 4 Weeks	Length (m): 0.20	Width (m): 0.20	Depth (mm): 51.00

Comments:

Defect Date: 11-June-2022

Defect Category: BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	4.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions:		
DCD92-3093694-51	DEFECT	25m and 40m lhs num 45	R3 - 4 Weeks	Length (m): 0.30	Width (m): 0.30	Depth (mm): 51.00

Comments:

Defect Date: 11-June-2022

Defect Category: BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	8.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Copyright

Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 12/08/2019
Until Less Than: 12/08/2024

Section:
7035U0011_01 BOGHILL RD1: HYDEPARK RD TO FLUSH RD (DIV. BOUNDARY)

Commencement date of Inspection: 11 Jun 2022 **Inspect History ID & Description:** 3093694 - Full Sector - Safety Inspection of AAN4-06-ANTRIM & NEWTOWNABBEY **Inspector Name:** [redacted]

Class: Unclassified **Environment:** RURAL **Traffic Level:** Low Traffic

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions:
DCD92-3093694-52	DEFECT	65m and 80m lhs num 45	R3 - 4 Weeks	Length (m): 0.30 Width (m): 0.30 Depth (mm): 51.00

Comments:

Defect Date: 11-June-2022

Defect Category: BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	9.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions:
DCD92-3093694-53	ROADS SERVICE REFERRAL	all rd	Not Applicable	Length (m): Width (m): Depth (mm):

Comments: s/water

Defect Date: 11-June-2022

Defect Category: STRETCH COMMENTS

Completion Comments: noted

Photographs or Documents attached: No

Copyright

Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 12/08/2019
Until Less Than: 12/08/2024

Section:
7035U0011_01 BOGHILL RD1: HYDEPARK RD TO FLUSH RD (DIV. BOUNDARY)

Commencement date of Inspection: 11 Jun 2022 **Inspect History ID & Description:** 3093694 - Full Sector - Safety Inspection of AAN4-06-ANTRIM & NEWTOWNABBEY **Inspector Name:** [redacted]

Class: Unclassified **Environment:** RURAL **Traffic Level:** Low Traffic

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions:		
DCD92-3093694-54	DEFECT	opp 52	R3 - 4 Weeks	Length (m): 0.30	Width (m): 0.30	Depth (mm): 51.00

Comments:

Defect Date: 11-June-2022

Defect Category: BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	2.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions:		
DCD92-3093694-55	DEFECT	40m lhs 55	R3 - 4 Weeks	Length (m): 0.30	Width (m): 0.20	Depth (mm): 51.00

Comments:

Defect Date: 11-June-2022

Defect Category: BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Copyright

Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 12/08/2019
Until Less Than: 12/08/2024

Section:
7035U0011_01 BOGHILL RD1: HYDEPARK RD TO FLUSH RD (DIV. BOUNDARY)

Commencement date of Inspection: 11 Jun 2022 **Inspect History ID & Description:** 3093694 - Full Sector - Safety Inspection of AAN4-06-ANTRIM & NEWTOWNABBEY **Inspector Name:** [redacted]

Class: Unclassified **Environment:** RURAL **Traffic Level:** Low Traffic

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions:
DCD92-3093694-56	DEFECT	num 63	R3 - 4 Weeks	Length (m): 0.20 Width (m): 0.20 Depth (mm): 51.00

Comments:

Defect Date: 11-June-2022

Defect Category: BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions:
DCD92-3093694-57	DEFECT	before give way sign at flush rd	R3 - 4 Weeks	Length (m): 0.20 Width (m): 0.20 Depth (mm): 51.00

Comments:

Defect Date: 11-June-2022

Defect Category: BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	2.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Copyright

Defect Inspections (By Road Section) Report

Department for Infrastructure

Selection Criteria:

Dates:
From: 12/08/2019
Until Less Than: 12/08/2024

Section:
7035U0011_01 BOGHILL RD1: HYDEPARK RD TO FLUSH RD (DIV. BOUNDARY)

Commencement date of Inspection: 11 Jun 2022 **Inspect History ID & Description:** 3093694 - Full Sector - Safety Inspection of AAN4-06-ANTRIM & NEWTOWNABBEY **Inspector Name:** [redacted]

Class: Unclassified **Environment:** RURAL **Traffic Level:** Low Traffic

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions:
DCD92-3093694-58	DEFECT	after give way sign at flush rd	R3 - 4 Weeks	Length (m): 0.20 Width (m): 0.20 Depth (mm): 51.00

Comments:

Defect Date: 11-June-2022

Defect Category: BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	3.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions:
DCD92-3093694-59	DEFECT	junction of flush rd	R3 - 4 Weeks	Length (m): 0.20 Width (m): 0.20 Depth (mm): 51.00

Comments:

Defect Date: 11-June-2022

Defect Category: BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	4.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Copyright

Defect Inspections (By Road Section) Report

Department for Infrastructure

Selection Criteria:

Dates:
From: 12/08/2019
Until Less Than: 12/08/2024

Section:
7035U0011_01 BOGHILL RD1: HYDEPARK RD TO FLUSH RD (DIV. BOUNDARY)

Commencement date of Inspection: 11 Jun 2022 **Inspect History ID & Description:** 3093694 - Full Sector - Safety Inspection of AAN4-06-ANTRIM & NEWTOWNABBEY **Inspector Name:** [redacted]

Class: Unclassified **Environment:** RURAL **Traffic Level:** Low Traffic

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
DCD92-3093694-60	ROADS SERVICE REFERRAL	all rd	Not Applicable			

Comments: s/water

Defect Date:	Defect Category:	Completion Comments:
11-June-2022	STRETCH COMMENTS	noted

Photographs or Documents attached: No

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
DCD92-3093694-61	DEFECT	junct hydepark rd	R4 - next available programme			

Comments: stop markings

Defect Date:	Defect Category:
11-June-2022	ROAD MARKINGS FADED (CYFD)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
K33731A	^ 1600mm letters	4.00	no	L 0.00	W 0.00	D 0.00
K31241A	^ 200mm continuous white screed	2.00	LIN.M	L 2.00	W 0.00	D 0.00
K31321A	^ 100mm intermittent white screed	9.00	LIN.M	L 9.00	W 0.00	D 0.00

Photographs or Documents attached: No

Copyright

Defect Inspections (By Road Section) Report

Department for Infrastructure

Selection Criteria:

Dates:
From: 12/08/2019
Until Less Than: 12/08/2024

Section:
7035U0011_01 BOGHILL RD1: HYDEPARK RD TO FLUSH RD (DIV. BOUNDARY)

Commencement date of Inspection:	**11 Jun 2022**	**Inspect History ID & Description:**	**3093694 - Full Sector - Safety Inspection of AAN4-06-ANTRIM & NEWTOWNABBEY**	**Inspector Name:**	[redacted]
Class: Unclassified		**Environment:** RURAL		**Traffic Level:** Low Traffic	

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
DCD92-3093694-62	DEFECT	junct flush rd	R4 - next available programme			

Comments: give way markings

Defect Date: 11-June-2022

Defect Category: ROAD MARKINGS FADED (CYFD)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
K33101A	^ Triangle white diag No 1023	1.00	no	L 0.00	W 0.00	D 0.00
K31341A	^ 200mm intermittent white screed	10.00	LIN.M	L 10.00	W 0.00	D 0.00
K31321A	^ 100mm intermittent white screed	12.00	LIN.M	L 12.00	W 0.00	D 0.00

Photographs or Documents attached: No

Stretch Comments: ?

Copyright

Defect Inspections (By Road Section) Report

Department for Infrastructure

Selection Criteria:

Dates:
From: 12/08/2019
Until Less Than: 12/08/2024

Section:
7035U0011_01 BOGHILL RD1: HYDEPARK RD TO FLUSH RD (DIV. BOUNDARY)

Commencement date of Inspection: 12 Dec 2021 **Inspect History ID & Description:** 3090671 - Full Sector - Safety Inspection of AAN4-06-ANTRIM & NEWTOWNABBEY **Inspector Name:** [redacted]

Class: Unclassified **Environment:** RURAL **Traffic Level:** Low Traffic

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
DCD92-3090671-15	ROADS SERVICE REFERRAL	all rd	Not Applicable			

Comments: h/s water all rd

Defect Date: 12-December-2021 **Defect Category:** STRETCH COMMENTS **Completion Comments:** noted

Photographs or Documents attached: No

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
DCD92-3090671-16	DEFECT	40m rhs num 40	R3 - 4 Weeks	0.20	0.20	51.00

Comments: make safe

Defect Date: 12-December-2021 **Defect Category:** BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D30061A	^ Temp. patch 6mm deferred set 0-1m2	2.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Copyright

Defect Inspections (By Road Section) Report

Department for Infrastructure

Selection Criteria:

Dates:
From: 12/08/2019
Until Less Than: 12/08/2024

Section:
7035U0011_01 BOGHILL RD1: HYDEPARK RD TO FLUSH RD (DIV. BOUNDARY)

Commencement date of Inspection: 12 Dec 2021 **Inspect History ID & Description:** 3090671 - Full Sector - Safety Inspection of AAN4-06-ANTRIM & NEWTOWNABBEY **Inspector Name:** [redacted]

Class: Unclassified **Environment:** RURAL **Traffic Level:** Low Traffic

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions:		
DCD92-3090671-17	DEFECT	rhs num 40 make safe	R3 - 4 Weeks	Length (m): 0.20	Width (m): 0.20	Depth (mm): 51.00

Comments:

Defect Date: 12-December-2021

Defect Category: BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D30061A	^ Temp. patch 6mm deferred set 0-1m2	2.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions:		
DCD92-3090671-18	DEFECT	20m rhs num 49 make safe	R3 - 4 Weeks	Length (m): 0.20	Width (m): 0.20	Depth (mm): 51.00

Comments:

Defect Date: 12-December-2021

Defect Category: BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D30061A	^ Temp. patch 6mm deferred set 0-1m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Copyright

Defect Inspections (By Road Section) Report

Department for Infrastructure

Selection Criteria:

Dates:
From: 12/08/2019
Until Less Than: 12/08/2024

Section:
7035U0011_01 BOGHILL RD1: HYDEPARK RD TO FLUSH RD (DIV. BOUNDARY)

Commencement date of Inspection: 12 Dec 2021 **Inspect History ID & Description:** 3090671 - Full Sector - Safety Inspection of AAN4-06-ANTRIM & NEWTOWNABBEY **Inspector Name:** [redacted]

Class: Unclassified **Environment:** RURAL **Traffic Level:** Low Traffic

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions:		
DCD92-3090671-19	DEFECT	opp 55 make safe	R3 - 4 Weeks	Length (m): 0.20	Width (m): 0.20	Depth (mm): 55.00

Comments:

Defect Date: 12-December-2021

Defect Category: BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D30061A	^ Temp. patch 6mm deferred set 0-1m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions:		
DCD92-3090671-20	DEFECT	30m rhs 55 make safe	R3 - 4 Weeks	Length (m): 0.20	Width (m): 0.20	Depth (mm): 51.00

Comments:

Defect Date: 12-December-2021

Defect Category: BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D30061A	^ Temp. patch 6mm deferred set 0-1m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Copyright

Defect Inspections (By Road Section) Report

Department for Infrastructure

Selection Criteria:

Dates:
From: 12/08/2019
Until Less Than: 12/08/2024

Section:
7035U0011_01 BOGHILL RD1: HYDEPARK RD TO FLUSH RD (DIV. BOUNDARY)

Commencement date of Inspection: 12 Dec 2021 **Inspect History ID & Description:** 3090671 - Full Sector - Safety Inspection of AAN4-06-ANTRIM & NEWTOWNABBEY **Inspector Name:** [redacted]

Class: Unclassified **Environment:** RURAL **Traffic Level:** Low Traffic

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions:		
DCD92-3090671-21	DEFECT	num 63 make safe	R3 - 4 Weeks	Length (m): 0.20	Width (m): 0.20	Depth (mm): 51.00

Comments:

Defect Date: 12-December-2021

Defect Category: BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D30061A	^ Temp. patch 6mm deferred set 0-1m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions:		
DCD92-3090671-22	DEFECT	60m rhs 64 make safe	R3 - 4 Weeks	Length (m): 0.20	Width (m): 0.20	Depth (mm): 51.00

Comments:

Defect Date: 12-December-2021

Defect Category: BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D30061A	^ Temp. patch 6mm deferred set 0-1m2	2.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Stretch Comments: ?

Copyright

Defect Inspections (By Road Section) Report

Department for Infrastructure

Selection Criteria:

Dates:
From: 12/08/2019
Until Less Than: 12/08/2024

Section:
7035U0011_01 BOGHILL RD1: HYDEPARK RD TO FLUSH RD (DIV. BOUNDARY)

Commencement date of Inspection: 17 Jun 2021 **Inspect History ID & Description:** 3087703 - Full Sector - Safety Inspection of AAN4-06-ANTRIM & NEWTOWNABBEY **Inspector Name:** [redacted]

Class: Unclassified **Environment:** RURAL **Traffic Level:** Low Traffic

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions:		
DCD92-3087703-36	DEFECT	45m rhs num 40	R3 - 4 Weeks	Length (m): 0.30	Width (m): 0.30	Depth (mm): 51.00

Comments:

Defect Date: 17-June-2021

Defect Category: BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	8.00	no	L 0.00	W 0.00	D 0.00

Photographs or Documents attached: No

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions:		
DCD92-3087703-37	DEFECT	35m lhs 45	R3 - 4 Weeks	Length (m): 0.30	Width (m): 0.30	Depth (mm): 75.00

Comments:

Defect Date: 17-June-2021

Defect Category: BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D23112A	^ 100mm bit. patch W/C & B/C 1-3 m2	3.00	SQ.M	L 3.00	W 1.00	D 0.00
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	3.00	no	L 0.00	W 0.00	D 0.00

Photographs or Documents attached: No

Copyright

Defect Inspections (By Road Section) Report

Department for Infrastructure

Selection Criteria:

Dates:
From: 12/08/2019
Until Less Than: 12/08/2024

Section:
7035U0011_01 BOGHILL RD1: HYDEPARK RD TO FLUSH RD (DIV. BOUNDARY)

Commencement date of Inspection: 17 Jun 2021 **Inspect History ID & Description:** 3087703 - Full Sector - Safety Inspection of AAN4-06-ANTRIM & NEWTOWNABBEY **Inspector Name:** [redacted]

Class: Unclassified **Environment:** RURAL **Traffic Level:** Low Traffic

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions:		
DCD92-3087703-38	DEFECT	50m lhs num 45	R3 - 4 Weeks	Length (m): 0.30	Width (m): 0.30	Depth (mm): 51.00

Comments:

Defect Date: 17-June-2021

Defect Category: BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	3.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions:		
DCD92-3087703-39	DEFECT	35m lhs 63	R3 - 4 Weeks	Length (m): 0.30	Width (m): 0.30	Depth (mm): 55.00

Comments:

Defect Date: 17-June-2021

Defect Category: BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Copyright

Defect Inspections (By Road Section) Report

Department for Infrastructure

Selection Criteria:

Dates:
From: 12/08/2019
Until Less Than: 12/08/2024

Section:
7035U0011_01 BOGHILL RD1: HYDEPARK RD TO FLUSH RD (DIV. BOUNDARY)

Commencement date of Inspection: 17 Jun 2021 **Inspect History ID & Description:** 3087703 - Full Sector - Safety Inspection of AAN4-06-ANTRIM & NEWTOWNABBEY **Inspector Name:** [redacted]

Class: Unclassified **Environment:** RURAL **Traffic Level:** Low Traffic

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions:		
DCD92-3087703-40	DEFECT	12m lhs 64	R3 - 4 Weeks	Length (m): 0.30	Width (m): 0.30	Depth (mm): 51.00

Comments:

Defect Date: 17-June-2021

Defect Category: BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00	W 0.00	D 0.00

Photographs or Documents attached: No

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions:		
DCD92-3087703-41	DEFECT	junct flush rd	R3 - 4 Weeks	Length (m): 0.40	Width (m): 0.40	Depth (mm): 55.00

Comments:

Defect Date: 17-June-2021

Defect Category: BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D23112A	^ 100mm bit. patch W/C & B/C 1-3 m2	1.50	SQ.M	L 1.50	W 1.00	D 0.00
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00	W 0.00	D 0.00

Photographs or Documents attached: No

Copyright

Defect Inspections (By Road Section) Report

Department for Infrastructure

Selection Criteria:

Dates:
From: 12/08/2019
Until Less Than: 12/08/2024

Section:
7035U0011_01 BOGHILL RD1: HYDEPARK RD TO FLUSH RD (DIV. BOUNDARY)

Commencement date of Inspection: 17 Jun 2021 **Inspect History ID & Description:** 3087703 - Full Sector - Safety Inspection of AAN4-06-ANTRIM & NEWTOWNABBEY **Inspector Name:** [redacted]

Class: Unclassified **Environment:** RURAL **Traffic Level:** Low Traffic

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions:		
DCD92-3087703-42	DEFECT	num 51	R3 - 4 Weeks	Length (m): 0.40	Width (m): 0.40	Depth (mm): 75.00

Comments:

Defect Date: 17-June-2021

Defect Category: BITMAC EDGE DETERIORATION (CBED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23113A	^ 100mm bit. patch W/C & B/C 3-15 m2	4.00	SQ.M	L 8.00 W 0.50 D 0.00

Photographs or Documents attached: No

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions:		
DCD92-3087703-43	DEFECT	10m and 20m lhs num 45	R3 - 4 Weeks	Length (m): 0.30	Width (m): 0.20	Depth (mm): 51.00

Comments:

Defect Date: 17-June-2021

Defect Category: BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	2.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Stretch Comments: ?

Copyright

Defect Inspections (By Road Section) Report

Department for Infrastructure

Selection Criteria:

Dates:
From: 12/08/2019
Until Less Than: 12/08/2024

Section:
7035U0011_01 BOGHILL RD1: HYDEPARK RD TO FLUSH RD (DIV. BOUNDARY)

Commencement date of Inspection: 10 Dec 2020 **Inspect History ID & Description:** 3084680 - Full Sector - Safety Inspection of AAN4-06-ANTRIM & NEWTOWNABBEY **Inspector Name:** [redacted]

Class: Unclassified **Environment:** RURAL **Traffic Level:** Low Traffic

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
DCD92-3084680-30	ROADS SERVICE REFERRAL	all rd	Not Applicable			

Comments: h/s water

Defect Date: 10-December-2020 **Defect Category:** STRETCH COMMENTS **Completion Comments:** issued noted

Photographs or Documents attached: No

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
DCD92-3084680-31	DEFECT	junct of hydepark rd	R4 - next available programme			

Comments: 1 give way sign and 4 clearway signs ordered rathmore depot

Defect Date: 10-December-2020 **Defect Category:** TRAFFIC SIGN FADED (TSFD)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
Y51111A	^ Dispose sign 0-1m2	5.00	no	L 0.00	W 0.00	D 0.00
R11224A	^ Triangular class 2 sign 900-1500mm high	1.00	no	L 0.00	W 0.00	D 0.00
R11234A	^ Circular class 2 sign 900-1500mm dia	4.00	no	L 0.00	W 0.00	D 0.00

Photographs or Documents attached: No

Copyright

Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:

From: 12/08/2019

Until Less Than: 12/08/2024

Section:

7035U0011_01 BOGHILL RD1: HYDEPARK RD TO FLUSH RD (DIV. BOUNDARY)

Stretch Comments: ?

Copyright

Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 12/08/2019
Until Less Than: 12/08/2024

Section:
7035U0011_01 BOGHILL RD1: HYDEPARK RD TO FLUSH RD (DIV. BOUNDARY)

Commencement date of Inspection: 17 Jun 2020 **Inspect History ID & Description:** 3081834 - Full Sector - Safety Inspection of AAN4-06-ANTRIM & NEWTOWNABBEY **Inspector Name:** [redacted]

Class: Unclassified **Environment:** RURAL **Traffic Level:** Low Traffic

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
DCD92-3081834-66	ROADS SERVICE REFERRAL	all rd	Not Applicable			

Comments: h/s water

Defect Date: 17-June-2020 **Defect Category:** STRETCH COMMENTS **Completion Comments:** work noted

Photographs or Documents attached: No

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
DCD92-3081834-67	DEFECT	70m rhs num 40	R3 - 4 Weeks	0.10	0.10	51.00

Comments:

Defect Date: 17-June-2020 **Defect Category:** BITMAC POTHOLE (CBPH) **Completion Comments:** No Resource/ capacity at this time

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	3.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Copyright

Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 12/08/2019
Until Less Than: 12/08/2024

Section:
7035U0011_01 BOGHILL RD1: HYDEPARK RD TO FLUSH RD (DIV. BOUNDARY)

Commencement date of Inspection: 17 Jun 2020 **Inspect History ID & Description:** 3081834 - Full Sector - Safety Inspection of AAN4-06-ANTRIM & NEWTOWNABBEY **Inspector Name:** [redacted]

Class: Unclassified **Environment:** RURAL **Traffic Level:** Low Traffic

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions:
DCD92-3081834-68	DEFECT	30m lhs num 64	R3 - 4 Weeks	Length (m): 0.10 Width (m): 0.10 Depth (mm): 51.00

Comments:

Defect Date:	Defect Category:	Completion Comments:
17-June-2020	BITMAC POTHOLE (CBPH)	No Resource/ capacity at this time

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Stretch Comments: ?

Copyright

Defect Inspections (By Road Section) Report

Department for Infrastructure

Selection Criteria:

Dates:
From: 12/08/2019
Until Less Than: 12/08/2024

Section:
7035U0011_01 BOGHILL RD1: HYDEPARK RD TO FLUSH RD (DIV. BOUNDARY)

Commencement date of Inspection: 12 Dec 2019 **Inspect History ID & Description:** 3078882 - Full Sector - Safety Inspection of AAN4-06-ANTRIM & NEWTOWNABBEY **Inspector Name:** [redacted]

Class: Unclassified **Environment:** RURAL **Traffic Level:** Low Traffic

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
DCD92-3078882-28	ROADS SERVICE REFERRAL	all rd	Not Applicable			

Comments: h/s water

Defect Date:	Defect Category:	Completion Comments:
12-December-2019	STRETCH COMMENTS	issued noted

Photographs or Documents attached: No

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
DCD92-3078882-29	DEFECT	from hydepark rd to flush rd no marks bad weather	R4 - next available programme	0.20	0.20	35.00

Comments: p.s.d patches

Defect Date:	Defect Category:
12-December-2019	BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D23111A	^ 100mm bit. patch W/C & B/C <1 m2	15.00	no	L 0.00	W 0.00	D 0.00

Photographs or Documents attached: No

Stretch Comments: ?

Copyright

Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 12/08/2019
Until Less Than: 12/08/2024

Section:
7035U0011_01 BOGHILL RD1: HYDEPARK RD TO FLUSH RD (DIV. BOUNDARY)

Commencement date of Inspection:	Inspect History ID & Description:	Inspector Name:
	3085991 - Full Sector - Safety Inspection of AAN4-03-ANTRIM & NEWTOWNABBEY	

Class: Unclassified **Environment:** RURAL **Traffic Level:** Low Traffic

Type: Ad Hoc Defect

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
DCD92-3085991-140	DEFECT	junct flush rd	R4 - next available programme			

Comments: reset post 2 signs and new post

Defect Date: 09-March-2021

Defect Category: TRAFFIC SIGN POST DAMAGED (TSPG)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
R13110A	^ Loosen and reset post	1.00	no	L 0.00 W 0.00 D 0.00
Y51111A	^ Dispose sign 0-1m2	2.00	no	L 0.00 W 0.00 D 0.00
R11224A	^ Triangular class 2 sign 900-1500mm high	2.00	no	L 0.00 W 0.00 D 0.00
G01001A	^ Unplanned envir. work norm.hrs (2-man operation)	2.00	HR	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Copyright

Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 12/08/2019
Until Less Than: 12/08/2024

Section:
7035U0011_01 BOGHILL RD1: HYDEPARK RD TO FLUSH RD (DIV. BOUNDARY)

Commencement date of Inspection:	Inspect History ID & Description:	Inspector Name:
	3083341 - 1 Monthly - Safety Inspection of AAN4-04-ANTRIM & NEWTOWNABBEY	

Class: Unclassified **Environment:** RURAL **Traffic Level:** Low Traffic

Type: Ad Hoc Defect

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
DCD92-3083341-9	DEFECT	junct boghill rd and flush rd	R4 - next available programme			

Comments: remove post and signs to depot knocked over

Defect Date: 10-September-2020

Defect Category: TRAFFIC SIGN POST DEFECTIVE (TSPD)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
G01001A	^ Unplanned envir. work norm.hrs (2-man operation)	1.00	HR	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Copyright

Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 12/08/2019
Until Less Than: 12/08/2024

Section:
7035U0011_01 BOGHILL RD1: HYDEPARK RD TO FLUSH RD (DIV. BOUNDARY)

Commencement date of Inspection:	Inspect History ID & Description:	Inspector Name:
	3082543 - 1 and 3 Monthly - Safety Inspection of AAN4-10-ANTRIM & NEWTOWNABBEY	

Class: Unclassified **Environment:** RURAL **Traffic Level:** Low Traffic

Type: Ad Hoc Defect

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
DCD92-3082543-13	DEFECT	junct boghill rd and hydepark rd	R4 - next available programme			

Comments: brambles grass branches to be cut for sighlines at junction of boghill and hydepark rd can this be done asap please

Defect Date: 30-July-2020

Defect Category: TREES/BUSHES OVERHANGING PAVEMENT (TBOP)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
G01001A	^ Unplanned envir. work norm.hrs (2-man operation)	1.00	HR	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Copyright

Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 12/08/2019
Until Less Than: 12/08/2024

Section:
7035U0011_01 BOGHILL RD1: HYDEPARK RD TO FLUSH RD (DIV. BOUNDARY)

Commencement date of Inspection: Ad Hoc Defect - See I **Inspect History ID & Description:** Ad Hoc Defect - No Inspection ID **Inspector Name:**

Class: Unclassified **Environment:** RURAL **Traffic Level:** Low Traffic

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
D2101915	DEFECT	Boghill rd 3/4 of length to flush rd	R4 - next available programme			

Comments: Please set tyres on verge for council collection

Defect Date: 27-January-2021

Defect Category: BONFIRE MATERIAL ON SURFACE (BMOS)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
Y26100A	Dispose debris	30.00	CU.M	L 60.00 W 0.50 D 0.00

Photographs or Documents attached: No

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions: Length (m):	Width (m):	Depth (mm):
D2112424	DEFECT	Opposite RHS of 55 Boghill Road	R3 - 4 Weeks	**0.90**	**0.90**	**51.00**

Comments: temporary bitmac patch

Defect Date: 28-April-2021

Defect Category: BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D30061A	^ Temp. patch 6mm deferred set 0-1m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Copyright

Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 12/08/2019
Until Less Than: 12/08/2024

Section:
7035U0011_01 BOGHILL RD1: HYDEPARK RD TO FLUSH RD (DIV. BOUNDARY)

Commencement date of Inspection: **Ad Hoc Defect - See I**

Inspect History ID & Description: Ad Hoc Defect - No Inspection ID

Inspector Name:

Class: Unclassified **Environment:** RURAL **Traffic Level:** Low Traffic

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions:
D249014977	DEFECT	?	R2 - 5 Working days	**Length (m):** 1.30 **Width (m):** 0.80 **Depth (mm):** 130.00

Comments: Job card instructed by [redacted] - inspected 13/2/24

Defect Date: 13-February-2024

Defect Category: BITMAC POTHOLE (CBPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D23222A	100mm deep Bitmac c/w patch (14mm wc in CGA/ 20mm bc in DAC) - 1-3 m2	2.53	m2	L 2.30 W 1.10 D 0.00

Photographs or Documents attached: No

Copyright