

# HORN

## INFORMATION

This inspection applies to all vehicles.

## METHOD OF INSPECTION

Operate the horn control and note the volume and character of the sound emitted.

## REASON FOR REJECTION

	<b>Deficiency Category</b>
1.	
a. The horn control missing or not readily accessible to the driver.	MAJOR
b. The horn control is insecure	MINOR
c. The horn is insecure	MINOR
d. The horn does not function properly	MINOR
e. The horn does not function.	MAJOR
f. The sound emitted by the horn is obviously not loud enough to be heard by another road user.	MAJOR
g. A gong, bell, siren or two or more tone horn fitted.	MAJOR

**Note:**

When operated, a two or more tone horn automatically produces a sound which alternates at regular intervals between fixed notes.

A vehicle is allowed to be fitted with a bell, gong or siren, but not two-tone, only as part of an anti-theft device.

- h. For a vehicle first used on or after 30 September 1976 a sound emitted by the horn is:

I. not a constant note

MINOR

II. not continuous or uniform

MINOR

III. harsh or grating

MINOR

Excluding ambulances.