



PLC Report

Selection Criteria:

Section Code Selected: 7065C0286_01

3ERA

Report Start Date: 24/07/2020 00:00:00

Section Description: BALLYLUCAS RD1: MINERSTOWN RD A2 TO BALLYNOE RD U1204

Report End Date (Less than): 24/07/2021 23:59:59

Enquiries

Enquiry ID	Enquiry Date	Received By	Enquirer's Name/Remark	Resp of	Class	Enquiry Cat/ Status/Type	Road ID/ Location
Public Enquiry							
W2199537	10-Jan-2021	PIP		DOWN	Informal	Public Enquiry Standard - Completed Enquiries	7065C0286_01 BALLYLUCAS RD1: MINERSTOWN RD A2 TO BALLYNOE RD U1204 ? Broken Flags / Kerbs
W2110325	30-Jun-2021	PIP		DOWN	Informal	Public Enquiry Standard - Completed Enquiries	7065C0286_01 BALLYLUCAS RD1: MINERSTOWN RD A2 TO BALLYNOE RD U1204 ? Broken Flags / Kerbs
W2110325	30-Jun-2021	PIP		DOWN	Informal	Public Enquiry Standard - Completed Enquiries	7065C0286_01 BALLYLUCAS RD1: MINERSTOWN RD A2 TO BALLYNOE RD U1204 ? Pothole
W2110325	30-Jun-2021	PIP		DOWN	Informal	Public Enquiry Standard - Completed Enquiries	7065C0286_01 BALLYLUCAS RD1: MINERSTOWN RD A2 TO BALLYNOE RD U1204 ? Broken Flags / Kerbs
W2110325	30-Jun-2021	PIP		DOWN	Informal	Public Enquiry Standard - Completed Enquiries	7065C0286_01 BALLYLUCAS RD1: MINERSTOWN RD A2 TO BALLYNOE RD U1204 ? Broken Flags / Kerbs

Inspection Defects

Defect Reference	Incident Date	Item Category/Detail	Location	Instruction Source	Defect Status	Response Time	Actual Completion
DCD98-3082444-16	27/07/2020	DEFECT	AT HSE 62		Completed	R2 - 5 Working days	31-Jul-2020
		BITMAC EDGE DETERIORATION (CBED)					Inspection Histroy Name/UID: 3 Monthly - Safety Inspection of 3ERA-DOWN on 24 July 2020 / 3082444
DCD98-3082444-17	27/07/2020	DEFECT	OPP HSE 62		Completed	R2 - 5 Working days	31-Jul-2020
		BITMAC EDGE DETERIORATION (CBED)					Inspection Histroy Name/UID: 3 Monthly - Safety Inspection of 3ERA-DOWN on 24 July 2020 / 3082444
DCD98-3082444-	27/07/2020	DEFECT	60m BEFORE JCT CASTLESCREEN RD		Completed	R4 - next	03-Aug-2020

WARNING FOR BEND AHEAD NEEDS
CUT BACK,

TRAFFIC SIGN OVERGROWN (TSOG)

Inspection Histroy Name/UID: 3 Monthly - Safety Inspection of 3ERA-DOWN on 24 July 2020 / 3082444

[DCD98-3083896-22](#)

22/10/2020

DEFECT

2m from glen rd

Completed

R2 - 5 Working days 29-Oct-2020

at F/H

BITMAC POTHOLE (CBPH)

Inspection Histroy Name/UID: 3 Monthly - Safety Inspection of 3ERA-DOWN on 20 October 2020 / 3083896

Defects Raised Outside of Inspections

Defect Reference	Incident Date	Item Category/Detail	Location	Instruction Source	Defect Status	Response Time	Actual Completion
D2106989	29/03/2021	DEFECT	In hollow before Glen Rd		Completed	R4 - next available programme	27-Sep-2021

Clean and jet gullies and manhole

GULLY BLOCKED (CGBL)

Inspection Histroy Name/UID: /

Inspections

Survey Date	Inspect History	Inspector	Driver	Weather	Surface Condit
27/07/2020	3082444 - 3 Monthly - Safety Inspection of 3ERA-DOWN on 24 July 2020			Raining	DRY
22/10/2020	3083896 - 3 Monthly - Safety Inspection of 3ERA-DOWN on 20 October 2020			Fine	DRY
20/01/2021	3085369 - 3 Monthly - Safety Inspection of 3ERA-DOWN on 18 January 2021			Fine	DRY



Inspection Report

Inspection Date: 26-Jul-2021 Inspect History ID: 3088288 - 3 Monthly - Safety Inspection of 3ERA-DOWN on 20 July 2021 Inspection Time: 3 Monthly - Safety Inspection
 Inspector: [REDACTED]

Section Code: 7065C0286_01 Section Description: BALLYLUCAS RD1: MINERSTOWN RD A2 TO BALLYNOE RD U1204

Defect Ref: [DCD98-3088288-38](#) Defect Type: DEFECT Comments: stop/go req Location Description: on sweeping bend after ballynoe rd jut Priority: R3 - 4 Weeks Defect Dimensions: Length (m): 5.30 Width (m): 0.50 Depth (mm): 60.00

Recorded Date: 26-July-2021
 BITMAC EDGE DETERIORATION ON RURAL UNKERBED RD WITHIN 250MM OF RD EDGE (CBER)

Recorded By:

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D20053A	^ 70mm overlay bit.patch 14mm 3-15sqm.	3.24	SQ.M	L 5.40 W 0.60 D 0.00

Defect Ref: [DCD98-3088288-39](#) Defect Type: DEFECT Comments: remove/scrape bitmac lumps of rd and jetpatch defect Location Description: sweeping bend at castlescreen jut Priority: R4 - next available programme Defect Dimensions: Length (m): Width (m): Depth (mm):

Recorded Date: 26-July-2021
 DEBRIS STICKING TO SURFACE (DSSF)

Recorded By:

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
G01001A	^ Unplanned envir. work norm.hrs	2.00	HR	L 0.00 W 0.00 D 0.00

Inspection Date: 26-Jul-2021 Inspect History ID: 3088288 - 3 Monthly - Safety Inspection of 3ERA-DOWN on 20 July 2021 Inspection Time: 3 Monthly - Safety Inspection
 Inspector: [REDACTED]

Section Code: 7065C0286_01 Section Description: BALLYLUCAS RD1: MINERSTOWN RD A2 TO BALLYNOE RD U1204

Defect Ref: [DCD98-3088288-40](#) Defect Type: DEFECT Comments: at hydrant Location Description: at glen rd jut Priority: R2 - 5 Working days Defect Dimensions: Length (m): 0.60 Width (m): 0.50 Depth (mm): 55.00

Recorded Date: 26-July-2021 BITMAC POTHOLE (CBPH)
 Recorded By:

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D20051A	^ 70mm overlay bit.patch 14mm 0-1sqm.	1.00	no	L 0.00 V 0.00 D 0.00

Inspection Date: 20-Oct-2021 Inspect History ID: 3089802 - 3 Monthly - Safety Inspection of 3ERA-DOWN on 19 October 2021 Inspection Time: 3 Monthly - Safety Inspection
 Inspector:

Section Code: 7065C0286_01 Section Description: BALLYLUCAS RD1: MINERSTOWN RD A2 TO BALLYNOE RD U1204

Defect Ref: [DCD98-3089802-19](#) Defect Type: DEFECT Comments: Location Description: opp glen rd jut Priority: R2 - 5 Working days Defect Dimensions: Length 0.40 Width (m): 0.40 Depth (mm): 55.00

Recorded Date: 20-October-2021 BITMAC POTHOLE (CBPH)
 Recorded By:

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D71021A	^ Velocity patch 0-1m2	1.00	no	L 0.00 V 0.00 D 0.00