

HORN

APPLICATION

This inspection applies to all vehicles.

PROCEDURE AND STANDARDS

Operate horn control and listen to sound emitted. Check controls and mounting. Vehicles first used from 31 Dec 1976 must have a horn that produces a continuous or uniform sound.

REASONS FOR FAILURE

	Deficiency Category
1. Horn control:	
a. Missing.	MAJOR
b. Cannot be reached easily from the driving seat.	MINOR
c. Insecure.	MINOR
2. Horn:	
a. Does not work.	MINOR
b. Is not loud enough to be heard by other road users.	MINOR
c. Sound not continuous or uniform.	MINOR
d. Insecure	MINOR