

# HORN

## APPLICATION

This inspection applies to all vehicles.

## PROCEDURE AND STANDARDS

Operate horn control and listen to sound emitted. Check controls and mounting. Vehicles first used from 31 Dec 1976 must have a horn that produces a continuous or uniform sound.

## REASONS FOR FAILURE

	<b>Deficiency Category</b>
1. Horn control:	
a. Missing.	MAJOR
b. Cannot be reached easily from the driving seat.	MAJOR
c. Insecure.	MINOR
2. Horn:	
a. Does not work.	MAJOR
b. Is not loud enough to be heard by other road users.	MAJOR
c. Sound not continuous or uniform.	MINOR
d. Insecure	MINOR