



# Inspection Report

<b>Inspection Date:</b> See Recorded Date	<b>Inspect History ID:</b> 3108260 - 1 Monthly - WFE Safety Inspection of C609-BANBRIDGE / CRAIGAVON on 09/02/2024	<b>Inspection Type:</b> 1 Monthly - WFE Safety Inspection
		<b>Inspector:</b>

<b>Section Code:</b> 7060C0706_01	<b>Section Description:</b> KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD
--------------------------------------	--

<b>Defect Ref:</b> <a href="#">DCD249016000</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b> Bt manhole surround deteriorating	<b>Location Description:</b> Outside kiln avenue	<b>Priority:</b> R2 - 5 Working days	<b>Defect Dimensions:</b> <b>Length (m): 2.50</b>	<b>Width (m): 1.35</b>	<b>Depth (mm): 90.00</b>
--	-------------------------------	---	---	---	--	------------------------	--------------------------

**Recorded Date:** 14-February-2024  
**Recorded By:** [REDACTED]

<b>Repair Description:</b> D24023A	<b>Repair Item Name:</b> ^ 70mm bit. patch w/c 3-15 m2	<b>Quantity:</b> 3.38	<b>Units:</b> SQ.M	<b>Repair Measures:</b> L 2.50 W 1.35 D 0.00
---------------------------------------	---	--------------------------	-----------------------	---

<b>Defect Ref:</b> <a href="#">DCD249021183</a>	<b>Defect Type:</b> THIRD PARTY REFERRAL	<b>Comments:</b> ?	<b>Location Description:</b> 10m from kiln avenue	<b>Priority:</b> R4 - next available programme	<b>Defect Dimensions:</b> <b>Length (m):</b>	<b>Width (m):</b>	<b>Depth (mm):</b>
--	---	-----------------------	--	---	---	-------------------	--------------------

**Recorded Date:** 20-February-2024  
**Recorded By:** [REDACTED]



# Inspection Report

<b>Inspection</b>	<b>Date: See Recorded Date</b>	<b>Inspect History ID: -</b>	<b>Inspection Type:</b>
			<b>Inspector:</b>

<b>Section Code:</b> 7060C0706_01	<b>Section Description:</b> KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD
--------------------------------------	--

<b>Defect Ref:</b> <a href="#">D249028121</a>	<b>Defect Type:</b> DEFECT	<b>Comments:</b> Make safe / replace manhole cover.  Made safe by O&M Steel Plate 1/3/24  Passed to Small Scale Contractor [REDACTED] repaired 2/3/24	<b>Location Description:</b> Kiln Road at Traffic Lights	<b>Priority</b> R2 - 5 Working days	<b>Defect Dimensions:</b> <b>Length (m): 50.00</b>	<b>Width (m): 0.00</b>	<b>Depth (mm): 0.00</b>
--	-------------------------------	--	---	--	---	------------------------	-------------------------

**Recorded Date:** 28-February-2024  
**Recorded By:** [REDACTED]

**MANHOLE LID/COVER BROKEN (MMBR)**

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
<b>U06050A</b>	<b>Gully top (D400) 150mm deep x (600mm x 600mm) double triangular</b>	<b>1.00</b>	<b>no</b>	<b>L 0.00 W 0.00 D 0.00</b>

<b>Defect Ref:</b> <a href="#">D249050507</a>	<b>Defect Type:</b> ROADS SERVICE EMERGENCY RESPONSE	<b>Comments:</b> Sign off loose Manhole Cover	<b>Location Description:</b> Kiln Road near Kiln Avenue	<b>Priority</b> R0 - As Soon As Practical	<b>Defect Dimensions:</b> <b>Length (m):</b>	<b>Width (m):</b>	<b>Depth (mm):</b>
--	---	--	--	--	---	-------------------	--------------------

**Recorded Date:** 08-April-2024  
**Recorded By:** [REDACTED]

**CULVERT / MANHOLE COLLAPSE (CMER)**

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
<b>G01001A</b>	<b>^ Unplanned envir. work norm.hrs (2-man operation)</b>	<b>1.00</b>	<b>HR</b>	<b>L 0.00 W 0.00 D 0.00</b>



# Inspection Report

<b>Inspection Date:</b> See Recorded Date	<b>Inspect History ID:</b> 3109180 - 1 Monthly - WFE Safety Inspection of C506-BANBRIDGE / CRAIGAVON on 04/04/2024	<b>Inspection Type:</b> 1 Monthly - WFE Safety Inspection
		<b>Inspector:</b>

<b>Section Code:</b> 7060C0706_01	<b>Section Description:</b> KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD
--------------------------------------	--

Defect Ref: [DCD249063156](#)      Defect Type: DEFECT      Comments: ?      Location Description: Lough road / kiln road traffic lights      Priority: R2 - 5 Working days      Defect Dimensions: Length (m): 1.50      Width (m): 0.90      Depth (mm): 85.00

Recorded Date: 24-April-2024      ASPHALT POTHOLE (CAPH)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures		
D24022A	^ 70mm bit. patch w/c 1-3 m2	1.72	SQ.M	L 1.50	W 1.15	D 0.00
D24022A	^ 70mm bit. patch w/c 1-3 m2	1.43	SQ.M	L 1.30	W 1.10	D 0.00
D24021A	^ 70mm bit. patch w/c <1 m2	1.00	no	L 0.00	W 0.00	D 0.00



# Inspection Report

Inspection Date: 3-Mar-2024      Inspect History ID: 3108149 - 3 Monthly - WFE Safety Inspection of C506-BANBRIDGE / CRAIGAVON on 04/02/2024      Inspection Type: 3 Monthly - WFE Safety Inspection  
 Inspector: [REDACTED]

Section Code: 7060C0706\_01      Section Description: KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD

Defect Ref: [DCD249030066](#)      Defect Type: DEFECT      Comments: ?      Location Description: At Silverwood Green junction      Priority: R3 - 4 Weeks      Defect Dimensions: Length (m): 0.40      Width (m): 0.30      Depth (mm): 27.00

Recorded Date: 03-March-2024      ASPHALT POTHOLE (CAPH)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D24421A	70mm deep Bitmac W/C patch in 14mm CGA - 0-1 m2	1.00	no	L 0.00      W 0.00      D 0.00

Defect Ref: [DCD249030067](#)      Defect Type: THIRD PARTY REFERRAL      Comments: Cover noisy. Damage to surrounding area      Location Description: Near Kiln Lane junction      Priority: R4 - next available programme      Defect Dimensions: Length (m):      Width (m):      Depth (mm):

Recorded Date: 03-March-2024      UTILITY MANHOLE LID/COVER DEFECTIVE (UMDF)

Recorded By: [REDACTED]



# Inspection Report

Inspection Date: 3-Mar-2024

Inspect History ID: 3108149 - 3 Monthly - WFE Safety Inspection of C506-BANBRIDGE / CRAIGAVON on 04/02/2024

Inspection Type: 3 Monthly - WFE Safety Inspection

Inspector: [REDACTED]

Section Code:  
7060C0706\_01

Section Description:  
KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD

Defect Ref: <a href="#">DCD249030068</a>	Defect Type: THIRD PARTY REFERRAL	Comments: Covers noisy. Damage to surrounding area	Location Description: Near Kiln Avenue junction	Priority: R4 - next available programme	Defect Dimensions:			
					Length (m):	Width (m):	Depth (mm):	
Recorded Date: 03-March-2024	UTILITY MANHOLE LID/COVER DEFECTIVE (UMDF)							

Recorded By:  
[REDACTED]



# Inspection Report

Inspection Date: 7-May-2024      Inspect History ID: 3109706 - 3 Monthly - WFE Safety Inspection of C506-BANBRIDGE / CRAIGAVON on 04/05/2024      Inspection Type: 3 Monthly - WFE Safety Inspection  
 Inspector: [REDACTED]

Section Code: 7060C0706\_01      Section Description: KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD

Defect Ref: [DCD249073395](#)      Defect Type: DEFECT      Comments: ?      Location Description: 10m from silverwood green      Priority: R2 - 5 Working days      Defect Dimensions: Length (m): 0.72      Width (m): 0.72      Depth (mm): 52.00

Recorded Date: 08-May-2024      BITMAC POTHOLE (CBPH)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D24021A	^ 70mm bit. patch w/c <1 m2	1.00	no	L 0.00      W 0.00      D 0.00

Defect Ref: [DCD249073405](#)      Defect Type: DEFECT      Comments: ?      Location Description: 5m from silverwood green      Priority: R2 - 5 Working days      Defect Dimensions: Length (m): 1.20      Width (m): 0.48      Depth (mm): 84.00

Recorded Date: 08-May-2024      BITMAC POTHOLE (CBPH)

Recorded By: [REDACTED]

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures
D24021A	^ 70mm bit. patch w/c <1 m2	1.00	no	L 0.00      W 0.00      D 0.00



# Inspection Report

Inspection Date: 7-May-2024      Inspect History ID: 3109706 - 3 Monthly - WFE Safety Inspection of C506-BANBRIDGE / CRAIGAVON on 04/05/2024      Inspection Type: 3 Monthly - WFE Safety Inspection  
 Inspector: [REDACTED]

Section Code: 7060C0706\_01      Section Description: KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD

Defect Ref:	Defect Type:	Comments:	Location Description:	Priority	Defect Dimensions:		
<a href="#">DCD249073416</a>	THIRD PARTY REFERRAL	Low and noisy  NIW notified NISRANS LA REF 1433936	Opp kiln vale	From Matrix	Length (m): 0.00	Width (m): 0.00	Depth (mm): 0.00
Recorded Date:	UTILITY MANHOLE LID/COVER LOW (UMLO)						
08-May-2024							
Recorded By:	[REDACTED]						

## Selection Criteria:

Section Code Selected: 7060C0706\_01

C506

Report Start Date: 28/01/2022 00:00:00

Section Description: KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD

Report End Date (Less than): 29/01/2024 00:00:00

## Enquiries

Enquiry ID	Enquiry Date	Received By	Enquirer's Name/Remark	Resp of	Class	Enquiry Cat/ Status/Type	Road ID/ Location
<b>Call Centre Incident (Major)</b>							
<a href="#">W221112818</a>	01-Nov-2022	PIP	[REDACTED]	[REDACTED]	Informal	Call Centre Incident (Major) High Priority - Completed Collapsed Manhole or Culvert	7060C0706_01 KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD ?
<a href="#">W221115025</a>	11-Nov-2022	PIP	[REDACTED]	[REDACTED]	Informal	Call Centre Incident (Major) High Priority - Completed Collapsed Manhole or Culvert	7060C0706_01 KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD At Jun Lough Road.
<b>Call Centre Public Enquiry</b>							
<a href="#">W231140619</a>	26-Jan-2023	PIP	[REDACTED]	[REDACTED]	Informal	Call Centre Public Enquiry Standard - Completed Enquiries Pothole	7060C0706_01 KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD ?
<b>Complaint</b>							
<a href="#">W221092777</a>	06-Jul-2022	PIP	[REDACTED]	[REDACTED]	Informal	Complaint Standard - Completed Enquiries Hedge / Tree	7060C0706_01 KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD ?
<b>Incident (major)</b>							
<a href="#">W221117960</a>	26-Nov-2022	PIP	[REDACTED]	BANBRIDGE/C RAIGAVON	Informal	Incident (major) High Priority - Completed Manhole Cover missing	7060C0706_01 KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD ?
<b>Public Enquiry</b>							



# PLC Report

**Selection Criteria:**

Section Code Selected: 7060C0706\_01

C506

Report Start Date: 28/01/2022 00:00:00

Section Description: KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD

Report End Date (Less than): 29/01/2024 00:00:00

## Enquiries

<u>Enquiry ID</u>	<u>Enquiry Date</u>	<u>Received By</u>	<u>Enquirer's Name/Remark</u>	<u>Resp of</u>	<u>Class</u>	<u>Enquiry Cat/ Status/Type</u>	<u>Road ID/ Location</u>
<b>Public Enquiry</b>							
<a href="#">E2201989</a>	05-May-2022				Informal	Public Enquiry Standard - Completed Enquiries Pothole	7060C0706_01 KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD Hello A new incident has been submitted. View Incident  Date: 05/03/2022, 20:16:27  Latitude: -6.35169524699449 Longitude: 54.4768380819917 Address: Lough Road, Lurgan, Craigavon, County Armagh, Northern Ireland, BT66 6, GBRPostcode: BT66 6 Category: Potholes Council: NI Roads Notes: Potholes on entrance to kiln road
<a href="#">E2203145</a>	18-Jul-2022				Informal	Public Enquiry Standard - Completed Enquiries Hedge / Tree	7060C0706_01 KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD Hi,  I've received a complaint about an overgrown hedge beside the footpath at the junction of Kiln road and lough road. I understand two children crashed into each other on their bikes as they could see each other around the corner. Could this hedge be cut back urgently?  Kind regards, Cllr Peter Lavery,
<a href="#">W221108528</a>	10-Oct-2022	PIP			Informal	Public Enquiry Standard - Completed Enquiries Noisy Manhole	7060C0706_01 KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD ?
<a href="#">W221110615</a>	23-Oct-2022	PIP			Informal	Public Enquiry Standard - Completed Enquiries Sunken Manhole	7060C0706_01 KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD ?

**Selection Criteria:**

Section Code Selected: 7060C0706\_01

C506

Report Start Date: 28/01/2022 00:00:00

Section Description: KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD

Report End Date (Less than): 29/01/2024 00:00:00

## Enquiries

Enquiry ID	Enquiry Date	Received By	Enquirer's Name/Remark	Resp of	Class	Enquiry Cat/ Status/Type	Road ID/ Location
<b>Public Enquiry</b>							
<a href="#">W221111248</a>	26-Oct-2022	PIP	[REDACTED]	[REDACTED]	Informal	Public Enquiry Standard - Completed Enquiries Other Surface Defect (e.g. broken flag / kerb)	7060C0706_01 KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD ?
<a href="#">W221114759</a>	09-Nov-2022	PIP	[REDACTED]	[REDACTED]	Informal	Public Enquiry Standard - New Sunken Manhole	7060C0706_01 KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD ?
<a href="#">W221115335</a>	14-Nov-2022	PIP	[REDACTED]	[REDACTED]	Informal	Public Enquiry Standard - New Other Surface Defect (e.g. broken flag / kerb)	7060C0706_01 KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD ?
<a href="#">E2204825</a>	15-Nov-2022	[REDACTED]	Carla Lockhart	BANBRIDGE/C RAIGAVON	Informal	Public Enquiry Standard - Completed Enquiries Damaged Ironwork	7060C0706_01 KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD To whom it may concern:  I have been contacted in relation to a loose manhole cover at the junction with Kiln Road / Lough Road, Lurgan (please see attached pic).  I would be most grateful if the area could be inspected and the appropriate work carried out to rectify this problem.  Kind Regards  Carla
<a href="#">E2204847</a>	17-Nov-2022	[REDACTED]	[REDACTED]	BANBRIDGE/C RAIGAVON	Informal	Public Enquiry Standard - Completed Enquiries Ironwork	7060C0706_01 KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD Near Lough Road jct - manhole low on one side near traffic lights at Lough Road jct
<a href="#">W221116365</a>	21-Nov-2022	PIP	[REDACTED]	[REDACTED]	Informal	Public Enquiry Standard - Completed Enquiries Sunken Manhole	7060C0706_01 KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD At Jun Lough Road.

**Selection Criteria:**

Section Code Selected: 7060C0706\_01

C506

Report Start Date: 28/01/2022 00:00:00

Section Description: KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD

Report End Date (Less than): 29/01/2024 00:00:00

## Enquiries

Enquiry ID	Enquiry Date	Received By	Enquirer's Name/Remark	Resp of	Class	Enquiry Cat/ Status/Type	Road ID/ Location
<b>Public Enquiry</b>							
<a href="#">E2204866</a>	21-Nov-2022	[REDACTED]	[REDACTED]	[REDACTED]	Informal	Public Enquiry Standard - Completed Enquiries Damaged Ironwork	7060C0706_01 KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD Hi,  There is a broken manhole lid at the junction of Kiln Road and Lough Road in the Annesborough area of Lurgan (see pic attached). It has been reported for three weeks now put has yet to be repaired. Could an update be urgently provided as to when this will be repaired as a few residents have contacted me saying it has caused their car damage.  Kind regards,
<a href="#">W221117952</a>	25-Nov-2022	PIP	[REDACTED]	[REDACTED]	Informal	Public Enquiry Standard - New Sunken Manhole	7060C0706_01 KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD ?
<a href="#">W221117980</a>	26-Nov-2022	PIP	[REDACTED]	[REDACTED]	Informal	Public Enquiry Standard - New Other Surface Defect (e.g. broken flag / kerb)	7060C0706_01 KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD ?
<a href="#">W231167564</a>	08-May-2023	PIP	[REDACTED] psni	BANBRIDGE/C RAIGAVON	Informal	Public Enquiry High Priority - Completed Gully Lid Missing	7060C0706_01 KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD ?
<a href="#">W231167566</a>	08-May-2023	PIP	[REDACTED]	[REDACTED]	Informal	Public Enquiry Standard - Completed Enquiries Other Surface Defect (e.g. broken flag / kerb)	7060C0706_01 KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD ?
<a href="#">W241223752</a>	07-Jan-2024	PIP	[REDACTED]	[REDACTED]	Informal	Public Enquiry Standard - New Missing or Faded Road Marks	7060C0706_01 KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD ?



# PLC Report

**Selection Criteria:**

Section Code Selected: 7060C0706\_01

C506

Report Start Date: 28/01/2022 00:00:00

Section Description: KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD

Report End Date (Less than): 29/01/2024 00:00:00

## Enquiries

<u>Enquiry ID</u>	<u>Enquiry Date</u>	<u>Received By</u>	<u>Enquirer's Name/Remark</u>	<u>Resp of</u>	<u>Class</u>	<u>Enquiry Cat/ Status/Type</u>	<u>Road ID/ Location</u>
<b>Public Enquiry</b>							
<a href="#">W241230446</a>	21-Jan-2024	PIP	[REDACTED]	[REDACTED]	Informal	Public Enquiry Standard - Completed Enquiries Pothole	7060C0706_01 KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD ?
<b>Public Traffic Signal Enquiry</b>							
<a href="#">W221094448</a>	21-Jul-2022	PIP	[REDACTED]	BANBRIDGE/C RAIGAVON	Informal	Public Traffic Signal Enquiry Traffic Signal Issue (Noticed) Signal Operation Fault	7060C0706_01 KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD ?
<a href="#">W221110926</a>	25-Oct-2022	PIP	[REDACTED]	BANBRIDGE/C RAIGAVON	Informal	Public Traffic Signal Enquiry Traffic Signal Issue (Noticed) All Signals Out	7060C0706_01 KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD ?



# PLC Report



## Selection Criteria:

Section Code Selected: 7060C0706\_01

C506

Report Start Date: 28/01/2022 00:00:00

Section Description: KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD

Report End Date (Less than): 29/01/2024 00:00:00

## Inspection Defects

Defect Reference	Incident Date	Item Category/Detail	Location	Instruction Source	Defect Status	Response Time	Actual Completion
<a href="#">DCD73-3091475-1</a> <a href="#">5</a>	03/02/2022	DEFECT CARRIAGEWAY MANHOLE LID/COVER LOW (CMLO)	OPP SL 0132		Completed	R2 - 5 Working days	07-Feb-2022
<b>Inspection Histroy Name/UID:</b> 3 Monthly - Safety Inspection of C506-BANBRIDGE / CRAIGAVON on 03 February 2022 / 3091475							
<a href="#">DCD73-3093034-1</a> <a href="#">7</a>	10/05/2022	DEFECT BITMAC POTHOLE (CBPH)	10M SILVERWOOD GREEN		Completed	R2 - 5 Working days	17-May-2022
<b>Inspection Histroy Name/UID:</b> 3 Monthly - Safety Inspection of C506-BANBRIDGE / CRAIGAVON on 10 May 2022 / 3093034							
<a href="#">DCD73-3093034-1</a> <a href="#">8</a>	10/05/2022	THIRD PARTY REFERRAL NOISY LA REF 1266992	SL 0121 UTILITY MANHOLE LID/COVER DEFECTIVE (UMDF)		Third Party Referral	R4 - next available programme	11-May-2022
<b>Inspection Histroy Name/UID:</b> 3 Monthly - Safety Inspection of C506-BANBRIDGE / CRAIGAVON on 10 May 2022 / 3093034							
<a href="#">DCD73-3093034-4</a> <a href="#">6</a>	11/05/2022	DEFECT FOOTPATH KERB HIGH (FKHI)	HO 8		Completed	R2 - 5 Working days	17-May-2022
<b>Inspection Histroy Name/UID:</b> 3 Monthly - Safety Inspection of C506-BANBRIDGE / CRAIGAVON on 10 May 2022 / 3093034							
<a href="#">DCD73-3093034-4</a> <a href="#">7</a>	11/05/2022	DEFECT REMOVE SIGN FROM VERGE	AT SILVERWOOD RD DEBRIS ON SURFACE (DOSF)		Completed	R4 - next available programme	26-Aug-2022
<b>Inspection Histroy Name/UID:</b> 3 Monthly - Safety Inspection of C506-BANBRIDGE / CRAIGAVON on 10 May 2022 / 3093034							
<a href="#">DCD73-3094512-1</a> <a href="#">8</a>	03/08/2022	THIRD PARTY REFERRAL NOISY LA REF 1182169	SL 0119 UTILITY MANHOLE LID/COVER DEFECTIVE (UMDF)		Third Party Referral	R4 - next available programme	04-Aug-2022
<b>Inspection Histroy Name/UID:</b> 3 Monthly - Safety Inspection of C506-BANBRIDGE / CRAIGAVON on 03 August 2022 / 3094512							



# PLC Report



## Selection Criteria:

Section Code Selected: 7060C0706\_01

C506

Report Start Date: 28/01/2022 00:00:00

Section Description: KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD

Report End Date (Less than): 29/01/2024 00:00:00

## Inspection Defects

Defect Reference	Incident Date	Item Category/Detail	Location	Instruction Source	Defect Status	Response Time	Actual Completion
<a href="#">DCD73-3094512-19</a>	03/08/2022	DEFECT BITMAC POTHOLE (CBPH)	10M SL 0130		Completed	R2 - 5 Working days	05-Aug-2022
				<b>Inspection Histroy Name/UID:</b> 3 Monthly - Safety Inspection of C506-BANBRIDGE / CRAIGAVON on 03 August 2022 / 3094512			
<a href="#">DCD73-3094512-20</a>	03/08/2022	DEFECT BITMAC POTHOLE (CBPH)	SL 0132		Completed	R2 - 5 Working days	05-Aug-2022
				<b>Inspection Histroy Name/UID:</b> 3 Monthly - Safety Inspection of C506-BANBRIDGE / CRAIGAVON on 03 August 2022 / 3094512			
<a href="#">DCD73-3094512-21</a>	03/08/2022	THIRD PARTY REFERRAL NOISY LA REF 1289073 UTILITY MANHOLE LID/COVER DEFECTIVE (UMDF)	HO 32		Third Party Referral	R4 - next available programme	04-Aug-2022
				<b>Inspection Histroy Name/UID:</b> 3 Monthly - Safety Inspection of C506-BANBRIDGE / CRAIGAVON on 03 August 2022 / 3094512			
<a href="#">DCD73-3095757-7</a>	19/10/2022	THIRD PARTY REFERRAL LA REF 1309191 UTILITY MANHOLE LID/COVER BROKEN (UMBR)	TRAFFKC LIGHTS KILN RD		Third Party Referral	R2 - 5 Working days	20-Oct-2022
				<b>Inspection Histroy Name/UID:</b> 6 Monthly - Safety Inspection of C605-BANBRIDGE / CRAIGAVON on 19 October 2022 / 3095757			
<a href="#">DCD73-3096027-12</a>	01/11/2022	DEFECT BITMAC POTHOLE (CBPH)	SL 0132		Completed	R2 - 5 Working days	02-Nov-2022
				<b>Inspection Histroy Name/UID:</b> 3 Monthly - Safety Inspection of C506-BANBRIDGE / CRAIGAVON on 01 November 2022 / 3096027			
<a href="#">DCD238790439</a>	03/02/2023	DEFECT BITMAC POTHOLE (CBPH)	Opp sl 0132		Completed	R2 - 5 Working days	08-Feb-2022
				<b>Inspection Histroy Name/UID:</b> 3 Monthly - Safety Inspection of C506 - BANBRIDGE / CRAIGAVON 04/02/2023 / 3101593			
<a href="#">DCD238861249</a>	05/05/2023	DEFECT ASPHALT POTHOLE (CAPH)	At lough rd		Work Not Done	R2 - 5 Working days	11-May-2022
				<b>Inspection Histroy Name/UID:</b> 3 Monthly - WFE Safety Inspection of C506 - BANBRIDGE / CRAIGAVON on 04/05/2023 / 3103281			



# PLC Report

**Selection Criteria:**

Section Code Selected: 7060C0706\_01

C506

Report Start Date: 28/01/2022 00:00:00

Section Description: KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD

Report End Date (Less than): 29/01/2024 00:00:00

## Inspection Defects

Defect Reference	Incident Date	Item Category/Detail	Location	Instruction Source	Defect Status	Response Time	Actual Completion
<a href="#">DCD238861264</a>	05/05/2023	DEFECT	Opposite sl 0132		Completed	R2 - 5 Working days	11-May-202
?		BITMAC POTHOLE (CBPH)		<b>Inspection Histroy Name/UID:</b> 3 Monthly - WFE Safety Inspection of C506 - BANBRIDGE / CRAIGAVON on 04/05/2023 / 3103281			
<a href="#">DCD238988195</a>	28/12/2023	DEFECT	At Annsborough traffic lights		Completed	R2 - 5 Working days	05-Jan-2024
?		BITMAC POTHOLE (CBPH)		<b>Inspection Histroy Name/UID:</b> Full Sector - WFE Safety Inspection of South Adhoc on 13/09/2023 / 3106541			

**Selection Criteria:**

Section Code Selected: 7060C0706\_01

C506

Report Start Date: 28/01/2022 00:00:00

Section Description: KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD

Report End Date (Less than): 29/01/2024 00:00:00

## Defects Raised Outside of Inspections

Defect Reference	Incident Date	Item Category/Detail	Location	Instruction Source	Defect Status	Response Time	Actual Completion
<a href="#">D228664285</a>	19/07/2022	DEFECT	Kiln Road around bend at Lough Road Junction. - Verge and hedge overgrowing footpath.		Completed	R4 - next available programme	29-Jul-2022
Cut back verged and hedge at back of footpath - DFI Land		VERGE GRASS OVERGROWN (VGOG)	Inspection Histroy Name/UID: /				
<a href="#">D228733284</a>	01/11/2022	ROADS SERVICE EMERGENCY RESPONSE	52 Kiln Road		Completed	R0 - As Soon As Practical	01-Nov-202
NIWater MH cover in chamber - sign off.		MANHOLE LID MISSING (MHER)	Inspection Histroy Name/UID: /				
<a href="#">D228752783</a>	28/11/2022	DEFECT	Kiln Road at Jun Lough Road.		Works Order Issued	R2 - 5 Working days	01-Jan-9999
?		CARRIAGEWAY MANHOLE LID/COVER BROKEN (CMBR)	Inspection Histroy Name/UID: /				
<a href="#">D238863802</a>	10/05/2023	DEFECT	Kiln road near recently repaired MH BY niwater		Completed	R4 - next available programme	12-May-202
Lift signs & cones placed by out of hours.		TRAFFIC SIGN DISPLACED (TSDI)	Inspection Histroy Name/UID: /				



# PLC Report

**Selection Criteria:**

Section Code Selected: 7060C0706\_01

C506

Report Start Date: 28/01/2022 00:00:00

Section Description: KILN RD1: A0076 02 LOUGH RD TO B0002 24 SILVERWOOD RD

Report End Date (Less than): 29/01/2024 00:00:00

## Inspections

Survey Date	Inspect History	Inspector	Driver	Weather	Surface
03/02/2022	3091475 - 3 Monthly - Safety Inspection of C506-BANBRIDGE / CRAIGAVON on 03 February 2022	█		Fine	DRY
10/05/2022	3093034 - 3 Monthly - Safety Inspection of C506-BANBRIDGE / CRAIGAVON on 10 May 2022	█		Fine	DRY
03/08/2022	3094512 - 3 Monthly - Safety Inspection of C506-BANBRIDGE / CRAIGAVON on 03 August 2022	█		Fine	DRY
01/11/2022	3096027 - 3 Monthly - Safety Inspection of C506-BANBRIDGE / CRAIGAVON on 01 November 2022	█		Fine	DRY
03/02/2023	3101593 - 3 Monthly - Safety Inspection of C506 - BANBRIDGE / CRAIGAVON on 04/02/2023	█	█	Fine	DRY
05/05/2023	3103281 - 3 Monthly - WFE Safety Inspection of C506 - BANBRIDGE / CRAIGAVON on 04/05/2023	█	█	Fine	DRY
10/08/2023	3104745 - 3 Monthly - WFE Safety Inspection of C506 - BANBRIDGE / CRAIGAVON on 04/08/2023	█	█	Fine	DRY
16/11/2023	3106358 - 3 Monthly - WFE Safety Inspection of C506 - BANBRIDGE / CRAIGAVON on 04/11/2023	█		Fine	DRY