



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/11/2022  
Until Less Than: 27/11/2024

**Section:**  
7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	17 Sep 2024	<b>Inspect History ID &amp; Description:</b>	3112256 - Full Sector - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

**Ref:** [DCD249144142](#)      **Defect Type:** DEFECT      **Location Description:** Ch 710 rhs      **Priority:** R2 - 5 Working days      **Defect Dimensions:** Length (m): 1.30      Width (m): 0.70      Depth (mm): 80.00

**Comments:** ?

**Defect Date:** 17-September-2024      **Defect Category:** ASPHALT POTHOLE (CAPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D13231A	100mm deep Asphalt c/w patch (14mm wc/ 20mm bc in HRA, 14/20 chips) - 0-1 m2	1.00	no	L 0.00      W 0.00      D 0.00

**Photographs or Documents attached:** No

**Ref:** [DCD249144150](#)      **Defect Type:** DEFECT      **Location Description:** Ch 540 rhs      **Priority:** R2 - 5 Working days      **Defect Dimensions:** Length (m): 1.40      Width (m): 0.60      Depth (mm): 80.00

**Comments:** ?

**Defect Date:** 17-September-2024      **Defect Category:** ASPHALT POTHOLE (CAPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D13231A	100mm deep Asphalt c/w patch (14mm wc/ 20mm bc in HRA, 14/20 chips) - 0-1 m2	1.00	no	L 0.00      W 0.00      D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/11/2022  
Until Less Than: 27/11/2024

**Section:**  
7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	17 Sep 2024	<b>Inspect History ID &amp; Description:</b>	3112256 - Full Sector - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

**Ref:** [DCD249144161](#)      **Defect Type:** DEFECT      **Location Description:** At BT pole 7162 rhs      **Priority:** R2 - 5 Working days      **Defect Dimensions:** Length (m): 3.30      Width (m): 1.40      Depth (mm): 57.00

**Comments:** ?

**Defect Date:** 17-September-2024      **Defect Category:** ASPHALT POTHOLE (CAPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D13233A	100mm deep Asphalt c/w patch (14mm wc/ 20mm bc in HRA, 14/20 chips) - 3-15 m2	4.62	m2	L 3.30      W 1.40      D 0.00

**Photographs or Documents attached:** No

**Ref:** [DCD249144171](#)      **Defect Type:** DEFECT      **Location Description:** Opposite house number 317 / patch is on the left      **Priority:** R2 - 5 Working days      **Defect Dimensions:** Length (m): 3.00      Width (m): 1.00      Depth (mm): 55.00

**Comments:** ?

**Defect Date:** 17-September-2024      **Defect Category:** ASPHALT POTHOLE (CAPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D13232A	100mm deep Asphalt c/w patch (14mm wc/ 20mm bc in HRA, 14/20 chips) - 1-3 m2	3.00	m2	L 3.00      W 1.00      D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/11/2022  
Until Less Than: 27/11/2024

**Section:**  
7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	17 Sep 2024	<b>Inspect History ID &amp; Description:</b>	3112256 - Full Sector - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

**Ref:** [DCD249144178](#)  
**Defect Type:** DEFECT  
**Location Description:** Before house number 317 / patch is on the left  
**Priority:** R2 - 5 Working days  
**Defect Dimensions:** Length (m): 7.00 Width (m): 0.60 Depth (mm): 58.00  
**Comments:** ?  
**Defect Date:** 17-September-2024  
**Defect Category:** ASPHALT EDGE DETERIORATION (CAED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D13233A	100mm deep Asphalt c/w patch (14mm wc/ 20mm bc in HRA, 14/20 chips) - 3-15 m2	4.20	m2	L 7.00 W 0.60 D 0.00

**Photographs or Documents attached:** No

**Ref:** [DCD249144190](#)  
**Defect Type:** DEFECT  
**Location Description:** Ch 1610 lhs  
**Priority:** R2 - 5 Working days  
**Defect Dimensions:** Length (m): 2.00 Width (m): 1.00 Depth (mm): 60.00  
**Comments:** ?  
**Defect Date:** 17-September-2024  
**Defect Category:** ASPHALT POTHOLE (CAPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D13232A	100mm deep Asphalt c/w patch (14mm wc/ 20mm bc in HRA, 14/20 chips) - 1-3 m2	2.00	m2	L 2.00 W 1.00 D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/11/2022  
Until Less Than: 27/11/2024

**Section:**  
7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	17 Sep 2024	<b>Inspect History ID &amp; Description:</b>	3112256 - Full Sector - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

**Ref:** [DCD249144200](#)      **Defect Type:** THIRD PARTY REFERRAL      **Location Description:** Bt Manhole lid frame loose rattling rocking sunk at BT pole 904 rhs      **Priority:** R4 - next available programme      **Defect Dimensions:** Length (m):      Width (m):      Depth (mm):

**Comments:** ?

**Defect Date:** 17-September-2024      **Defect Category:** UTILITY MANHOLE LID/COVER DEFECTIVE (UMDF)

**Photographs or Documents attached:** Yes

<b>Ref:</b> <a href="#">DCD249144216</a>	<b>Defect Type:</b> DEFECT	<b>Location Description:</b> Ch 1845 rhs / @ BT Pole 903 rh	<b>Priority:</b> R2 - 5 Working days	<b>Defect Dimensions:</b> Length (m): 1.30      Width (m): 0.60      Depth (mm): 54.00	
<b>Comments:</b> ?					
<b>Defect Date:</b> 17-September-2024	<b>Defect Category:</b> ASPHALT POTHOLE (CAPH)				
	<b>Repair Losi Code:</b>	<b>Repair Item Name:</b>	<b>Quantity</b>	<b>Units</b>	<b>Repair Measures</b>
	D13231A	100mm deep Asphalt c/w patch (14mm wc/ 20mm bc in HRA, 14/20 chips) - 0-1 m2	1.00	no	L 0.00      W 0.00      D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/11/2022  
Until Less Than: 27/11/2024

**Section:**  
7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	17 Sep 2024	<b>Inspect History ID &amp; Description:</b>	3112256 - Full Sector - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

<b>Ref:</b> <a href="#">DCD249144223</a>	<b>Defect Type:</b> DEFECT	<b>Location Description:</b> Outlets and gullies need cleaned complete stretch lhs and rhs/ complaint from residents road flooding.	<b>Priority</b> R4 - next available programme	<b>Defect Dimensions:</b> <b>Length (m):</b>	<b>Width (m):</b>	<b>Depth (mm):</b>
<b>Comments:</b>	?					
<b>Defect Date:</b> 17-September-2024	<b>Defect Category:</b> VERGE OUTLET OVERGROWN (VOOG)	<b>Completion Comments:</b> r4				

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
X41000A	^ Scheduled cleaning of roadside outlet	1.00	no	L 0.00	W 0.00	D 0.00
X77000A	^ Scheduled cleaning of gully surround	1.00	no	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No

<b>Ref:</b> <a href="#">DCD249144247</a>	<b>Defect Type:</b> THIRD PARTY REFERRAL	<b>Location Description:</b> Bt Manhole lid frame loose rattling rocking sunk near house number 333 rhs	<b>Priority</b> R4 - next available programme	<b>Defect Dimensions:</b> <b>Length (m): 0.80</b>	<b>Width (m): 0.80</b>	<b>Depth (mm): 60.00</b>
<b>Comments:</b>	?					
<b>Defect Date:</b> 17-September-2024	<b>Defect Category:</b> UTILITY MANHOLE LID/COVER DEFECTIVE (UMDF)					

**Photographs or Documents attached:** Yes



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/11/2022  
Until Less Than: 27/11/2024

**Section:**  
7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	17 Sep 2024	<b>Inspect History ID &amp; Description:</b>	3112256 - Full Sector - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

<b>Ref:</b> <a href="#">DCD249144266</a>	<b>Defect Type:</b> DEFECT	<b>Location Description:</b> At house number 333 rhs / Ch 2190 rhs gully blocked needs cleaning and jetting complaint from resident, flooding at entrance.	<b>Priority</b> R4 - next available programme	<b>Defect Dimensions:</b> <b>Length (m):</b>	<b>Width (m):</b>	<b>Depth (mm):</b>
<b>Comments:</b>	?					
<b>Defect Date:</b> 17-September-2024	<b>Defect Category:</b> GULLY BLOCKED (CGBL)	<b>Completion Comments:</b> PASSED TO G TOWN				

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
X15011A	^ Responsive machine gully emptying	1.00	no	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** Yes

<b>Ref:</b> <a href="#">DCD249144298</a>	<b>Defect Type:</b> DEFECT	<b>Location Description:</b> Ch 0 to Ch 3040 lhs and rhs	<b>Priority</b> R4 - next available programme	<b>Defect Dimensions:</b> <b>Length (m):</b>	<b>Width (m):</b>	<b>Depth (mm):</b>
<b>Comments:</b>	Cut briars lhs and rhs					
<b>Defect Date:</b> 17-September-2024	<b>Defect Category:</b> TREES/BUSHES OVERHANGING PAVEMENT (TBOP)	<b>Completion Comments:</b> r4				

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
G42100A	^ Cut occassional briars both sides of roa	3.04	km	L 3.04	W 0.00	D 0.00

**Photographs or Documents attached:** No



## Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**

From: 01/11/2022

Until Less Than: 27/11/2024

**Section:**

7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

**Stretch Comments:**



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/11/2022  
Until Less Than: 27/11/2024

**Section:**  
7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	25 Jun 2024	<b>Inspect History ID &amp; Description:</b>	3110587 - 1 and 3 Monthly - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

**Ref:** [DCD249105360](#)      **Defect Type:** DEFECT      **Location Description:** Ch 2110 rhs @ house number 333 rhs      **Priority:** R2 - 5 Working days      **Defect Dimensions:** Length (m): 0.80      Width (m): 0.70      Depth (mm): 60.00

**Comments:** ?

**Defect Date:** 25-June-2024      **Defect Category:** ASPHALT POTHOLE (CAPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D13231A	100mm deep Asphalt c/w patch (14mm wc/ 20mm bc in HRA, 14/20 chips) - 0-1 m2	1.00	no	L 0.00      W 0.00      D 0.00

**Photographs or Documents attached:** No

**Ref:** [DCD249105382](#)      **Defect Type:** DEFECT      **Location Description:** Ch 2550 rhs at BT box      **Priority:** R2 - 5 Working days      **Defect Dimensions:** Length (m): 1.30      Width (m): 0.50      Depth (mm): 95.00

**Comments:** ?

**Defect Date:** 25-June-2024      **Defect Category:** ASPHALT POTHOLE (CAPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D13231A	100mm deep Asphalt c/w patch (14mm wc/ 20mm bc in HRA, 14/20 chips) - 0-1 m2	1.00	no	L 0.00      W 0.00      D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/11/2022  
Until Less Than: 27/11/2024

**Section:**  
7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	25 Jun 2024	<b>Inspect History ID &amp; Description:</b>	3110587 - 1 and 3 Monthly - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

**Ref:** [DCD249105399](#)      **Defect Type:** DEFECT      **Location Description:** Ch 2935 rhs @ house number 347 rhs      **Priority:** R2 - 5 Working days      **Defect Dimensions:** Length (m): 0.70      Width (m): 0.50      Depth (mm): 54.00

**Comments:** ?

**Defect Date:** 25-June-2024      **Defect Category:** ASPHALT POTHOLE (CAPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D13231A	100mm deep Asphalt c/w patch (14mm wc/ 20mm bc in HRA, 14/20 chips) - 0-1 m2	1.00	no	L 0.00      W 0.00      D 0.00

**Photographs or Documents attached:** No

**Ref:** [DCD249105412](#)      **Defect Type:** DEFECT      **Location Description:** At Johnstonstown Road jct      **Priority:** R2 - 5 Working days      **Defect Dimensions:** Length (m): 0.80      Width (m): 0.50      Depth (mm): 58.00

**Comments:** ?

**Defect Date:** 25-June-2024      **Defect Category:** ASPHALT POTHOLE (CAPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D13231A	100mm deep Asphalt c/w patch (14mm wc/ 20mm bc in HRA, 14/20 chips) - 0-1 m2	1.00	no	L 0.00      W 0.00      D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/11/2022  
Until Less Than: 27/11/2024

**Section:**  
7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	25 Jun 2024	<b>Inspect History ID &amp; Description:</b>	3110587 - 1 and 3 Monthly - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

Ref:	Defect Type:	Location Description:	Priority	Defect Dimensions:		
				Length (m):	Width (m):	Depth (mm):
<a href="#">DCD249105476</a>	THIRD PARTY REFERRAL	Ch 730 rhs at BT box/ BT box loose rocking rattling sunk.	R4 - next available programme			
<b>Comments:</b>	?					
<b>Defect Date:</b>	<b>Defect Category:</b>					
25-June-2024	UTILITY MANHOLE LID/COVER DEFECTIVE (UMDF)					

**Photographs or Documents attached:** Yes

**Stretch Comments:**



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/11/2022  
Until Less Than: 27/11/2024

**Section:**  
7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	09 Apr 2024	<b>Inspect History ID &amp; Description:</b>	3108934 - Full Sector - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

<b>Ref:</b> <a href="#">DCD249051265</a>	<b>Defect Type:</b> DEFECT	<b>Location Description:</b> Outlets and gullies need cleaned complete stretch lhs and rhs.	<b>Priority:</b> R4 - next available programme	<b>Defect Dimensions:</b>	<b>Length (m):</b>	<b>Width (m):</b>	<b>Depth (mm):</b>
---	-------------------------------	--	---	---------------------------	--------------------	-------------------	--------------------

**Comments:** ?

<b>Defect Date:</b> 09-April-2024	<b>Defect Category:</b> VERGE OUTLET OVERGROWN (VOOG)	<b>Completion Comments:</b> r4
--------------------------------------	---	-----------------------------------

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
X41000A	^ Scheduled cleaning of roadside outlet	1.00	no	L 0.00	W 0.00	D 0.00
X77000A	^ Scheduled cleaning of gully surround	1.00	no	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No

**Stretch Comments:**



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/11/2022  
Until Less Than: 27/11/2024

**Section:**  
7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	21 Dec 2023	<b>Inspect History ID &amp; Description:</b>	3107100 - 1 and 3 Monthly - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

**Ref:** [DCD238987965](#)      **Defect Type:** DEFECT      **Location Description:** Ch 465 rhs      **Priority:** R2 - 5 Working days      **Defect Dimensions:** Length (m): 0.70      Width (m): 0.60      Depth (mm): 70.00

**Comments:** ?

**Defect Date:** 21-December-2023      **Defect Category:** ASPHALT POTHOLE (CAPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D13231A	100mm deep Asphalt c/w patch (14mm wc/ 20mm bc in HRA, 14/20 chips) - 0-1 m2	1.00	no	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/11/2022  
Until Less Than: 27/11/2024

**Section:**  
7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	21 Dec 2023	<b>Inspect History ID &amp; Description:</b>	3107100 - 1 and 3 Monthly - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

<b>Ref:</b> <a href="#">DCD238987977</a>	<b>Defect Type:</b> DEFECT	<b>Location Description:</b> Outlets and gullies need cleaned complete stretch lhs and rhs	<b>Priority:</b> R4 - next available programme	<b>Defect Dimensions:</b>	<b>Length (m):</b>	<b>Width (m):</b>	<b>Depth (mm):</b>
---	-------------------------------	---	---	---------------------------	--------------------	-------------------	--------------------

**Comments:** ?

<b>Defect Date:</b> 21-December-2023	<b>Defect Category:</b> VERGE OUTLET OVERGROWN (VOOG)	<b>Completion Comments:</b> r4
---	---	-----------------------------------

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
X41000A	^ Scheduled cleaning of roadside outlet	1.00	no	L 0.00	W 0.00	D 0.00
X77000A	^ Scheduled cleaning of gully surround	1.00	no	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No

**Stretch Comments:**



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/11/2022  
Until Less Than: 27/11/2024

**Section:**  
7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	18 Sep 2023	<b>Inspect History ID &amp; Description:</b>	3105592 - Full Sector - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

**Ref:** [DCD238933456](#)      **Defect Type:** ROADS SERVICE REFERRAL      **Location Description:** At house number 333 rhs water ponding at entrance to house complaint from home owner.      **Priority:** R4 - next available programme      **Defect Dimensions:** Length (m):      Width (m):      Depth (mm):

**Comments:** Water ponding at house number 333 rhs complaint from home owner. Needs a gully.

**Defect Date:** 18-September-2023      **Defect Category:** WATER SEEPING (CWSP)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
U01001A	^ Unplanned drainage works norm.hrs (2-man operation)	1.00	HR	L 0.00      W 0.00      D 0.00

**Photographs or Documents attached:** No

**Ref:** [DCD238933462](#)      **Defect Type:** DEFECT      **Location Description:** Ch 0 to Ch 3040 lhs and rhs.      **Priority:** R4 - next available programme      **Defect Dimensions:** Length (m):      Width (m):      Depth (mm):

**Comments:** Cut briars lhs and rhs

**Defect Date:** 18-September-2023      **Defect Category:** TREES/BUSHES OVERHANGING PAVEMENT (TBOP)      **Completion Comments:** r4 dem

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
G42100A	^ Cut occassional briars both sides of roa	3.04	km	L 3.04      W 0.00      D 0.00

**Photographs or Documents attached:** No



## Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**

From: 01/11/2022

Until Less Than: 27/11/2024

**Section:**

7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

**Stretch Comments:**



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/11/2022  
Until Less Than: 27/11/2024

**Section:**  
7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	23 Jun 2023	<b>Inspect History ID &amp; Description:</b>	3104153 - 1 and 3 Monthly - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

<b>Ref:</b> <a href="#">DCD238891440</a>	<b>Defect Type:</b> ROADS SERVICE REFERRAL	<b>Location Description:</b> Complete stretch lhs and rhs Asphalt patches not done by Contractor.	<b>Priority:</b> R4 - next available programme	<b>Defect Dimensions:</b>			
<b>Comments:</b>	Asphalt patches still not done by Contractor						
<b>Defect Date:</b> 23-June-2023	<b>Defect Category:</b> PREVIOUSLY RECORDED NOT DONE (PRND)			<b>Length (m):</b>	<b>Width (m):</b>	<b>Depth (mm):</b>	

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D01001A	^ Unplanned patching work norm.hrs (2-man operation)	1.00	HR	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No

**Stretch Comments:**



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/11/2022  
Until Less Than: 27/11/2024

**Section:**  
7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	30 Mar 2023	<b>Inspect History ID &amp; Description:</b>	3102462 - Full Sector - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

<b>Ref:</b> <a href="#">DCD238835226</a>	<b>Defect Type:</b> DEFECT	<b>Location Description:</b> Ch 2506 lhs / rhs/ 2 number patches	<b>Priority</b> R2 - 5 Working days	<b>Defect Dimensions:</b>		
				<b>Length (m):</b> 2.00	<b>Width (m):</b> 0.50	<b>Depth (mm):</b> 52.00

**Comments:** 2 number patches

**Defect Date:** 30-March-2023  
**Defect Category:** ASPHALT POTHOLE (CAPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D13441A	^ 100mm patch 14mm W/C & 20mm B/C HRA <1m2	2.00	no	L 0.00	W 0.00	D 0.00
Z17771A	TTM on Trunk and A Class Rds - Hire and Maintenance of TM Equipment on Work Zone <= 500m	0.00	day	L 0.00	W 0.00	D 0.00
Z19731A	TTM on Trunk and A Class Rds - Design, Set Out, Install & Remove of TM on Works Zone =< 500m	0.00	item	L 0.00	W 0.00	D 0.00
Z19760A	TTM on Trunk and A Class Rds - Design, Set Out , Install & Remove of Approach Zone and End Zone	0.00	item	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/11/2022  
Until Less Than: 27/11/2024

**Section:**  
7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	30 Mar 2023	<b>Inspect History ID &amp; Description:</b>	3102462 - Full Sector - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

<b>Ref:</b> <a href="#">DCD238835233</a>	<b>Defect Type:</b> ROADS SERVICE REFERRAL	<b>Location Description:</b> Complete stretch lhs and rhs Asphalt patches not done by Contractor	<b>Priority:</b> R4 - next available programme	<b>Defect Dimensions:</b>			
<b>Comments:</b>	?			<b>Length (m):</b>	<b>Width (m):</b>	<b>Depth (mm):</b>	
<b>Defect Date:</b> 30-March-2023	<b>Defect Category:</b> PREVIOUSLY RECORDED NOT DONE (PRND)						

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D01001A	^ Unplanned patching work norm.hrs (2-man operation)	1.00	HR	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:** From: 01/11/2022 Until Less Than: 27/11/2024

**Section:** 7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	30 Mar 2023	<b>Inspect History ID &amp; Description:</b>	3102462 - Full Sector - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

<b>Ref:</b>	<b>Defect Type:</b>	<b>Location Description:</b>	<b>Priority</b>	<b>Defect Dimensions:</b>		
<a href="#">DCD238835247</a>	DEFECT	Ch 1978 Rhs	R2 - 5 Working days	<b>Length (m):</b> 1.80	<b>Width (m):</b> 1.20	<b>Depth (mm):</b> 71.00

**Comments:** ?

<b>Defect Date:</b>	<b>Defect Category:</b>
30-March-2023	ASPHALT POTHOLE (CAPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D13442A	^ 100mm patch 14mm /20mm HRA 1-3 m2	2.16	SQ.M	L 1.80	W 1.20	D 0.00
Z17771A	TTM on Trunk and A Class Rds - Hire and Maintenance of TM Equipment on Work Zone <= 500m	0.00	day	L 0.00	W 0.00	D 0.00
Z19731A	TTM on Trunk and A Class Rds - Design, Set Out, Install & Remove of TM on Works Zone =< 500m	0.00	item	L 0.00	W 0.00	D 0.00
Z19760A	TTM on Trunk and A Class Rds - Design, Set Out , Install & Remove of Approach Zone and End Zone	0.00	item	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/11/2022  
Until Less Than: 27/11/2024

**Section:**  
7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	30 Mar 2023	<b>Inspect History ID &amp; Description:</b>	3102462 - Full Sector - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

**Ref:** [DCD238835257](#)  
**Defect Type:** DEFECT  
**Location Description:** Ch 1734 lhs  
**Priority:** R2 - 5 Working days  
**Defect Dimensions:** Length (m): 1.20 Width (m): 0.70 Depth (mm): 52.00  
**Comments:** ?  
**Defect Date:** 30-March-2023  
**Defect Category:** ASPHALT POTHOLE (CAPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D13441A	^ 100mm patch 14mm W/C & 20mm B/C HRA <1m2	1.00	no	L 0.00	W 0.00	D 0.00
Z17771A	TTM on Trunk and A Class Rds - Hire and Maintenance of TM Equipment on Work Zone <= 500m	0.00	day	L 0.00	W 0.00	D 0.00
Z19731A	TTM on Trunk and A Class Rds - Design, Set Out, Install & Remove of TM on Works Zone =< 500m	0.00	item	L 0.00	W 0.00	D 0.00
Z19760A	TTM on Trunk and A Class Rds - Design, Set Out , Install & Remove of Approach Zone and End Zone	0.00	item	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/11/2022  
Until Less Than: 27/11/2024

**Section:**  
7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	30 Mar 2023	<b>Inspect History ID &amp; Description:</b>	3102462 - Full Sector - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

<b>Ref:</b> <a href="#">DCD238835262</a>	<b>Defect Type:</b> DEFECT	<b>Location Description:</b> Ch 1668 Rhs/ @ BT Pole 904 Rhs	<b>Priority</b> R2 - 5 Working days	<b>Defect Dimensions:</b>		
				<b>Length (m):</b>	<b>Width (m):</b>	<b>Depth (mm):</b>
				1.40	0.60	53.00

**Comments:**

**Defect Date:** 30-March-2023

**Defect Category:** ASPHALT POTHOLE (CAPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D13441A	^ 100mm patch 14mm W/C & 20mm B/C HRA <1m2	1.00	no	L 0.00	W 0.00	D 0.00
Z17771A	TTM on Trunk and A Class Rds - Hire and Maintenance of TM Equipment on Work Zone <= 500m	0.00	day	L 0.00	W 0.00	D 0.00
Z19731A	TTM on Trunk and A Class Rds - Design, Set Out, Install & Remove of TM on Works Zone =< 500m	0.00	item	L 0.00	W 0.00	D 0.00
Z19760A	TTM on Trunk and A Class Rds - Design, Set Out , Install & Remove of Approach Zone and End Zone	0.00	item	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/11/2022  
Until Less Than: 27/11/2024

**Section:**  
7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	30 Mar 2023	<b>Inspect History ID &amp; Description:</b>	3102462 - Full Sector - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

**Ref:** [DCD238835272](#)  
**Defect Type:** DEFECT  
**Location Description:** Ch 1687 lhs / opposite BT Pole 904  
**Priority:** R2 - 5 Working days  
**Defect Dimensions:** Length (m): 30.50 Width (m): 0.60 Depth (mm): 70.00  
**Comments:** ?  
**Defect Date:** 30-March-2023  
**Defect Category:** ASPHALT EDGE DETERIORATION (CAED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures					
D13444A	^ 100mm patch14mm /20mm HRA 15-50 m2	18.30	SQ.M	L	30.50	W	0.60	D	0.00
Z17771A	TTM on Trunk and A Class Rds - Hire and Maintenance of TM Equipment on Work Zone <= 500m	0.00	day	L	0.00	W	0.00	D	0.00
Z19731A	TTM on Trunk and A Class Rds - Design, Set Out, Install & Remove of TM on Works Zone =< 500m	0.00	item	L	0.00	W	0.00	D	0.00
Z19760A	TTM on Trunk and A Class Rds - Design, Set Out , Install & Remove of Approach Zone and End Zone	0.00	item	L	0.00	W	0.00	D	0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/11/2022  
Until Less Than: 27/11/2024

**Section:**  
7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	30 Mar 2023	<b>Inspect History ID &amp; Description:</b>	3102462 - Full Sector - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

<b>Ref:</b> <a href="#">DCD238835279</a>	<b>Defect Type:</b> DEFECT	<b>Location Description:</b> Ch 1574 lhs	<b>Priority</b> R2 - 5 Working days	<b>Defect Dimensions:</b>		
				<b>Length (m):</b> 2.40	<b>Width (m):</b> 0.50	<b>Depth (mm):</b> 52.00

**Comments:** ?

<b>Defect Date:</b> 30-March-2023	<b>Defect Category:</b> ASPHALT POTHOLE (CAPH)
--------------------------------------	---

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D13442A	^ 100mm patch 14mm /20mm HRA 1-3 m2	1.20	SQ.M	L 2.40	W 0.50	D 0.00
Z17771A	TTM on Trunk and A Class Rds - Hire and Maintenance of TM Equipment on Work Zone <= 500m	0.00	day	L 0.00	W 0.00	D 0.00
Z19731A	TTM on Trunk and A Class Rds - Design, Set Out, Install & Remove of TM on Works Zone =< 500m	0.00	item	L 0.00	W 0.00	D 0.00
Z19760A	TTM on Trunk and A Class Rds - Design, Set Out , Install & Remove of Approach Zone and End Zone	0.00	item	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/11/2022  
Until Less Than: 27/11/2024

**Section:**  
7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	30 Mar 2023	<b>Inspect History ID &amp; Description:</b>	3102462 - Full Sector - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

**Ref:** [DCD238835283](#)  
**Defect Type:** DEFECT  
**Location Description:** Ch 1555 lhs  
**Priority:** R2 - 5 Working days  
**Defect Dimensions:** Length (m): 4.60 Width (m): 0.60 Depth (mm): 57.00  
**Comments:** ?  
**Defect Date:** 30-March-2023  
**Defect Category:** ASPHALT POTHOLE (CAPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D13442A	^ 100mm patch 14mm /20mm HRA 1-3 m2	2.76	SQ.M	L 4.60	W 0.60	D 0.00
Z17771A	TTM on Trunk and A Class Rds - Hire and Maintenance of TM Equipment on Work Zone <= 500m	0.00	day	L 0.00	W 0.00	D 0.00
Z19731A	TTM on Trunk and A Class Rds - Design, Set Out, Install & Remove of TM on Works Zone =< 500m	0.00	item	L 0.00	W 0.00	D 0.00
Z19760A	TTM on Trunk and A Class Rds - Design, Set Out , Install & Remove of Approach Zone and End Zone	0.00	item	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/11/2022  
Until Less Than: 27/11/2024

**Section:**  
7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	30 Mar 2023	<b>Inspect History ID &amp; Description:</b>	3102462 - Full Sector - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

<b>Ref:</b> <a href="#">DCD238835288</a>	<b>Defect Type:</b> DEFECT	<b>Location Description:</b> Ch 1543 lhs	<b>Priority</b> R2 - 5 Working days	<b>Defect Dimensions:</b>		
				<b>Length (m):</b> 3.20	<b>Width (m):</b> 0.70	<b>Depth (mm):</b> 53.00

**Comments:** ?

<b>Defect Date:</b> 30-March-2023	<b>Defect Category:</b> ASPHALT POTHOLE (CAPH)
--------------------------------------	---

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D13442A	^ 100mm patch 14mm /20mm HRA 1-3 m2	2.24	SQ.M	L 3.20	W 0.70	D 0.00
Z17771A	TTM on Trunk and A Class Rds - Hire and Maintenance of TM Equipment on Work Zone <= 500m	0.00	day	L 0.00	W 0.00	D 0.00
Z19731A	TTM on Trunk and A Class Rds - Design, Set Out, Install & Remove of TM on Works Zone =< 500m	0.00	item	L 0.00	W 0.00	D 0.00
Z19760A	TTM on Trunk and A Class Rds - Design, Set Out , Install & Remove of Approach Zone and End Zone	0.00	item	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/11/2022  
Until Less Than: 27/11/2024

**Section:**  
7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	30 Mar 2023	<b>Inspect History ID &amp; Description:</b>	3102462 - Full Sector - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

**Ref:** [DCD238835291](#)  
**Defect Type:** DEFECT  
**Location Description:** Ch 1496 lhs  
**Priority:** R2 - 5 Working days  
**Defect Dimensions:** Length (m): 1.50 Width (m): 0.50 Depth (mm): 53.00  
**Comments:** ?  
**Defect Date:** 30-March-2023  
**Defect Category:** ASPHALT EDGE DETERIORATION (CAED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D13441A	^ 100mm patch 14mm W/C & 20mm B/C HRA <1m2	1.00	no	L 0.00	W 0.00	D 0.00
Z17771A	TTM on Trunk and A Class Rds - Hire and Maintenance of TM Equipment on Work Zone <= 500m	0.00	day	L 0.00	W 0.00	D 0.00
Z19731A	TTM on Trunk and A Class Rds - Design, Set Out, Install & Remove of TM on Works Zone =< 500m	0.00	item	L 0.00	W 0.00	D 0.00
Z19760A	TTM on Trunk and A Class Rds - Design, Set Out , Install & Remove of Approach Zone and End Zone	0.00	item	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/11/2022  
Until Less Than: 27/11/2024

**Section:**  
7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	30 Mar 2023	<b>Inspect History ID &amp; Description:</b>	3102462 - Full Sector - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

<b>Ref:</b> <a href="#">DCD238835308</a>	<b>Defect Type:</b> DEFECT	<b>Location Description:</b> Ch 1375 rhs	<b>Priority</b> R2 - 5 Working days	<b>Defect Dimensions:</b>		
				<b>Length (m):</b> 2.00	<b>Width (m):</b> 0.70	<b>Depth (mm):</b> 52.00

**Comments:** ?

**Defect Date:**  
30-March-2023

**Defect Category:**  
ASPHALT POTHOLE (CAPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D13442A	^ 100mm patch 14mm /20mm HRA 1-3 m2	1.40	SQ.M	L 2.00	W 0.70	D 0.00
Z17771A	TTM on Trunk and A Class Rds - Hire and Maintenance of TM Equipment on Work Zone <= 500m	0.00	day	L 0.00	W 0.00	D 0.00
Z19731A	TTM on Trunk and A Class Rds - Design, Set Out, Install & Remove of TM on Works Zone =< 500m	0.00	item	L 0.00	W 0.00	D 0.00
Z19760A	TTM on Trunk and A Class Rds - Design, Set Out , Install & Remove of Approach Zone and End Zone	0.00	item	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/11/2022  
Until Less Than: 27/11/2024

**Section:**  
7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	30 Mar 2023	<b>Inspect History ID &amp; Description:</b>	3102462 - Full Sector - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

**Ref:** [DCD238835321](#)  
**Defect Type:** DEFECT  
**Location Description:** Ch 1236 Rhs  
**Priority:** R2 - 5 Working days  
**Defect Dimensions:** Length (m): 1.60 Width (m): 1.30 Depth (mm): 54.00  
**Comments:** ?  
**Defect Date:** 30-March-2023  
**Defect Category:** ASPHALT POTHOLE (CAPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D13442A	^ 100mm patch 14mm /20mm HRA 1-3 m2	2.08	SQ.M	L 1.60	W 1.30	D 0.00
Z17771A	TTM on Trunk and A Class Rds - Hire and Maintenance of TM Equipment on Work Zone <= 500m	0.00	day	L 0.00	W 0.00	D 0.00
Z19731A	TTM on Trunk and A Class Rds - Design, Set Out, Install & Remove of TM on Works Zone =< 500m	0.00	item	L 0.00	W 0.00	D 0.00
Z19760A	TTM on Trunk and A Class Rds - Design, Set Out , Install & Remove of Approach Zone and End Zone	0.00	item	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/11/2022  
Until Less Than: 27/11/2024

**Section:**  
7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	30 Mar 2023	<b>Inspect History ID &amp; Description:</b>	3102462 - Full Sector - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

<b>Ref:</b> <a href="#">DCD238835330</a>	<b>Defect Type:</b> DEFECT	<b>Location Description:</b> Ch 1134 Rhs	<b>Priority</b> R2 - 5 Working days	<b>Defect Dimensions:</b>		
				<b>Length (m):</b> 1.10	<b>Width (m):</b> 1.10	<b>Depth (mm):</b> 60.00

**Comments:** ?

<b>Defect Date:</b> 30-March-2023	<b>Defect Category:</b> ASPHALT POTHOLE (CAPH)
--------------------------------------	---

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D13442A	^ 100mm patch 14mm /20mm HRA 1-3 m2	1.21	SQ.M	L 1.10	W 1.10	D 0.00
Z17771A	TTM on Trunk and A Class Rds - Hire and Maintenance of TM Equipment on Work Zone <= 500m	0.00	day	L 0.00	W 0.00	D 0.00
Z19731A	TTM on Trunk and A Class Rds - Design, Set Out, Install & Remove of TM on Works Zone =< 500m	0.00	item	L 0.00	W 0.00	D 0.00
Z19760A	TTM on Trunk and A Class Rds - Design, Set Out , Install & Remove of Approach Zone and End Zone	0.00	item	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/11/2022  
Until Less Than: 27/11/2024

**Section:**  
7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	30 Mar 2023	<b>Inspect History ID &amp; Description:</b>	3102462 - Full Sector - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

**Ref:** [DCD238835345](#)  
**Defect Type:** DEFECT  
**Location Description:** Ch 958 Rhs  
**Priority:** R2 - 5 Working days  
**Defect Dimensions:** Length (m): 1.10 Width (m): 1.60 Depth (mm): 60.00  
**Comments:** ?  
**Defect Date:** 30-March-2023  
**Defect Category:** ASPHALT POTHOLE (CAPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D13442A	^ 100mm patch 14mm /20mm HRA 1-3 m2	1.76	SQ.M	L 1.60	W 1.10	D 0.00
Z17771A	TTM on Trunk and A Class Rds - Hire and Maintenance of TM Equipment on Work Zone <= 500m	0.00	day	L 0.00	W 0.00	D 0.00
Z19731A	TTM on Trunk and A Class Rds - Design, Set Out, Install & Remove of TM on Works Zone =< 500m	0.00	item	L 0.00	W 0.00	D 0.00
Z19760A	TTM on Trunk and A Class Rds - Design, Set Out , Install & Remove of Approach Zone and End Zone	0.00	item	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/11/2022  
Until Less Than: 27/11/2024

**Section:**  
7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	30 Mar 2023	<b>Inspect History ID &amp; Description:</b>	3102462 - Full Sector - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

<b>Ref:</b> <a href="#">DCD238835373</a>	<b>Defect Type:</b> DEFECT	<b>Location Description:</b> Ch 938 Rhs	<b>Priority</b> R2 - 5 Working days	<b>Defect Dimensions:</b>		
				<b>Length (m):</b> 4.80	<b>Width (m):</b> 0.70	<b>Depth (mm):</b> 57.00

**Comments:** ?

<b>Defect Date:</b> 30-March-2023	<b>Defect Category:</b> ASPHALT EDGE DETERIORATION (CAED)
--------------------------------------	--

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D13442A	^ 100mm patch 14mm /20mm HRA 1-3 m2	3.36	SQ.M	L 4.80	W 0.70	D 0.00
Z17771A	TTM on Trunk and A Class Rds - Hire and Maintenance of TM Equipment on Work Zone <= 500m	0.00	day	L 0.00	W 0.00	D 0.00
Z19731A	TTM on Trunk and A Class Rds - Design, Set Out, Install & Remove of TM on Works Zone =< 500m	0.00	item	L 0.00	W 0.00	D 0.00
Z19760A	TTM on Trunk and A Class Rds - Design, Set Out , Install & Remove of Approach Zone and End Zone	0.00	item	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/11/2022  
Until Less Than: 27/11/2024

**Section:**  
7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	30 Mar 2023	<b>Inspect History ID &amp; Description:</b>	3102462 - Full Sector - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

**Ref:** [DCD238835385](#)  
**Defect Type:** DEFECT  
**Location Description:** Ch 800 Rhs  
**Priority:** R2 - 5 Working days  
**Defect Dimensions:** Length (m): 1.00 Width (m): 0.80 Depth (mm): 60.00  
**Comments:** ?  
**Defect Date:** 30-March-2023  
**Defect Category:** ASPHALT EDGE DETERIORATION (CAED)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D13441A	^ 100mm patch 14mm W/C & 20mm B/C HRA <1m2	1.00	no	L 0.00	W 0.00	D 0.00
Z17771A	TTM on Trunk and A Class Rds - Hire and Maintenance of TM Equipment on Work Zone <= 500m	0.00	day	L 0.00	W 0.00	D 0.00
Z19731A	TTM on Trunk and A Class Rds - Design, Set Out, Install & Remove of TM on Works Zone =< 500m	0.00	item	L 0.00	W 0.00	D 0.00
Z19760A	TTM on Trunk and A Class Rds - Design, Set Out , Install & Remove of Approach Zone and End Zone	0.00	item	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/11/2022  
Until Less Than: 27/11/2024

**Section:**  
7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	30 Mar 2023	<b>Inspect History ID &amp; Description:</b>	3102462 - Full Sector - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

<b>Ref:</b> <a href="#">DCD238835391</a>	<b>Defect Type:</b> DEFECT	<b>Location Description:</b> Ch 786 Rhs	<b>Priority</b> R2 - 5 Working days	<b>Defect Dimensions:</b>		
				<b>Length (m):</b> 1.40	<b>Width (m):</b> 1.20	<b>Depth (mm):</b> 53.00

**Comments:** ?

<b>Defect Date:</b> 30-March-2023	<b>Defect Category:</b> ASPHALT POTHOLE (CAPH)
--------------------------------------	---

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D13442A	^ 100mm patch 14mm /20mm HRA 1-3 m2	1.68	SQ.M	L 1.40	W 1.20	D 0.00
Z17771A	TTM on Trunk and A Class Rds - Hire and Maintenance of TM Equipment on Work Zone <= 500m	0.00	day	L 0.00	W 0.00	D 0.00
Z19731A	TTM on Trunk and A Class Rds - Design, Set Out, Install & Remove of TM on Works Zone =< 500m	0.00	item	L 0.00	W 0.00	D 0.00
Z19760A	TTM on Trunk and A Class Rds - Design, Set Out , Install & Remove of Approach Zone and End Zone	0.00	item	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/11/2022  
Until Less Than: 27/11/2024

**Section:**  
7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	30 Mar 2023	<b>Inspect History ID &amp; Description:</b>	3102462 - Full Sector - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

**Ref:** [DCD238835394](#)  
**Defect Type:** DEFECT  
**Location Description:** Ch 645 lhs / rhs  
**Priority:** R2 - 5 Working days  
**Defect Dimensions:** Length (m): 6.60 Width (m): 1.00 Depth (mm): 78.00  
**Comments:** ?  
**Defect Date:** 30-March-2023  
**Defect Category:** ASPHALT POTHOLE (CAPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D13443A	^ 100mm patch 14mm /20mm HRA 3-15 m2	6.60	SQ.M	L 6.60	W 1.00	D 0.00
Z17771A	TTM on Trunk and A Class Rds - Hire and Maintenance of TM Equipment on Work Zone <= 500m	0.00	day	L 0.00	W 0.00	D 0.00
Z19731A	TTM on Trunk and A Class Rds - Design, Set Out, Install & Remove of TM on Works Zone =< 500m	0.00	item	L 0.00	W 0.00	D 0.00
Z19760A	TTM on Trunk and A Class Rds - Design, Set Out , Install & Remove of Approach Zone and End Zone	0.00	item	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/11/2022  
Until Less Than: 27/11/2024

**Section:**  
7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	30 Mar 2023	<b>Inspect History ID &amp; Description:</b>	3102462 - Full Sector - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

<b>Ref:</b> <a href="#">DCD238835397</a>	<b>Defect Type:</b> DEFECT	<b>Location Description:</b> Ch 438 lhs	<b>Priority</b> R2 - 5 Working days	<b>Defect Dimensions:</b>		
				<b>Length (m):</b> 3.40	<b>Width (m):</b> 1.00	<b>Depth (mm):</b> 53.00

**Comments:** ?

**Defect Date:**  
30-March-2023

**Defect Category:**  
ASPHALT POTHOLE (CAPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D13443A	^ 100mm patch 14mm /20mm HRA 3-15 m2	3.40	SQ.M	L 3.40	W 1.00	D 0.00
Z17771A	TTM on Trunk and A Class Rds - Hire and Maintenance of TM Equipment on Work Zone <= 500m	0.00	day	L 0.00	W 0.00	D 0.00
Z19731A	TTM on Trunk and A Class Rds - Design, Set Out, Install & Remove of TM on Works Zone =< 500m	0.00	item	L 0.00	W 0.00	D 0.00
Z19760A	TTM on Trunk and A Class Rds - Design, Set Out , Install & Remove of Approach Zone and End Zone	0.00	item	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/11/2022  
Until Less Than: 27/11/2024

**Section:**  
7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	30 Mar 2023	<b>Inspect History ID &amp; Description:</b>	3102462 - Full Sector - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

**Ref:** [DCD238835404](#)  
**Defect Type:** DEFECT  
**Location Description:** Ch 412 Rhs  
**Priority:** R2 - 5 Working days  
**Defect Dimensions:** Length (m): 14.60 Width (m): 1.50 Depth (mm): 57.00  
**Comments:** ?  
**Defect Date:** 30-March-2023  
**Defect Category:** ASPHALT POTHOLE (CAPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D13444A	^ 100mm patch14mm /20mm HRA 15-50 m2	21.90	SQ.M	L 14.60	W 1.50	D 0.00
Z17771A	TTM on Trunk and A Class Rds - Hire and Maintenance of TM Equipment on Work Zone <= 500m	0.00	day	L 0.00	W 0.00	D 0.00
Z19731A	TTM on Trunk and A Class Rds - Design, Set Out, Install & Remove of TM on Works Zone =< 500m	0.00	item	L 0.00	W 0.00	D 0.00
Z19760A	TTM on Trunk and A Class Rds - Design, Set Out , Install & Remove of Approach Zone and End Zone	0.00	item	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/11/2022  
Until Less Than: 27/11/2024

**Section:**  
7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	30 Mar 2023	<b>Inspect History ID &amp; Description:</b>	3102462 - Full Sector - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

<b>Ref:</b> <a href="#">DCD238835421</a>	<b>Defect Type:</b> DEFECT	<b>Location Description:</b> Ch 382 lhs	<b>Priority</b> R2 - 5 Working days	<b>Defect Dimensions:</b>		
				<b>Length (m):</b> 15.20	<b>Width (m):</b> 1.30	<b>Depth (mm):</b> 57.00

**Comments:** ?

**Defect Date:**  
30-March-2023

**Defect Category:**  
ASPHALT POTHOLE (CAPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D13444A	^ 100mm patch14mm /20mm HRA 15-50 m2	19.76	SQ.M	L 15.20	W 1.30	D 0.00
Z17771A	TTM on Trunk and A Class Rds - Hire and Maintenance of TM Equipment on Work Zone <= 500m	0.00	day	L 0.00	W 0.00	D 0.00
Z19731A	TTM on Trunk and A Class Rds - Design, Set Out, Install & Remove of TM on Works Zone =< 500m	0.00	item	L 0.00	W 0.00	D 0.00
Z19760A	TTM on Trunk and A Class Rds - Design, Set Out , Install & Remove of Approach Zone and End Zone	0.00	item	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/11/2022  
Until Less Than: 27/11/2024

**Section:**  
7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	30 Mar 2023	<b>Inspect History ID &amp; Description:</b>	3102462 - Full Sector - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

**Ref:** [DCD238835431](#)  
**Defect Type:** DEFECT  
**Location Description:** Ch 377 Rhs  
**Priority:** R2 - 5 Working days  
**Defect Dimensions:** Length (m): 36.30 Width (m): 1.30 Depth (mm): 60.00  
**Comments:** ?  
**Defect Date:** 30-March-2023  
**Defect Category:** ASPHALT POTHOLE (CAPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures					
D13444A	^ 100mm patch14mm /20mm HRA 15-50 m2	47.19	SQ.M	L	36.30	W	1.30	D	0.00
Z17771A	TTM on Trunk and A Class Rds - Hire and Maintenance of TM Equipment on Work Zone <= 500m	0.00	day	L	0.00	W	0.00	D	0.00
Z19731A	TTM on Trunk and A Class Rds - Design, Set Out, Install & Remove of TM on Works Zone =< 500m	0.00	item	L	0.00	W	0.00	D	0.00
Z19760A	TTM on Trunk and A Class Rds - Design, Set Out , Install & Remove of Approach Zone and End Zone	0.00	item	L	0.00	W	0.00	D	0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/11/2022  
Until Less Than: 27/11/2024

**Section:**  
7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	30 Mar 2023	<b>Inspect History ID &amp; Description:</b>	3102462 - Full Sector - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

<b>Ref:</b> <a href="#">DCD238835445</a>	<b>Defect Type:</b> DEFECT	<b>Location Description:</b> Ch 312 lhs	<b>Priority</b> R2 - 5 Working days	<b>Defect Dimensions:</b>		
				<b>Length (m):</b> 20.00	<b>Width (m):</b> 1.20	<b>Depth (mm):</b> 56.00

**Comments:** ?

**Defect Date:**  
30-March-2023

**Defect Category:**  
ASPHALT POTHOLE (CAPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D13444A	^ 100mm patch14mm /20mm HRA 15-50 m2	24.00	SQ.M	L 20.00	W 1.20	D 0.00
Z17771A	TTM on Trunk and A Class Rds - Hire and Maintenance of TM Equipment on Work Zone <= 500m	0.00	day	L 0.00	W 0.00	D 0.00
Z19731A	TTM on Trunk and A Class Rds - Design, Set Out, Install & Remove of TM on Works Zone =< 500m	0.00	item	L 0.00	W 0.00	D 0.00
Z19760A	TTM on Trunk and A Class Rds - Design, Set Out , Install & Remove of Approach Zone and End Zone	0.00	item	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/11/2022  
Until Less Than: 27/11/2024

**Section:**  
7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	30 Mar 2023	<b>Inspect History ID &amp; Description:</b>	3102462 - Full Sector - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

**Ref:** [DCD238835471](#)  
**Defect Type:** DEFECT  
**Location Description:** Ch 157 lhs  
**Priority:** R2 - 5 Working days  
**Defect Dimensions:** Length (m): 39.00 Width (m): 1.00 Depth (mm): 55.00  
**Comments:** ?  
**Defect Date:** 30-March-2023  
**Defect Category:** ASPHALT POTHOLE (CAPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D13444A	^ 100mm patch14mm /20mm HRA 15-50 m2	39.00	SQ.M	L 39.00	W 1.00	D 0.00
Z17771A	TTM on Trunk and A Class Rds - Hire and Maintenance of TM Equipment on Work Zone <= 500m	0.00	day	L 0.00	W 0.00	D 0.00
Z19731A	TTM on Trunk and A Class Rds - Design, Set Out, Install & Remove of TM on Works Zone =< 500m	0.00	item	L 0.00	W 0.00	D 0.00
Z19760A	TTM on Trunk and A Class Rds - Design, Set Out , Install & Remove of Approach Zone and End Zone	0.00	item	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/11/2022  
Until Less Than: 27/11/2024

**Section:**  
7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	30 Mar 2023	<b>Inspect History ID &amp; Description:</b>	3102462 - Full Sector - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

<b>Ref:</b> <a href="#">DCD238835478</a>	<b>Defect Type:</b> DEFECT	<b>Location Description:</b> Ch 36 lhs	<b>Priority</b> R2 - 5 Working days	<b>Defect Dimensions:</b>		
				<b>Length (m):</b> 25.70	<b>Width (m):</b> 1.20	<b>Depth (mm):</b> 54.00

**Comments:** ?

<b>Defect Date:</b> 30-March-2023	<b>Defect Category:</b> ASPHALT POTHOLE (CAPH)
--------------------------------------	---

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D13444A	^ 100mm patch14mm /20mm HRA 15-50 m2	30.84	SQ.M	L 25.70	W 1.20	D 0.00
Z17771A	TTM on Trunk and A Class Rds - Hire and Maintenance of TM Equipment on Work Zone <= 500m	0.00	day	L 0.00	W 0.00	D 0.00
Z19731A	TTM on Trunk and A Class Rds - Design, Set Out, Install & Remove of TM on Works Zone =< 500m	0.00	item	L 0.00	W 0.00	D 0.00
Z19760A	TTM on Trunk and A Class Rds - Design, Set Out , Install & Remove of Approach Zone and End Zone	0.00	item	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/11/2022  
Until Less Than: 27/11/2024

**Section:**  
7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	30 Mar 2023	<b>Inspect History ID &amp; Description:</b>	3102462 - Full Sector - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

**Ref:** [DCD238835483](#)  
**Defect Type:** DEFECT  
**Location Description:** Ch 22 lhs  
**Priority:** R2 - 5 Working days  
**Defect Dimensions:** Length (m): 16.80 Width (m): 1.30 Depth (mm): 54.00  
**Comments:** ?  
**Defect Date:** 30-March-2023  
**Defect Category:** ASPHALT POTHOLE (CAPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D13444A	^ 100mm patch14mm /20mm HRA 15-50 m2	21.84	SQ.M	L 16.80	W 1.30	D 0.00
Z17771A	TTM on Trunk and A Class Rds - Hire and Maintenance of TM Equipment on Work Zone <= 500m	0.00	day	L 0.00	W 0.00	D 0.00
Z19731A	TTM on Trunk and A Class Rds - Design, Set Out, Install & Remove of TM on Works Zone =< 500m	0.00	item	L 0.00	W 0.00	D 0.00
Z19760A	TTM on Trunk and A Class Rds - Design, Set Out , Install & Remove of Approach Zone and End Zone	0.00	item	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No

**Stretch Comments:**



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
 From: 01/11/2022  
 Until Less Than: 27/11/2024

**Section:**  
 7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	12 Jan 2023	<b>Inspect History ID &amp; Description:</b>	3100313 - 1 and 3 Monthly - Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

<b>Ref:</b> <a href="#">DCD70-3100313-26</a>	<b>Defect Type:</b> DEFECT	<b>Location Description:</b> CH 1220 RHS	<b>Priority</b> R2 - 5 Working days	<b>Defect Dimensions:</b>		
				<b>Length (m):</b> 1.20	<b>Width (m):</b> 1.00	<b>Depth (mm):</b> 60.00

**Comments:**

<b>Defect Date:</b> 12-January-2023	<b>Defect Category:</b> ASPHALT POTHOLE (CAPH)
--	---

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D13442A	^ 100mm patch 14mm /20mm HRA 1-3 m2	1.20	SQ.M	L 1.20	W 1.00	D 0.00

**Photographs or Documents attached:** No

<b>Ref:</b> <a href="#">DCD70-3100313-27</a>	<b>Defect Type:</b> DEFECT	<b>Location Description:</b> CH 1343 LHS	<b>Priority</b> R2 - 5 Working days	<b>Defect Dimensions:</b>		
				<b>Length (m):</b> 0.60	<b>Width (m):</b> 0.50	<b>Depth (mm):</b> 61.00

**Comments:**

<b>Defect Date:</b> 12-January-2023	<b>Defect Category:</b> ASPHALT POTHOLE (CAPH)
--	---

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D13441A	^ 100mm patch 14mm W/C & 20mm B/C HRA <1m2	1.00	no	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
 From: 01/11/2022  
 Until Less Than: 27/11/2024

**Section:**  
 7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	12 Jan 2023	<b>Inspect History ID &amp; Description:</b>	3100313 - 1 and 3 Monthly - Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

<b>Ref:</b> <a href="#">DCD70-3100313-28</a>	<b>Defect Type:</b> DEFECT	<b>Location Description:</b> CH 1557 LHS	<b>Priority</b> R2 - 5 Working days	<b>Defect Dimensions:</b>		
				<b>Length (m):</b> 1.60	<b>Width (m):</b> 0.60	<b>Depth (mm):</b> 57.00

**Comments:**

<b>Defect Date:</b> 12-January-2023	<b>Defect Category:</b> ASPHALT POTHOLE (CAPH)
--	---

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D13441A	^ 100mm patch 14mm W/C & 20mm B/C HRA <1m2	1.00	no	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No

<b>Ref:</b> <a href="#">DCD70-3100313-29</a>	<b>Defect Type:</b> DEFECT	<b>Location Description:</b> CH 1853 RHS	<b>Priority</b> R2 - 5 Working days	<b>Defect Dimensions:</b>		
				<b>Length (m):</b> 0.80	<b>Width (m):</b> 0.50	<b>Depth (mm):</b> 88.00

**Comments:**

<b>Defect Date:</b> 12-January-2023	<b>Defect Category:</b> ASPHALT POTHOLE (CAPH)
--	---

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D13441A	^ 100mm patch 14mm W/C & 20mm B/C HRA <1m2	1.00	no	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:** From: 01/11/2022 Until Less Than: 27/11/2024

**Section:** 7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	12 Jan 2023	<b>Inspect History ID &amp; Description:</b>	3100313 - 1 and 3 Monthly - Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

<b>Ref:</b>	<b>Defect Type:</b>	<b>Location Description:</b>	<b>Priority</b>	<b>Defect Dimensions:</b>		
<a href="#">DCD70-3100313-30</a>	DEFECT	CH 2200 RHS	R2 - 5 Working days	<b>Length (m):</b> 5.00	<b>Width (m):</b> 1.80	<b>Depth (mm):</b> 90.00

**Comments:**

**Defect Date:** 12-January-2023

**Defect Category:** ASPHALT POTHOLE (CAPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D13443A	^ 100mm patch 14mm /20mm HRA 3-15 m2	9.00	SQ.M	L 5.00	W 1.80	D 0.00

**Photographs or Documents attached:** No

<b>Ref:</b>	<b>Defect Type:</b>	<b>Location Description:</b>	<b>Priority</b>	<b>Defect Dimensions:</b>		
<a href="#">DCD70-3100313-31</a>	THIRD PARTY REFERRAL	NIW TOBY LID MISSING / OPP HO NO 336 / ABOVE HO NO 333 / BT POLE 1472 RHS /@ CH 2200 RHS / PHONED [REDACTED] @ 13.55 TO PUT THROUGH TO NIW [REDACTED] @ 13.55	R4 - next available programme	<b>Length (m):</b>	<b>Width (m):</b>	<b>Depth (mm):</b>

**Comments:** NIW TOBY LID MISSING / OPP HO NO 336 / ABOVE HO NO 333 / BT POLE 1472 RHS PHONED [REDACTED] @ 13.55

**Defect Date:** 12-January-2023

**Defect Category:** UTILITY VALVE COVER BROKEN (UVBR)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
G01001A	^ Unplanned envir. work norm.hrs (2-man operation)	1.00	HR	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:** From: 01/11/2022 Until Less Than: 27/11/2024

**Section:** 7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	12 Jan 2023	<b>Inspect History ID &amp; Description:</b>	3100313 - 1 and 3 Monthly - Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

<b>Ref:</b> <a href="#">DCD70-3100313-32</a>	<b>Defect Type:</b> DEFECT	<b>Location Description:</b> CH 2345 RHS	<b>Priority</b> R2 - 5 Working days	<b>Defect Dimensions:</b>		
				<b>Length (m):</b> 2.00	<b>Width (m):</b> 1.30	<b>Depth (mm):</b> 70.00

**Comments:**

**Defect Date:** 12-January-2023

**Defect Category:** ASPHALT POTHOLE (CAPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D13442A	^ 100mm patch 14mm /20mm HRA 1-3 m2	2.60	SQ.M	L 2.00	W 1.30	D 0.00

**Photographs or Documents attached:** No

<b>Ref:</b> <a href="#">DCD70-3100313-33</a>	<b>Defect Type:</b> DEFECT	<b>Location Description:</b> CH 0 TO CH 3040 LHS / RHS	<b>Priority</b> R4 - next available programme	<b>Defect Dimensions:</b>	<b>Length (m):</b>	<b>Width (m):</b>	<b>Depth (mm):</b>
---	-------------------------------	---	--	---------------------------	--------------------	-------------------	--------------------

**Comments:** OUTLETS / GULLIES NEED CLEANED ROAD FLOODING /

**Defect Date:** 12-January-2023

**Defect Category:** VERGE OUTLET OVERGROWN (VOOG)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
X41000A	^ Scheduled cleaning of roadside outlet	1.00	no	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No

**Stretch Comments: ?**



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**

From: 01/11/2022

Until Less Than: 27/11/2024

**Section:**

7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	<b>Inspect History ID &amp; Description:</b>	3110191 - Full Sector - WFE Safety Inspection of BLC2-11-MID & EAST ANTRIM	<b>Inspector Name:</b>
<b>Class:</b> A Class	<b>Environment:</b> RURAL	<b>Traffic Level:</b> Medium Traffic	

<b>Type:</b> Ad Hoc Defect						
<b>Ref:</b> <a href="#">DCD249094007</a>	<b>Defect Type:</b> THIRD PARTY REFERRAL	<b>Location Description:</b> Bt Manhole lid frame loose rattling rocking sunk/ @ BT Pole 1455	<b>Priority:</b> R4 - next available programme	<b>Defect Dimensions:</b>		
				<b>Length (m):</b>	<b>Width (m):</b>	<b>Depth (mm):</b>
<b>Comments:</b>	?					

<b>Defect Date:</b> 05-June-2024	<b>Defect Category:</b> UTILITY MANHOLE LID/COVER DEFECTIVE (UMDF)
-------------------------------------	---

**Photographs or Documents attached:** Yes



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/11/2022  
Until Less Than: 27/11/2024

**Section:**  
7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	<b>Inspect History ID &amp; Description:</b>	3109533 - Full Sector - WFE Safety Inspection of BLC2-10-MID & EAST ANTRIM	<b>Inspector Name:</b>
<b>Class:</b> A Class	<b>Environment:</b> RURAL	<b>Traffic Level:</b> Medium Traffic	

**Type:** Ad Hoc Defect

<b>Ref:</b> <a href="#">DCD249083682</a>	<b>Defect Type:</b> THIRD PARTY REFERRAL	<b>Location Description:</b> At BT Pole 332 rhs/ near Quarrytown Road jct/ BT Manhole lid frame loose rattling rocking sunk.	<b>Priority:</b> R4 - next available programme	<b>Defect Dimensions:</b>		
				<b>Length (m):</b>	<b>Width (m):</b>	<b>Depth (mm):</b>

**Comments:** ?

<b>Defect Date:</b> 20-May-2024	<b>Defect Category:</b> UTILITY MANHOLE LID/COVER DEFECTIVE (UMDF)
------------------------------------	---

**Photographs or Documents attached:** Yes



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**

From: 01/11/2022

Until Less Than: 27/11/2024

**Section:**

7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

Commencement date of Inspection:	Ad Hoc Defect - See	Inspect History ID & Description:	Ad Hoc Defect - No Inspection ID	Inspector Name:
Class: A Class		Environment: RURAL	Traffic Level: Medium Traffic	



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:** From: 01/11/2022 Until Less Than: 27/11/2024

**Section:** 7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	<b>Ad Hoc Defect - See</b>	<b>Inspect History ID &amp; Description:</b>	<b>Ad Hoc Defect - No Inspection ID</b>	<b>Inspector Name:</b>
<b>Class: A Class</b>	<b>Environment: RURAL</b>	<b>Traffic Level: Medium Traffic</b>		

<b>Ref:</b> <a href="#">D238917335</a>	<b>Defect Type:</b> DEFECT	<b>Location Description:</b> Cushendall Road.	<b>Priority</b> R2 - 5 Working days	<b>Defect Dimensions:</b> <b>Length (m): 48.00</b>	<b>Width (m): 1.60</b>	<b>Depth (mm): 55.00</b>
---	-------------------------------	--	--	---	------------------------	--------------------------

**Comments:** Asphalt patches for road edge failure,  
  
As discussed on site with [REDACTED]  
  
48m x 1.6m,  
  
32m x 1.6m.

<b>Defect Date:</b> 17-August-2023	<b>Defect Category:</b> ASPHALT EDGE DETERIORATION (CAED)
---------------------------------------	--

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures			
D13444A	^ 100mm patch14mm /20mm HRA 15-50 m2	25.60	SQ.M	L 16.00	W 1.60	D 0.00	
D13444A	^ 100mm patch14mm /20mm HRA 15-50 m2	25.60	SQ.M	L 16.00	W 1.60	D 0.00	
D13444A	^ 100mm patch14mm /20mm HRA 15-50 m2	38.40	SQ.M	L 24.00	W 1.60	D 0.00	
D13444A	^ 100mm patch14mm /20mm HRA 15-50 m2	38.40	SQ.M	L 24.00	W 1.60	D 0.00	
Z17771A	TTM on Trunk and A Class Rds - Hire and Maintenance of TM Equipment on Work Zone <= 500m	0.00	day	L 0.00	W 0.00	D 0.00	



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:** From: 01/11/2022 Until Less Than: 27/11/2024

**Section:** 7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	<b>Ad Hoc Defect - See Inspect History ID &amp; Description:</b>	<b>Ad Hoc Defect - No Inspection ID</b>	<b>Inspector Name:</b>
<b>Class:</b> A Class	<b>Environment:</b> RURAL	<b>Traffic Level:</b> Medium Traffic	

<b>Ref:</b> <a href="#">D238917335</a>	<b>Defect Type:</b> DEFECT	<b>Location Description:</b> Cushendall Road.	<b>Priority</b> R2 - 5 Working days	<b>Defect Dimensions:</b>		
<b>Comments:</b>	Asphalt patches for road edge failure,  As discussed on site with JJ Boyd.  48m x 1.6m,  32m x 1.6m.					
	<b>Length (m):</b> 48.00	<b>Width (m):</b> 1.60	<b>Depth (mm):</b> 55.00			

<b>Defect Date:</b> 17-August-2023	<b>Defect Category:</b> ASPHALT EDGE DETERIORATION (CAED)
---------------------------------------	--

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
Z19731A	TTM on Trunk and A Class Rds - Design, Set Out, Install & Remove of TM on Works Zone =< 500m	0.00	item	L 0.00	W 0.00	D 0.00
Z19760A	TTM on Trunk and A Class Rds - Design, Set Out , Install & Remove of Approach Zone and End Zone	0.00	item	L 0.00	W 0.00	D 0.00
Z01700A	EO all items for Priority 2 response	707.02	%	L 0.00	W 0.00	D 0.00
Z01700A	EO all items for Priority 2 response	707.02	%	L 0.00	W 0.00	D 0.00
Z01700A	EO all items for Priority 2 response	1,060.54	%	L 0.00	W 0.00	D 0.00



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:** From: 01/11/2022 Until Less Than: 27/11/2024

**Section:** 7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	<b>Ad Hoc Defect - See</b>	<b>Inspect History ID &amp; Description:</b>	<b>Ad Hoc Defect - No Inspection ID</b>	<b>Inspector Name:</b>
<b>Class: A Class</b>	<b>Environment: RURAL</b>		<b>Traffic Level: Medium Traffic</b>	

<b>Ref:</b> <a href="#">D238917335</a>	<b>Defect Type:</b> DEFECT	<b>Location Description:</b> Cushendall Road.	<b>Priority</b> R2 - 5 Working days	<b>Defect Dimensions:</b>		
<b>Comments:</b>	Asphalt patches for road edge failure,  As discussed on site with JJ Boyd.  48m x 1.6m,  32m x 1.6m.					
	<b>Length (m):</b> 48.00	<b>Width (m):</b> 1.60	<b>Depth (mm): 55.00</b>			

<b>Defect Date:</b> 17-August-2023	<b>Defect Category:</b> ASPHALT EDGE DETERIORATION (CAED)
---------------------------------------	--

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
Z01700A	EO all items for Priority 2 response	1,060.54	%	L 0.00	W 0.00	D 0.00
Z01700A	EO all items for Priority 2 response	0.00	%	L 0.00	W 0.00	D 0.00
Z01700A	EO all items for Priority 2 response	0.00	%	L 0.00	W 0.00	D 0.00
Z01700A	EO all items for Priority 2 response	0.00	%	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:** From: 01/11/2022 Until Less Than: 27/11/2024

**Section:** 7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	<b>Ad Hoc Defect - See</b>	<b>Inspect History ID &amp; Description:</b>	<b>Ad Hoc Defect - No Inspection ID</b>	<b>Inspector Name:</b>
<b>Class: A Class</b>	<b>Environment: RURAL</b>	<b>Traffic Level: Medium Traffic</b>		

**Ref:** [D249034460](#)

**Defect Type:** DEFECT

**Location Description:** Cushendall Road  
100m south of house no. 347  
  
and Cushendall Road 60m south of junction with Clogher Road

**Priority:** R4 - next available programme

**Defect Dimensions:**  
**Length (m):**                      **Width (m):**                      **Depth (mm):**

**Comments:** Cattle Crossing Sign Face Missing  
Cushendall Road 100m south of house no. 347

Part Time Speed Limit Ahead sign for turning/Correction  
Cushendall Road 60m south of junction with Clogher Road

**Defect Date:** 07-March-2024

**Defect Category:** TRAFFIC SIGN MISSING (TSMI)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
R11224A	^ Triangular class 2 sign 900-1500mm high	1.00	no	L 0.00      W 0.00      D 0.00
R93210A	^ Repair sign face	1.00	no	L 0.00      W 0.00      D 0.00
R64212A	^ Clean sign 0-1sq.m	1.00	no	L 0.00      W 0.00      D 0.00
R64214A	^ Clean sign 3-6sq.m	1.00	no	L 0.00      W 0.00      D 0.00

**Photographs or Documents attached:** No





### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:** From: 01/01/2025 Until Less Than: 21/01/2025

**Section:** 7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	15 Jan 2025	<b>Inspect History ID &amp; Description:</b>	3114130 - 1 and 3 Monthly - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

**Ref:** [DCD259198663](#)

**Defect Type:** DEFECT

**Location Description:** At BT pole 1459 lhs / opposite house number 289

**Priority:** R2 - 5 Working days

**Defect Dimensions:** Length (m): 1.00 Width (m): 0.90 Depth (mm): 60.00

**Comments:** ?

**Defect Date:** 15-January-2025

**Defect Category:** ASPHALT POTHOLE (CAPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D13231A	100mm deep Asphalt c/w patch (14mm wc/ 20mm bc in HRA, 14/20 chips) - 0-1 m2	1.00	no	L 0.00	W 0.00	D 0.00
Z11310A	Footway or Verge Priority Signage TTM Closure in a 2xlane single c/way	0.00	item	L 0.00	W 0.00	D 0.00
Z11320A	Carriageway Priority Signage TTM Lane Closure to a 2xlane single c/way	0.00	item	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/01/2025  
Until Less Than: 21/01/2025

**Section:**  
7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	15 Jan 2025	<b>Inspect History ID &amp; Description:</b>	3114130 - 1 and 3 Monthly - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

<b>Ref:</b> <a href="#">DCD259198671</a>	<b>Defect Type:</b> DEFECT	<b>Location Description:</b> Patch number 2 rhs at Manhole	<b>Priority</b> R2 - 5 Working days	<b>Defect Dimensions:</b>		
				<b>Length (m):</b> 1.50	<b>Width (m):</b> 1.20	<b>Depth (mm):</b> 60.00

**Comments:** ?

<b>Defect Date:</b> 15-January-2025	<b>Defect Category:</b> ASPHALT POTHOLE (CAPH)
--	---

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D13232A	100mm deep Asphalt c/w patch (14mm wc/ 20mm bc in HRA, 14/20 chips) - 1-3 m2	1.80	m2	L 1.50	W 1.20	D 0.00
Z11310A	Footway or Verge Priority Signage TTM Closure in a 2xlane single c/way	0.00	item	L 0.00	W 0.00	D 0.00
Z11320A	Carriageway Priority Signage TTM Lane Closure to a 2xlane single c/way	0.00	item	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
 From: 01/01/2025  
 Until Less Than: 21/01/2025

**Section:**  
 7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	15 Jan 2025	<b>Inspect History ID &amp; Description:</b>	3114130 - 1 and 3 Monthly - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

**Ref:** [DCD259198680](#)

**Defect Type:** DEFECT

**Location Description:** Patch number 3 rhs / before Quarrytown Road Jct

**Priority:** R2 - 5 Working days

**Defect Dimensions:**  
 Length (m): 1.10    Width (m): 1.00    Depth (mm): 56.00

**Comments:** ?

**Defect Date:** 15-January-2025

**Defect Category:** ASPHALT POTHOLE (CAPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D13232A	100mm deep Asphalt c/w patch (14mm wc/ 20mm bc in HRA, 14/20 chips) - 1-3 m2	1.10	m2	L 1.10	W 1.00	D 0.00
Z11310A	Footway or Verge Priority Signage TTM Closure in a 2xlane single c/way	0.00	item	L 0.00	W 0.00	D 0.00
Z11320A	Carriageway Priority Signage TTM Lane Closure to a 2xlane single c/way	0.00	item	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/01/2025  
Until Less Than: 21/01/2025

**Section:**  
7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	15 Jan 2025	<b>Inspect History ID &amp; Description:</b>	3114130 - 1 and 3 Monthly - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

<b>Ref:</b> <a href="#">DCD259198682</a>	<b>Defect Type:</b> DEFECT	<b>Location Description:</b> Patch is 4 rhs at Quarrytown Road Jct	<b>Priority</b> R2 - 5 Working days	<b>Defect Dimensions:</b>		
				<b>Length (m):</b> 5.60	<b>Width (m):</b> 0.50	<b>Depth (mm):</b> 58.00

**Comments:** ?

<b>Defect Date:</b> 15-January-2025	<b>Defect Category:</b> ASPHALT POTHOLE (CAPH)
--	---

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D13232A	100mm deep Asphalt c/w patch (14mm wc/ 20mm bc in HRA, 14/20 chips) - 1-3 m2	2.80	m2	L 5.60	W 0.50	D 0.00
Z11310A	Footway or Verge Priority Signage TTM Closure in a 2xlane single c/way	0.00	item	L 0.00	W 0.00	D 0.00
Z11320A	Carriageway Priority Signage TTM Lane Closure to a 2xlane single c/way	0.00	item	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/01/2025  
Until Less Than: 21/01/2025

**Section:**  
7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	15 Jan 2025	<b>Inspect History ID &amp; Description:</b>	3114130 - 1 and 3 Monthly - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

**Ref:** [DCD259198692](#)  
**Defect Type:** DEFECT  
**Location Description:** Patch number 5 lhs /@ house number 304 lhs  
**Priority:** R2 - 5 Working days  
**Defect Dimensions:** Length (m): 5.20 Width (m): 0.70 Depth (mm): 55.00  
**Comments:** ?  
**Defect Date:** 15-January-2025  
**Defect Category:** ASPHALT POTHOLE (CAPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D13232A	100mm deep Asphalt c/w patch (14mm wc/ 20mm bc in HRA, 14/20 chips) - 1-3 m2	3.64	m2	L 5.20	W 0.70	D 0.00
Z11310A	Footway or Verge Priority Signage TTM Closure in a 2xlane single c/way	0.00	item	L 0.00	W 0.00	D 0.00
Z11320A	Carriageway Priority Signage TTM Lane Closure to a 2xlane single c/way	0.00	item	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
 From: 01/01/2025  
 Until Less Than: 21/01/2025

**Section:**  
 7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	15 Jan 2025	<b>Inspect History ID &amp; Description:</b>	3114130 - 1 and 3 Monthly - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

<b>Ref:</b> <a href="#">DCD259198735</a>	<b>Defect Type:</b> DEFECT	<b>Location Description:</b> Ch 2845 rhs / @ house number 337 rhs / patch number 6 rhs	<b>Priority</b> R2 - 5 Working days	<b>Defect Dimensions:</b>		
				<b>Length (m):</b> 0.60	<b>Width (m):</b> 0.50	<b>Depth (mm):</b> 54.00

**Comments:** ?

<b>Defect Date:</b> 15-January-2025	<b>Defect Category:</b> ASPHALT POTHOLE (CAPH)
--	---

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D13231A	100mm deep Asphalt c/w patch (14mm wc/ 20mm bc in HRA, 14/20 chips) - 0-1 m2	1.00	no	L 0.00	W 0.00	D 0.00
Z11310A	Footway or Verge Priority Signage TTM Closure in a 2xlane single c/way	0.00	item	L 0.00	W 0.00	D 0.00
Z11320A	Carriageway Priority Signage TTM Lane Closure to a 2xlane single c/way	0.00	item	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
 From: 01/01/2025  
 Until Less Than: 21/01/2025

**Section:**  
 7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	15 Jan 2025	<b>Inspect History ID &amp; Description:</b>	3114130 - 1 and 3 Monthly - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

**Ref:** [DCD259198741](#)

**Defect Type:** DEFECT

**Location Description:** Ch 0 to Ch 3040 lhs and rhs

**Priority:** R4 - next available programme

**Defect Dimensions:**  
 Length (m):                      Width (m):                      Depth (mm):

**Comments:** Cut briars lhs and rhs

**Defect Date:** 15-January-2025

**Defect Category:** TREES/BUSHES OVERHANGING PAVEMENT (TBOP)

**Completion Comments:** r4 jm

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
G42100A	^ Cut occassional briars both sides of roa	3.04	km	L 3.04	W 0.00	D 0.00

**Photographs or Documents attached:** No



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:** From: 01/01/2025 Until Less Than: 21/01/2025

**Section:** 7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

<b>Commencement date of Inspection:</b>	15 Jan 2025	<b>Inspect History ID &amp; Description:</b>	3114130 - 1 and 3 Monthly - WFE Safety Inspection of BLC2-09-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	RURAL	<b>Traffic Level:</b>	Medium Traffic

<b>Ref:</b> <a href="#">DCD259198744</a>	<b>Defect Type:</b> DEFECT	<b>Location Description:</b> Outlets and gullies need cleaned complete stretch lhs and rhs, complaint from residents road flooding.	<b>Priority:</b> R4 - next available programme	<b>Defect Dimensions:</b>	<b>Length (m):</b>	<b>Width (m):</b>	<b>Depth (mm):</b>
---	-------------------------------	--	---	---------------------------	--------------------	-------------------	--------------------

**Comments:** ?

<b>Defect Date:</b> 15-January-2025	<b>Defect Category:</b> VERGE OUTLET OVERGROWN (VOOG)	<b>Completion Comments:</b> r4
--	---	-----------------------------------

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
X41000A	^ Scheduled cleaning of roadside outlet	1.00	no	L 0.00	W 0.00	D 0.00
X77000A	^ Scheduled cleaning of gully surround	1.00	no	L 0.00	W 0.00	D 0.00

**Photographs or Documents attached:** No

**Stretch Comments:**





### Enquiries (By Road Section)

Road Section: 7020A0043\_03 CUSHENDALL RD: CLOUGHWATER RD TO LISNACROGHER RD

Date Range: From 01/11/2022 12:45:00 until less than 27/11/2024 12:46:00

Category: No filter  
Type: No filter  
Source: No filter  
Client Office: No filter  
Division: No filter  
Enquiry Status: No filter

Location: No filter

Assigned to: No filter

Enquiry ID:	Date/time Received:	Enquirer Name:	Input Type:	Enquiry Type:	Comments to Customer:	Location / Description:	Enquiry Received By:	Assigned to:	Date/time assigned	Internal Action Comments:	Status:
<a href="#">W231130496</a>	3/1/23 11:08 am	(1) [REDACTED]	Public Enquiry	Blocked Gully On Road	?	?	PIP	[REDACTED]	3/1/23 11:08 am	?	Standard - Completed Enquiries

PIP Comments: Blocked gully on road and surface ponding at 333/336 Cushendall Road Ballymena BT43 6PS

Date/time inspection: 6-Jan-2023  
Inspector Name: [REDACTED]  
NFA Category: Defect added to planned works programme  
NFA Comments: passed onto greentown for clean & jet  
Item Details:  
Defect Reference:

Photographs or Documents attached: No



### Enquiries (By Road Section)

Enquiry ID:	Date/time Received:	Enquirer Name:	Input Type:	Enquiry Type:	Comments to Customer:	Location / Description:	Enquiry Received By:	Assigned to:	Date/time assigned	Internal Action Comments:	Status:
<a href="#">W231141621</a>	30/1/23 6:19 pm	[REDACTED]	Public Enquiry	Pothole	?	?	PIP	[REDACTED]	30/1/23 6:19 pm	?	Standard - Completed Enquiries
					Date/time inspection:	Inspector Name:	NFA Category:	NFA Comments:	Item Details:	Defect Reference:	
					6-Feb-2023	[REDACTED]	Utility Notified (BT)	BT contractor to repair			
<p>PIP Comments: Folks there is a hole on the road, left hand side heading towards Ballymena just on the corner after the longest straight on that part of road. I hit it a number of days ago so was aware of it since and thought it had also maybe been marked a few days ago and since I first hit it. However, I am after hitting it again this evening as I was in a row of traffic and meeting a row of traffic. So it's bad enough and in a bad enough place that even being aware of it does not mean it can be avoided. Where it is at and the number of days it has been there now I am surprised there has not been a serious accident. I am concerned for the impact on my own car and I am sure others have had similar experience. Any chance of getting it sorted?</p>											
Photographs or Documents attached:					No						



### Enquiries (By Road Section)

Enquiry ID:	Date/time Received:	Enquirer Name:	Input Type:	Enquiry Type:	Comments to Customer:	Location / Description:	Enquiry Received By:	Assigned to:	Date/time assigned	Internal Action Comments:	Status:
<a href="#">W231142092</a>	1/2/23 11:27 am	(1) [Redacted] [Redacted] [Redacted] [Redacted] (5) [Redacted] [Redacted]	Public Enquiry	Pothole	?	?	PIP	[Redacted]	1/2/23 11:27 am	?	Standard - Completed Enquiries

Date/time inspection: 6-Feb-2023  
 Inspector Name: [Redacted]  
 NFA Category: Utility Notified (BT)  
 NFA Comments: BT contractor to repair, there defect on road  
 Item Details:  
 Defect Reference:

PIP Comments: Pot hole is on an already repaired surface, it is deep enough that I burst my tyre. it is also in a dangerous part of the road, where you are unable to avoid it, if there is oncoming traffic.

Photographs or Documents attached: Yes

Enquiry ID:	Date/time Received:	Enquirer Name:	Input Type:	Enquiry Type:	Comments to Customer:	Location / Description:	Enquiry Received By:	Assigned to:	Date/time assigned	Internal Action Comments:	Status:
<a href="#">W231142221</a>	1/2/23 3:38 pm	[Redacted] [Redacted] [Redacted]	Call Centre Public Enquiry	Pothole	?	?	PIP	[Redacted]	1/2/23 3:38 pm	?	Standard - Completed Enquiries

Date/time inspection: 6-Feb-2023  
 Inspector Name: [Redacted]  
 NFA Category: Utility Notified (BT)  
 NFA Comments: BT contractor to repair, they left defect in road  
 Item Details:  
 Defect Reference:

PIP Comments: pothole is not easily sited as on slight bend - is about 8-10 inches - caller is worried that if are motorcycle hit hit hit could be very dangerous

Photographs or Documents attached: No



### Enquiries (By Road Section)

Enquiry ID:	Date/time Received:	Enquirer Name:	Input Type:	Enquiry Type:	Comments to Customer:	Location / Description:	Enquiry Received By:	Assigned to:	Date/time assigned	Internal Action Comments:	Status:
<a href="#">W231142361</a>	1/2/23 11:59 pm	[REDACTED]	Call Centre Public Enquiry	Pothole	?	?	PIP	[REDACTED]	1/2/23 11:59 pm	?	Standard - Completed Enquiries

PIP Comments: Received 2 different calls about a pothole at this location tonight damaging car wheels. Contacted DS for. DS confirmed it is an NI Water issue and they have already been contacted.

Date/time inspection:	Inspector Name:	NFA Category:	NFA Comments:	Item Details:	Defect Reference:
6-Feb-2023	[REDACTED]	Utility Notified (BT)	BT contractor to repair		

Photographs or Documents attached: No

Enquiry ID:	Date/time Received:	Enquirer Name:	Input Type:	Enquiry Type:	Comments to Customer:	Location / Description:	Enquiry Received By:	Assigned to:	Date/time assigned	Internal Action Comments:	Status:
<a href="#">W231142646</a>	2/2/23 9:12 pm	(1) [REDACTED]	Public Enquiry	Pothole	?	?	PIP	[REDACTED]	2/2/23 9:12 pm	?	Standard - Completed Enquiries

PIP Comments: Really bad pothole Have witnessed 3 cars on separate occasions have to pull in due to flat or burst tyre from deep pot hole. Have also hit it twice but as I know where it is I know to watch our but others don't know

Date/time inspection:	Inspector Name:	NFA Category:	NFA Comments:	Item Details:	Defect Reference:
6-Feb-2023	[REDACTED]	Utility Notified (BT)	bt contractor to repair rd and liable for claims		

Photographs or Documents attached: No





### Enquiries (By Road Section)

Enquiry ID:	Date/time Received:	Enquirer Name:	Input Type:	Enquiry Type:	Comments to Customer:	Location / Description:	Enquiry Received By:	Assigned to:	Date/time assigned:	Internal Action Comments:	Status:
<a href="#">W231159980</a>	5/4/23 5:30 pm	(1) PSNI PSNI	Call Centre Incident (Major)	Traffic Collision	?	?	PIP	MID & EAST ANTRIM	5/4/23 5:30 pm	?	High Priority - Completed

Date/time inspection: Inspector Name: NFA Category: NFA Comments: Item Details: Defect Reference:

PIP Comments: 309 Cushendall Road, RTA Report from PSNI Inc 976050423 Oil and Debris on road from RTA

Photographs or Documents attached: No

**Incident Response Task**

Client Operative (Updated on App Only): <b>Brian.Tierney</b>	Can enquiry be closed without action by DFI Roads? <b>No</b>	Flood Treatment Options: ?	Is Follow-up Action Required? [Normal Office Hours] <b>Yes</b>
Instruct Contractor: <b>Yes</b>	Reason For No Action: ?	Number of Sandbags Deployed: <b>0</b>	Follow up Details: <b>? Need to lift signs</b>
Contractor: <b>ALL</b>	Is Traffic Progression Affected? <b>Yes</b>	Number of Gullies Cleared: <b>0</b>	Close / Complete Enquiry? <b>Yes</b>
O&M Supervisor: [Redacted]	Road Closure Type: <b>Full Closure</b>	Number of Properties Affected: <b>0</b>	Attendance Officer: [Redacted]
Date Contractor Instructed: <b>05/04/2023 17:39</b>	Closure Details: <b>? PSNI HAD ROAD CLOSED</b>	Number of Roads Affected: <b>0</b>	Attendance Date: <b>06/04/2023 19:59</b>
Client Comments: <b>Passed to OOH</b>	Was A Third Party Notified? <b>No</b>	Treatment Comments: ?	
	Third Party Comments: ?		
	Significant Newsworthy Incident? <b>No</b>		
	News Comments: ?		



### Enquiries (By Road Section)

Enquiry ID:	Date/time Received:	Enquirer Name:	Input Type:	Enquiry Type:	Comments to Customer:	Location / Description:	Enquiry Received By:	Assigned to:	Date/time assigned	Internal Action Comments:	Status:
<a href="#">W231160013</a>	5/4/23 8:35 pm	(1) PSNI PSNI	Call Centre Public Enquiry	Oil Spillage	?	?	PIP	MID & EAST ANTRIM	5/4/23 8:35 pm	Spoke with [redacted] who was happy that the Road surface had been treated and in addition has put out warning signs	High Priority - Completed

Date/time inspection: Inspector Name: NFA Category: NFA Comments: Item Details: Defect Reference:

PIP Comments: Oil spill from earlier, PSNI Crew still waiting on clean up

Photographs or Documents attached: No

Incident Response Task			
Client Operative (Updated on App Only): [redacted]	Can enquiry be closed without action by DFI Roads? <b>Yes</b>	Flood Treatment Options: ?	Is Follow-up Action Required? [Normal Office Hours] <b>No</b>
Instruct Contractor: <b>No</b>	Reason For No Action: [redacted] contacted and has already attended and	Number of Sandbags Deployed: <b>0</b>	Follow up Details: ?
Contractor: <b>ALL</b>	Is Traffic Progression Affected? <b>No</b>	Number of Gullies Cleared: <b>0</b>	Close / Complete Enquiry? <b>Please Select</b>
O&M Supervisor: <b>0</b>	Road Closure Type: <b>Please Select</b>	Number of Properties Affected: <b>0</b>	Attendance Officer: [redacted]
Date Contractor Instructed: <b>01/01/1900 00:00</b>	Closure Details: ?	Number of Roads Affected: <b>0</b>	Attendance Date: <b>05/04/2023 20:44</b>
Client Comments: ?	Was A Third Party Notified? <b>Yes</b>	Treatment Comments: ?	
	Third Party Comments: ?		
	Significant Newsworthy Incident? <b>No</b>		
	News Comments: ?		



### Enquiries (By Road Section)

Enquiry ID:	Date/time Received:	Enquirer Name:	Input Type:	Enquiry Type:	Comments to Customer:	Location / Description:	Enquiry Received By:	Assigned to:	Date/time assigned	Internal Action Comments:	Status:
<a href="#">W231171009</a>	18/5/23 4:51 pm	(1) [REDACTED]	Public Enquiry	Other Surface Defect (E.G. Broken Flag / Kerb)	Passed to contractor for repair, our contractor is currently not meeting large volume of work, however the work order has been issued and the work should be completed soon.	?	PIP	[REDACTED]	18/5/23 4:51 pm	?	Standard - Completed Enquiries
<b>Bulk NFA Details:</b>		This defect has been recorded following an inspection of line with current policy.									
<b>PIP Comments:</b> Pothole 2feet long 6 Inches wide marked with yellow paint approx 6weeks now along with other defects on this road STILL NOT repaired											
<b>Photographs or Documents attached:</b>					No						

Enquiry ID:	Date/time Received:	Enquirer Name:	Input Type:	Enquiry Type:	Comments to Customer:	Location / Description:	Enquiry Received By:	Assigned to:	Date/time assigned	Internal Action Comments:	Status:
<a href="#">W231184199</a>	24/7/23 9:27 am	(1) [REDACTED]	Public Enquiry	Pothole	Pothole has now been repaired, have passed to blocked gully to contractor	?	PIP	[REDACTED]	24/7/23 9:27 am	?	Standard - Completed Enquiries
<b>Bulk NFA Details:</b>		This defect has been included within works programme together with other planned work to be addressed in the future, subject to budgetary constraints.									
<b>PIP Comments:</b> Block drains and pot holes . Causing flooding in road and damage to car.											
<b>Photographs or Documents attached:</b>					No						

Enquiry ID:	Date/time Received:	Enquirer Name:	Input Type:	Enquiry Type:	Comments to Customer:	Location / Description:	Enquiry Received By:	Assigned to:	Date/time assigned	Internal Action Comments:	Status:
<a href="#">W231184393</a>	24/7/23 6:05 pm	(1) [REDACTED]	Public Enquiry	Pothole	Pothole has now been repaired, have passed to blocked gully to contractor	?	PIP	[REDACTED]	24/7/23 6:05 pm	?	Standard - Completed Enquiries
<b>Bulk NFA Details:</b>		This defect has been included within works programme together with other planned work to be addressed in the future, subject to budgetary constraints.									
<b>PIP Comments:</b> Next to 333 Cushendall Road											
<b>Photographs or Documents attached:</b>					Yes						



### Enquiries (By Road Section)

Enquiry ID:	Date/time Received:	Enquirer Name:	Input Type:	Enquiry Type:	Comments to Customer:	Location / Description:	Enquiry Received By:	Assigned to:	Date/time assigned:	Internal Action Comments:	Status:
<a href="#">W231185208</a>	28/7/23 2:32 pm	(1) [REDACTED]	FLOODING - Into inhabited building	Rainwater From Nearby Road (Into Inhabited Building)	Works order raised for Water Barr and kerb reinstatement.	385 Cushendall Road.	PIP	[REDACTED]	28/7/23 2:32 pm	Work order raised.	High Priority - Completed
					Date/time inspection:	Inspector Name:	NFA Category:	NFA Comments:	Item Details:	Defect Reference:	

PIP Comments: When it rains there is a puddle of water that goes into this mans house and the water also floods into the neighbours yard

Photographs or Documents attached: No

Incident Response Task			
Client Operative (Updated on App Only): <b>ALL USERS</b>	Can enquiry be closed without action by DFI Roads? <b>No</b>	Flood Treatment Options: ?	Is Follow-up Action Required? [Normal Office Hours] <b>No</b>
Instruct Contractor: <b>No</b>	Reason For No Action: ?	Number of Sandbags Deployed: <b>0</b>	Follow up Details: ?
Contractor: <b>ALL</b>	Is Traffic Progression Affected? <b>No</b>	Number of Gullies Cleared: <b>0</b>	Close / Complete Enquiry? <b>Yes</b>
O&M Supervisor: <b>0</b>	Road Closure Type: <b>Please Select</b>	Number of Properties Affected: <b>0</b>	Attendance Officer: [REDACTED]
Date Contractor Instructed: <b>28/07/2023 00:00</b>	Closure Details: ?	Number of Roads Affected: <b>0</b>	Attendance Date: <b>28/07/2023 00:00</b>
Client Comments: <b>Works order raised.</b>	Was A Third Party Notified? <b>No</b>	Treatment Comments: ?	
	Third Party Comments: ?		
	Significant Newsworthy Incident? <b>No</b>		
	News Comments: ?		



### Enquiries (By Road Section)

Enquiry ID:	Date/time Received:	Enquirer Name:	Input Type:	Enquiry Type:	Comments to Customer:	Location / Description:	Enquiry Received By:	Assigned to:	Date/time assigned	Internal Action Comments:	Status:
<a href="#">W241229205</a>	17/1/24 2:39 pm	(1) [REDACTED]	Call Centre Public Enquiry	Gritting Issue	Snow cleared, grit piles will be left on schedule before next period of bad weather.	?	PIP	[REDACTED]	17/1/24 2:39 pm	?	Standard - Completed Enquiries

**Bulk NFA Details:** It is not possible to salt all roads with available resources, therefore DfI Roads must treat areas with the highest traffic volumes that benefit the most road users. Footways are not treated. Salt boxes/piles may be provided for self-help use.

**PIP Comments:** Request for this road to be gritted also as people with special needs will be travelling between the rockwell road, cloughwater road & cushendall road

Photographs or Documents attached: No

Enquiry ID:	Date/time Received:	Enquirer Name:	Input Type:	Enquiry Type:	Comments to Customer:	Location / Description:	Enquiry Received By:	Assigned to:	Date/time assigned	Internal Action Comments:	Status:
<a href="#">W241245778</a>	27/2/24 11:55 am	(1) [REDACTED]	Public Enquiry	Missing Road Sign (General)	Cattle crossing sign and Part time Speed limit ahead sign passed to contractor for replacement/turning	Cushendall Road 100m south of house no. 347  and 60m south of junction with Clogher Road	PIP	[REDACTED]	27/2/24 11:55 am	Cattle crossing sign passed to O&M for replacement and School Part Time Speed Limit ahead sign passed to O&M to turn/correct	Standard - Completed Enquiries

**PIP Comments:** CATTLE CROSSING WARNING SIGN MISSING.      Date/time inspection: 7-Mar-2024      Inspector Name: All Users      NFA Category:      NFA Comments:      Item Details: TRAFFIC SIGN MISSING (TSMI)      Defect Reference: [D249034460](#)

Photographs or Documents attached: No



### Enquiries (By Road Section)

Enquiry ID:	Date/time Received:	Enquirer Name:	Input Type:	Enquiry Type:	Comments to Customer:	Location / Description:	Enquiry Received By:	Assigned to:	Date/time assigned	Internal Action Comments:	Status:
<a href="#">W241291327</a>	1/10/24 12:03 pm	(1) [Redacted]	Public Enquiry	Material Obstructing Passage (General)	Thank you for this enquiry. This has been inspected, a piece of material was removed from the carriageway near this location.	50m down from 333 Cushendall Road on carriageway	PIP	[Redacted]	1/10/24 12:03 pm	NFA Curtain removed from carriageway	High Priority - Completed
					Date/time inspection:	Inspector Name:	NFA Category:	NFA Comments:	Item Details:	Defect Reference:	

PIP Comments: objects on road drivers swerving to avoid

Photographs or Documents attached: No

#### Incident Response Task

Client Operative (Updated on App Only): <b>ALL USERS</b>	Can enquiry be closed without action by DFI Roads? <b>No</b>	Flood Treatment Options: ?	Is Follow-up Action Required? [Normal Office Hours] <b>No</b>
Instruct Contractor: <b>No</b>	Reason For No Action: ?	Number of Sandbags Deployed: <b>0</b>	Follow up Details: ?
Contractor: <b>ALL</b>	Is Traffic Progression Affected? <b>No</b>	Number of Gullies Cleared: <b>0</b>	Close / Complete Enquiry? <b>Yes</b>
O&M Supervisor: <b>0</b>	Road Closure Type: <b>Please Select</b>	Number of Properties Affected: <b>0</b>	Attendance Officer: <b>ALL USERS</b>
Date Contractor Instructed: <b>01/01/1900 00:00</b>	Closure Details: ?	Number of Roads Affected: <b>0</b>	Attendance Date: <b>01/01/1900 00:00</b>
Client Comments: <b>NFA Material removed from carriageway at this location</b>	Was A Third Party Notified? <b>No</b>	Treatment Comments: ?	
	Third Party Comments: ?		
	Significant Newsworthy Incident? <b>No</b>		
	News Comments: ?		



### Enquiries (By Road Section)

Enquiry ID:	Date/time Received:	Enquirer Name:	Input Type:	Enquiry Type:	Comments to Customer:	Location / Description:	Enquiry Received By:	Assigned to:	Date/time assigned:	Internal Action Comments:	Status:
<a href="#">W241301688</a>	27/11/24 8:07 am	(1) PSNI PSNI	Incident (major)	Collapse d Manhole Or Culvert	27/11/24 Contacted BT Contractor by phone and BT, through Symology. Job being organised for an emergency repair. LA1469511	?	PIP	[Redacted]	27/11/24 8:07 am	27/11/24 Contacted BT Contractor by phone and BT, through Symology. Job being organised for an emergency repair. LA 1469511	High Priority - Completed
	Date/time inspection:	Inspector Name:	NFA Category:	NFA Comments:	Item Details:	Defect Reference:					

PIP Comments: MOP reported to police that a manhole cover has come loose near the "Montgomery Straight" on the Cushendall Road

Photographs or Documents attached: No

Incident Response Task			
Client Operative (Updated on App Only): [Redacted]	Can enquiry be closed without action by DFI Roads? <b>No</b>	Flood Treatment Options: ?	Is Follow-up Action Required? [Normal Office Hours] <b>No</b>
Instruct Contractor: <b>No</b>	Reason For No Action: ?	Number of Sandbags Deployed: <b>0</b>	Follow up Details: <b>Passed to SO for action.</b>
Contractor: <b>ALL</b>	Is Traffic Progression Affected? <b>No</b>	Number of Gullies Cleared: <b>0</b>	Close / Complete Enquiry? <b>Yes</b>
O&M Supervisor: <b>0</b>	Road Closure Type: <b>Please Select</b>	Number of Properties Affected: <b>0</b>	Attendance Officer: [Redacted]
Date Contractor Instructed: <b>01/01/1900 00:00</b>	Closure Details: ?	Number of Roads Affected: <b>0</b>	Attendance Date: <b>27/11/2024 08:13</b>
Client Comments: ?	Was A Third Party Notified? <b>No</b>	Treatment Comments: ?	
	Third Party Comments: ?		
	Significant Newsworthy Incident? <b>No</b>		
	News Comments: ?		

### Enquiries (By Road Section)

