



PLC Report

Selection Criteria:

Section Code Selected: 7060U1411_02

C605

Report Start Date: 03/03/2020 00:00:00

Section Description: POLLOCK DR1: U1411 01 POLLOCK DR TO U1413 08 GLENFIELD RD

Report End Date (Less than): 16/06/2022 23:59:59

Enquiries

Enquiry ID	Enquiry Date	Received By	Enquirer's Name/Remark	Resp of	Class	Enquiry Cat/ Status/Type	Road ID/ Location
Call Centre Incident (Major)							
W2096060	02-Jun-2020	PIP			Informal	Call Centre Incident (Major) High Priority - Completed Manhole Cover missing	7060U1411_02 POLLOCK DR1: U1411 01 POLLOCK DR TO U1413 08 GLENFIELD RD ?
Call Centre Public Enquiry							
W2096060	02-Jun-2020	PIP			Informal	Call Centre Public Enquiry Standard - Completed Enquiries Pothole	7060U1411_02 POLLOCK DR1: U1411 01 POLLOCK DR TO U1413 08 GLENFIELD RD ?
W2110162	17-Mar-2021	PIP	Carla Lockhart		Informal	Call Centre Public Enquiry Standard - Completed Enquiries Pothole	7060U1411_02 POLLOCK DR1: U1411 01 POLLOCK DR TO U1413 08 GLENFIELD RD ?
Public Enquiry							
W2110155	14-Mar-2021	PIP			Informal	Public Enquiry Standard - Completed Enquiries Pothole	7060U1411_02 POLLOCK DR1: U1411 01 POLLOCK DR TO U1413 08 GLENFIELD RD ?
E2102460	22-Mar-2021		Carla Lockhart		Informal	Public Enquiry Standard - Completed Enquiries Pothole	7060U1411_02 POLLOCK DR1: U1411 01 POLLOCK DR TO U1413 08 GLENFIELD RD Pothole - Ramp outside Dickson Primary School, Lurgan
W2210761	31-Mar-2022	PIP			Informal	Public Enquiry Standard - Completed Enquiries Pothole	7060U1411_02 POLLOCK DR1: U1411 01 POLLOCK DR TO U1413 08 GLENFIELD RD ?

Inspection Defects

Defect Reference	Incident Date	Item Category/Detail	Location	Instruction Source	Defect Status	Response Time	Actual Completion
DCD73-3083878-	14/10/2020	DEFECT ASPHALT CRACKED (CACR)	SL 0127		Completed	R2 - 5 Working days	20-Oct-2020
					Inspection Histroy Name/UID: 3 Monthly - Safety Inspection of C605-BANBRIDGE / CRAIGAVON on 14 October 2020 / 3083878		
DCD73-3085366-11	21/01/2021	DEFECT BITMAC POTHOLE (CBPH)	HO 31		Completed	R2 - 5 Working days	23-Jan-2021
					Inspection Histroy Name/UID: 3 Monthly - Safety Inspection of C605 - BANBRIDGE / CRAIGAVON on 21 January 2021 / 3085366		
DCD73-3086187-61	16/03/2021	DEFECT BITMAC POTHOLE (CBPH)	HO 29		Completed	R2 - 5 Working days	17-Mar-2021
					Inspection Histroy Name/UID: 6 Monthly - Safety Inspection of C505-BANBRIDGE / CRAIGAVON on 11 March 2021 / 3086187		
DCD73-3086775-	19/04/2021	DEFECT ASPHALT POTHOLE (CAPH)	SCHOOL GATES		Completed	R2 - 5 Working days	26-Apr-2021
					Inspection Histroy Name/UID: 3 Monthly - Safety Inspection of C605 - BANBRIDGE / CRAIGAVON on 19 April 2021 / 3086775		
DCD73-3086775-	19/04/2021	DEFECT ASPHALT POTHOLE (CAPH)	HO 37		Completed	R2 - 5 Working days	26-Apr-2021
					Inspection Histroy Name/UID: 3 Monthly - Safety Inspection of C605 - BANBRIDGE / CRAIGAVON on 19 April 2021 / 3086775		
DCD73-3086775-	19/04/2021	DEFECT ASPHALT POTHOLE (CAPH)	SL 0124		Completed	R2 - 5 Working days	26-Apr-2021
					Inspection Histroy Name/UID: 3 Monthly - Safety Inspection of C605 - BANBRIDGE / CRAIGAVON on 19 April 2021 / 3086775		
DCD73-3089796-	15/10/2021	DEFECT ASPHALT POTHOLE (CAPH)	MINI RBT		Completed	R2 - 5 Working days	25-Oct-2021
					Inspection Histroy Name/UID: 3 Monthly - Safety Inspection of C605 - BANBRIDGE / CRAIGAVON on 15 October 2021 / 3089796		

Inspection Defects

Defect Reference	Incident Date	Item Category/Detail	Location	Instruction Source	Defect Status	Response Time	Actual Completion
DCD73-3091262-	17/01/2022	DEFECT ASPHALT POTHOLE (CAPH)	HO 31		Completed	R2 - 5 Working days	24-Jan-2022
					Inspection Histroy Name/UID: 3 Monthly - Safety Inspection of C605 - BANBRIDGE / CRAIGAVON on 17 January 2022 / 3091262		
DCD73-3091262-	17/01/2022	DEFECT	HO 37		Completed	R2 - 5 Working days	24-Jan-2022

ASPHALT POTHOLE (CAPH)

Inspection Histroy Name/UID: 3 Monthly - Safety Inspection of C605 - BANBRIDGE / CRAIGAVON on 17 January 2022 / 3091262

DCD73-3092600-	06/04/2022	DEFECT	HO 27	Completed	R2 - 5 Working days	11-Apr-2022
ASPHALT POTHOLE (CAPH)			Inspection Histroy Name/UID: 1 Monthly - Safety Inspection of C609 - BANBRIDGE / CRAIGAVON on 06 April 2022 / 3092600			

Defects Raised Outside of Inspections

Defect Reference	Incident Date	Item Category/Detail	Location	Instruction Source	Defect Status	Response Time	Actual Completion
------------------	---------------	----------------------	----------	--------------------	---------------	---------------	-------------------

No Defects Found Outside of Inspections For Selected Criteria

Inspections

Survey Date	Inspect History	Inspector	Driver	Weather	Surface Condit
21/04/2020	3080953 - 3 Monthly - Safety Inspection of C605-BANBRIDGE / CRAIGAVON on 21 April 2020			Fine	DRY
28/07/2020	3082436 - 3 Monthly - Safety Inspection of C605-BANBRIDGE / CRAIGAVON on 28 July 2020			Fine	DRY
14/10/2020	3083878 - 3 Monthly - Safety Inspection of C605-BANBRIDGE / CRAIGAVON on 14 October 2020			Fine	DRY
21/01/2021	3085366 - 3 Monthly - Safety Inspection of C605 - BANBRIDGE / CRAIGAVON on 21 January 2021			Fine	DRY
19/04/2021	3086775 - 3 Monthly - Safety Inspection of C605 - BANBRIDGE / CRAIGAVON on 19 April 2021			Fine	DRY
20/07/2021	3088280 - 3 Monthly - Safety Inspection of C605 - BANBRIDGE / CRAIGAVON on 19 July 2021			Fine	DRY
15/10/2021	3089796 - 3 Monthly - Safety Inspection of C605 - BANBRIDGE / CRAIGAVON on 15 October 2021			Fine	DRY
17/01/2022	3091262 - 3 Monthly - Safety Inspection of C605 - BANBRIDGE / CRAIGAVON on 17 January 2022			Fine	DRY
14/04/2022	3092772 - 3 Monthly - Safety Inspection of C605 - BANBRIDGE / CRAIGAVON on 14 April 2022			Fine	DRY



Inspection Report

Inspection Date:	See Recorded Date	Inspect History ID: 3092600 - 1 Monthly - Safety Inspection of C609 - BANBRIDGE / CRAIGAVON on 06 April 2022	Inspection Type:	1 Monthly - Safety Inspection
			Inspector:	

Section Code:	Section Description:
7060U1411_02	POLLOCK DR1: U1411 01 POLLOCK DR TO U1413 08 GLENFIELD RD

Defect Ref:	Defect Type:	Comments:	Location Description:	Priority	Defect Dimensions:					
DCD73-3092600-4	DEFECT		HO 27	R2 - 5 Working days	Length	0.60	Width (m):	0.30	Depth (mm):	70.00
Recorded Date:	ASPHALT POTHOLE (CAPH)									
06-April-2022										
Recorded By:										

Repair Description:	Repair Item Name:	Quantity	Units	Repair Measures							
D24021A	^ 70mm bit. patch w/c <1 m2	1.00	no	L	0.00	W	0.00	D	0.00		

Inspection Date:	14-Apr-2022	Inspect History ID: 3092772 - 3 Monthly - Safety Inspection of C605 - BANBRIDGE / CRAIGAVON on 14 April 2022	Inspection Type:	3 Monthly - Safety Inspection
			Inspector:	<input type="text"/>

No Defects found on: 7060U1411_02 - POLLOCK DR1: U1411 01 POLLOCK DR TO U1413 08 GLENFIELD RD by