



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:

From: 01/12/2023

Until Less Than: 03/02/2024

Section:

7060U6404_01 DOCK ST1: A0002 17 CHURCH ST TO U6404 02 MARINE PDE

Commencement date of Inspection:	17 Dec 2023	Inspect History ID & Description:	3107098 - 1 Monthly - WFE Safety Inspection of E648-NEWRY and MOURNE	Inspector Name:	<input type="text"/>
Class:	Unclassified	Environment:	URBAN	Traffic Level:	High Traffic
Comments:					

No Defects Found During Inspection

Photographs or Documents attached:





Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 01/12/2023
Until Less Than: 03/02/2024

Section:
7060U6404_03 HAVELOCK PL1: U6404 10 THOMAS ST TO U6404 09 GREAT GEORGES ST

Commencement date of Inspection:	17 Dec 2023	Inspect History ID & Description:	3107098 - 1 Monthly - WFE Safety Inspection of E648-NEWRY and MOURNE	Inspector Name:	<input type="text"/>
Class:	Unclassified	Environment:	URBAN	Traffic Level:	High Traffic

Ref: DCD238986308	Defect Type: THIRD PARTY REFERRAL	Location Description: Various locations along this rd	Priority: R4 - next available programme	Defect Dimensions: Length (m): 0.00 Width (m): 0.00 Depth (mm): 0.00
Comments: Someone has dug op footpath in various locations and bitmac again	Defect Category: SERVICE REINSTATEMENT DEFECTIVE (SRDF)			

Photographs or Documents attached: Yes





Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
 From: 01/12/2023
 Until Less Than: 03/02/2024

Section:
 7060U6404_02 MARINE PDE1: U6404 01 DOCK ST TO U6404 10 THOMAS ST

Commencement date of Inspection:	17 Dec 2023	Inspect History ID & Description:	3107098 - 1 Monthly - WFE Safety Inspection of E648-NEWRY and MOURNE	Inspector Name:	<input type="text"/>
Class:	Unclassified	Environment:	URBAN	Traffic Level:	High Traffic

Ref: [DCD238986304](#)
Defect Type: DEFECT
Location Description: Opp vecchia roma at sl 01 on parking area
Priority: R2 - 5 Working days
Defect Dimensions:
 Length (m): 0.30 Width (m): 0.30 Depth (mm): 40.00

Comments: ?

Defect Date: 17-December-2023
Defect Category: ASPHALT POTHOLE (CAPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D20051A	^ 70mm overlay bit.patch 14mm 0-1sqm.	1.00	no	L 0.00	W 0.00	D 0.00

Photographs or Documents attached: No

Ref: [DCD238986305](#)
Defect Type: THIRD PARTY REFERRAL
Location Description: Next door to the marine bar
Priority: R4 - next available programme
Defect Dimensions:
 Length (m): 0.00 Width (m): 0.00 Depth (mm): 0.00

Comments: Need to replace flags they broke,think it bt

Defect Date: 17-December-2023
Defect Category: SERVICE REINSTATEMENT DEFECTIVE (SRDF)

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
 From: 01/12/2023
 Until Less Than: 03/02/2024

Section:
 7060U6404_02 MARINE PDE1: U6404 01 DOCK ST TO U6404 10 THOMAS ST

Commencement date of Inspection:	17 Dec 2023	Inspect History ID & Description:	3107098 - 1 Monthly - WFE Safety Inspection of E648-NEWRY and MOURNE	Inspector Name:	<input type="text"/>
Class:	Unclassified	Environment:	URBAN	Traffic Level:	High Traffic

Ref: [DCD238986306](#)

Defect Type: DEFECT

Location Description: Opp Thomas st

Priority: R2 - 5 Working days

Defect Dimensions: Length (m): 0.45 Width (m): 0.40 Depth (mm): 45.00

Comments: Dig patches out

Defect Date: 17-December-2023

Defect Category: CONCRETE POTHOLE (CCPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D24021A	^ 70mm bit. patch w/c <1 m2	2.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No





Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:

From: 01/12/2023

Until Less Than: 03/02/2024

Section:

7060U6404_04 OSBORNE PROMENADE1: U6404 09 GREAT GEORGES ST TO U6404 08 PRINCESS ST

Commencement date of Inspection:	17 Dec 2023	Inspect History ID & Description:	3107098 - 1 Monthly - WFE Safety Inspection of E648-NEWRY and MOURNE	Inspector Name:	<input type="text"/>
Class:	Unclassified	Environment:	URBAN	Traffic Level:	High Traffic

Ref: DCD238986307	Defect Type: DEFECT	Location Description: 20m past sl 13	Priority R2 - 5 Working days	Defect Dimensions:		
Comments: Side entrance gully keeps off.need new gully				Length (m): 0.50	Width (m): 0.40	Depth (mm): 50.00
Defect Date: 17-December-2023	Defect Category: FOOTWAY GULLY LID HIGH (FGHH)					

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
U12262A	^ Reset f/way gully top 150-300mm	1.00	no	L 0.00	W 0.00	D 0.00
G01001A	^ Unplanned envir. work norm.hrs (2-man operation)	2.00	HR	L 0.00	W 0.00	D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:

From: 01/12/2023

Until Less Than: 03/02/2024

Section:

7060U6404_05 SEAVIEW1: U6404 08 PRINCESS ST TO A0002 19 SEAVIEW

Commencement date of Inspection:	17 Dec 2023	Inspect History ID & Description:	3107098 - 1 Monthly - WFE Safety Inspection of E648-NEWRY and MOURNE	Inspector Name:	<input type="text"/>
Class:	Unclassified	Environment:	URBAN	Traffic Level:	High Traffic
Comments:					

No Defects Found During Inspection

Photographs or Documents attached:

