



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**

From: 01/03/2024

Until Less Than: 30/06/2024

**Section:**

7020A0026\_45 LARNE RD LK1: BRIDGE STREET TO BRAIDWATER RBT

<b>Commencement date of Inspection:</b>	11 Jun 2024	<b>Inspect History ID &amp; Description:</b>	3108935 - 1 Monthly - WFE Safety Inspection of BLC1-08-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	URBAN	<b>Traffic Level:</b>	High Traffic
<b>Comments:</b>					

**No Defects Found During Inspection**

**Photographs or Documents attached:**

**Stretch Comments:**



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**

From: 01/03/2024

Until Less Than: 30/06/2024

**Section:**

7020A0026\_45 LARNE RD LK1: BRIDGE STREET TO BRAIDWATER RBT

<b>Commencement date of Inspection:</b>	01 Mar 2024	<b>Inspect History ID &amp; Description:</b>	3107882 - 1 Monthly - WFE Safety Inspection of BLC1-08-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	URBAN	<b>Traffic Level:</b>	High Traffic
<b>Comments:</b>					

**No Defects Found During Inspection**

**Photographs or Documents attached:**

**Stretch Comments:**





### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**

From: 01/03/2024

Until Less Than: 30/06/2024

**Section:**

7020A0026\_52 LARNE RD LK1: BRAIDWATER RBT TO BRIDGE STREET LINK (82)

<b>Commencement date of Inspection:</b>	11 Jun 2024	<b>Inspect History ID &amp; Description:</b>	3108935 - 1 Monthly - WFE Safety Inspection of BLC1-08-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	URBAN	<b>Traffic Level:</b>	High Traffic
<b>Comments:</b>					

**No Defects Found During Inspection**

**Photographs or Documents attached:**

**Stretch Comments:**



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**

From: 01/03/2024

Until Less Than: 30/06/2024

**Section:**

7020A0026\_52 LARNE RD LK1: BRAIDWATER RBT TO BRIDGE STREET LINK (82)

<b>Commencement date of Inspection:</b>	01 Mar 2024	<b>Inspect History ID &amp; Description:</b>	3107882 - 1 Monthly - WFE Safety Inspection of BLC1-08-MID & EAST ANTRIM	<b>Inspector Name:</b>	[REDACTED]
<b>Class:</b>	A Class	<b>Environment:</b>	URBAN	<b>Traffic Level:</b>	High Traffic
<b>Comments:</b>					

**No Defects Found During Inspection**

**Photographs or Documents attached:**

**Stretch Comments:**



### Defect Inspections (By Road Section) Report

Selection Criteria:

**Dates:**  
From: 01/03/2024  
Until Less Than: 30/06/2024

**Section:**  
7020A0026\_52 LARNE RD LK1: BRAIDWATER RBT TO BRIDGE STREET LINK (82)

<b>Commencement date of Inspection:</b>	<b>Ad Hoc Defect - See</b>	<b>Inspect History ID &amp; Description:</b>	<b>Ad Hoc Defect - No Inspection ID</b>	<b>Inspector Name:</b>
<b>Class: A Class</b>	<b>Environment: URBAN</b>	<b>Traffic Level: High Traffic</b>		

**Ref:** [D249081054](#)      **Defect Type:** DEFECT      **Location Description:** Larne Road Link      **Priority:** R4 - next available programme

In verge behind VRS barrier between SL101 and SL103 adjacent to Pets at Home

**Defect Dimensions:**  
**Length (m):**      **Width (m):**      **Depth (mm):**

**Comments:** Please cut back tree obstructing and clean sign face of give way/ Lane information sign following councillor complaints

**Defect Date:** 15-May-2024      **Defect Category:**  
 TRAFFIC SIGN  
 OVERGROWN (TSOG)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
Y10102A	Cut overgrowth >1.8m high	5.00	SQ.M	L 5.00      W 1.00      D 0.00
R64214A	^ Clean sign 3-6sq.m	1.00	no	L 0.00      W 0.00      D 0.00
R64100A	^ Clean sign post	1.00	no	L 0.00      W 0.00      D 0.00

**Photographs or Documents attached:** No

