



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 01/02/2017
Until Less Than: 28/02/2018

Section:
7020U2200_01 BROUGHSHANE ST1: A42 CHAPEL RBT TO BALLYMONEY STREET

Commencement date of Inspection:	15 Feb 2018	Inspect History ID & Description:	3067086 - 1 Monthly - Safety Inspection of BLC1-06-MID & EAST ANTRIM	Inspector Name:	[REDACTED]
Class:	Unclassified	Environment:	URBAN	Traffic Level:	High Traffic

Ref: DCD89-3067086-7	Defect Type: DEFECT	Comments:	Location Description: at crosskeys meats rd centre	Priority R2 - 5 Working days	Defect Dimensions: Length (m): 0.30 Width (m): 0.20 Depth (mm): 30.00
Defect Date: 15-February-2018	Defect Category: ASPHALT POTHOLE (CAPH)				

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D30061A	^ Temp. patch 6mm deferred set 0-1m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Ref: DCD89-3067086-8	Defect Type: THIRD PARTY REFERRAL	Comments: area failing	Location Description: at a mclean bookmakers	Priority R4 - next available programme	Defect Dimensions: Length (m): 2.10 Width (m): 1.00 Depth (mm): 21.00
Defect Date: 15-February-2018	Defect Category: SERVICE REINSTATEMENT DEFECTIVE (SRDF)				

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D01001A	^ Unplanned patching work norm.hrs	1.00	HR	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:

From: 01/02/2017

Until Less Than: 28/02/2018

Section:

7020U2200_01 BROUGHSHANE ST1: A42 CHAPEL RBT TO BALLYMONEY STREET

Commencement date of Inspection:	15 Feb 2018	Inspect History ID & Description:	3067086 - 1 Monthly - Safety Inspection of BLC1-06-MID & EAST ANTRIM	Inspector Name:	██████████
---	-------------	--	--	------------------------	------------

Class: Unclassified	Environment: URBAN	Traffic Level: High Traffic
----------------------------	---------------------------	------------------------------------

Ref: DCD89-3067086-9	Defect Type: THIRD PARTY REFERRAL	Comments: new olay potholing	Location Description: traffic lights near northern bank	Priority R4 - next available programme	Defect Dimensions:		
Defect Date: 15-February-2018	Defect Category: HAZARD CAUSED BY ON-GOING WORKS (SAOW)				Length (m):	Width (m):	Depth (mm):

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
D01001A	^ Unplanned patching work norm.hrs	1.00	HR	L 0.00	W 0.00	D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:

From: 01/02/2017

Until Less Than: 28/02/2018

Section:

7020U2200_01 BROUGHSHANE ST1: A42 CHAPEL RBT TO BALLYMONEY STREET

Commencement date of Inspection:	08 Jan 2018	Inspect History ID & Description:	3066141 - Full Sector - Safety Inspection of BLC1-06-MID & EAST ANTRIM	Inspector Name:	[REDACTED]
Class: Unclassified		Environment: URBAN		Traffic Level: High Traffic	

No Defects Found During Inspection

Photographs or Documents attached:



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 01/02/2017
Until Less Than: 28/02/2018

Section:
7020U2200_01 BROUGHSHANE ST1: A42 CHAPEL RBT TO BALLYMONEY STREET

Commencement date of Inspection: 16 Nov 2017 **Inspect History ID & Description:** 3065692 - 1 Monthly - Safety Inspection of BLC1-06-MID & EAST ANTRIM **Inspector Name:** [REDACTED]

Class: Unclassified **Environment:** URBAN **Traffic Level:** High Traffic

Ref: DCD95-3065692-17	Defect Type: DEFECT	Comments:	Location Description: at abbey insurance	Priority R2 - 5 Working days	Defect Dimensions: Length (m): 0.40 Width (m): 0.20 Depth (mm): 25.00		
Defect Date: 16-November-2017	Defect Category: ASPHALT POTHOLE (FAPH)						
Repair Losi Code: D30061A		Repair Item Name: ^ Temp. patch 6mm deferred set 0-1m2	Quantity 1.00	Units no	Repair Measures L 0.00 W 0.00 D 0.00		

Photographs or Documents attached: No

Ref: DCD95-3065692-18	Defect Type: DEFECT	Comments:	Location Description: loading area at country furnishings	Priority R2 - 5 Working days	Defect Dimensions: Length (m): 0.50 Width (m): 0.15 Depth (mm): 30.00		
Defect Date: 16-November-2017	Defect Category: ASPHALT EDGE DETERIORATION (CAED)						
Repair Losi Code: D30061A		Repair Item Name: ^ Temp. patch 6mm deferred set 0-1m2	Quantity 1.00	Units no	Repair Measures L 0.00 W 0.00 D 0.00		

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 01/02/2017
Until Less Than: 28/02/2018

Section:
7020U2200_01 BROUGHSHANE ST1: A42 CHAPEL RBT TO BALLYMONEY STREET

Commencement date of Inspection: 16 Nov 2017 **Inspect History ID & Description:** 3065692 - 1 Monthly - Safety Inspection of BLC1-06-MID & EAST ANTRIM **Inspector Name:** [REDACTED]

Class: Unclassified **Environment:** URBAN **Traffic Level:** High Traffic

Ref: DCD95-3065692-19	Defect Type: DEFECT	Comments:	Location Description: jct granville dr	Priority R2 - 5 Working days	Defect Dimensions: Length (m): 0.20 Width (m): 0.20 Depth (mm): 30.00		
Defect Date: 16-November-2017	Defect Category: ASPHALT POTHOLE (FAPH)						
Repair Losi Code: D30061A		Repair Item Name: ^ Temp. patch 6mm deferred set 0-1m2	Quantity 1.00	Units no	Repair Measures L 0.00 W 0.00 D 0.00		

Photographs or Documents attached: No

Ref: DCD95-3065692-20	Defect Type: DEFECT	Comments:	Location Description: jct broadway ave	Priority R2 - 5 Working days	Defect Dimensions: Length (m): 0.30 Width (m): 0.30 Depth (mm): 25.00		
Defect Date: 16-November-2017	Defect Category: ASPHALT POTHOLE (CAPH)						
Repair Losi Code: D30061A		Repair Item Name: ^ Temp. patch 6mm deferred set 0-1m2	Quantity 2.00	Units no	Repair Measures L 0.00 W 0.00 D 0.00		

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 01/02/2017
Until Less Than: 28/02/2018

Section:
7020U2200_01 BROUGHSHANE ST1: A42 CHAPEL RBT TO BALLYMONEY STREET

Commencement date of Inspection: 24 Oct 2017 **Inspect History ID & Description:** 3065195 - 1 Monthly - Safety Inspection of BLC1-06-MID & EAST ANTRIM **Inspector Name:** [REDACTED]

Class: Unclassified **Environment:** URBAN **Traffic Level:** High Traffic

Ref: DCD95-3065195-16	Defect Type: DEFECT	Comments:	Location Description: on roundabout	Priority R2 - 5 Working days	Defect Dimensions: Length (m): 0.20 Width (m): 0.20 Depth (mm): 25.00		
Defect Date: 24-October-2017	Defect Category: ASPHALT POTHOLE (CAPH)						
Repair Losi Code: D30061A		Repair Item Name: ^ Temp. patch 6mm deferred set 0-1m2	Quantity 2.00	Units no	Repair Measures L 0.00 W 0.00 D 0.00		

Photographs or Documents attached: No

Ref: DCD95-3065195-17	Defect Type: DEFECT	Comments:	Location Description: gully at sl 2	Priority R2 - 5 Working days	Defect Dimensions: Length (m): 0.20 Width (m): 0.20 Depth (mm): 22.00		
Defect Date: 24-October-2017	Defect Category: ASPHALT POTHOLE (CAPH)						
Repair Losi Code: D30061A		Repair Item Name: ^ Temp. patch 6mm deferred set 0-1m2	Quantity 1.00	Units no	Repair Measures L 0.00 W 0.00 D 0.00		

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 01/02/2017
Until Less Than: 28/02/2018

Section:
7020U2200_01 BROUGHSHANE ST1: A42 CHAPEL RBT TO BALLYMONEY STREET

Commencement date of Inspection: 24 Oct 2017 **Inspect History ID & Description:** 3065195 - 1 Monthly - Safety Inspection of BLC1-06-MID & EAST ANTRIM **Inspector Name:** [REDACTED]

Class: Unclassified **Environment:** URBAN **Traffic Level:** High Traffic

Ref: DCD95-3065195-18	Defect Type: DEFECT	Comments: rocking highly tactile flag	Location Description: jct suffolk st broughshane st	Priority: R2 - 5 Working days	Defect Dimensions: Length (m): 0.40 Width (m): 0.20 Depth (mm): 25.00		
Defect Date: 24-October-2017	Defect Category: FLAGS HIGH (FFHI)						

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures			
M33540A	^ Lift & relay tactile slab.	1.00	SQ.M	L 1.00	W 1.00	D 0.00	

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:

From: 01/02/2017

Until Less Than: 28/02/2018

Section:

7020U2200_01 BROUGHSHANE ST1: A42 CHAPEL RBT TO BALLYMONEY STREET

Commencement date of Inspection:	25 Sep 2017	Inspect History ID & Description:	3064721 - 1 and 3 Monthly - Safety Inspection of BLC1-06-MID & EAST ANTRIM	Inspector Name:	[REDACTED]
Class:	Unclassified	Environment:	URBAN	Traffic Level:	High Traffic

No Defects Found During Inspection

Photographs or Documents attached:



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:

From: 01/02/2017

Until Less Than: 28/02/2018

Section:

7020U2200_01 BROUGHSHANE ST1: A42 CHAPEL RBT TO BALLYMONEY STREET

Commencement date of Inspection:	15 Aug 2017	Inspect History ID & Description:	3064230 - 1 Monthly - Safety Inspection of BLC1-06-MID & EAST ANTRIM	Inspector Name:	[REDACTED]
Class: Unclassified		Environment: URBAN		Traffic Level: High Traffic	

No Defects Found During Inspection

Photographs or Documents attached:



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:

From: 01/02/2017

Until Less Than: 28/02/2018

Section:

7020U2200_01 BROUGHSHANE ST1: A42 CHAPEL RBT TO BALLYMONEY STREET

Commencement date of Inspection:	18 Jul 2017	Inspect History ID & Description:	3063813 - 1 Monthly - Safety Inspection of BLC1-06-MID & EAST ANTRIM	Inspector Name:	[REDACTED]
Class:	Unclassified	Environment:	URBAN	Traffic Level:	High Traffic

No Defects Found During Inspection

Photographs or Documents attached:



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 01/02/2017
Until Less Than: 28/02/2018

Section:
7020U2200_01 BROUGHSHANE ST1: A42 CHAPEL RBT TO BALLYMONEY STREET

Commencement date of Inspection:	14 Jun 2017	Inspect History ID & Description:	3063229 - Full Sector - Safety Inspection of BLC1-06-MID & EAST ANTRIM	Inspector Name:	[REDACTED]
Class:	Unclassified	Environment:	URBAN	Traffic Level:	High Traffic

Ref: DCD67-3063229-10	Defect Type: DEFECT	Comments: failed at gully	Location Description: on summerfield roundabout at gully	Priority R2 - 5 Working days	Defect Dimensions:		
					Length (m): 0.30	Width (m): 0.30	Depth (mm): 35.00
Defect Date: 14-June-2017	Defect Category: ASPHALT POTHOLE (CAPH)						

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures			
D30061A	^ Temp. patch 6mm deferred set 0-1m2	1.00	no	L 0.00	W 0.00	D 0.00	

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 01/02/2017
Until Less Than: 28/02/2018

Section:
7020U2200_01 BROUGHSHANE ST1: A42 CHAPEL RBT TO BALLYMONEY STREET

Commencement date of Inspection: 16 May 2017 **Inspect History ID & Description:** 3062772 - 1 Monthly - Safety Inspection of BLC1-06-MID & EAST ANTRIM **Inspector Name:** [REDACTED]

Class: Unclassified **Environment:** URBAN **Traffic Level:** High Traffic

Ref: DCD67-3062772-6	Defect Type: DEFECT	Comments:	Location Description: at crosskeys meats	Priority R2 - 5 Working days	Defect Dimensions:		
Defect Date: 16-May-2017	Defect Category: ASPHALT POTHOLE (FAPH)				Length (m): 0.40	Width (m): 0.20	Depth (mm): 45.00

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures			
D30061A	^ Temp. patch 6mm deferred set 0-1m2	1.00	no	L 0.00	W 0.00	D 0.00	

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:

From: 01/02/2017

Until Less Than: 28/02/2018

Section:

7020U2200_01 BROUGHSHANE ST1: A42 CHAPEL RBT TO BALLYMONEY STREET

Commencement date of Inspection:	11 Apr 2017	Inspect History ID & Description:	3061616 - 1 Monthly - Safety Inspection of BLC1-06-MID & EAST ANTRIM	Inspector Name:	[REDACTED]
Class: Unclassified		Environment: URBAN		Traffic Level: High Traffic	

No Defects Found During Inspection

Photographs or Documents attached:



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:

From: 01/02/2017

Until Less Than: 28/02/2018

Section:

7020U2200_01 BROUGHSHANE ST1: A42 CHAPEL RBT TO BALLYMONEY STREET

Commencement date of Inspection:	20 Mar 2017	Inspect History ID & Description:	3061570 - 1 and 3 Monthly - Safety Inspection of BLC1-06-MID & EAST ANTRIM	Inspector Name:	[REDACTED]
Class: Unclassified		Environment: URBAN		Traffic Level: High Traffic	

No Defects Found During Inspection

Photographs or Documents attached:



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 01/02/2017
Until Less Than: 28/02/2018

Section:
7020U2200_01 BROUGHSHANE ST1: A42 CHAPEL RBT TO BALLYMONEY STREET

Commencement date of Inspection:	13 Feb 2017	Inspect History ID & Description:	3061057 - 1 Monthly - Safety Inspection of BLC1-06-MID & EAST ANTRIM	Inspector Name:	[REDACTED]
Class:	Unclassified	Environment:	URBAN	Traffic Level:	High Traffic

Ref: [DCD67-3061057-8](#) **Defect Type:** DEFECT **Comments:** **Location Description:** at crosskeys meats **Priority:** R2 - 5 Working days **Defect Dimensions:** Length (m): 0.30 Width (m): 0.20 Depth (mm): 35.00

Defect Date: 13-February-2017 **Defect Category:** ASPHALT POTHOLE (CAPH)

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures		
Z01700A	EO all items for Priority 2 response	15.56	%	L 0.00	W 0.00	D 0.00
Z01700A	EO all items for Priority 2 response	15.56	%	L 0.00	W 0.00	D 0.00
Z01700A	EO all items for Priority 2 response	15.56	%	L 0.00	W 0.00	D 0.00
D16041A	^ 45mm patch 14mm asphalt 0-1 m2	1.00	no	L 0.00	W 0.00	D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 01/02/2017
Until Less Than: 28/02/2018

Section:
7020U2200_01 BROUGHSHANE ST1: A42 CHAPEL RBT TO BALLYMONEY STREET

Commencement date of Inspection: Ad Hoc Defect - See Inspect History ID & Description: Ad Hoc Defect - No Inspection ID **Inspector Name:** [REDACTED]

Class: Unclassified **Environment:** URBAN **Traffic Level:** High Traffic

Ref: D1800550	Defect Type: DEFECT	Comments: [REDACTED]	Location Description: AT CROSSING DIAMONDS SHOP	Priority R2 - 5 Working days	Defect Dimensions: Length (m): 3.00	Width (m): 1.00	Depth (mm): 21.00
---	-------------------------------	--------------------------------	--	--	--	------------------------	--------------------------

Defect Date: 09-January-2018	Defect Category: ASPHALT POTHOLE (CAPH)
--	--

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D13443A	^ 100mm patch 14mm /20mm HRA 3-15 m2	3.00	SQ.M	L 3.00 W 1.00 D 0.00

Photographs or Documents attached: No

Ref: D1800552	Defect Type: DEFECT	Comments: [REDACTED]	Location Description: AT NURSERY SHOP	Priority R2 - 5 Working days	Defect Dimensions: Length (m): 2.00	Width (m): 1.00	Depth (mm): 21.00
---	-------------------------------	--------------------------------	--	--	--	------------------------	--------------------------

Defect Date: 09-January-2018	Defect Category: ASPHALT POTHOLE (CAPH)
--	--

Repair Losi Code:	Repair Item Name:	Quantity	Units	Repair Measures
D13442A	^ 100mm patch 14mm /20mm HRA 1-3 m2	2.00	SQ.M	L 2.00 W 1.00 D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:

From: 01/02/2017

Until Less Than: 28/02/2018

Section:

7020U2200_01 BROUGHSHANE ST1: A42 CHAPEL RBT TO BALLYMONEY STREET

